

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:		1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM		5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM			
IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assessment Category
8 CAD #:	D2B	Interior Boiler Insulation Interior Burner Refractory	BOILER ROOM (1351)	6 Sq Ft	N	ASSUMED	5
Comments: TWO (2) BOILERS.					Sample #:		
20 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	1941 ADDITION STAGE (1253)	300 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
51 CAD #:	V0C	Sink Undercoating Black	ROOM 2245	15 Sq Ft	N	5 CH	5
Comments: THREE (3) SINKS.					Sample #:		
52 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 2245	40 Sq Ft	N	ASSUMED	5
Comments: BEHIND SINKS.					Sample #:		
57 CAD #:	K3B	Miscellaneous Flooring Black Floor Mastic (1941)	LIBRARY (2250)	1200 Sq Ft	N	10 CH	5
Comments: UNDER CARPET ON NORTH SIDE OF ROOM.					Sample #:	021109ML-47	
58 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	LIBRARY (2250)	100 Sq Ft	N	ASSUMED	5
Comments: AT SOUTH WALL BEHIND CABINETS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
59 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	LIBRARY (2250)	15 Sq Ft	N	ASSUMED	5
Comments: ON SOUTH SIDE BEHIND CABINETS.					Sample #:		
63 CAD #:	P0D	Fire Doors Warnock Hersey -Wood 1 Hr Rating	1924 ORIGINAL BUILDING EAST & WEST STAIRWELL	180 Sq Ft	N	ASSUMED	5
Comments: 2 SETS PER FLOOR.					Sample #:		
66 CAD #:	X1B	Miscellaneous Material 6" X 6" Red Quarry Floor Tile System	1924 ORIGINAL BUILDING EAST STAIRWELL	900 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
74 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	ROOM 2255	15 Sq Ft	N	ASSUMED	5
Comments: MOST BEHIND WHITEBOARD.					Sample #:		
80 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	ROOM 2254	15 Sq Ft	N	ASSUMED	5
Comments: PARTIALLY COVERED BY WHITEBOARDS.					Sample #:		
97 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	2ND FLOOR HALLWAY OUTSIDE ROOM 3245	18 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
101 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 3245	880 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
102 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 3245	20 Sq Ft	N	5 CH	5
Comments: WHITE PUCKS.					Sample #: 072511MV-02		
104 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 3245	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
108 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 3248	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
109 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 3248	20 Sq Ft	N	5 CH	5
Comments:					Sample #:		
110 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 3248	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
114 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 3250	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
115 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 3250	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
116 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 3250	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
118 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 3251	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
119 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 3251	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
122 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 3253	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
123 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 3253	15 Sq Ft	N	5 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
124 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 3253	70 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
128 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 3252	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
129 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 3252	15 Sq Ft	N	5 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
130 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 3252	70 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
139 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	ROOM 3257	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
145 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	ROOM 3254	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
162 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	4TH FLOOR HALLWAY OUTSIDE ROOM 4247	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
164 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 4247	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
165 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 4247	20 Sq Ft	N	5 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
166 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 4247	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
170 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 4250	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
171 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 4250	20 Sq Ft	N	5 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
172 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 4250	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
176 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 4250A	140 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
178 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 4255	700 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
179 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 4255	15 Sq Ft	N	5 CH	5
Comments:					Sample #:		
180 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 4255	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
185 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1941 Addition	ROOM 4252	900 Sq Ft	N	ASSUMED	5
Comments: UNDER 12" TILE.					Sample #:		
186 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1941)	ROOM 4252	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
187 CAD #:	X0T	Miscellaneous Material Wood Frame Corkboard Adhesive (1941)	ROOM 4252	50 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
190 CAD #:	V0C	Sink Undercoating Black	ROOM 4252	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #: 021109ML-50		
199 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	ROOM 4259	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
205 CAD #:	X0B	Miscellaneous Material Wood Frame Chalkboard Adhesive (1924)	ROOM 4258	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
211 CAD #:	B2C	Millboard Pipe Insulation 1954 Addition	HALLWAY OUTSIDE ROOMS 1105 & 1107	10 Lin Ft	N	5 CH	5
Comments: ESTIMATED IN WALL CHASE FEEDING DRINKING FOUNTAINS. SOME VISIBLE FROM ABOVE CEILING. INACCESSIBLE FOR REMOVAL.					Sample #: ACB-450T-A012		
212 CAD #:	A2C	Mudded Pipe Joints on Millboard Insulation 1954 Addition	HALLWAY OUTSIDE ROOMS 1105 & 1107	2 Joints	N	45 CH, 5 AM	5
Comments: IN WALL CHASE FEEDING DRINKING FOUNTAIN. VISIBLE FROM ABOVE CEILING. INACCESSIBLE FOR REMOVAL.					Sample #:		
216 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/11A	1954 ADDITION GYMNASIUM/LUNCH ROOM (1110)	750 Sq Ft	N	3 CH	5
Comments:					Sample #:		
217 CAD #:	T0A	Light Cord Insulation 1954 Addition	1954 ADDITION GYMNASIUM/LUNCH ROOM (1110)	5 Lin Ft	N	ASSUMED	5
Comments: SIX (6) LIGHTS WITH CHORDS ASSUMED. DIFFICULT TO VERIFY. VERIFY PRIOR TO REPLACEMENT OR DISTURBANCE.					Sample #:		
219 CAD #:	B2C	Millboard Pipe Insulation 1954 Addition	ROOM 1105	15 Lin Ft	N	5 CH	5
Comments: IN WALL CHASE FEEDING SINK. VISIBLE FROM ABOVE CEILING IN HALLWAY. INACCESSIBLE FOR REMOVAL.					Sample #:		
220 CAD #:	A2C	Mudded Pipe Joints on Millboard Insulation 1954 Addition	ROOM 1105	2 Joints	N	45 CH, 5 AM	5
Comments: IN WALL CHASE FEEDING SINK. VISIBLE FROM ABOVE CEILING IN HALLWAY. INACCESSIBLE FOR REMOVAL.					Sample #:		
224 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 1105	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
225 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 1105	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
226 CAD #:	X1C	Miscellaneous Material Multi Sized Brown Ceramic Floor Tile System	RESTROOMS 1104 AND 1106	350 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
227 CAD #:	X1D	Miscellaneous Material 4" X 4" Teal Ceramic Wall Tile System	RESTROOM 1104	350 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
228 CAD #:	X1E	Miscellaneous Material 4" X 4" Yellow Ceramic Wall Tile System	RESTROOM 1106	350 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
229 CAD #:	B2C	Millboard Pipe Insulation 1954 Addition	ROOM 1107	12 Lin Ft	N	5 CH	5
Comments: IN WALL CHASE FEEDING SINK. VISIBLE FROM ABOVE CEILING IN HALLWAY. INACCESSIBLE FOR REMOVAL.					Sample #:		
230 CAD #:	A2C	Mudded Pipe Joints on Millboard Insulation 1954 Addition	ROOM 1107	2 Joints	N	45 CH, 5 AM	5
Comments: IN WALL CHASE FEEDING SINK. VISIBLE FROM ABOVE CEILING IN HALLWAY. INACCESSIBLE FOR REMOVAL.					Sample #:		
233 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 1107	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
234 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 1107	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
237 CAD #:	B2C	Millboard Pipe Insulation 1954 Addition	ROOM 1109	12 Lin Ft	N	5 CH	5
Comments: IN WALL CHASE FEEDING SINK. VISIBLE FROM ABOVE CEILING IN HALLWAY. INACCESSIBLE FOR REMOVAL.					Sample #:		
238 CAD #:	A2C	Mudded Pipe Joints on Millboard Insulation 1954 Addition	ROOM 1109	2 Joints	N	45 CH, 5 AM	5
Comments: IN WALL CHASE FEEDING SINK. VISIBLE FROM ABOVE CEILING IN HALLWAY. INACCESSIBLE FOR REMOVAL.					Sample #: 021109ML-60		
242 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 1109	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
243 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 1109	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
244 CAD #:	X0F	Miscellaneous Material Tan Terrazzo-Look Sheet Vinyl	ROOM 1109	12 Sq Ft	N	30 CH	5
Comments: ON COUNTERTOP NEAR SINK.					Sample #: 021109ML-56		
253 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1111	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
254 CAD #:	X0V	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 1111	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
261 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1114	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
262 CAD #:	X0V	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 1114	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
269 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	RAMP (TA5)	100 Sq Ft	N	3 CH	5
Comments:					Sample #: 021109ML-31		
281 CAD #:	P0B	Fire Doors Metal - 1-1/2 Hr Rating (Underwriter's Laboratories)	MECHANICAL ROOM (2303A)	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
284 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Dark Brown with Red Streaks	ROOM 2304	250 Sq Ft	N	8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: ASSUMED UNDER CARPET. VISIBLE AT THRESHOLD.					Sample #:		
290 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Dark Brown with Red Streaks	OFFICE NORTH OF ROOM 2304	150 Sq Ft	N	8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: UNDER CARPET.					Sample #: 081121CW-01		
295 CAD #:	X1E	Miscellaneous Material 4" X 4" Yellow Ceramic Wall Tile System	STAFF ROOM 2307 RESTROOM	140 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
301 CAD #:	X1E	Miscellaneous Material 4" X 4" Yellow Ceramic Wall Tile System	ROOM 2309 RESTROOM	140 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
303 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 2102	10 Sq Ft	N	3 CH	5
Comments: AT ENTRANCE.					Sample #:		
308 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 2102	5 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.					Sample #:		
309 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2102	175 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
311 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	STORAGE ROOM 2102A	45 Sq Ft	N	3 CH	5
Comments:					Sample #: 031709-ML-01		
313 CAD #:	X1C	Miscellaneous Material Multi Sized Brown Ceramic Floor Tile System	RESTROOM 2102B	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
315 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 2104	10 Sq Ft	N	3 CH	5
Comments: AT ENTRANCE.					Sample #:		
320 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 2104	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
321 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2104	175 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
323 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	STORAGE ROOM 2104A	45 Sq Ft	N	3 CH	5
Comments: EXPOSED ADHESIVE PUCKS WHERE TILES ARE MISSING.					Sample #:		
325 CAD #:	X1C	Miscellaneous Material Multi Sized Brown Ceramic Floor Tile System	RESTROOM 2104B	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
328 CAD #:	X1C	Miscellaneous Material Multi Sized Brown Ceramic Floor Tile System	BOYS' RESTROOM 2108	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
329 CAD #:	X1D	Miscellaneous Material 4" X 4" Teal Ceramic Wall Tile System	BOYS' RESTROOM 2108	400 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
332 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 2109	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.					Sample #:		
333 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2109	60 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
336 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 2109A	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.					Sample #:		
337 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2109A	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
339 CAD #:	X1C	Miscellaneous Material Multi Sized Brown Ceramic Floor Tile System	GIRLS' RESTROOM 2110	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
340 CAD #:	X1G	Miscellaneous Material 4" X 4" Pink Ceramic Wall Tile System	GIRLS' RESTROOM 2110	400 Sq Ft	N	ASSUMED	5
Comments: CRACKING AT BASE. MONITOR.					Sample #:		
347 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 2111	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
348 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2111	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
352 CAD #:	X0D	Miscellaneous Material Metal Frame Chalkboard Adhesive (1954)	ROOM 2113	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
353 CAD #:	X0U	Miscellaneous Material Metal Frame Corkboard Adhesive (1954)	ROOM 2113	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
362 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 2114	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
363 CAD #:	X0V	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 2114	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
368 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 2115	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
369 CAD #:	X0V	Miscellaneous Material Metal Frame Corkboard Adhesive (1966)	ROOM 2115	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		