

INSPECTION CERTIFICATION for Saint Paul Public Schools -- Txuj Ci Hmong Language & Culture Lower

STATEMENT OF BUILDING ACCESS

On behalf of Saint Paul Public Schools for Txuj Ci Hmong Language & Culture Lower, I certify that I have provided access to all areas within the building to IEA's inspector identified below for the purpose of inspecting for asbestos-containing building materials (ACBM) as mandated by 40 CFR 763.85, "Inspections and Reinspections."

Additionally, I have discussed any concerns I have regarding identified or non-identified ACBM within this building.

Signature

Date of Inspection

INSPECTOR

As mandated by 40 CFR 763.85, "Inspections and Reinspections," I certify that I have inspected all accessible areas in Txuj Ci Hmong Language & Culture Lower for the purpose of identifying and assessing asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Inspector. A copy of my certification/accreditation is attached.

Signature

Print Name

Date of Inspection

State Certification/Accreditation Number

MANAGEMENT PLANNER

I certify that I have reviewed all of the inspection data for Txuj Ci Hmong Language & Culture Lower and have appropriately provided assessments and response actions for identified asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Management Planner. A copy of my certification/accreditation is attached.

Signature

Print Name

Date of Review

State Certification/Accreditation Number

Inspector State Certification/Accreditation



SPH
Director, Env. Health Div.



Certified by:
State of Minnesota
Department of Health
Expires: 05/16/2025
Grant O. Gervais
1031 13th Ave Se
Minneapolis, MN 55414

No. A115101 Issued: 06/06/2024

Management Planner State Certification/Accreditation



SPH
Director, Env. Health Div.



Certified by:
State of Minnesota
Department of Health
Expires: 08/02/2025
Matt A Lindberg
11816 Ghia St NE
Blaine, MN 55449

No. AM3896 Issued: 08/20/2024

Chart A - Immediate Response Situations

The following is a list of those events that contain damaged asbestos material and should be considered to be potential hazards. It is imperative that the following immediate response situations are corrected as soon as possible but no later than six months from the date of this inspection to avoid increased risk of exposure to airborne asbestos fibers. The district should take extra precaution to ensure that properly trained personnel use appropriate techniques to implement these responses.

Following is an explanation of the immediate Response Action codes identified in this report.

EPA ASSESSMENT CATEGORY				RESPONSE ACTION			
1 = Damaged or significantly damaged TSI ACM.				A = Cleanup ACM debris.			
2 = Damaged friable surfacing ACM.				B = Encapsulate slight damage on TSI.			
3 = Significantly damaged friable surfacing ACM.				C = Patch TSI and/or repair ACM cover.			
4 = Damaged or significantly damaged friable miscellaneous ACM.				D = Enclose or protect accessible sections with protective barrier.			
5 = ACBM with potential for damage.				E = Remove section of damaged ACM.			
6 = ACBM with potential for significant damage.				F = Remove ACM and replace with non-ACM.			
7 = Remaining friable ACBM or friable suspected ACBM.				G = Isolate area until repaired/removed.			
				H = Encapsulate slight damage.			
				I = Remove and replace damaged or loose tile section.			
				J = Monitor condition of material(s).			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Amount of Damage	EPA Assess.	Immediate Response Action	Comments
17 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Beige w/Brown Streaks	ROOM 0001	700 Sq Ft	2 Sq Ft	5	I	ENTRANCE FROM BOILER ROOM OR ACROSS HALL FROM MAIN OFFICE. TILE MISSING BY BOILER ROOM ENTRANCE WITH EXPOSED MASTIC. TILES LOOSE IN CENTER.
101 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	CUSTODIAL CLOSET 1105	25 Sq Ft	15 Sq Ft	5	E	SEVERAL TILES MISSING WITH EXPOSED MASTIC. MOISTURE DAMAGE ON REMAINING TILES. MASTIC IS DEGRADING FROM WATER DAMAGE. TILE DEBRIS FOUND. RECOMMEND REMOVAL.
150 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	ROOM 1408	40 Sq Ft	15 Sq Ft	5	E	1/2 TILE MISSING.
176 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	ROOM 1418	15 Sq Ft	5 Sq Ft	5	I	LARGE PIECES MISSING, MASTIC EXPOSED. SEVERAL LOOSE TILES.
182 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	ROOM 1419 CUSTODIAL	20 Sq Ft	20 Sq Ft	5	E	ONLY MASTIC REMAINS. MASTIC IS WEARING AWAY.