

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Information

---

Page Last Modified: 02/28/2025

**Building Information****1. Name of school district**

East Islip Union Free School District

**2. SED District 8-Digit BEDS Code**

58-05-03-03

**3. Building Name:**

East Islip High School

**4. SED 4-Digit Facility Code:**

0-010

**5. Survey Inspection Date:**

08/20/2024

**6. Building 911 Address:**

1 Redman Street

**7. City:**

Islip Terrace

**8. Zip Code:**

11752

**9. Certificate of Occupancy Status:**☒ A - Annual☐ T - Temporary☐ N - None**10. Certificate of Occupancy Expiration Date:**

12/01/2025

**10a. Is this a manufactured building? (Relocatable, modular, portable)**☐ Yes☒ No**11. Have there been renovations or construction in the building during the past 12 months?**☒ Yes☐ No**12. Was major construction/renovation work since 2015 conducted when school was in session?**☒ Yes☐ No**13. Estimated capital construction expenses anticipated for this building through the 2024 calendar year excluding maintenance (to be answered after the building inspection is complete)**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Information

---

Page Last Modified: 02/28/2025

2,036,022.52

**14. Overall building rating (to be answered after the building inspection is complete)**

- ☐ Excellent  
☒ Satisfactory  
☐ Unsatisfactory  
☐ Failing

**15. Was overall building rating established after consultation with health and safety committee in accordance with Commissioner's Regulations 155.4(c)(1)?**

- ☒ Yes  
☐ No

**16. A/E Firm Name:**

H2M Architects + Engineers

**17. A/E Firm Address:**

538 Broad Hollow Road, 4th Floor East, Melville, NY 11747

**18. A/E Firm Phone Number:**

6317568000

**19. E-mail:**

rwildermuth@h2m.com

**20. A/E Name:**

Robert Wildermuth

**21. A/E License #:**

026314

**Building Age, Gross Square Footage and Maintenance Staff****22. Building Age**

	Year
Original Construction	1970
Addition #1	2002
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Building Information

Page Last Modified: 02/28/2025

	Year
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

23. Square feet of construction

	Sq Feet
Original construction	201,100.00
Addition #1	37,400.00
Addition #2	(No Response)
Addition #3	(No Response)
Addition #4	(No Response)
Addition #5	(No Response)
Addition #6	(No Response)
Addition #7	(No Response)
Addition #8	(No Response)
Addition #9	(No Response)

24. Gross square ft. of Building as currently configured:

238,500

25. Number of Floors:

2

26. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	12
Part-time custodians:	1
Totals:	13

Building Ownership and Occupancy Status

27. Building Ownership (check one):

- ☒ Owned and used by district
- ☐ Owned by District and leased to non-district entity
- ☐ Owned by District, part used by district, part leased to non-district entity
- ☐ Owned by non-district entity and leased to district

28. For which of the following purposes is the building currently used? (check all that apply)

- ☒ Used for student instructional purposes

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**

## Building Information

Page Last Modified: 02/28/2025

- ☐ Used for district administration
- ☐ Used for other district purposes
- ☐ Used by other organization(s)

**Building Users**

**29. How many students were registered to receive instruction in this building as of the last year? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)**

1,201

**30. Of these registered students, how many receive most of their instruction in:**

	Quantity
Permanent instructional spaces (i.e., regular classrooms)	1,201
Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	(No Response)
Non-instructional spaces used as instructional spaces	(No Response)

**31. If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2019? (check all that apply)**

- ☐ Cafeteria
- ☐ Gymnasium
- ☐ Administrative Spaces
- ☐ Library
- ☐ Lobby
- ☐ Stairwell
- ☐ Storage space
- ☐ Other (please describe)
- ☒ None

**32. Grades Housed**

- |                                       |  |
|---------------------------------------|--|
| <input type="checkbox"/> Pre-K        | <input type="checkbox"/> 7th             |
| <input type="checkbox"/> Kindergarten | <input type="checkbox"/> 8th             |
| <input type="checkbox"/> 1st          | <input checked="" type="checkbox"/> 9th  |
| <input type="checkbox"/> 2nd          | <input checked="" type="checkbox"/> 10th |
| <input type="checkbox"/> 3rd          | <input checked="" type="checkbox"/> 11th |
| <input type="checkbox"/> 4th          | <input checked="" type="checkbox"/> 12th |
| <input type="checkbox"/> 5th          | <input type="checkbox"/> N/A (none)      |
| <input type="checkbox"/> 6th          |  |

**33. For how many instructional days during the school year prior to the BCS assigned year (July 1 through June 30) was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**

Building Information

---

Page Last Modified: 02/28/2025

0

**34. Is the building used for instructional purposes in the summer?**

☐ Yes

☒ No

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Program Spaces

---

Page Last Modified: 02/28/2025

**Program Spaces****35. Number of instructional classrooms:**

74

**36. Gross square footage of all instructional classrooms (combined):**

57,500.00

**37. Other spaces provided:**

- |   |  |  |
|---|--|--|
| <input type="checkbox"/> a. N/A (none)                | <input checked="" type="checkbox"/> j. Health Office           | <input checked="" type="checkbox"/> s. Resource Rooms    |
| <input checked="" type="checkbox"/> b. Administration | <input type="checkbox"/> k. Home & Careers                     | <input checked="" type="checkbox"/> t. Science Labs      |
| <input checked="" type="checkbox"/> c. Art            | <input checked="" type="checkbox"/> l. Kitchen                 | <input checked="" type="checkbox"/> u. Special Education |
| <input checked="" type="checkbox"/> d. Audio Visual   | <input checked="" type="checkbox"/> m. Large Group Instruction | <input type="checkbox"/> v. Swimming Pool                |
| <input checked="" type="checkbox"/> e. Auditorium     | <input checked="" type="checkbox"/> n. Library                 | <input type="checkbox"/> w. Teacher Resource             |
| <input checked="" type="checkbox"/> f. Cafeteria      | <input checked="" type="checkbox"/> o. Multipurpose Rooms      | <input type="checkbox"/> x. Technology/Shop              |
| <input checked="" type="checkbox"/> g. Computer Room  | <input type="checkbox"/> p. Music                              | <input type="checkbox"/> y. Other (please describe)      |
| <input checked="" type="checkbox"/> h. Guidance       | <input type="checkbox"/> q. Pre-K                              |  |
| <input checked="" type="checkbox"/> i. Gymnasium      | <input type="checkbox"/> r. Remedial Rooms                     |  |

**37a. Describe other spaces**

(No Response)

**Space Adequacy****38. Rating of space adequacy:**

- ☒ Good
- ☐ Fair
- ☐ Poor

**38a. Enter comments:**

(No Response)

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Site Utilities

Page Last Modified: 02/28/2025

SITE UTILITIES

39. Water (H)

- ☒ Yes
- ☐ No

39a. Type of Service:

- ☒ Municipal or Utility provided
- ☐ Well
- ☐ Other

39b. Types of water service piping

- ☐ Iron
- ☒ Galvanized
- ☒ Copper
- ☐ Lead
- ☐ PVC
- ☐ Other
- ☐ N/A (None)

39c. Overall condition of water service piping

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

39d. Year of Last Major Reconstruction/Replacement:

2003

39e. Expected Remaining Useful Life (Years):

19

39f. Cost to Reconstruct/Replace \$:

(No Response)

39g. Comments:

(No Response)

40. Site Sanitary (H)

- ☒ Yes
- ☐ No

40a. Type of Service:

- ☒ Municipal or utility sewer

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Site Utilities

---

Page Last Modified: 02/28/2025

☐ Site septic☐ Other**40b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**40c. Year of Last Major Reconstruction/Replacement:**

2003

**40d. Expected Remaining Useful Life (Years):**

19

**40e. Cost to reconstruct/Replace \$:**

(No Response)

**40f. Comments:**

(No Response)

**41. Site Gas**☒ Yes☐ No**41a. Type of gas service:**☒ Natural Gas☐ Liquid Petroleum**41b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**41c. Year of Last Major Reconstruction/Replacement;**

1990

**41d. Expected Remaining Useful Life (Years):**

14

**41e. Cost to Reconstruct/Replace \$:**

(No Response)

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Site Utilities

---

Page Last Modified: 02/28/2025

**41f. Comments:**

(No Response)

**42. Site Fuel Oil**☒ Yes☐ No**42a. Number of Above-Ground Tanks:**

0

**42a.1 Capacity of Above-Ground Tanks (gallons):**

0

**42b. Number of Below-Ground Tanks:**

1

**42b.1 Capacity of Below-Ground Tanks (gallons):**

10,000

**42c. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure☐ N/A**42d. Year of Last Major Reconstruction/Replacement:**

1990

**42e. Expected Remaining Useful Life (Years):**

9

**42f. Cost to Reconstruct/Replace \$:**

(No Response)

**42g. Comments:**

(No Response)

**43. Site Electrical, Including Exterior Distribution**☒ Yes☐ No**43a. Service Provider:**☒ Municipal or utility provided☐ Self-Generated☐ Other

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Site Utilities

Page Last Modified: 02/28/2025

☐ N/A

**43b. Type of Service:**

☐ Above Ground  
☒ Below Ground  
☐ N/A

**43c. Condition:**

☐ Excellent  
☐ Satisfactory  
☒ Unsatisfactory  
☐ Non-Functioning  
☐ Critical Failure

**43d. Year of Last Major Reconstruction/Replacement:**

2003

**43e. Expected Remaining Useful Life (Years):**

1

**43f. Cost to Reconstruct/Replace \$:**

600,000.00

**43g. Comments:**

The existing service entrance switchgear and distribution panelboards in the basement electrical room have reached the end of their serviceable life and require replacement along with existing utility service evaluation. Utility service upgrade is needed per the school district.

SITE FEATURES

44. Closed Drainage Pipe Stormwater Management System

44a. Does this facility have a closed pipe system?

☒ Yes  
☐ No

**44b. Condition:**

☐ Excellent  
☒ Satisfactory  
☐ Unsatisfactory  
☐ Non-Functioning  
☐ Critical Failure

**44c. Year of Last Major Reconstruction/Replacement:**

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Site Utilities

---

Page Last Modified: 02/28/2025

2003

**44d. Expected Remaining Useful Life (Years):**

19

**44e. Cost to Reconstruct/Replace \$:**

(No Response)

**44f. Comments:**

(No Response)

**45. Open Drainage Pipe Stormwater Management System****45a. Does this facility have an open stormwater system (ditch)?**☒ Yes☐ No**45b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**45c. Year of Last Major Reconstruction/Replacement:**

2003

**45d. Expected Remaining Useful Life (Years):**

19

**45e. Cost to Reconstruct/Replace \$:**

(No Response)

**45f. Comments:**

(No Response)

**46. Catch Basins/Drop Inlets/Manholes****46a. Does this facility have catch basins/drop inlets/manholes?**☒ Yes☐ No**46b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Site Utilities

---

Page Last Modified: 02/28/2025

☐ Non-Functioning☐ Critical Failure**46c. Year of Last Major Reconstruction/Replacement:**

2003

**46d. Expected Remaining Useful Life (Years):**

19

**46e. Cost to Reconstruct/Replace \$:**

(No Response)

**46f. Comments:**

(No Response)

**47. Culverts****47a. Does this facility have culverts?**☒ Yes☐ No**47b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**47c. Year of Last Major Reconstruction/Replacement:**

2003

**47d. Expected Remaining Useful Life (Years):**

19

**47e. Cost to Reconstruct/Replace \$:**

(No Response)

**47f. Comments:**

(No Response)

**48. Outfalls****48a. Does this facility have outfalls?**☒ Yes☐ No**48b. Condition:**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Site Utilities

---

Page Last Modified: 02/28/2025

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**48c. Year of Last Major Reconstruction/Replacement:**

2003

**48d. Expected Remaining Useful Life (Years):**

19

**48e. Cost to Reconstruct/Replace \$:**

(No Response)

**48f. Comments:**

(No Response)

**49. Infiltration Basins/Chambers****49a. Does this facility have infiltration basins/chambers?**

- ☐ Yes
- ☒ No

**50. Retention Basins****50a. Does this facility have retention basins?**

- ☐ Yes
- ☒ No

**51. Wetponds****51a. Does this facility have wetponds?**

- ☐ Yes
- ☒ No

**52. Manufactured Stormwater Proprietary Units****52a. Does this facility have proprietary units?**

- ☒ Yes
- ☐ No

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Site Utilities

---

Page Last Modified: 02/28/2025

**52b. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**52c. Year of Last Major Reconstruction/Replacement:**

2003

**52d. Expected Remaining Useful Life (Years):**

19

**52e. Cost to Reconstruct/Replace \$:**

(No Response)

**52f. Comments:**

(No Response)

**53. Point of Outfall Discharge: (check all that apply)**

- ☐ Municipal storm sewer system
- ☐ Combined sewer system
- ☐ Surface Water
- ☐ On-site recharge
- ☐ Other (describe)
- ☒ Not Applicable

**54. Outfall Reconnaissance Inventory****Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?**

- ☐ Yes
- ☐ No
- ☒ Not Applicable

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Other Site Features

---

Page Last Modified: 02/27/2025

**SITE FEATURES****55. Pavement (Roadways and Parking Lots)**☒ Yes☐ No**55a. Type: (check all that apply)**☐ Concrete☒ Asphalt☐ Gravel☐ Other**55b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**55c. Year of Last Major Reconstruction/Replacement:**

2023

**55d. Expected Remaining Useful Life (Years):**

20

**55e. Cost to Reconstruct/Replace \$:**

0.00

**55f. Comments:**

Southwest parking lot and new northeast bus loop recently completed.

**56. Sidewalks**☒ Yes☐ No**56a. Type: (check all that apply)**☐ Asphalt☒ Concrete☐ Gravel☐ Paver☐ Other**56b. Condition:**☐ Excellent

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Other Site Features

---

Page Last Modified: 02/27/2025

- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**56c. Year of Last Major Reconstruction/Replacement:**

2006

**56d. Expected Remaining Useful Life (Years):**

5

**56e. Cost to Reconstruct/Replace \$:**

60,000.00

**56f. Comments:**

existing pavers  
main entrance

**57. Playgrounds and Playground Equipment**

- ☐ Yes
- ☒ No

**58. Athletic Fields and Play Fields**

- ☒ Yes
- ☐ No

**58a. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**58b. Year of Last Major Reconstruction/Replacement:**

2020

**58c. Expected Remaining Useful Life (Years):**

7

**58d. Cost to Reconstruct/Replace \$:**

12,000.00

**58e. Comments:**

Replace existing perimeter fencing near Spur Dr. road (160 L.F.)

**58f. Does the facility have synthetic turf field(s)**

---

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Other Site Features

---

Page Last Modified: 02/27/2025

☒ Yes☐ No**58f.1 If Yes, how many synthetic turf fields?**

2

**58f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):**

20

**58f.3 Type of synthetic turf field infill:**

(No Response)

**59. Exterior Bleachers / Stadiums**☐ Yes☒ No**60. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)**☒ Yes☐ No**60a. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**60b. Year of Last Major Reconstruction/Replacement:**

2020

**60c. Expected Remaining Useful Life (Years):**

19

**60d. Cost to Reconstruct/Replace \$:**

(No Response)

**60e. Comments:**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Structure

---

Page Last Modified: 02/27/2025

**Building Structure****61. Foundation (S)****61a. Type (check all that apply):**

- ☒ Reinforced Concrete
- ☐ Masonry on Concrete Footing
- ☐ Other (specify)

**61a1. If "Other" please specify**

(No Response)

**61b. Evidence of structural concerns (check all that apply):**

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

**61c. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**61d. Year of Last Major Reconstruction/Replacement:**

2003

**61e. Expected Remaining Useful Life (Years):**

19

**61f. Cost to Reconstruct/Replace \$:**

(No Response)

**61g. Comments:**

(No Response)

**62. Piers (S)**

- ☒ Yes
- ☐ No

**62a. Type (check all that apply)**

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Building Structure

Page Last Modified: 02/27/2025

☐ Concrete

☒ Masonry

☐ Steel

☐ Stone

☐ Wood

☐ Other (specify)

☐ N/A (none)

62a1. If "Other" please specify

(No Response)

62b. Evidence of structural concerns (check all that apply)

☐ Structural Cracks

☐ Heaving/Jacking

☐ Decay/Corrosion

☐ Water Penetration

☐ Unsupported Ends

☐ Other

☒ None

62c. Condition:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

62d. Year of Last Major Reconstruction/Replacement

2003

62e. Expected Remaining Useful Life (Years):

19

62f. Cost to Reconstruct/Replace \$:

(No Response)

62g. Comments:

(No Response)

63. Columns (S)

Type (check all that apply):

☐ Concrete

☒ Masonry

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Structure

---

Page Last Modified: 02/27/2025

- ☐ Steel
- ☐ Stone
- ☐ Wood
- ☐ Other (specify)
- ☐ N/A (None)

**63.1. If "Other" please specify**

(No Response)

**63a. Evidence of structural concerns (check all that apply)**

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

**63b. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**63c. Year of Last Major Reconstruction/Replacement**

2003

**63d. Expected Remaining Useful Life (Years):**

19

**63e. Cost to Reconstruct/Replace \$:**

(No Response)

**63f. Comments:**

(No Response)

**64. Footings (S)****Type (check all that apply):**

- ☒ Concrete
- ☐ Other (specify)

**64a. Evidence of structural concerns (check all that apply)**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Structure

---

Page Last Modified: 02/27/2025

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other (specify)
- ☒ None

**64.a1. If "Other" please specify**

(No Response)

**64b. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**64c. Year of Last Major Reconstruction/Replacement**

2003

**64d. Expected Remaining Useful Life (Years):**

19

**64e. Cost to Reconstruct/Replace \$:**

(No Response)

**64f. Comments:**

(No Response)

**65. Structural Floors (S)****65a. Type (check all that apply):**

- ☐ Concrete Deck on Wood Structure
- ☒ Concrete/Metal Deck/Metal Joists
- ☐ Cast in Place Concrete Structural System
- ☐ Precast Concrete Structural System
- ☐ Reinforced Concrete Slab on Grade
- ☐ Wood Deck on Wood Trusses
- ☐ Wood Deck on Wood Joists
- ☐ Other (specify)

**65b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Structure

---

Page Last Modified: 02/27/2025

- ☐ Structural Cracks
- ☐ Unsupported Ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously Damaged/Missing Components
- ☐ Other Problems
- ☒ None

**65b.1 Describe Other Problems:**

(No Response)

**65c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):**

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

**65d. Overall Condition of Structural Floors:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**65e. Year of Last Major Reconstruction/Replacement:**

2003

**65f. Expected Remaining Useful Life (Years):**

19

**65g. Cost to Reconstruct/Replace \$:**

(No Response)

**65h. Comments:**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Envelope

---

Page Last Modified: 02/27/2025

**BUILDING ENVELOPE****66. Exterior Walls/Columns (S)****66a. Material (check all that apply):**

- ☐ Aluminum/Glass Curtain Wall
- ☒ Brick
- ☐ Concrete
- ☐ Composite Insulated Panels
- ☒ Masonry
- ☐ Steel
- ☐ Wood
- ☐ Other (specify)

**66b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.)  
(check all that apply):**

- ☐ Structural Cracks
- ☐ Rot/Decay/Corrosion
- ☐ Other Problems
- ☒ None

**66b.1 Describe Other Problems:**

(No Response)

**66c. Evidence of Concerns with Exterior Cladding (check all that apply):**

- ☐ Cracks/Gaps
- ☐ Inadequate Flashing
- ☐ Efflorescence
- ☐ Moisture Penetration
- ☐ Rot/Decay/Corrosion
- ☐ Other Problems
- ☒ None

**66c.1 Describe Other Problems:**

(No Response)

**66d. Overall Condition of Exterior Walls/Columns:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Building Envelope

---

Page Last Modified: 02/27/2025

**66e. Year of Last Major Reconstruction/Replacement:**

2003

**66f. Expected Remaining Useful Life (Years):**

19

**66g. Cost to Reconstruct/Replace \$:**

(No Response)

**66h. Comments:**

(No Response)

**67. Chimneys (S)**☒ Yes☐ No**67a. Material (check all that apply):**☒ Masonry☐ Concrete☐ Metal☐ Wood☐ Other**67a.1 Specify other:**

(No Response)

**67b. Overall Condition of Chimneys:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical failure**67c. Year of Last Major Reconstruction/Replacement:**

1970

**67.d Expected Remaining Useful Life (Years):**

9

**67e. Cost to Reconstruct/Replace \$:**

(No Response)

**67f. Comments:**

(No Response)

**68. Parapets (S)**☐ Yes

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Building Envelope

---

Page Last Modified: 02/27/2025

☒ No**69. Exterior Doors****69a. Overall Condition of Exterior Door Units:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**69b. Do any exterior doors have magnetic locking devices?**

- ☒ Yes
- ☐ No

**69c. Safety/Security features are adequate?**

- ☒ Yes
- ☐ No

**69d. Year of Last Major Reconstruction/Replacement:**

2021

**69e. Expected Remaining Useful Life (Years):**

14

**69f. Cost to Reconstruct/Replace \$:**

(No Response)

**69g. Comments:**

Existing exterior garage doors currently being replaced.

**70. Exterior Steps, Stairs, Ramps (S)**

- ☒ Yes
- ☐ No

**70a. Construction Type (Check all that apply)**

- ☒ Concrete
- ☐ Paver
- ☐ Steel
- ☐ Wood
- ☐ Other (specify)

**70b. If "other", specify here**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Envelope

---

Page Last Modified: 02/27/2025

**70c. Overall Condition of Exterior Steps, Stairs and Ramps**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**70d. Year of Last Major Reconstruction/Replacement:**

1970

**70e. Expected Remaining Useful Life (Years):**

7

**70f. Cost to Reconstruct/Replace \$:**

50,000.00

**70g. Comments:**

Replace existing railings and bollards at main entrance, spot repair to curbing/slab (30 L.F.)

**71. Fire Escapes (S)****71a. Does This Facility Have One or More Fire Escapes?**

- ☐ Yes
- ☒ No

**72. Windows**

- ☒ Yes
- ☐ No

**72a. Window Material: (check all that apply)**

- ☒ Aluminum
- ☐ Steel
- ☐ Vinyl
- ☐ Solid Wood
- ☐ Wood w/ External Cladding System
- ☐ Other

**72a1. If "Other" please specify**

(No Response)

**72b. Overall Condition of Windows:**

- ☐ Excellent
- ☒ Satisfactory

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Envelope

---

Page Last Modified: 02/27/2025

- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**72c. All Rescue Windows are Operable:**

- ☒ Yes
- ☐ No
- ☐ N/A

**72d. Year of Last Major Reconstruction/Replacement:**

2003

**72e. Expected Remaining Useful Life (Years):**

10

**72f. Cost to Reconstruct/Replace \$:**

(No Response)

**72g. Comments:**

(No Response)

**73. Roof and Skylights (S)**

- ☒ Yes
- ☐ No

**73a. Type of roof construction (check all that apply):**

- ☒ Concrete on metal deck on metal trusses/joists
- ☐ Concrete (poured or plank) on concrete beams
- ☐ Gypsum (poured or plank) on metal trusses/joists
- ☐ Metal deck on metal trusses/joists
- ☐ Wood deck on wood trusses/joists
- ☐ Wood deck on metal trusses/joists
- ☐ Tectum on metal trusses/joists
- ☐ Other (describe below)

**73a.1 Other roof construction type:**

(No Response)

**73b. Type of roofing material (check all that apply):**

- ☒ Single-ply membrane
- ☐ Built-up
- ☐ Asphalt shingle
- ☐ Pre-formed metal
- ☐ IRMA

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Envelope

---

Page Last Modified: 02/27/2025

- ☐ Slate
- ☐ Fluid applied seamless surfacing
- ☒ Other (describe below)

**73b.1 Other roofing material:**

(No Response)

**73c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):**

- ☐ Structural cracks
- ☐ Unsupported ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously damaged/missing components
- ☐ Other concerns (describe)
- ☒ None

**73c.1 Describe other concerns:**

(No Response)

**73d. Evidence of structural concerns with roof deck (check all that apply):**

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

**73e. Does this facility have skylights?**

- ☒ Yes
- ☐ No

**73f. Skylight material (check all that apply):**

- ☐ Plastic
- ☒ Glass
- ☐ Other
- ☐ N/A

**73g. Overall condition of skylights:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Envelope

---

Page Last Modified: 02/27/2025

**73h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):**

- ☐ Failures/Splits/Cracks
- ☐ Rot/Decay/Corrosion
- ☐ Inadequate flashing/curbs/pitch pockets
- ☐ Inadequate or poorly functioning roof drains
- ☐ Evidence of water penetration/active leaks
- ☐ Other (specify)
- ☒ None

**73h.1 Specify other concerns:**

(No Response)

**73i. Overall Condition of Roof and Skylights:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**73j. Year of Last Major Reconstruction/Replacement:**

2019

**73k. Expected Remaining Useful Life (Years):**

29

**73l. Cost to Reconstruct/Replace \$:**

(No Response)

**73m. Comments:**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**

## Building Interiors

Page Last Modified: 02/27/2025

**BUILDING INTERIOR****74. Interior Bearing Walls and Fire Walls (S)**☒ Yes☐ No**74a. Overall condition of interior bearing walls and fire walls:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-functioning☐ Critical Failure**74b. Year of Last Major Reconstruction/Replacement:**

2003

**74c. Expected Remaining Useful Life (Years):**

10

**74d. Cost to Reconstruct/Replace \$:**

10,000.00

**74e. Comments:**

Repair various interior masonry cracks in gymnasiums (200 S.F.) Remove cmu block, replace &amp; re-tooth, repaint areas.

**74.f Regulatory**

Have design professionals provided inventory of construction regulated under BCNYS Ch7, including assessment of their condition and maintenance, as required by NYSFC Ch7 and NYSPMC 703? This includes, but is not limited to:

[check each item provided to the district]

☒ Fire-resistance rated assemblies;☒ Smoke barriers and smoke partitions;☒ Penetrations, joints, voids, door☒ Assessment of Ch7 regulated assembly either damaged, altered, breached, or penetrated;☒ Confirmation of compliant repair or protection of Ch7 regulated assembly either damaged, altered, breached, or penetrated;☐ Other:**74.f Other:**

(No Response)

**75. Other Interior Walls**☒ Yes☐ No

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Interiors

---

Page Last Modified: 02/27/2025

**75a. Overall condition of other interior walls:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**75b. Year of Last Major Reconstruction/Replacement:**

2003

**75c. Expected Remaining Useful Life (Years):**

5

**75d. Cost to Reconstruct/Replace \$:**

30,000.00

**75e. Comments:**

Replace wireglass storefront system entry lobbies and corridors throughtout. (150 S.F)

**76. Carpet**

- ☒ Yes
- ☐ No

**76a. Where located (check all that apply):**

- ☐ Classrooms
- ☐ Corridors
- ☒ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☒ Other Areas

**76b. Condition:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**76c. Year of Last Major Reconstruction/Replacement:**

2008

**76d. Expected Remaining Useful Life (Years):**

9

**76e. Cost to Reconstruct/Replace \$:**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Interiors

---

Page Last Modified: 02/27/2025

**76f. Comments:**

(No Response)

**77. Resilient Tiles or Sheet Flooring**☒ Yes☐ No**77a. Where located (check all that apply):**

- ☒ Classrooms
- ☒ Corridors
- ☐ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☐ Other Areas

**77b. Overall condition of resilient tiles or sheet flooring:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**77c. Year of Last Major Reconstruction/Replacement:**

2021

**77d. Expected Remaining Useful Life (Years):**

10

**77e. Cost to Reconstruct/Replace \$:**

(No Response)

**77f. Comments:**

(No Response)

**78. Hard Flooring (concrete; ceramic tile; stone; etc)**☒ Yes☐ No**78a. Where located (check all that apply):**

- ☐ Classrooms
- ☐ Corridors
- ☐ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☐ Kitchen
- ☐ Locker Rooms/Toilet Rooms

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Interiors

---

Page Last Modified: 02/27/2025

☒ Other Areas**78b. Overall condition of hard flooring:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**78c. Year of Last Major Reconstruction/Replacement:**

2021

**78d. Expected Remaining Useful Life (Years):**

9

**78e. Cost to Reconstruct/Replace \$:**

(No Response)

**78f. Comments:**

(No Response)

**79. Wood Flooring**

- ☒ Yes
- ☐ No

**79a. Where located (check all that apply):**

- ☒ Classrooms
- ☐ Corridors
- ☐ Offices
- ☐ Assembly Spaces (Auditorium, Gym, Play Room, etc.)
- ☒ Other Areas

**79b. Overall condition of wood flooring:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**79c. Year of Last Major Reconstruction/Replacement:**

1990

**79d. Expected Remaining Useful Life (Years):**

9

**79e. Cost to Reconstruct/Replace \$:**

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Building Interiors

---

Page Last Modified: 02/27/2025

(No Response)

**79f. Comments:**

(No Response)

**80. Ceilings (H)**☒ Yes☐ No**80a. Overall condition of ceilings:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**80b. Year of Last Major Reconstruction/Replacement:**

2008

**80c. Expected Remaining Useful Life (Years):**

7

**80d. Cost to Reconstruct/Replace \$:**

170,400.00

**80e. Comments:**

Replace end of life spline (4,500 S.F.) and damaged/old acoustic ceiling panels with new 2'x2' ACP. Gymnasium Corridor ceilings (4,020 S.F.)

**81. Lockers**☒ Yes☐ No**81a. Overall condition of lockers:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**81b. Year of Last Major Reconstruction/Replacement:**

2008

**81c. Expected Remaining Useful Life (Years):**

14

**81d. Cost to Reconstruct/Replace \$:**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Interiors

---

Page Last Modified: 02/27/2025

(No Response)

**81e. Comments:**

(No Response)

**82. Interior Doors**☒ Yes☐ No**82a. Overall condition of interior door units:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**82b. Overall condition of interior door hardware:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**82c. Year of Last Major Reconstruction/Replacement:**

2021

**82d. Expected Remaining Useful Life (Years):**

7

**82e. Cost to Reconstruct/Replace \$:**

381,000.00

**82f. Comments:**

Replace 2 (Single) and 28 (Double) egress / interior doors. Replace 50 hardware sets throughout. Push bars/panic hardware.

**83. Interior Stairs (H)**☒ Yes☐ No**83a. Overall condition of interior stairs:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Building Interiors

---

Page Last Modified: 02/27/2025

**83b. Stair material**

- ☒ Concrete
- ☐ Steel
- ☐ Wood
- ☐ Other

**83c. Year of Last Major Reconstruction/Replacement:**

2003

**83d. Expected Remaining Useful Life (Years):**

19

**83e. Cost to Reconstruct/Replace \$:**

(No Response)

**83f. Comments:**

(No Response)

**84. Elevator, Lift, and Escalators (H)**

- ☒ Yes
- ☐ No

**84a. Overall condition of elevators, lifts, escalators:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**84b. Year of Last Major Reconstruction/Replacement:**

2005

**84c. Expected Remaining Useful Life (Years):**

7

**84d. Cost to Reconstruct/Replace \$**

150,000.00

**84e. Comments:**

Existing freight elevator upgrade.

**85. Swimming Pool and Swimming Pool Systems (H)**

- ☐ Yes
- ☒ No

**86. Interior Bleachers**

---

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Building Interiors

Page Last Modified: 02/27/2025

☒ Yes

☐ No

86a. Overall condition of interior bleachers:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

86b. Year of Last Major Reconstruction/Replacement:

2020

86c. Expected Remaining Useful Life (Years):

24

86d. Cost to Reconstruct/Replace \$

(No Response)

86e. Comments:

(No Response)

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

HVAC Systems

Page Last Modified: 02/27/2025

HVAC Systems

87. Heat Generating Systems (H)

- ☒ Yes
- ☐ No

87a. Heat generation source (check all that apply):

- ☐ Biomass
- ☒ Boiler / Hot Water
- ☐ Boiler / Steam
- ☐ Cogeneration Plant
- ☐ Electric
- ☐ Furnace / Forced Air
- ☐ Geothermal
- ☐ Heat Pump
- ☐ Unit Ventilation
- ☐ Other (describe below)

87a.1 Other heat generation source:

(No Response)

87b. Overall condition of heat generating systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

87c. Year of Last Major Reconstruction/Replacement:

2003

87d. Expected Remaining Useful Life (Years):

7

87e. Cost to Reconstruct/Replace \$:

25,000.00

87f. Comments:

Provide manual override controls for existing boiler system.

88. Ventilation System (exhaust fans, etc) (H)

- ☒ Yes
- ☐ No

88a. Type of ventilation system (check all that apply)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**HVAC Systems

---

Page Last Modified: 02/27/2025

- |  |   |
|--|---|
| <input type="checkbox"/> Natural ventilation                   | <input type="checkbox"/> Heat pump                          |
| <input type="checkbox"/> Central system                        | <input type="checkbox"/> Split system/ variable refrigerant |
| <input type="checkbox"/> Energy recovery ventilator            | <input type="checkbox"/> Powered relief air system          |
| <input type="checkbox"/> Rooftop units                         | <input type="checkbox"/> Gravity/barometric relief          |
| <input checked="" type="checkbox"/> Unitary (UVs, FC/BC, PTAC) | <input type="checkbox"/> Other (specify)                    |
| <input type="checkbox"/> Forced air furnace                    |   |

**88b. If "Other" please specify here**

(No Response)

**88c. Overall condition of ventilation systems**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical Failure

**88d. Year of last major reconstruction/replacement**

2020

**88e. Expected remaining useful life (years):**

5

**88f. Cost to reconstruct/replace \$:**

1,36,0000

**88g. Comments**

Existing exhaust fan replacement 32 and 13 vent replacment throughout.

**89a. Types of mechanical cooling**

- ☐ Chiller/chilled water
- ☐ Geothermal
- ☐ Air cooled
- ☐ Water cooled
- ☐ DX/Split system
- ☒ Heat pump

**89. Mechanical Cooling / Air-Conditioning Systems**

- ☒ Yes
- ☐ No

**89b. Overall condition of cooling/air-conditioning systems:**

- ☐ Excellent
- ☒ Satisfactory

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**HVAC Systems

---

Page Last Modified: 02/27/2025

- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**89c. Year of Last Major Construction/Replacement:**

2001

**89d. Expected Remaining Useful Life (Years):**

14

**89e. Cost to Reconstruct/Replace \$:**

0.00

**89f. Comments:**

(No Response)

**90. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectors, Traps, Insulation, etc. (H)**

- ☒ Yes
- ☐ No

**90a. Overall condition of piped heating and cooling distribution systems:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**90b. Year of Last Major Reconstruction/Replacement:**

2001

**90c. Expected Remaining Useful Life (Years):**

14

**90d. Cost to Reconstruct/Replace \$:**

(No Response)

**90e. Comments:**

(No Response)

**91. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)**

- ☒ Yes
- ☐ No

**91a. Overall condition of ducted heating and cooling distribution systems:**

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

HVAC Systems

Page Last Modified: 02/27/2025

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

2001

91c. Expected Remaining Useful Life (Years):

9

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

92. HVAC Control Systems (H)

☒ Yes

☐ No

92a. Type of control system

☐ Pneumatic

☒ Electric

☐ Digital Direct Control (DDC)

☐ Web based DDC

92b. Overall condition of control systems:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

92c. Year of Last Major Reconstruction/Replacement:

2018

92d. Expected Remaining Useful Life (Years):

19

92e. Cost to Reconstruct/Replace \$:

(No Response)

92f. Comments:

(No Response)

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Plumbing Systems

---

Page Last Modified: 02/27/2025

**PLUMBING****93. Water Supply System (H)**☒ Yes☐ No**93a. Types of pipes (check all that apply):**

- ☐ Asbestos/transite
- ☒ Copper
- ☒ Galvanized
- ☐ Iron
- ☐ Lead
- ☐ PVC/CPVC/PEX/Plastic
- ☐ Other (specify)

**93b. If "Other" please specify here**

(No Response)

**93c. Overall condition of water supply system:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**93d. Year of Last Major Reconstruction/Replacement:**

2001

**93e. Expected Remaining Useful Life (Years):**

24

**93f. Cost to Reconstruct/Replace \$:**

(No Response)

**93g. Comments:**

(No Response)

**94. Sanitary System (H)**☒ Yes☐ No**94a. Types of pipes (check all that apply):**

- ☐ Iron
- ☒ Galvanized
- ☒ Copper

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Plumbing Systems

Page Last Modified: 02/27/2025

☐ Glass/ceramic

☐ PVC/CPVC/ABS/poly propylene/plastic

☐ Lead

☐ Other (specify)

94a1. If "Other" please specify

(No Response)

94b. Types of special sanitary systems (Check all that apply)

☐ Acid waste and vent

☒ Grease interceptor

☒ Oil separator

☐ Pumping station

☐ Sediment trap

☐ Septic tank

☐ Waste water treatment plant

94c. Overall condition of sanitary system:

☐ Excellent

☒ Satisfactory

☐ Unsatisfactory

☐ Non-Functioning

☐ Critical Failure

94d. Year of Last Major Reconstruction/Replacement:

2003

94e. Expected Remaining Useful Life (Years):

19

94f. Cost to Reconstruct/Replace \$:

0.00

94g. Comments:

(No Response)

95. Storm Water Drainage System (H)

☒ Yes

☐ No

95a. Types of pipes (check all that apply)

☐ Iron

☒ Galvanized

☒ Copper

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Plumbing Systems

---

Page Last Modified: 02/27/2025

- ☐ Lead
- ☐ Plastic
- ☐ Other

**95a1. If "Other" please specify**

(No Response)

**95b. Overall condition of storm water drainage system**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**95c. Year of Last Major Reconstruction/Replacement**

2003

**95d. Expected Remaining Useful Life (Years)**

19

**95e. Cost to Reconstruct/Replace \$:**

0

**95f. Comments:**

(No Response)

**96. Hot Water Heaters (H)**

- ☒ Yes
- ☐ No

**96a. Type of fuel (check all that apply):**

- ☒ Oil
- ☐ Natural Gas
- ☐ Electricity
- ☐ Propane
- ☐ Other (specify)

**96b. If "Other" please specify**

(No Response)

**96c. Overall condition of hot water heaters:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Plumbing Systems

---

Page Last Modified: 02/27/2025

☐ Critical Failure**96d. Year of Last Major Reconstruction/Replacement:**

2003

**96e. Expected Remaining Useful Life (Years):**

19

**96f. Cost to Reconstruct/Replace \$:**

0.00

**96g. Comments:**

(No Response)

**97. Plumbing Fixtures (H)**☒ Yes☐ No**97a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, sinks, showers, etc):**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**97b. Year of Last Major Reconstruction/Replacement:**

2021

**97c. Expected Remaining Useful Life (Years):**

19

**97d. Cost to Reconstruct/Replace \$:**

0.00

**97e. Comments:**

(No Response)

**98. Water Outlets/Taps for Drinking/Cooking Purposes (H)**☒ Yes☐ No**98a. Overall condition of water outlets/taps (drinking fountains, bubblers, bottle fillers, kitchen prep, ice machines, etc).**☐ Excellent☒ Satisfactory☐ Unsatisfactory

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Plumbing Systems

---

Page Last Modified: 02/27/2025

☐ Non-Functioning

☐ Critical Failure

**98b. Year of last major reconstruction/replacement:**  
1970

**98c. Expected remaining useful life (years):**  
9

**98d. Cost to reconstruct/replace \$:**  
0

**98e. Comments**  
(No Response)

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Fire Suppression Systems

---

Page Last Modified: 02/27/2025

**Fire Suppression Systems****99. Fire Suppression System (H)**☒ Yes☐ No**99a. Type of fire suppression system (check all that apply)**

- ☐ Wet sprinkler system
- ☐ Dry sprinkler system
- ☒ Standpipes
- ☐ Hose cabinets
- ☒ Kitchen hood fire suppression
- ☐ Data special agent suppression
- ☐ Limited area sprinkler system
- ☐ Dust collector spark arrestor
- ☐ Paint booth fire suppression
- ☐ Other (describe)

**99b. If "other" please describe below**

(No Response)

**99c. Overall condition of sprinkler systems:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

**99d. Year of Last Major Reconstruction/Replacement:**

2007

**99e. Expected Remaining Useful Life (Years):**

10

**99f. Cost to Reconstruct/Replace \$:**

(No Response)

**99g. Comments:**

(No Response)

**100. Kitchen Hoods (H)**☒ Yes☐ No**100a. Type of hood**

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Fire Suppression Systems

Page Last Modified: 02/27/2025

- ☒ Yes- Type 1 grease and smoke
- ☒ Yes- Type 2 heat and condensation

100b. Is kitchen exhaust system appropriate for all current appliances it serves?

- ☒ Yes
- ☐ No

100c. Overall Condition of Kitchen Hoods

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

100d. Year of Last Major Reconstruction/Replacement:

2007

100e. Expected Remaining Useful Life (Years):

10

100f. Cost to Reconstruct/Replace \$:

(No Response)

100g. Comments

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Electrical Systems

---

Page Last Modified: 02/27/2025

**ELECTRICAL SYSTEMS****101. Electrical Power Distribution System (H)**☒ Yes☐ No**101a. Electrical supply meets current needs:**☒ Yes☐ No**101b. Condition of electrical power distribution system:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**101c. Year of last major reconstruction/replacement?**

2000

**101d. Expected remaining useful life (years):**

10

**101e. Cost to reconstruct/replace:**

125,000.00

**101f. Comments:**

There are at least 5 panelboards within the building have reached the end of their serviceable life and require replacement.

**102. Lighting Fixtures (H)**☒ Yes☐ No**102a. Condition of lighting figures:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-functioning☐ Critical failure**102b. Year of last major reconstruction/replacement:**

2018

**102c. Expected remaining useful life (years):**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Electrical Systems

---

Page Last Modified: 02/27/2025

18

**102d. Cost to reconstruct/replace:**

(No Response)

**102e. Comments**

(No Response)

**103. Emergency/ Exit Lighting Systems (H):**☒ Yes☐ No**103a. Overall condition of emergency/exit lighting systems:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-functioning☐ Critical failure**103b. Year of last major reconstruction/replacement:**

2003

**103c. Expected remaining useful life (years):**

9

**103d. Cost to reconstruct/replace:**

(No Response)

**103e. Comments**

(No Response)

**104. Emergency or standby power system (H)**☒ Yes☐ No**104a. Types of back-up power system (check all that apply)**☒ Generator fuel gas/ propane☐ Generator diesel/ fuel oil☐ Receptacle for mobile generator connection☐ Central battery inverter☐ Integral fixture/ battery equipment☐ Other (specify)**104b. If "other" please describe here**

(No Response)

**104c. Overall condition of emergency/standby power systems:**

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Electrical Systems

---

Page Last Modified: 02/27/2025

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical failure
- ☐ N/A

**104d. Year of last major reconstruction/replacement**

1995

**104e. Expected remaining useful life (years):**

12

**104f. Cost to reconstruct/replace:**

500,000

**104g. Comments**

Replace generator with new to provide power to emergency life safety equipment.

**105. Fire Alarm Systems (manual, automatic fire detection, and notification appliances) (H)**

- ☒ Yes
- ☐ No

**105a. Overall condition of fire alarm system:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical failure

**105b. Year of last major reconstruction/replacement:**

2011

**105c. Expected remaining useful life (years):**

5

**105d. Cost to reconstruct/replace:**

700,000

**105e. Comments**

Fire alarm system and controls upgrades.

**106. Carbon Monoxide Alarm System (H)**

- ☒ Yes
- ☐ No

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Electrical Systems

---

Page Last Modified: 02/27/2025

**106a. Type of alarm system:**

- ☐ 10-year battery stand alone alarm
- ☒ hardwired/interconnected detection and alarm
- ☐ gas detection (eg NG/CO)
- ☐ Other (specify)

**106b. If "Other" please specify**

(No Response)

**106c. Overall condition of carbon monoxide alarm system:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical failure

**106d. Year of last major reconstruction/replacement:**

2003

**106e. Expected remaining useful life (years):**

8

**106f. Cost to reconstruct/replace:**

480,000.00

**106g. Comments**

Public adress and master time clock systems upgrades.

**107. Communication Systems (H)**

- ☒ Yes
- ☐ No

**107a. Type of communication system (check all that apply)**

- ☒ Public Address
- ☒ Phones (VOIP)
- ☒ Phones (Cellular)
- ☐ Phones (other)
- ☒ Mass Notification
- ☒ Emergency voice communication fire alarm system
- ☒ Lockdown notification system
- ☐ Other (eg. radio) (describe below)

**107b. If "Other" please describe**

(No Response)

2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Electrical Systems

---

Page Last Modified: 02/27/2025

107c. Communication systems are adequate:

- ☒ Yes
- ☐ No

107d. Condition of communication system:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-functioning
- ☐ Critical failure

107e. Year of last major reconstruction/replacement:

2003

107f. Expected remaining useful life:

8

107g. Cost to replace/reconstruct:

(No Response)

107h. Comments

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Student Transportation Facilities

---

Page Last Modified: 08/21/2024

**Student Transportation Facilities****108. Is this building a transportation facility**☐ Yes☒ No**109. Does this facility have a fuel dispensing system?**☐ Yes☒ No**110. Does this facility have vehicle lifts**☒ Yes☐ No**110a. Overall condition of vehicle lifts**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-functioning☐ Critical failure☐ N/A**110b. Year of last major reconstruction/replacement**

2003

**110c. Expected remaining useful life (years):**

19

**110d. Cost to reconstruct/replace:**

(No Response)

**110e. Comments**

(No Response)

**111. Does this facility have a bus wash system?**☐ Yes☒ No

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Accessibility

---

Page Last Modified: 08/21/2024

**ACCESSIBILITY****112. Exterior Accessible Route to Building (H)**

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

**Is there an accessible exterior route as specified above?**☒ Yes☐ No**112a. Features provided for exterior accessible route (check all that apply)**☒ Curb ramps☐ Exterior ramps☒ Handicap parking**112b. Cost of improvements needed to provide exterior accessible route to building \$:**

(No Response)

**112c. Comment**

(No Response)

**113. Is there an exterior accessible route to recreational facilities?**☒ Yes☐ No**113a. Cost of improvements to provide exterior accessible route(s) to recreational facilities \$:**

(No Response)

**113b. Comments**

(No Response)

**114. Exterior recreational facilities that are on an accessible route and meet accessibility standards (check all that apply)**☐ Playground and play equipment☒ Playfield(s)☒ Athletic Field(s)☐ Exterior Bleachers☐ Bathroom Facilities☐ Concession Stand**114a. Cost of improvements to provide exterior accessible recreational facilities \$:**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Accessibility

---

Page Last Modified: 08/21/2024

**114b. Comments**

(No Response)

**115. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)**

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an interior accessible interior route as specified above?

☒ Yes☐ No**115a. Cost of improvements needed to provide interior accessible route(s) as specified above \$:**

(No Response)

**115b. Comments**

(No Response)

**116. Does this facility have interior spaces that meet accessibility standards (check all that apply)**

- ☒ Classrooms
- ☒ Labs (science, art, technology, etc)
- ☒ Shops
- ☒ Main Office
- ☒ Health Office
- ☒ Gymnasium
- ☒ Cafeteria
- ☒ Auditorium
- ☒ Stage
- ☒ Restrooms on each floor

**116a. Cost of improvements to provide interior spaces that meet accessibility standards \$:**

(No Response)

**116b. Comments**

(No Response)

## 2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School

Environment/Comfort/Health

---

Page Last Modified: 08/21/2024

**ENVIRONMENT/COMFORT/HEALTH****117. General Appearance****117a. Overall Rating:**

- ☒ Good
- ☐ Fair
- ☐ Poor

**117b. Comments:**

(No Response)

**118. Cleanliness (H)****118a. Overall Rating:**

- ☒ Good
- ☐ Fair
- ☐ Poor

**118b. Comments:**

(No Response)

**119. Are there walk off mats; grills in the entryway?**

- ☒ Yes
- ☐ No

**119a. If yes: at least 6 feet long?**

- ☒ Yes
- ☐ No

**120. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education? (H)**

- ☐ Yes
- ☒ No

**121. Lighting Quality (H):****121a. Types of lighting in general purpose classrooms (check all that apply):**

- ☐ Daylight (natural)
- ☐ Not full spectrum
- ☐ Full spectrum
- ☒ LED
- ☐ Flourescent
- ☐ Other (describe)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Environment/Comfort/Health

---

Page Last Modified: 08/21/2024

**121b. Are there blinds in the classroom to prevent glare?**☒ Yes☐ No**121c. Overall Rating:**☒ Good☐ Fair☐ Poor**121d. Comments:**

(No Response)

**122. Evidence of Vermin (H)****122a. Is there evidence of active infestations of...(check all that apply)?**☐ Rodents☐ Wood-boring or Wood-eating Insects☐ Cockroaches☐ Other Vermin☒ None

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Indoor Air Quality

---

Page Last Modified: 02/27/2025

**Indoor Air Quality****123. Mold (H)****123a. Is there visible mold or moldy odors?**

- ☐ Yes  
☒ No

**123b. Are any surfaces constructed of any of the following materials?**

- ☐ Paper-faced or gypsum products  
☐ Cellulose products (typically ceiling tiles)  
☒ Not Applicable

**123c. Is there evidence of water intrusion?**

- ☐ Yes  
☒ No

**123d. Estimated cost of necessary improvements \$:**

(No Response)

**123e. Comments:**

(No Response)

**124. Humidity/Moisture (H)****124a. Overall rating of humidity/moisture condition in building:**

- ☐ Good  
☒ Fair  
☐ Poor

**124b. Are any of the following found in/or around classroom areas (check all that apply)?**

- ☐ Active leaks in roof  
☐ Active leaks in plumbing  
☐ Moisture condensation  
☒ Visible stains or water damage  
☐ None

**124c. Are any of the following found in/or around other areas (check all that apply)?**

- ☐ Active leaks in roof  
☐ Active leaks in plumbing  
☐ Moisture condensation  
☐ Visible stains or water damage  
☒ None

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Indoor Air Quality

---

Page Last Modified: 02/27/2025

**125. Ventilation: fresh air intake locations, air filters, etc. (H)****125a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?**☐ Yes☒ No**125b. Is there accumulated dirt, dust or debris around fresh air intakes?**☐ Yes☒ No**125c. Are fresh air intakes free of blockage?**☒ Yes☐ No**125d. Is accumulated dirt, dust or debris in ductwork?**☐ Yes☒ No**125e. Are dampers functioning as designed?**☒ Yes☐ No**125f. Condition of air filters:**☒ Good☐ Fair☐ Poor**125g. Outside air is adequate for occupant load:**☒ Yes☐ No**125h. Rating of ventilation/indoor air quality:**☒ Good☐ Fair☐ Poor**125i. Comments:**

(No Response)

**126. Indoor Air Quality (IAQ) Plan (H)****126a. Does the school district use EPA's *Tools for Schools* program?**☒ Yes

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Indoor Air Quality

---

Page Last Modified: 02/27/2025

☐ No**126b. If No, is some other IAQ management plan used?**☒ Yes☐ No**126c. Has the District assigned IAQ responsibilities to a designated individual?**☒ Yes☐ No**126c.1 If Yes, what is their job title?**

Facilities Administrator

**127. Does the school practice Integrated Pest Management (IPM)? (H)**☒ Yes☐ No**127a. Is vegetation kept one foot away from the building?**☒ Yes☐ No**127b. Are crevices and holes in walls, floors and pavement sealed or eliminated?**☐ Yes☒ No**127c. Is there a certified pesticide applicator on staff?**☐ Yes☒ No**127d. Are pesticides used in the building?**☐ Yes☒ No**127d.1 If Yes, how are they typically applied?**☐ Spot treatment☐ Area wide treatments**127e. Are pesticides used on the grounds?**☐ Yes☒ No**127e.1 If Yes, was an emergency exemption granted by the Board of Education?**☐ Yes

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**Indoor Air Quality

---

Page Last Modified: 02/27/2025

☐ No**128. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?****(H)**☐ Yes☒ No**128a. Has the facility been tested for the presence of radon?**☐ Yes☒ No**128b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?**☐ Yes☐ No**128c. If Yes, did the school take steps to mitigate the elevated radon levels?**☐ Yes, active mitigation system installed☐ Yes, passive mitigation system made active☐ Yes, ventilation controls (HVAC) adjusted☐ Yes, other (describe)☐ No action taken**128c.1 Describe other actions taken to mitigate elevated radon levels:**

(No Response)

**2024 BUILDING CONDITION SURVEY - 2024 - East Islip High School**

Emergency Shelter

---

Page Last Modified: 02/27/2025

**Emergency Shelter**

**129. Does this building serve as an emergency shelter?**

☐ Yes

☒ No

**130. List the district's occupied buildings which require the BCS**

(No Response)