

Fire Inspection Violation Summary  
West Irondequoit CSD

Date of Inspection – January 31, 2025  
Inspector – Kelly Wasson, NYS CEO 0309-7117B

**No Violations at the Time of Inspection:**

*Administration Building  
Briarwood School  
DES Services Bldg.  
Grandstand & Press Box  
Brookview School  
Lakeview School  
Iroquois School  
Sproule Field House*

*Oakview School  
Concession Stand  
E & M Teaching Center  
Oakview School  
Listwood School  
Colebrook School  
Sugar Shack  
Athletic Storage*

**Seneca School**

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
<b>14C-2 F315</b>	<b><i>Doors requiring closers are not rendered inoperable by removal of the closer of the installation of any non-automatic hold open device.</i></b>	<b>The library door was found propped open. Doors with closers cannot be propped open.</b>
<i>During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:</i>		<b>February 6, 2025</b>

**DES Services Barn**

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
<b>15A-2 F807.1</b>	<b>Furnishings do not obstruct or obscure exits.</b>	<b>A box was restricting access to the north exit door.</b>
<i>During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:</i>		<b>February 6, 2025</b>

### Pinegrove Bldg.

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
12 E-1 F604	No electrical system hazards observed or reported.	Tutoring Center - String lights were found in the room. String lights are only allowed for 90 days under the electrical code.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 6, 2025</b>

### Irondequoit High School

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
12 E-1 F604	No electrical system hazards observed or reported.	Classrooms 2081, 2040, 3058, 2043, 2056, 2071, - String lights were found in the room. String lights are only allowed for 90 days under the electrical code.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 13, 2025</b>
14C-2 F315	<i>Doors requiring closers are not rendered inoperable by removal of the closer of the installation of any non-automatic hold open device.</i>	<i>Classroom 2079 Doors were found propped open. Doors equipped with closers must be kept closed.</i>
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 13, 2025</b>

### Dake Jr. High School

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
12 E-1 F604	No electrical system hazards observed or reported.	Classrooms 122, 127, 209, 302, 303- String lights were found in the room. String lights are only allowed for 90 days under the electrical code.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 12, 2025</b>
14A-2 F701.2	Fire resistance rating of rated construction is maintained	Room 236 – The side door is covered with paper. The door cannot be covered with paper.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 12, 2025</b>
15A-2 F801	Furnishings do not obstruct or obscure exits.	Band Room - Furniture by exits. Exits and hallway must have clear access
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 12, 2025</b>

## Rogers - Southlawn School

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
12 E-1 F604	No electrical system hazards observed or reported.	Room 166, 180 - String lights were found in the room. String lights are only allowed for 90 days under the electrical code.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 18, 2025</b>
15C-2 F807.5.2.2	Artwork and teaching materials are limited to not more than 20% of the corridor wall area.	Hallway by 186 – There was excessive artwork in the hallway.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 18, 2025</b>

## Helmer Nature Center

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
14C-2 F315	<i>Doors requiring closers are not rendered inoperable by removal of the closer of the installation of any non-automatic hold open device.</i>	The boiler room door was found propped open. Doors with closers cannot be propped open.
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 6, 2025</b>
16D-2 F915.6	Carbon Monoxide detection and alarm systems are operative and maintained in accordance with Code; and records are available for review on premises.	The CO Monitor for the boiler room could not be found//
During the re-inspection, the identified issue(s) were found to be corrected. The re-inspection occurred on:		<b>February 6, 2025</b>