

Portland Public Schools
Lead and Copper Water Sampling Results
A (Initial) and B (Follow-Up) Sample Data
Green Thumb School

Sample Identification # and Location	Date/Time Collected	Date/Time Analyzed	Container ID	Analyte	Results	PPS Action Level*	Units
305-1310-B-001A Hallway (Near Landscaping) Metal Fountain	12/13/18 6:29 AM	12/17/18 9:08 PM	18033967	Copper	< 0.1	1.3	ppm
305-1310-B-001A Hallway (Near Landscaping) Metal Fountain	12/13/18 6:29 AM	12/17/18 9:08 PM	18033967	Lead	3	15	ppb
305-1310-B-001B Hallway (Near Landscaping) Metal Fountain	12/13/18 6:29 AM	12/17/18 9:12 PM	18033969	Copper	< 0.1	1.3	ppm
305-1310-B-001B Hallway (Near Landscaping) Metal Fountain	12/13/18 6:29 AM	12/17/18 9:12 PM	18033969	Lead	2	15	ppb
305-1307-N/A-001A (Outside Porcelain Drinking Fountain)	12/13/18 6:20 AM	12/17/18 9:15 PM	18033970	Copper	0.4	1.3	ppm
305-1307-N/A-001A (Outside Porcelain Drinking Fountain)	12/13/18 6:20 AM	12/17/18 9:15 PM	18033970	Lead	2	15	ppb
305-1307-N/A-001B (Outside Porcelain Drinking Fountain)	12/13/18 6:20 AM	12/17/18 9:19 PM	18033971	Copper	< 0.1	1.3	ppm
305-1307-N/A-001B (Outside Porcelain Drinking Fountain)	12/13/18 6:20 AM	12/17/18 9:19 PM	18033971	Lead	4	15	ppb
305-1310-A-001A (Hallway Bottle Filler)	12/13/18 6:27 AM	12/17/18 9:22 PM	18033972	Copper	< 0.1	1.3	ppm
305-1310-A-001A (Hallway Bottle Filler)	12/13/18 6:27 AM	12/17/18 9:22 PM	18033972	Lead	3	15	ppb
305-1310-A-001B (Hallway Bottle Filler)	12/13/18 6:27 AM	12/17/18 9:26 PM	18033973	Copper	< 0.1	1.3	ppm
305-1310-A-001B (Hallway Bottle Filler)	12/13/18 6:27 AM	12/17/18 9:26 PM	18033973	Lead	2	15	ppb
305-1312-N/A-001A (Staff Food Prep Faucet)	12/13/18 6:15 AM	12/17/18 9:30 PM	18033974	Copper	0.3	1.3	ppm
305-1312-N/A-001A (Staff Food Prep Faucet)	12/13/18 6:15 AM	12/17/18 9:30 PM	18033974	Lead	26	15	ppb
305-1312-N/A-001B (Staff Food Prep Faucet)	12/13/18 6:15 AM	12/17/18 9:33 PM	18033975	Copper	0.3	1.3	ppm
305-1312-N/A-001B (Staff Food Prep Faucet)	12/13/18 6:15 AM	12/17/18 9:33 PM	18033975	Lead	1	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.