

ADDENDUM 1

IMPORTANT DOCUMENT – Request for Proposal #26-0003

Structural Removal & Base Prep

ADDENDUM DATE: September 30th, 2025

UPDATE: ASBESTOS REMOVAL -

BUILDING ASSESSMENT: ASBESTOS REINSPECTION DATA

PLEASE ACKNOWLEDGE RECEIPT OF THIS ADDENDUM AND RETURN IT WITH YOUR SUBMITTAL. FAILURE TO SIGN AND RETURN WITH YOUR SUBMITTAL COULD RESULT IN REJECTION OF YOUR PROPOSAL.

SIGNATURE

PRINT OR TYPE NAME

COMPANY NAME

EMAIL ADDRESS



**Hendry County School Board - Clewiston Two Story White Brick Building
BUILDING ASSESSMENT**

September 10, 2021

Occupational Health Conservation, Inc.							Asbestos Reinspection Data				
AHERA Inspector : Rose, Paul F. Date of Reinspection : 11/8/95 to 11/14/95 Facility Number : 12				AHERA Reinspection County Administration Sub-Office 435 East Circle Drive Clewiston, Florida							
Building No./ Homogeneous Area	Material	Homogeneous Area Location	Air Erosion	Type of Material	Fri.	Status	Damage Evidence	Condition	Damage Potential	HR	RP
02/004	9" x 9" Cream/Tan Floor Tile and Mastic	Building No. 2, Main Building - Second Floor Room Nos. 016B, 017, 017A, 017B, 017C, 017D, 017E, 018, 018A, 018B, 021 and 021B	None	Miscellaneous	No	Remains	Physical: 5% Water: None Delamination: 1%	Damaged	Moderate	5	3
02/005	12" x 12" Dark Brown/White Floor Tile and Mastic	Building No. 2, Main Building - Second Floor Room Nos. 016D, 017, 017A and 017B	None	Miscellaneous	No	Remains	Physical: 5% Water: 1% Delamination: 1%	Damaged	Low	4	4
02/010*	12" x 12" Beige/Brown Floor Tile	Building No. 2, Main Building - Second Floor Room No. 017	None	Miscellaneous	No	Remains	Physical: 2% Water: None Delamination: 2%	Good	Moderate	2	6
02/OHC011*	Window Caulking	Building No. 2, Main Building - Windows	None	Miscellaneous	No	Remains	Physical: 8% Water: None Delamination: 4%	Damaged	Moderate	5	3
03/005*	9" x 9" Light Green Floor Tile and Mastic	Building No. 3 - Room No. 002	None	Miscellaneous	No	Enclosed	Physical: 4% Water: None Delamination: 1%	Good	Low	1	7
03/006*	9" x 9" Tan/White Floor Tile	Building No. 3 - Room No. 001	None	Miscellaneous	No	Enclosed	Physical: 3% Water: None Delamination: 1%	Good	Low	1	7
03/007*	12" x 12" Green Speckled Floor Tile and Mastic	Building No. 3 - Hallways A, B and C	None	Miscellaneous	No	Enclosed	Physical: 2% Water: None Delamination: 1%	Good	Low	1	7

Fri.=Friable; HR=Hazard Ranking; RP=Response Priority

* Other observations regarding this material were noted by the inspector. See Other Observations section of this report.

951838

Page 1