

Fire Inspection Violation Summary
West Irondequoit CSD

Date of Inspection – January 31, 2025
Inspector – Kelly Wasson, NYS CEO 0309-7117B

No Violations at the Time of Inspection:

*Administration Building
Briarwood School
DES Services Bldg.
Grandstand & Press Box
Brookview School
Lakeview School
Iroquois School
Sproule Field House
Pinegrove Bldg.
DES Services Barn*

*Oakview Operations Bldg.
Concession Stand
E & M Teaching Center
Oakview School
Listwood School
Colebrook School
Sugar Shack
Athletic Storage
Seneca School
Helmer Nature Center*

Irondequoit High School

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
6F-1 155.7	Storage in storerooms and classroom areas is orderly and restricted to items of obvious value and usefulness.	PAC – There is excess storage behind the seating risers. Storage in this area should be minimized.
12 E-1 F604	No electrical system hazards observed or reported.	Classrooms 2087, 1144, Performing Arts Center - String lights were found in the room. String lights are only allowed for 90 days under the electrical code.
12J-1 F604.5	Extension cords are properly used and are not a substitute permanent wiring	Room 3033 – An extension cord was in use. Extension cords are for short term use only.
14C-2 F315	Doors requiring closers are not rendered inoperable by removal of the closer or the installation of any non-automatic hold open device.	Doors were found propped open. Doors equipped with closers must be kept closed.

Safety Note	Room 2033, 2023 – A “Chemical Storage Room” sticker is needed for the door.
-------------	---

Dake Jr. High School

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
6F-1 155.7	Storage in storerooms and classrooms areas is orderly and restricted to items of obvious value and usefulness	Basement – There is excess storage in the corridor. Items need to be moved to their storage areas or removed. .
12 E-1 F604	No electrical system hazards observed or reported.	Classroom 302, 304 - String lights were found in the room. String lights are only allowed for 90 days under the electrical code.
14A-2 F701.2	Fire resistance rating of rated construction is maintained	Room 236 – The side door is covered with paper. The door cannot be covered with paper.
15B-1 F807.5.2	Storage of clothing and personal belongings in corridors and lobbies is compliant.	Classroom 198 – Bookbag were blocking the exit door. The doors must be able to open from both sides.

Rogers - Southlawn School

<u>Code Section</u>	<u>Description</u>	<u>Violation</u>
2E-2 155.7	Emergency rescue windows are free of obstructing bars, screens, grilles, or classroom equipment, or if so equipped, windows must be releasable or removable from the inside without the use of a key, tool, or force greater than that needed for normal operation.	Classroom 185 – The rescue window was blocked. nothing
14A-2 F701.2	Fire resistance rating of rated construction is maintained	Room 147 – The classroom door is covered with paper. The door cannot be covered with paper.
15D-2 F807.2	Curtains, drapes, hangings, and other decorative materials suspended from walls or ceiling shall comply with Section 807.2 and shall not exceed 10% of the specific wall or ceiling to which they are attached	Classrooms 185, 186 - Fabric panels must be flame resistant or non-combustible. SED specifically prohibits these panels because they have not been tested with the light fixture.
16B-2 F906.5	Portable fire extinguishers are located in a conspicuous location, are readily accessible, are not obstructed or obscured, and are maintained in accordance with this section and NFPA.	Kitchen– The K extinguisher in the kitchen is past due for inspection and must be replaced.

