




NOTES:

- Verification or confirmation of previous findings in other reports was not confirmed via bulk sampling and analysis.
- This figure should be used in conjunction with the associated AHERA reinspection report and management plan update.
- Additional asbestos containing materials may be present in hidden areas such as flooring underlayments, wall and ceiling voids, and sub-grade areas.

ASBESTOS CONTAINING MATERIALS:

Cementitious (Transite) Wall Panels



AHERA Reinspection – Newington Elementary School
Approximate Locations of ACBMs

10 King Charles Circle
Summerville, South Carolina 29485

1

Figure

Project No.
25-2340ES