

Saint Paul Public Schools

Six Month Periodic Surveillance Report for:

Located at:

Early Learning Hub West

1317 Charles Avenue

Saint Paul, MN 55104

Conducted On: 3/6/2026

Conducted By: Grant Gervais

Key									
% of Asbestos		EPA Assessment Category				Response Action			
CH	Chrysotile	1 = Damaged or significantly damaged TSI ACM.				A = Cleanup ACM debris.			
AM	Amosite	2 = Damaged friable surfacing ACM.				B = Encapsulate slight damage on TSI.			
CR	Crocidolite	3 = Significantly damaged friable surfacing ACM.				C = Patch TSI and/or repair ACM cover.			
ACT	Actinolite	4 = Damaged or significantly damaged friable miscellaneous ACM.				D = Enclose or protect accessible sections with protective barrier.			
TR	Tremolite	5 = ACBM with potential for damage.				E = Remove section of damaged ACM.			
ANT	Anthophyllite	6 = ACBM with potential for significant damage.				F = Remove ACM and replace with non-ACM.			
Assumed	Suspect materials that have not been tested	7 = Remaining friable ACBM or friable suspect ACBM.				G = Isolate area until repaired/removed.			
None	Materials that have been tested and have been found to not contain asbestos					H = Encapsulate slight damage.			
Detected						I = Remove and replace damaged or loose tile section.			
NSM	Nonsuspect material					J = Monitor condition of material(s).			
NEW	Materials which are known to be installed since the original AHERA inspection (1988/1989) may be listed as NEW . These materials are required to be sampled under the EPA's NESHAP Rule prior to renovation or demolition activities.								

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
1 CAD #:	N0A	Drywall/Joint Compound Walls & Ceilings	THROUGHOUT BUILDING	15000 Sq Ft			NONE DETECTED		
Comments:						Sample #: 2001-1501-AHQC1			
2 CAD #:	N0B	Drywall/Joint Compound Smooth Soffit	THROUGHOUT BUILDING	5000 Sq Ft			NONE DETECTED		
Comments:						Sample #: 467-JJT-4			
3 CAD #:	N0C	Drywall/Joint Compound Divider Wall Panels	THROUGHOUT BUILDING	20000 Sq Ft			NONE DETECTED		
Comments:						Sample #: 102308MV-21			
4 CAD #:	Q0G	Carpet Adhesive Gray/Tan Berber Carpet	THROUGHOUT BUILDING	4000 Sq Ft			NONE DETECTED		
Comments:						Sample #: 102308MV-12			
5 CAD #:	X1B	Miscellaneous Material 6" Brown Quarry Tile	THROUGHOUT BUILDING	400 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments: AT ENTRANCE 1160A. INCLUDES BASEBOARD THROUGHOUT.						Sample #:			
6 CAD #:	J3A	Miscellaneous Cementitious Material Black Window Sills	THROUGHOUT BUILDING	300 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments:						Sample #: 102308MV-22			
7 CAD #:	X0C	Miscellaneous Material Red Fire Stop	THROUGHOUT BUILDING	200 Sq Ft			NONE DETECTED		
Comments:						Sample #: 102308MV-4			
8 CAD #:	X1D	Miscellaneous Material 1" X 1" Yellow Ceramic Floor Tile Systems	THROUGHOUT 1973 ORIGINAL BUILDING RESTROOMS	1200 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
9 CAD #:	P0B	Fire Doors Metal -1.5 Hour (Underwriter Laboratories)	BOILER ROOM (1161)	20 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
10 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	BOILER ROOM (1161)	6 Joints			NONE DETECTED		
Comments: FITTINGS OFF WATER HEATER.						Sample #: 467-JJT-6			
11 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	BOILER ROOM (1161)	120 Joints			NONE DETECTED		
Comments:						Sample #: 509-Q-7P, 8P			
12 CAD #:	C3A	Miscellaneous Tank Insulation 1974 Original Building	BOILER ROOM (1161)	12 Sq Ft			NONE DETECTED		
Comments: HEAT EXCHANGER ON NORTH WALL.						Sample #: 467-JJT-27, 28, 29			
13 CAD #:	D1A	Boiler Gaskets Burner Gasket	BOILER ROOM (1161)	2 Sq Ft			NONE DETECTED		
Comments: BOILER #2.						Sample #: 102308MV-2			
14 CAD #:	X0A	Miscellaneous Material AHU Seam Tar Gasket	BOILER ROOM (1161)	20 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: AHU #1.						Sample #: 102308MV-1			
15 CAD #:	L0B	Flexible Duct Connector Black Vinyl	BOILER ROOM (1161)	5 Sq Ft			NONE DETECTED		
Comments: PAINTED WHITE.						Sample #: 2001-1501-AH-3			
16 CAD #:	X0B	Miscellaneous Material Black Damp Proofing	TUNNEL UNDER ROOM 1160B	150 Sq Ft			NONE DETECTED		
Comments: VISIBLE IN TUNNEL.						Sample #: 102308MV-3			
17 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	TUNNEL UNDER MAIN HALLWAY	120 Joints			NONE DETECTED		
Comments: OFF OF BOILER ROOM.						Sample #: 100-M1A, M1B, M1C			
18 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Dark Brown - Associated w/I1A	CAFETERIA (1162)	10 Sq Ft			NONE DETECTED		
Comments: RESIDUAL ABOVE CEILING.						Sample #:			
19 CAD #:	I3E	2' x 4' Ceiling Tile Vinyl-Coated Fiberglass (2011)	CAFETERIA (1162)	2200 Sq Ft			NSM		
Comments:						Sample #:			
20 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Aqua Mottle	CAFETERIA (1162)	2200 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
21 CAD #:	R0E	Baseboard/Mopboard Adhesive Black Baseboard	CAFETERIA (1162)	90 Sq Ft			NONE DETECTED		
Comments:						Sample #: 102308MV-29			
22 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	CAFETERIA STORAGE (1162D)	40 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			
23 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	CAFETERIA STORAGE (1162D)	5 Sq Ft			NONE DETECTED		
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
24 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	CAFETERIA STORAGE (1162C)	65 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			
25 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	CAFETERIA STORAGE (1162C)	10 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
26 CAD #:	K2J	12" x 12" Vinyl Floor Tile & Mastic Light Gray Mottle (2019)	KITCHEN DRY STORAGE (1162B)	255 Sq Ft			NEW		
Comments:						Sample #:			
27 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	KITCHEN DRY STORAGE (1162B)	15 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
28 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	CUSTODIAL OFFICE (1162A)	255 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			
29 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	CUSTODIAL OFFICE (1162A)	15 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
30 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	KITCHEN (1163)	30 Joints			NONE DETECTED		
Comments: ABOVE CEILING & UNDER SINK.						Sample #:			
31 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	KITCHEN (1163)	2 Joints			NONE DETECTED		
Comments:						Sample #:			
32 CAD #:	I2E	2' x 2' Acoustical Ceiling Tile Vinyl-Coated Gypsum (2011)	KITCHEN (1163)	740 Sq Ft			NSM		
Comments:						Sample #:			
33 CAD #:	X1C	Miscellaneous Material 6" Red Quarry Tile	KITCHEN (1163)	740 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
34 CAD #:	M0A	Plaster 1974 Original Building	KITCHEN STORAGE (1209)	275 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
35 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	KITCHEN STORAGE (1209)	6 Joints			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
36 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	KITCHEN STORAGE (1209)	2 Joints			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
37 CAD #:	M0A	Plaster 1974 Original Building	KITCHEN OFFICE (1209C)	80 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
38 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	KITCHEN OFFICE (1209C)	7 Joints			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:	467-JJT-26		

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
39 CAD #:	M0A	Plaster 1974 Original Building	KITCHEN RESTROOM (1209B)	40 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
40 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	KITCHEN RESTROOM (1209B)	25 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
41 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	KITCHEN CUSTODIAL CLOSET (1209A)	3 Joints			NONE DETECTED		
Comments:						Sample #:			
42 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	KITCHEN CUSTODIAL CLOSET (1209A)	3 Joints			NONE DETECTED		
Comments:						Sample #:			
43 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	ROOM 1202	2000 Sq Ft			NONE DETECTED		
Comments: NEW MATERIAL.						Sample #:			
44 CAD #:	I1A	1' x 1' Acoustical Ceiling Tile Grubs w/Nail & Pin Holes	ROOM 1202	390 Sq Ft			NONE DETECTED		
Comments: ON WALLS AT CEILING.						Sample #:	2001-1901-GEW-1B		
45 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Dark Brown - Associated w/I1A	ROOM 1202	88 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
46 CAD #:	Q0A	Carpet Adhesive Brown Berber Carpet	ROOM 1202	1000 Sq Ft			NONE DETECTED		
Comments:						Sample #:	080415BV-03		
47 CAD #:	X0M	Miscellaneous Material Corkboard Adhesive	ROOM 1202A & 1202B	2 Sq Ft			NONE DETECTED		
Comments: MOST CORK REMOVED W/RESIDUAL ADHESIVE LEFT ON WALL.						Sample #:	080415BV-01		
48 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 1202B (STORAGE CLOSET)	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
49 CAD #:	Q0C	Carpet Adhesive Brown w/Dark Brown Carpet	ROOM 1202B (STORAGE CLOSET)	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:	2001-1901-ZZ-6B		
50 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 1202A (OFFICE)	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
51 CAD #:	Q0C	Carpet Adhesive Brown w/Dark Brown Carpet	ROOM 1202A (OFFICE)	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
52 CAD #:	Q0C	Carpet Adhesive Brown w/Dark Brown Carpet	ROOM 1202C (SERVER ROOM)	100 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
53 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	HALLWAY 1205	8 Joints			NONE DETECTED		
Comments: FROM 1202 TO GYMNASIUM.						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
54 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	HALLWAY 1205	23 Joints			NONE DETECTED		
Comments: FROM 1202 TO GYMNASIUM.						Sample #:			
55 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	HALLWAY 1205	330 Sq Ft			NONE DETECTED		
Comments: FROM 1202 TO GYMNASIUM.						Sample #:	467-JJT-13		
56 CAD #:	Q0F	Carpet Adhesive Blue Multi-Shaded Carpet	HALLWAY 1205	750 Sq Ft			NONE DETECTED		
Comments: FROM ROOM 1202 TO GYMNASIUM.						Sample #:			
57 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Aqua Mottle	HALLWAY 1205	330 Sq Ft			NONE DETECTED		
Comments: NEAR DOOR 5.						Sample #:	467-JJT-31		
58 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	MECHANICAL ROOM (TE-1)	15 Joints			NONE DETECTED		
Comments: ACCESS THROUGH MAINTENANCE ROOM 1205A.						Sample #:			
59 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	MECHANICAL ROOM (TE-1)	11 Joints			NONE DETECTED		
Comments:						Sample #:	467-JJT-22		
60 CAD #:	X0A	Miscellaneous Material AHU Seam Tar Gasket	MECHANICAL ROOM (TE-1)	10 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: AHU #4.						Sample #:			
61 CAD #:	L0B	Flexible Duct Connector Black Vinyl	MECHANICAL ROOM (TE-1)	2 Sq Ft			NONE DETECTED		
Comments: PAINTED WHITE.						Sample #:			
62 CAD #:	P0A	Fire Doors Wood Composite - 1.5 Hr Rating (Eggers)	MECHANICAL ROOM (TE-1)	20 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments: ONE (1) DOOR.						Sample #:			
63 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	ROOM 1207	8 Joints			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
64 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	ROOM 1207	2 Joints			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
65 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 1207	480 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
66 CAD #:	Q0E	Carpet Adhesive Light Blue w/White & Pink Specks Berber Carpet	ROOM 1207	480 Sq Ft			NONE DETECTED		
Comments:						Sample #:	467-JJT-24		
67 CAD #:	R0D	Baseboard/Mopboard Adhesive Pink 4" Baseboard	ROOM 1207	30 Sq Ft			NONE DETECTED		
Comments:						Sample #:	080415BV-04		
68 CAD #:	V0A	Sink Undercoating Black	ROOM 1207	5 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: ONE (1) SINK.						Sample #:	2001-1501-EE1		

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
69 CAD #:	X0D	Miscellaneous Material Dark & Light Brown Laminate Countertop	ROOM 1207	25 Sq Ft			NONE DETECTED		
Comments:						Sample #: 467-JJT-25			
70 CAD #:	G1C	Sprayed-On Acoustical Finish White Fluffy (2011)	GYMNASIUM (1208)	7000 Sq Ft			NEW		
Comments:						Sample #:			
71 CAD #:	I3E	2' x 4' Ceiling Tile Vinyl-Coated Fiberglass (2011)	GYMNASIUM (1208)	480 Sq Ft			NSM		
Comments: CENTER.						Sample #:			
72 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Tan w/Brown & White Streaks	GYMNASIUM (1208)	4800 Sq Ft			NONE DETECTED		
Comments:						Sample #: 2001-1501-AH-2			
73 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	GYMNASIUM (1208)	75 Sq Ft			NONE DETECTED		
Comments:						Sample #: 2001-1901-ZZ-5B			
74 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	ROOM 1208A	5 Joints			NONE DETECTED		
Comments:						Sample #:			
75 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	ROOM 1208A	4 Joints			NONE DETECTED		
Comments:						Sample #:			
76 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	ROOM 1208C (SPRINKLER VALVE ROOM)	4 Joints			NONE DETECTED		
Comments:						Sample #:			
77 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	ROOM 1208C (SPRINKLER VALVE ROOM)	2 Joints			NONE DETECTED		
Comments:						Sample #:			
78 CAD #:	M0A	Plaster 1974 Original Building	MEN'S GYMNASIUM RESTROOM	120 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
79 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	MEN'S GYMNASIUM RESTROOM	125 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
80 CAD #:	M0A	Plaster 1974 Original Building	WOMEN'S GYMNASIUM RESTROOM	120 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
81 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	WOMEN'S GYMNASIUM RESTROOM	125 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
82 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	ROOM 1203	1500 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
83 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	ROOM 1203	900 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
84 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	ROOM 1203	35 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
85 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 1203	5 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments:						Sample #:			
86 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	ROOM 1203A	300 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
87 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	ROOM 1203A	190 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			
88 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	ROOM 1203A	15 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
89 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	ROOM 1203B	400 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
90 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	ROOM 1203B	260 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			
91 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	ROOM 1203B	15 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
92 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	ROOM 1201	1400 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
93 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	ROOM 1201	800 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:	030626GG-01		
94 CAD #:	V0A	Sink Undercoating Black	ROOM 1201	20 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: FOUR (4) SINKS.						Sample #:			
95 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 1201	5 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments:						Sample #:			
96 CAD #:	X0K	Miscellaneous Material Light Yellow Countertop	ROOM 1201	210 Sq Ft			NONE DETECTED		
Comments:						Sample #:	467-JJT-14		
97 CAD #:	I3A	2' x 4' Ceiling Tile Chicken Scratch w/Pin Holes	EAST/WEST HALLWAY FROM ROOM 1202 TO CAFETERIA	1200 Sq Ft			NONE DETECTED		
Comments:						Sample #:	467-JJT-23		
98 CAD #:	K2H	12" x 12" Vinyl Floor Tile & Mastic Solid Color Mottle (2008)	MAIN ENTRY & HALLWAY BY MAIN OFFICE	1000 Sq Ft			NONE DETECTED		
Comments: RED, YELLOW, GREEN, BLUE & GRAY.						Sample #:	102308MV-20		
99 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Gray Baseboard	MAIN ENTRY & HALLWAY BY MAIN OFFICE	40 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
100 CAD #:	N0D	Drywall/Joint Compound 2005 Addition	MAIN OFFICE	4000 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-19		

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
101 CAD #:	I2D	2' x 2' Acoustical Ceiling Tile Dents w/Pin Holes	MAIN OFFICE	2000 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-15		
102 CAD #:	Q0F	Carpet Adhesive Blue Multi-Shaded Carpet	MAIN OFFICE	2000 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-17		
103 CAD #:	R0G	Baseboard/Mopboard Adhesive 4" Light Blue Baseboard	MAIN OFFICE	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-13		
104 CAD #:	V0B	Sink Undercoating Gray	MAIN OFFICE	10 Sq Ft			NONE DETECTED		
Comments: TWO (2) SINKS. 1013 AND NURSE'S OFFICE						Sample #:	102308MV-16		
105 CAD #:	X1E	Miscellaneous Material 6" Gray Ceramic Floor Tile (2005)	MAIN OFFICE RESTROOM	50 Sq Ft			NEW		
Comments:						Sample #:			
106 CAD #:	X1F	Miscellaneous Material 4" Peach Ceramic Wall Tile System (2005)	MAIN OFFICE RESTROOM	80 Sq Ft			NEW		
Comments:						Sample #:			
107 CAD #:	K2G	12" x 12" Vinyl Floor Tile & Mastic White w/Multi-Colored Flecks (2005)	MAINTENANCE STORAGE	20 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
108 CAD #:	K2G	12" x 12" Vinyl Floor Tile & Mastic White w/Multi-Colored Flecks (2005)	NURSE'S AREA (1002)	800 Sq Ft			NONE DETECTED		
Comments: 2005 OFFICE AREA.						Sample #:	102308MV-14		
109 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Gray Baseboard	NURSE'S AREA (1002)	20 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-18		
110 CAD #:	X1E	Miscellaneous Material 6" Gray Ceramic Floor Tile (2005)	NURSE'S RESTROOM 1004	50 Sq Ft			NEW		
Comments:						Sample #:			
111 CAD #:	X1F	Miscellaneous Material 4" Peach Ceramic Wall Tile System (2005)	NURSE'S RESTROOM 1004	100 Sq Ft			NEW		
Comments:						Sample #:			
112 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	1ST FLOOR SOUTHEAST STAIRWELL (1999B)	60 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
113 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOMS 1141-1146	20 Sq Ft			NONE DETECTED		
Comments: RESIDUE ABOVE DIVIDER WALLS BETWEEN CONCRETE DECK						Sample #:	467-JJT-12		
114 CAD #:	I3B	2' x 4' Ceiling Tile Spray-On Look w/Revealed Edge (2014)	ROOMS 1141-1146	4000 Sq Ft			NEW		
Comments: INCLUDES RESTROOMS						Sample #:			
115 CAD #:	K3A	Miscellaneous Flooring 2' x 2' Light & Dark Gray Tile (2014)	ROOMS 1141-1146	4660 Sq Ft			NEW		
Comments:						Sample #:			
116 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	ROOM 1141	380 Sq Ft			NEW		
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
117 CAD #:	R0C	Baseboard/Mopboard Adhesive Black Baseboard (2014)	ROOM 1141	10 Sq Ft			NEW		
Comments:						Sample #:			
118 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 1141	5 Sq Ft			NEW		
Comments: ONE (1) SINK.						Sample #:			
119 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 1141	40 Sq Ft			NONE DETECTED		
Comments: ON BLOCK WALL. BOARD HAS BEEN REMOVED; RESIDUAL ADHESIVE PAINTED OVER.						Sample #: 032514BF-1			
120 CAD #:	X1G	Miscellaneous Material 12" Gray Ceramic Floor Tile System (2014)	ROOM 1141 RESTROOM	50 Sq Ft			NEW		
Comments:						Sample #:			
121 CAD #:	X1H	Miscellaneous Material 6" x 12" Gray Ceramic Wall Tile System (2014)	ROOM 1141 RESTROOM	100 Sq Ft			NEW		
Comments: INCLUDES GREEN & ORANGE ACCENT TILES.						Sample #:			
122 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	ROOM 1142	380 Sq Ft			NEW		
Comments:						Sample #:			
123 CAD #:	R0C	Baseboard/Mopboard Adhesive Black Baseboard (2014)	ROOM 1142	380 Sq Ft			NEW		
Comments:						Sample #:			
124 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 1142	5 Sq Ft			NEW		
Comments:						Sample #:			
125 CAD #:	X1G	Miscellaneous Material 12" Gray Ceramic Floor Tile System (2014)	ROOM 1142 RESTROOM	50 Sq Ft			NEW		
Comments:						Sample #:			
126 CAD #:	X1H	Miscellaneous Material 6" x 12" Gray Ceramic Wall Tile System (2014)	ROOM 1142 RESTROOM	100 Sq Ft			NEW		
Comments:						Sample #:			
127 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	ROOM 1143	120 Sq Ft			NEW		
Comments:						Sample #:			
128 CAD #:	R0C	Baseboard/Mopboard Adhesive Black Baseboard (2014)	ROOM 1143	10 Sq Ft			NEW		
Comments:						Sample #:			
129 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	ROOM 1144	120 Sq Ft			NEW		
Comments:						Sample #:			
130 CAD #:	R0C	Baseboard/Mopboard Adhesive Black Baseboard (2014)	ROOM 1144	10 Sq Ft			NEW		
Comments:						Sample #:			
131 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic White w/Red/Blue/Yellow Smears	ROOM 1145	960 Sq Ft			NONE DETECTED		
Comments:						Sample #: 102308MV-23; 467-JJT-9			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
132 CAD #:	K3C	Miscellaneous Flooring Old Black Flooring Mastic	ROOM 1145	960 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments: ESTIMATED UNDER 12" TILE (K2F). SAMPLED AND VERIFIED IN ONE LOCATION. MAY BE THROUGHOUT. VERIFY PRIOR TO DISTURBANCE.						Sample #: 082222-BF-1			
133 CAD #:	R0C	Baseboard/Mopboard Adhesive Black Baseboard (2014)	ROOM 1145	50 Sq Ft			NEW		
Comments:						Sample #:			
134 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 1145	20 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
135 CAD #:	V0A	Sink Undercoating Black	ROOM 1145	30 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: FOUR (4) SINKS.						Sample #:			
136 CAD #:	X0G	Miscellaneous Material Brown & Tan Countertop	ROOM 1145	75 Sq Ft			NONE DETECTED		
Comments:						Sample #: 467-JJT-25			
137 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Dark Brown - Associated w/I1A	ROOM 1146	5 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
138 CAD #:	R0C	Baseboard/Mopboard Adhesive Black Baseboard (2014)	ROOM 1146	5 Sq Ft			NEW		
Comments:						Sample #:			
139 CAD #:	V0A	Sink Undercoating Black	ROOM 1146	5 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: ONE (1) SINK.						Sample #:			
140 CAD #:	X0G	Miscellaneous Material Brown & Tan Countertop	ROOM 1146	30 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
141 CAD #:	X0H	Miscellaneous Material Red Duct Seam Caulk	ROOM 1146	5 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #: 102308MV-5			
142 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	HALLWAY OUTSIDE ROOMS 1140-1146	10 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
143 CAD #:	K3A	Miscellaneous Flooring 2' x 2' Light & Dark Gray Tile (2014)	HALLWAY OUTSIDE ROOMS 1140-1146	1000 Sq Ft			NEW		
Comments:						Sample #:			
144 CAD #:	X0H	Miscellaneous Material Red Duct Seam Caulk	HALLWAY OUTSIDE ROOMS 1140-1146	10 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
145 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	SOUTHWEST CUSTODIAL CLOSET (1148)	15 Joints			NONE DETECTED		
Comments:						Sample #:			
146 CAD #:	M0A	Plaster 1974 Original Building	1ST FLOOR GIRLS' RESTROOM (1147)	200 Sq Ft			NONE DETECTED		
Comments:						Sample #: 102308MV-8			
147 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	1ST FLOOR GIRLS' RESTROOM (1147)	350 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
148 CAD #:	M0A	Plaster 1974 Original Building	1ST FLOOR BOYS' RESTROOM (1149)	200 Sq Ft			NONE DETECTED		
Comments:						Sample #: 467-JJT-16			
149 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	1ST FLOOR BOYS' RESTROOM (1149)	350 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
150 CAD #:	X0H	Miscellaneous Material Red Duct Seam Caulk	ROOMS 1152-1158 & HALLWAY	50 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
151 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Dark Brown - Associated w/I1A	ROOMS 1153-1155	10 Sq Ft			NONE DETECTED		
Comments: RESIDUE ABOVE CEILING.						Sample #:			
152 CAD #:	I3B	2' x 4' Ceiling Tile Spray-On Look w/Revealed Edge (2014)	ROOMS 1153-1155	4500 Sq Ft			NEW		
Comments:						Sample #:			
153 CAD #:	K3A	Miscellaneous Flooring 2' x 2' Light & Dark Gray Tile (2014)	ROOMS 1153-1155	5900 Sq Ft			NEW		
Comments:						Sample #:			
154 CAD #:	Q0F	Carpet Adhesive Blue Multi-Shaded Carpet	ROOMS 1153-1155	3000 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
155 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 1153	4 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #: 467-JJT-30			
156 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Gray Baseboard	ROOM 1153	45 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
157 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 1153	10 Sq Ft			NEW		
Comments: TWO (2) SINKS.						Sample #:			
158 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 1153	5 Sq Ft			NONE DETECTED		
Comments: PAINTED OVER.						Sample #:			
159 CAD #:	X1G	Miscellaneous Material 12" Gray Ceramic Floor Tile System (2014)	ROOM 1153 RESTROOM	50 Sq Ft			NEW		
Comments:						Sample #:			
160 CAD #:	X1H	Miscellaneous Material 6" x 12" Gray Ceramic Wall Tile System (2014)	ROOM 1153 RESTROOM	100 Sq Ft			NEW		
Comments:						Sample #:			
161 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 1154	9 Sq Ft			NONE DETECTED		
Comments: ABOVE PERIMETER DIVIDER WALLS.						Sample #: 467-JJT-35			
162 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 1154	10 Sq Ft			NEW		
Comments: TWO (2) SINKS.						Sample #:			
163 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 1154	15 Sq Ft			NONE DETECTED		
Comments: PAINTED OVER.						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
164 CAD #:	X1G	Miscellaneous Material 12" Gray Ceramic Floor Tile System (2014)	ROOM 1154 RESTROOM	100 Sq Ft			NEW		
Comments: 2 RESTROOMS.						Sample #:			
165 CAD #:	X1H	Miscellaneous Material 6" x 12" Gray Ceramic Wall Tile System (2014)	ROOM 1154 RESTROOM	200 Sq Ft			NEW		
Comments: 2 RESTROOMS.						Sample #:			
166 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 1155	9 Sq Ft			NONE DETECTED		
Comments: ABOVE OLD DIVIDER WALL CEILING PLATE.						Sample #:	102308MV-27; 467-JJT-8		
167 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 1155	5 Sq Ft			NEW		
Comments: ONE (1) SINK.						Sample #:			
168 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 1155	5 Sq Ft			NONE DETECTED		
Comments: BEHIND WHITEBOARD.						Sample #:			
169 CAD #:	X1G	Miscellaneous Material 12" Gray Ceramic Floor Tile System (2014)	ROOM 1155 RESTROOM	49 Sq Ft			NEW		
Comments:						Sample #:			
170 CAD #:	X1H	Miscellaneous Material 6" x 12" Gray Ceramic Wall Tile System (2014)	ROOM 1155 RESTROOM	100 Sq Ft			NEW		
Comments:						Sample #:			
171 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	1ST FLOOR NORTHWEST STAIRWELL	80 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
172 CAD #:	K3B	Miscellaneous Flooring Gray Stair Tread (2014)	THROUGHOUT LOWER LEVEL STAIRWELLS	140 Sq Ft			NEW		
Comments:						Sample #:			
173 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	LOWER LEVEL AREA 0100	2000 Sq Ft			NEW		
Comments:						Sample #:			
174 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	LOWER LEVEL AREA 0100	5 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING ON DUCTWORK.						Sample #:	102308MV-7, 467-JJT-35		
175 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	LOWER LEVEL AREA 0100	150 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-9		
176 CAD #:	I3B	2' x 4' Ceiling Tile Spray-On Look w/Revealed Edge (2014)	LOWER LEVEL AREA 0100	600 Sq Ft			NEW		
Comments:						Sample #:			
177 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	LOWER LEVEL AREA 0100	4 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments:						Sample #:			
178 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	ROOM 0102	10 Joints			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
179 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 0102	500 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
180 CAD #:	K2I	12" x 12" Vinyl Floor Tile & Mastic Beige w/Multi-Colored Smudges	ROOM 0102	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:	102308MV-10		
181 CAD #:	R0B	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	ROOM 0102	35 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
182 CAD #:	V0A	Sink Undercoating Black	ROOM 0102	5 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: ONE (1) SINK.						Sample #:			
183 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 0102	5 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments:						Sample #:	102308MV-11		
184 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 0102 STORAGE ROOM	80 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
185 CAD #:	Q0H	Carpet Adhesive Bright Green Berber Carpet	ROOM 0102 STORAGE ROOM	80 Sq Ft			NONE DETECTED		
Comments:						Sample #:	080415BV-02		
186 CAD #:	X1I	Miscellaneous Material 2" X 2" Beige Ceramic Floor Tile System (20xx)	ROOM 0102 RESTROOM	30 Sq Ft			NEW		
Comments:						Sample #:			
187 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 0101	500 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
188 CAD #:	K2I	12" x 12" Vinyl Floor Tile & Mastic Beige w/Multi-Colored Smudges	ROOM 0101	200 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
189 CAD #:	X0F	Miscellaneous Material Wired Window Glaze	ROOM 0101	5 Sq Ft	0 Sq Ft	N	5 CH	5	
Comments:						Sample #:			
190 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 0101	5 Sq Ft			NEW		
Comments: ONE (1) SINK.						Sample #:			
191 CAD #:	I2C	2' x 2' Acoustical Ceiling Tile Bumpy w/Pin & Nail Holes	ROOM 0101 STORAGE	80 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
192 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Tan Smudges	ROOM 0101 STORAGE	45 Sq Ft	0 Sq Ft	N	4 CH (TILE), 10 CH (MASTIC)	5	
Comments:						Sample #:			
193 CAD #:	V0A	Sink Undercoating Black	ROOM 0101 STORAGE	5 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: ONE (1) SINK.						Sample #:			
194 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	ROOM 0101 RESTROOM	80 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
195 CAD #:	G1B	Sprayed-On Acoustical Finish Tan Texture (Re-Spray)	OLD MEDIA CENTER & 1ST FLOOR HALLWAY	5000 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
196 CAD #:	V0C	Sink Undercoating Gray (2014)	OLD MEDIA CENTER - MIDDLE BREAKOUT.	4 Sq Ft			NEW		
Comments: ONE (1) SINK.						Sample #:			
197 CAD #:	I3B	2' x 4' Ceiling Tile Spray-On Look w/Revealed Edge (2014)	THROUGHOUT 2ND FLOOR	9000 Sq Ft			NEW		
Comments:						Sample #:			
198 CAD #:	K3A	Miscellaneous Flooring 2' x 2' Light & Dark Gray Tile (2014)	THROUGHOUT 2ND FLOOR	3000 Sq Ft			NEW		
Comments:						Sample #:			
199 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Gray Baseboard	THROUGHOUT 2ND FLOOR	250 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
200 CAD #:	P0B	Fire Doors Metal -1.5 Hour (Underwriter Laboratories)	THROUGHOUT 2ND FLOOR	80 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments: FOUR (4) DOORS.						Sample #:			
201 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 2245	5 Sq Ft			NONE DETECTED		
Comments:						Sample #:	467-JJT-3		
202 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	ROOMS 2245	2220 Sq Ft			NEW		
Comments:						Sample #:			
203 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Gray Baseboard	ROOMS 2245	50 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
204 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOMS 2245A	4 Sq Ft			NEW		
Comments: ONE (1) SINK						Sample #:			
205 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOMS 2245C	4 Sq Ft			NEW		
Comments: ONE (1) SINK						Sample #:			
206 CAD #:	X0H	Miscellaneous Material Red Duct Seam Caulk	ROOMS 2244-2246 & HALLWAY	20 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
207 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Dark Brown - Associated w/I1A	ROOMS 2244-2246 & HALLWAY	20 Sq Ft			NONE DETECTED		
Comments: MOST REMOVED. RESIDUAL ON DECK.						Sample #:			
208 CAD #:	M0A	Plaster 1974 Original Building	2ND FLOOR GIRLS' RESTROOM (2247)	200 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
209 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	2ND FLOOR GIRLS' RESTROOM (2247)	5 Joints			NONE DETECTED		
Comments:						Sample #:			
210 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	2ND FLOOR GIRLS' RESTROOM (2247)	300 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
211 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	STAIRWELL BETWEEN RESTROOMS	6 Joints			NONE DETECTED		
Comments: SIX (6) JOINTS AT BOTTOM OF STEPS.						Sample #:			
212 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	CUSTODIAL ROOM (TA1)	25 Joints			NONE DETECTED		
Comments: ACCESS IN BOYS' RESTROOM.						Sample #:			
213 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	CUSTODIAL ROOM 2299D	2 Joints			NONE DETECTED		
Comments:						Sample #:			
214 CAD #:	P0B	Fire Doors Metal -1.5 Hour (Underwriter Laboratories)	CUSTODIAL ROOM 2299D	10 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
215 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	PENTHOUSE OFF OF ROOM 2299D	18 Joints			NONE DETECTED		
Comments:						Sample #:			
216 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation Canvas-Wrapped	PENTHOUSE OFF OF ROOM 2299D	4 Joints			NONE DETECTED		
Comments:						Sample #:			
217 CAD #:	L0B	Flexible Duct Connector Black Vinyl	PENTHOUSE OFF OF ROOM 2299D	13 Sq Ft			NONE DETECTED		
Comments: PAINTED WHITE.						Sample #:			
218 CAD #:	X0A	Miscellaneous Material AHU Seam Tar Gasket	PENTHOUSE OFF OF ROOM 2299D	5 Sq Ft	0 Sq Ft	N	3 CH	5	
Comments: AHU'S #2 & #3.						Sample #:			
219 CAD #:	M0A	Plaster 1974 Original Building	2ND FLOOR BOYS' RESTROOM	200 Sq Ft			NONE DETECTED		
Comments:						Sample #:			
220 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation Foil-Wrapped	2ND FLOOR BOYS' RESTROOM	11 Joints			NONE DETECTED		
Comments:						Sample #:			
221 CAD #:	X1J	Miscellaneous Material 1" X 2" Cream Ceramic Floor Tile System	2ND FLOOR BOYS' RESTROOM	300 Sq Ft	0 Sq Ft	N	ASSUMED	5	
Comments:						Sample #:			
222 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Dark Brown - Associated w/I1A	ROOMS 2252-2259 & ASSOCIATED HALLWAY	50 Sq Ft			NONE DETECTED		
Comments: REMOVED. RESIDUE ON DECK.						Sample #: 102308MV-24			
223 CAD #:	Q0B	Carpet Adhesive Dark Gray w/Light Gray Carpet Squares (2014)	ROOMS 2252-2254	3000 Sq Ft			NEW		
Comments:						Sample #:			
224 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 2253A	4 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			

IEA Event No.	Material Type	Material Id/Desc	Location	Estimated Amount Total	Estimated Damage	Friability	% of Asbestos	EPA Assess Category	Response Action
225 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 2253A	4 Sq Ft			NEW		
Comments: ONE (1) SINK						Sample #:			
226 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 2253	10 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
227 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 2253	5 Sq Ft			NONE DETECTED		
Comments: PAINTED OVER. INCLUDES ROOM 2253B.						Sample #:			
228 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 2253C	5 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING.						Sample #:			
229 CAD #:	X1A	Miscellaneous Material Chalkboard Adhesive	ROOM 2253C	5 Sq Ft			NONE DETECTED		
Comments: PAINTED OVER.						Sample #:			
230 CAD #:	V0C	Sink Undercoating Gray (2014)	ROOM 2253C	4 Sq Ft			NEW		
Comments: ONE (1) SINK						Sample #:			
231 CAD #:	G1A	Sprayed-On Acoustical Finish White Texture	ROOM 2254	4 Sq Ft			NONE DETECTED		
Comments: ABOVE CEILING. ABOVE PARTITION WALL.						Sample #:			



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352602124

Customer ID: IFEA50

Customer PO:

Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Phone: (612) 562-4444

Fax: (763) 315-7920

Received Date: 03/16/2026 8:00 AM

Analysis Date: 03/17/2026

Collected Date: 03/06/2026

Project: 202610040 Early Learning Hub WEST Saint Paul Public Schools

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
030626GG-01-Tile 352602124-0001	Room 1201 - 12"x12" Light brown w/ smudges	Brown Fibrous Heterogeneous		96.0% Non-fibrous (Other)	4% Chrysotile
HA: K2A					
030626GG-01-Masti c 352602124-0001A	Room 1201 - 12"x12" Light brown w/ smudges	Black Fibrous Heterogeneous		90.0% Non-fibrous (Other)	10% Chrysotile
HA: K2A					

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 03/17/2026 10:49:14



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352602124
Customer ID: IFEA50
Customer PO:
Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Project: 202610040 Early Learning Hub WEST Saint Paul Public Schools

Phone: (612) 562-4444
Fax: (763) 315-7920
Received Date: 03/16/2026 8:00 AM
Analysis Date: 03/17/2026
Collected Date: 03/06/2026

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 03/16/2026

Sample Receipt Time: 8:00 AM

Analysis Completed Date: 03/17/2026

Analysis Completed Time: 9:21 AM

Analyst(s):

Jillian Kipp PLM (2)


Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 03/17/2026 10:49:14



CHAIN OF CUSTODY

Page 1 of 1

OrderID: 352602124

© IEA, Inc. 2010