



East High Structural Analysis

Repair plan and temporary relocation overview

Wichita Public Schools

East High Structural Analysis

Repair plan and temporary relocation overview

Wichita Public Schools

- Safety remains the priority
- Monitoring is in place now
- Summer work begins when school ends
- First floor hallway repaired this summer
- Other first floor spaces temporary relocated (2026-27)






What we know now

Affected area

- Building section: West side / Roosevelt Jr. High section
- Primary work area: First-floor hallway
- Later work area: First-floor classrooms and offices
- Upper floors: Structurally solid; monitoring continues








GENERAL PICTURES
OF FLOOR CONDITIONS

Immediate repair timeline



What changes next school year?

Will stay in use

- Second floor
- Third floor
- Building areas outside the active first-floor repair zones

Temporarily relocated

- First-floor classrooms in the work zone
- First-floor offices in the work zone
- Parking to accommodate the construction staging zone



Context

- Oldest affected section built in 1921
- East now serves 2,300+ students
- Modern programs place different demands on the building
- From community feedback, preservation is a priority



Preservation Commitment

\$8.5 million

anticipated repair cost

Students and staff are safe, and we are moving quickly to fix what engineers found so East can continue operating safely for years to come.

