



November 7, 2025

Ventura Unified School District
ATTN: Ray Richards, Bond Construction
Project Manager
255 W. Stanley Avenue
Ventura, CA 93003
Via Email: Ray.Richards@venturausd.org

LIMITED ASBESTOS SURVEY: ATLAS (Saticoy) Elementary School-760 Jazmin Avenue, Ventura, CA 93003

Dear Ray Richards,

Environmental Testing Associates (ETA) conducted bulk sampling of suspect asbestos containing materials (ACM) at the above referenced commercial property. The samples were delivered under proper chain of custody to an accredited laboratory for analysis. The objective of the investigation was to determine the possible presence of asbestos within the building materials identified below which may be disturbed during remediation activities. No fire-related or structural damage was observed during this investigation.

1.0 SAMPLING FOR ASBESTOS AND PLM ANALYSIS RESULTS

ETA representative Mr. Kevin Riley, CAC 17-5871, NV-IJPM-1674 conducted the sampling activities. Mr. Riley is a State of California–DOSH-Certified Asbestos Consultant.

Sampling of suspect-ACM was conducted on October 20, 2025, following the provisions of 40 CFR Part 763-86. ETA collected 92 bulk samples and delivered them to LA Testing Laboratory an accredited laboratory located at 520 Mission Street, South Pasadena, California 91030 (800) 303-0047. (NVLAP # 200232-0). Due to multiple layers a total of 143 samples were analyzed by the laboratory.

Analysis of suspect ACM samples for asbestos was performed per Appendix A, Subpart F, 40 CFR Part 763, Section 1, Polarized Light Microscopy, by LA Testing which is accredited by the National Voluntary Laboratory Accreditation Program for asbestos analysis of bulk samples using polarized light microscopy.

Table 1.1 – Summary of Bulk Sampling for Asbestos:

Based on the analytical results (above) 1% or greater of **asbestos was detected** in the samples collected as listed in the locations as shown below. The removal of these materials tested is regulated as ACM in the State of California.

Sample ID No.	Sample Description	Asbestos Mineral Type & Percent
A-1 Coating	Roofing Materials White, Non-Fibrous, Homogeneous Admin (See Map)	No Asbestos Detected

Rycorp, Incorporated, dba
ENVIRONMENTAL TESTING ASSOCIATES
850 Hampshire Road, Suite G, Westlake Village, CA 91361
Phone: 800-550-7806 www.etatesting.com Fax: 805-497-7477

A-1a Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Admin (See Map)	No Asbestos Detected
A-1b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected
A-2 Coating	Roofing Materials White, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected
A-2a Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Admin (See Map)	No Asbestos Detected
A-2b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected
A-3 Coating	Roofing Materials White, Non-Fibrous, Heterogeneous	Admin (See Map)	No Asbestos Detected
A-3a Roofing	Roofing Materials Black, Fibrous, Heterogeneous	Admin (See Map)	No Asbestos Detected
A-3b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected
A-4	Penetration Mastic Black, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected
A-5	Penetration Mastic Black, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected

A-6	Penetration Mastic Black, Non-Fibrous, Homogeneous	Admin (See Map)	No Asbestos Detected
B-7 Coating	Roofing Materials White, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-7a Roofing	Roofing Materials Black, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-8 Coating	Roofing Materials White, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-8a Roofing	Roofing Materials Black, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-9 Coating	Roofing Materials White, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-9a Roofing	Roofing Materials Black, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-10	Penetration Mastic Black, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-11	Penetration Mastic Black, Non-Fibrous, Homogeneous	MPR (See Map)	No Asbestos Detected
B-12	Penetration Mastic White/Black, Non-Fibrous, Heterogeneous	MPR (See Map)	No Asbestos Detected

B-13 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Cafe (See Map)	No Asbestos Detected
B-13a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
B-14 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Cafe (See Map)	No Asbestos Detected
B-14a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
B-15 Roofing 1	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Cafe (See Map)	No Asbestos Detected
B-15a Roofing 2	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Cafe (See Map)	No Asbestos Detected
B-15b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
B-16 Coating	Penetration Mastic Gray, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
B-16a Mastic	Penetration Mastic Black, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
B-17 Coating	Penetration Mastic Gray, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected

B-17a Mastic	Penetration Mastic Black, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
B-18	Penetration Mastic Gray, Non-Fibrous, Homogeneous	Cafe (See Map)	No Asbestos Detected
C-19 Roofing 1 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected
C-19a Roofing 2 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected
C-19b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building C (See Map)	No Asbestos Detected
C-20 Roofing 1 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected
C-20a Roofing 2 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected
C-20b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building C (See Map)	No Asbestos Detected
C-21 Roofing 1 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected
C-21a Roofing 2 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected

C-21b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building C (See Map)	No Asbestos Detected
C-22	Penetration Mastic Black, Non-Fibrous, Homogeneous	Building C (See Map)	No Asbestos Detected
C-23	Penetration Mastic Black, Non-Fibrous, Homogeneous	Building C (See Map)	No Asbestos Detected
C-24	Penetration Mastic White/Black, Non-Fibrous, Heterogeneous	Building C (See Map)	No Asbestos Detected
D-25	Roofing Materials White/Black, Non-Fibrous, Homogeneous	Building D (See Map)	No Asbestos Detected
D-26	Roofing Materials White/Black, Non-Fibrous, Homogeneous	Building D (See Map)	No Asbestos Detected
D-27	Roofing Materials Gray/White, Non-Fibrous, Homogeneous	Building D (See Map)	No Asbestos Detected
D-28	Penetration Mastic White, Non-Fibrous, Homogeneous	Building D (See Map)	No Asbestos Detected
D-29	Penetration Mastic White, Non-Fibrous, Homogeneous	Building D (See Map)	No Asbestos Detected
D-30	Penetration Mastic White, Non-Fibrous, Homogeneous	Building D (See Map)	No Asbestos Detected

E-31	Roofing Materials White/Black, Fibrous, Homogeneous	Building E (See Map)	No Asbestos Detected
E-32	Roofing Materials White/Black, Fibrous, Homogeneous	Building E (See Map)	No Asbestos Detected
E-33	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building E (See Map)	No Asbestos Detected
E-34	Penetration Mastic White/Black, Fibrous, Homogeneous	Building E (See Map)	No Asbestos Detected
E-35	Penetration Mastic White/Black, Fibrous, Homogeneous	Building E (See Map)	No Asbestos Detected
E-36	Penetration Mastic White/Black, Non-Fibrous, Heterogeneous	Building E (See Map)	No Asbestos Detected
F-37 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-37a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-38 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-38a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected

F-39 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-39a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-40 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-40a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-41 Roofing	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-41a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-42 Roofing	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-42a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-43 Roofing	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
F-43a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected

F-44	Penetration Mastic Gray/White/Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-45	Penetration Mastic Gray/White/Black, Non-Fibrous, Homogeneous	Building F (See Map)	No Asbestos Detected
F-46	Penetration Mastic Gray/White/Black, Non-Fibrous, Heterogeneous	Building F (See Map)	No Asbestos Detected
G-47	Penetration Mastic Gray/White/Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-48	Penetration Mastic Gray/White/Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-49	Penetration Mastic Gray/White/Black, Non-Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-50 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-50a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-51 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-51a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected

G-52 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-52a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-53 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-53a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-54 Roofing	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-54a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-55 Roofing	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-55a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected
G-56 Roofing	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building G (See Map)	No Asbestos Detected
G-56a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building G (See Map)	No Asbestos Detected

H-57 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
H-57a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building H (See Map)	No Asbestos Detected
H-58 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
H-58a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building H (See Map)	No Asbestos Detected
H-59 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
H-59a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building H See Map	No Asbestos Detected
H-60 Roofing	Roofing Materials White/Black, Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
H-60a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building H (See Map)	No Asbestos Detected
H-61 Roofing/ Tar	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
H-62 Roofing/ Tar	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected

H-63 Roofing/ Tar	Roofing Materials White/Black, Non-Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
H-64	Penetration Mastic Gray/White/Black, Non-Fibrous, Homogeneous	Building H (See Map)	No Asbestos Detected
H-65	Penetration Mastic Gray/White/Black, Non-Fibrous, Homogeneous	Building H (See Map)	No Asbestos Detected
H-66	Penetration Mastic Gray/White/Black, Non-Fibrous, Heterogeneous	Building H (See Map)	No Asbestos Detected
I-67	Penetration Mastic Gray/Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-68	Penetration Mastic Gray/Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-69	Penetration Mastic Gray/Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
T-70 Roofing 1 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building T (See Map)	No Asbestos Detected
T-70a Roofing 2 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building T (See Map)	No Asbestos Detected
T-70b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building T (See Map)	No Asbestos Detected

T-71	Roofing Materials White/Black, Fibrous, Heterogeneous	Building T (See Map)	No Asbestos Detected
T-72 Roofing 1 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building T (See Map)	No Asbestos Detected
T-72a Roofing 2 Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building T (See Map)	No Asbestos Detected
T-72b Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building T (See Map)	No Asbestos Detected
T-73	Penetration Mastic Gray/Black, Non-Fibrous, Homogeneous	Building T (See Map)	8% Chrysotile Asbestos Detected
T-74	Penetration Mastic Gray/Black, Non-Fibrous, Homogeneous	Building T (See Map)	8% Chrysotile Asbestos Detected
T-75	Penetration Mastic Gray/Black, Non-Fibrous, Homogeneous	Building T (See Map)	8% Chrysotile Asbestos Detected
31-40-76 Roofing	Roofing Materials Black, Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-76a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-77 Roofing	Roofing Materials Black, Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected

31-40-77a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-78	Roofing Materials Black, Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-79	Roofing Materials Black, Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-80	Roofing Materials Black, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-81	Penetration Mastic Black, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-82	Penetration Mastic Black, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-83	Penetration Mastic White/Beige, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-84	Roofing Materials White/Beige, Non-Fibrous, Homogeneous	Classrooms 31-40 (See Map)	No Asbestos Detected
31-40-85	Penetration Mastic Gray, Non-Fibrous, Homogeneous	Classrooms 31-40 See Map	No Asbestos Detected
I-86 Roofing Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building I (See Map)	No Asbestos Detected

I-86a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-87 Roofing Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building I (See Map)	No Asbestos Detected
I-87a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-88 Roofing Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building I (See Map)	No Asbestos Detected
I-88a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-89 Roofing Shingle	Roofing Materials White/Black, Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-89a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-90 Roofing Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building I (See Map)	No Asbestos Detected
I-90a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected
I-91	Roofing Materials White/Black, Fibrous, Heterogeneous	Building I (See Map)	No Asbestos Detected

I-92 Roofing Shingle	Roofing Materials White/Black, Fibrous, Heterogeneous	Building I (See Map)	No Asbestos Detected
I-92a Tar	Roofing Materials Black, Non-Fibrous, Homogeneous	Building I (See Map)	No Asbestos Detected


See Attached "Polarized Microscopy Asbestos Analysis Report" and associated chain of custody document for additional detail regarding location of samples (Appendix A).

2.0 RECOMMENDATIONS

Due to the findings, removal of these items **is** required to be performed by a California-licensed and registered asbestos abatement contractor. This report should be kept as part of the permanent archive of the subject property. If you have any questions or comments concerning this information or this report, please contact our office.

Yours very truly,

ENVIRONMENTAL TESTING ASSOCIATES,



Kevin R. Riley, Certified Asbestos Consultant (17-5871)
NIOSH 582 Certification # 120400LA-06
NV-IJPM-1674
Attachments: Laboratory analytical results data sheet.

APPENDIX A

ANALYTICAL DATA



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Attention: Kevin Riley

Environmental Testing Associates

850 Hampshire Rd

Suite G

Westlake Village, CA 91361

Phone:

Fax: (805) 497-7377

Received Date: 11/04/2025 9:40 AM

Analysis Date: 11/04/2025

Collected Date: 10/20/2025

Project: ATLAS (Saticoy) Elementary School c/o VUSD/ 760 Jazmin Avenue, Ventura, CA 93003

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-1-Coating 322522993-0001	Roofing materials	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-1-Roofing 322522993-0001A	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
A-1-Tar 322522993-0001B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-2-Coating 322522993-0002	Roofing materials	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-2-Roofing 322522993-0002A	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
A-2-Tar 322522993-0002B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-3-Coating 322522993-0003	Roofing materials	White Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
A-3-Roofing 322522993-0003A	Roofing materials	Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
A-3-Tar 322522993-0003B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-4 322522993-0004	Penetration mastic	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
A-5 322522993-0005	Penetration mastic	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
A-6 322522993-0006	Penetration mastic	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
A-7-Coating 322522993-0007	Roofing materials	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-7-Roofing 322522993-0007A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-8-Coating 322522993-0008	Roofing materials	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-8-Roofing 322522993-0008A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
B-9-Coating 322522993-0009	Roofing materials	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-9-Roofing 322522993-0009A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-10 322522993-0010	Penetration mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-11 322522993-0011	Penetration mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-12 322522993-0012	Penetration mastic	White/Black Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
B-13-Roofing 322522993-0013	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
B-13-Tar 322522993-0013A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-14-Roofing 322522993-0014	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
B-14-Tar 322522993-0014A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-15-Roofing 1 322522993-0015	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
B-15-Roofing 2 322522993-0015A	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
B-15-Tar 322522993-0015B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
B-16-Coating 322522993-0016	Penetration mastic	Gray Non-Fibrous Homogeneous	2% Synthetic	98% Non-fibrous (Other)	None Detected
B-16-Mastic 322522993-0016A	Penetration mastic	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
B-17-Coating 322522993-0017	Penetration mastic	Gray Non-Fibrous Homogeneous	2% Synthetic	98% Non-fibrous (Other)	None Detected
B-17-Mastic 322522993-0017A	Penetration mastic	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
B-18 322522993-0018	Penetration mastic	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
C-19-Roofing 1 Shingle 322522993-0019	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
C-19-Roofing 2 Shingle 322522993-0019A	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@lateesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
C-19-Tar 322522993-0019B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
C-20-Roofing 1 Shingle 322522993-0020	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
C-20-Roofing 2 Shingle 322522993-0020A	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
C-20-Tar 322522993-0020B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
C-21-Roofing 1 Shingle 322522993-0021	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
C-21-Roofing 2 Shingle 322522993-0021A	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
C-21-Tar 322522993-0021B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
C-22 322522993-0022	Penetration mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
C-23 322522993-0023	Penetration mastic	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
C-24 322522993-0024	Penetration mastic	White/Black Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
D-25 322522993-0025	Roofing materials	White/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
D-26 322522993-0026	Roofing materials	White/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
D-27 322522993-0027	Roofing materials	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
D-28 322522993-0028	Penetration mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
D-29 322522993-0029	Penetration mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
D-30 322522993-0030	Penetration mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
E-31 322522993-0031	Roofing materials	White/Black Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
E-32 322522993-0032	Roofing materials	White/Black Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
E-33 322522993-0033	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@lateesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
E-34 322522993-0034	Penetration mastic	White/Black Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
E-35 322522993-0035	Penetration mastic	White/Black Fibrous Homogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
E-36 322522993-0036	Penetration mastic	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-37-Roofing 322522993-0037	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-37-Tar 322522993-0037A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-38-Roofing 322522993-0038	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-38-Tar 322522993-0038A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-39-Roofing 322522993-0039	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-39-Tar 322522993-0039A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-40-Roofing 322522993-0040	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-40-Tar 322522993-0040A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-41-Roofing 322522993-0041	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-41-Tar 322522993-0041A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-42-Roofing 322522993-0042	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-42-Tar 322522993-0042A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-43-Roofing 322522993-0043	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
F-43-Tar 322522993-0043A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
F-44 322522993-0044	Penetration mastic	Gray/White/Black Non-Fibrous Homogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected
F-45 322522993-0045	Penetration mastic	Gray/White/Black Non-Fibrous Homogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
F-46 322522993-0046	Penetration mastic	Gray/White/Black Non-Fibrous Heterogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected
G-47 322522993-0047	Penetration mastic	Gray/White/Black Non-Fibrous Homogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected
G-48 322522993-0048	Penetration mastic	Gray/White/Black Non-Fibrous Homogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected
G-49 322522993-0049	Penetration mastic	Gray/White/Black Non-Fibrous Heterogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected
G-50-Roofing 322522993-0050	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-50-Tar 322522993-0050A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
G-51-Roofing 322522993-0051	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-51-Tar 322522993-0051A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
G-52-Roofing 322522993-0052	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-52-Tar 322522993-0052A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
G-53-Roofing 322522993-0053	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-53-Tar 322522993-0053A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
G-54-Roofing 322522993-0054	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-54-Tar 322522993-0054A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
G-55-Roofing 322522993-0055	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-55-Tar 322522993-0055A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
G-56-Roofing 322522993-0056	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
G-56-Tar 322522993-0056A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
H-57-Roofing 322522993-0057	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@lateesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	<u>Non-Asbestos</u>		<u>Asbestos</u>
			% Fibrous	% Non-Fibrous	% Type
H-57-Tar 322522993-0057A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
H-58-Roofing 322522993-0058	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
H-58-Tar 322522993-0058A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
H-59-Roofing 322522993-0059	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
H-59-Tar 322522993-0059A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
H-60-Roofing 322522993-0060	Roofing materials	White/Black Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
H-60-Tar 322522993-0060A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
H-61-Roofing /Tar 322522993-0061 Unable to separate	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
H-62-Roofing/Tar 322522993-0062 Unable to separate	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
H-63-Roofing/Tar 322522993-0063 Unable to separate	Roofing materials	White/Black Non-Fibrous Heterogeneous	10% Synthetic	90% Non-fibrous (Other)	None Detected
H-64 322522993-0064	Penetration mastic	Gray/White/Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
H-65 322522993-0065	Penetration mastic	Gray/White/Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
H-66 322522993-0066	Penetration mastic	Gray/White/Black Non-Fibrous Heterogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
I-67 322522993-0067	Penetration mastic	Gray/Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
I-68 322522993-0068	Penetration mastic	Gray/Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
I-69 322522993-0069	Penetration mastic	Gray/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
T-70-Roofing 1 Shingle 322522993-0070	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
T-70-Roofing 2 Shingle 322522993-0070A	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
T-70-Tar 322522993-0070B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
T-71 322522993-0071	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
T-72-Roofing 1 Shingle 322522993-0072	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
T-72-Roofing 2 Shingle 322522993-0072A	Roofing materials	White/Black Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
T-72-Tar 322522993-0072B	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
T-73 322522993-0073	Penetration mastic	Gray/Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
T-74 322522993-0074	Penetration mastic	Gray/Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
T-75 322522993-0075	Penetration mastic	Gray/Black Non-Fibrous Homogeneous	10% Cellulose	82% Non-fibrous (Other)	8% Chrysotile
31-40-76-Roofing 322522993-0076	Roofing materials	Black Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-76-Tar 322522993-0076A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
31-40-77-Roofing 322522993-0077	Roofing materials	Black Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-77-Tar 322522993-0077A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
31-40-78 322522993-0078	Roofing materials	Black Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-79 322522993-0079	Roofing materials	Black Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-80 322522993-0080	Roofing materials	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-81 322522993-0081	Roofing materials	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-82 322522993-0082	Roofing materials	Black Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
31-40-83 322522993-0083	Penetration mastic	White/Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
31-40-84 322522993-0084	Penetration mastic	White/Beige Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 11/04/2025 18:01:32



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@latesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
31-40-85 322522993-0085	Penetration mastic	Gray Non-Fibrous Homogeneous	5% Fibrous (Other)	95% Non-fibrous (Other)	None Detected
I-86-Roofing Shingle 322522993-0086	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-86-Tar 322522993-0086A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
I-87-Roofing Shingle 322522993-0087	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-87-Tar 322522993-0087A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
I-88-Roofing Shingle 322522993-0088	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-88-Tar 322522993-0088A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
I-89-Roofing Shingle 322522993-0089	Roofing materials	White/Black Fibrous Homogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-89-Tar 322522993-0089A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
I-90-Roofing Shingle 322522993-0090	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-90-Tar 322522993-0090A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
I-91 322522993-0091	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-92-Roofing Shingle 322522993-0092	Roofing materials	White/Black Fibrous Heterogeneous	10% Glass	90% Non-fibrous (Other)	None Detected
I-92-Tar 322522993-0092A	Roofing materials	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected



LA Testing

520 Mission Street South Pasadena, CA 91030

Tel/Fax: (323) 254-9960 / (323) 254-9982

<http://www.LATesting.com> / pasadenalab@lateesting.com

LA Testing Order: 322522993

Customer ID: 32ETAS62

Customer PO:

Project ID:

Analyst(s)

James Siepler (92)

Nahid Motamedi (51)

Jerry Drapala Ph.D, Laboratory Manager
or Other Approved Signatory

LA Testing maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by LA Testing. LA Testing bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore LA Testing recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by LA Testing South Pasadena, CA NVLAP Lab Code 200232-0, CA ELAP 2283

Initial report from: 11/04/2025 18:01:32

#322522993

CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)

520 Mission Street, South Pasadena, CA

Phone: 800.303.0047 Fax: 323.254.9982



850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSDSampled by/Inspector: Kevin Riley Date: 10/20/25Project Address: 760 Jazmin Avenue, Ventura, CA 93003Client Name: Ray Richards, VUSDContact # (805) 342-6464Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
A-1	Roofing material	G/D/S D %L/D	800	PLM	Arriv Stearns	NK
A2		G/D/S D %L/D	1	PLM	1	1
A3		G/D/S D %L/D	1	PLM	1	1
		G/D/S D %L/D		PLM		
A4	permeation material	G/D/S D %L/D	600	PLM	Arriv Stearns	NK
A5		G/D/S D %L/D	1	PLM	1	1
A6		G/D/S D %L/D		PLM		

Relinquished by: [Signature]DATE: 11-3-25 TIME: 4:45☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Barvel (for)

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

DATE: 11/4/25 TIME: 9:40Page 1 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10.20.25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
B-7	ROCKING MATTING	G/D/S D %L/D	2 x 12	PLM	MPL - SEE MFG	WF
B-8		G/D/S D %L/D		PLM		
B-9		G/D/S D %L/D		PLM		
		G/D/S D %L/D		PLM		
B-10	DEWETATION MATTING	G/D/S D %L/D	60 1/4	PLM	MPL SEE MFG	WF
B-11		G/D/S D %L/D		PLM		
B-12		G/D/S D %L/D		PLM		

Relinquished by: [Signature] DATE: 11.3.25 TIME: 4:30 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Received by: Daisy Betwe (LTX) [Signature] DATE: 11/4/25 TIME: 9:40

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

Page 2 of 1

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
 520 Mission Street, South Pasadena, CA
 Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSDSampled by/Inspector: Kevin Riley Date: 10-21-25Project Address: 760 Jazmin Avenue, Ventura, CA 93003Client Name: Ray Richards, VUSDContact # (805) 342-6464Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
C-19	Rocking materials	G/D/S D %L/D	2 LK	PLM	BLAS C- 52% MD	NK
C-20		G/D/S D %L/D	1	PLM		1
C-21		G/D/S D %L/D		PLM		
		G/D/S D %L/D		PLM		
C-22	Retention material	G/D/S D %L/D	20*	PLM	BLAS C- 52% MD	NK
C-23		G/D/S D %L/D	1	PLM		1
C-24		G/D/S D %L/D		PLM		

Relinquished by: [Signature] DATE: 10-23-20 TIME: 9 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Betnelley[Signature]

Signature

Name (please print)

Requested Analysis Circle one:

DATE: 11/4/25 TIME: 9:40Page 4 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10-21-25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
D-25	Locking materials	G/D/S D %L/D	2K lb	PLM	Block Δ set mg	NK
D-26		G/D/S D %L/D		PLM		
D-27		G/D/S D %L/D		PLM		
		G/D/S D %L/D		PLM		
D-28	Peewee station monitor	G/D/S D %L/D	60	PLM	Block Δ - set mg	NK
D-29		G/D/S D %L/D		PLM		
D-30		G/D/S D %L/D		PLM		

Relinquished by: [Signature] DATE: 11-3-20 TIME: 7 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Berueta

Name (please print)

Requested Analysis Circle one:

[Signature]

Signature

6 Hour

Page 5 of 5

DATE: 11/4/25 TIME: 9:40

#322522993

CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)

520 Mission Street, South Pasadena, CA

Phone: 800.303.0047 Fax: 323.254.9982



850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSDSampled by/Inspector: Kevin Riley Date: 10-20-25Project Address: 760 Jazmin Avenue, Ventura, CA 93003Client Name: Ray Richards, VUSDContact # (805) 342-6464Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
E-31	Roofing materials	G/D/S D %L/D	2x12	PLM	Blob E. See my	NF
E-32		G/D/S D %L/D		PLM		
E-33		G/D/S D %L/D		PLM		
E-34	penetration mass	G/D/S D %L/D	6012	PLM	Blob E. See my	NF
E-35		G/D/S D %L/D		PLM		
E-36		G/D/S D %L/D		PLM		

Relinquished by: Kevin Riley CAC-17-5871DATE: 11-3-25 TIME: 7:11 ☒ Sent Via FedEx ☐ Hand Delivered to LabReceived by: Daisy Bette (left)DATE: 11/4/25 TIME: 9:40

Name (please print)

Signature

Requested Analysis Circle one:

6 Hour

Page 6 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10/20/25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
F-37	<i>Right wing markings</i>	GD/S D %L/D	<i>75%</i>	PLM	<i>BLDG F 322 mg</i>	<i>NF</i>
F-38		GD/S D %L/D		PLM		
F-39		GD/S D %L/D		PLM		
F-40		GD/S D %L/D		PLM		
F-41		GD/S D %L/D		PLM		
F-42		GD/S D %L/D		PLM		
F-43		GD/S D %L/D		PLM		

Relinquished by: *Kevin Riley* DATE: 10/20/25 TIME: 9 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: *Daisy Barrera* DATE: 11/17/25 TIME: 9:00

Name (please print)

Requested Analysis Circle one:

Signature

Page 7 of 7

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
 520 Mission Street, South Pasadena, CA
 Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10/20/25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
K-44	PERMUTATION	G/D/S D %L/D	60g	PLM	Block - 523 mg	NK
F-45		G/D/S D %L/D		PLM		
F-46		G/D/S D %L/D		PLM		
G-47	PERMUTATION	G/D/S D %L/D	60g	PLM	Block - 523 mg	NK
G-48		G/D/S D %L/D		PLM		
G-49		G/D/S D %L/D		PLM		

Relinquished by: [Signature] DATE: 11-3-25 TIME: 4 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Bethe (etx)

Name (please print)

Requested Analysis Circle one:

DATE: 11/4/25 TIME: 9:10

Signature [Signature] Page 8 of 15

6 Hour

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
 520 Mission Street, South Pasadena, CA
 Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10.20.25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
50	Roosting materials	G/D/S D	25 K	PLM	522	NK
51		%L/D	12	PLM		
52		G/D/S D		PLM		
53		%L/D		PLM		
54		G/D/S D		PLM		
55		%L/D		PLM		
56		G/D/S D		PLM		
57		%L/D		PLM		

Relinquished by: [Signature] DATE: 10.20.25 TIME: 2 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Received by: Daisy Betre (etx) [Signature] DATE: 11/14/25 TIME: 9:40

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

Page 9 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10.20.05

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
4-57	Running water	G/D/S D %/D	500	PLM	323 mg	NF
58		G/D/S D %/D		PLM		
59		G/D/S D %/D		PLM		
60		G/D/S D %/D		PLM		
61		G/D/S D %/D		PLM		
62		G/D/S D %/D		PLM		
63		G/D/S D %/D		PLM		

Relinquished by: [Signature] DATE: 1-3-08 TIME: 9 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Betreveler DATE: 11/4/08 TIME: 9:40

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

Page 10 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
 520 Mission Street, South Pasadena, CA
 Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10/24/25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
H-64	penetration mastic	G/D/S D %L/D	600g	PLM	BLOG H - SSS	NF
H-65		G/D/S D %L/D		PLM		
H-66		G/D/S D %L/D		PLM		
I-67	penetration mastic	G/D/S D %L/D	600g	PLM	BLOG H - SSS	NF
I-68		G/D/S D %L/D		PLM		
I-69		G/D/S D %L/D		PLM		

Relinquished by: [Signature] DATE: 10/3/25 TIME: 12 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Barile (LSS)

DATE: 11/4/25 TIME: 9:40

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

Page 11 of 15

#322522993

CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)

520 Mission Street, South Pasadena, CA

Phone: 800.303.0047 Fax: 323.254.9982



850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSDSampled by/Inspector: Kevin Riley Date: 10.20.25Project Address: 760 Jazmin Avenue, Ventura, CA 93003Client Name: Ray Richards, VUSDContact # (805) 342-6464Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
T-70	Reviewing materials	G/D/S D %L/D	500	PLM	Block + 522 mg	NF
T-71		G/D/S D %L/D	1	PLM		
T-72		G/D/S D %L/D	1	PLM		
T-73	Remediation material	G/D/S D %L/D	200	PLM	Block + 522 mg	NF
T-74		G/D/S D %L/D	1	PLM		
T-75		G/D/S D %L/D	1	PLM		

Relinquished by: [Signature] DATE: 11-3-25 TIME: 2 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley, CAC-17-5871

Received by: Daisy BetancourtDATE: 11/4/25 TIME: 9:40

Name (please print)

Signature

Requested Analysis Circle one:

6 Hour

Page 12 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10-20-25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
31-40 76	Roofing materials	G/D/S D %L/D	25K A	PLM	Classroom 52E 31-40 rug	WJ=
77		G/D/S D %L/D		PLM		
78		G/D/S D %L/D		PLM		
79		G/D/S D %L/D		PLM		
80		G/D/S D %L/D		PLM		
81		G/D/S D %L/D		PLM		
82		G/D/S D %L/D		PLM		

Relinquished by: [Signature] DATE: 11-3-25 TIME: 4 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Betve (LTX) DATE: 11/4/25 TIME: 9:40

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

Page 13 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10/21/25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
31-40	PERVATION MASTIC	G/D/S D	6 in	PLM	31-40 Classroom	532 mug NE
84		G/D/S D	1	PLM		
85		G/D/S D	1	PLM		
		G/D/S D		PLM		
		G/D/S D		PLM		
		G/D/S D		PLM		
		G/D/S D		PLM		
		G/D/S D		PLM		
		G/D/S D		PLM		
		G/D/S D		PLM		

Relinquished by: [Signature] DATE: 11-3-25 TIME: 1 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Bettrick (etx) [Signature] DATE: 11/14/25 TIME: 9:40

Name (please print)

Requested Analysis Circle one:

Signature

6 Hour

Page 14 of 15

#322522993



CHAIN OF CUSTODY

L.A. TESTING (NVLAP #200232-0)
520 Mission Street, South Pasadena, CA
Phone: 800.303.0047 Fax: 323.254.9982

850 Hampshire Road Suite G, Westlake Village, CA 91361

Phone: 805.497.7499 Fax: 805.497.7477

Project Name: ATLAS (Saticoy) Elementary School c/o VUSD

Sampled by/Inspector: Kevin Riley Date: 10/20/25

Project Address: 760 Jazmin Avenue, Ventura, CA 93003

Client Name: Ray Richards, VUSD

Contact # (805) 342-6464

Email: KRiley@etatesting.com, JWeber@etatesting.com, AHamel@etatesting.com

Sample #	Sample Description	Type	Volume	Code	Comments	F/NF
87	Rooming morning	G/D/S D	75% 1A	PLM	Blas I 525 wg	NF
88		%L/D		PLM		
89		G/D/S D		PLM		
90		%L/D		PLM		
91		G/D/S D		PLM		
92		%L/D		PLM		

Relinquished by: CKR DATE: 10-25 TIME: 7 ☒ Sent Via FedEx ☐ Hand Delivered to Lab

Kevin Riley CAC-17-5871

Received by: Daisy Betruve (efx) DATE: 11/4/25 TIME: 9:40

Name (please print)



Signature

Requested Analysis Circle one:

Page 15 of 15

Scitov / (A + C)

760 JAZZ in AVE.



36	82
35	81

EIC Admin

E31	30
E32	29
E33	28
E34	27

BLOCK E

77	32
78	33

74	31
75	30

72	29
73	28

70	27
71	26

E37	22
E38	21
E39	20
E40	19
E41	18
E42	17
E43	16

BLOCK F



G47	15
G48	14
G49	13
G50	12
G51	11
G52	10
G53	9
G54	8
G55	7
G56	6
G57	5
G58	4
G59	3
G60	2
G61	1

BLOCK G


H57	12
H58	11
H59	10
H60	9
H61	8
H62	7
H63	6
H64	5
H65	4
H66	3
H67	2
H68	1



BLOCK H



I67	1
I68	2
I69	3
I70	4
I71	5
I72	6
I73	7
I74	8
I75	9
I76	10
I77	11
I78	12
I79	13
I80	14
I81	15
I82	16
I83	17
I84	18
I85	19
I86	20
I87	21
I88	22
I89	23
I90	24
I91	25
I92	26
I93	27
I94	28
I95	29
I96	30
I97	31
I98	32
I99	33
I100	34
I101	35
I102	36
I103	37
I104	38
I105	39
I106	40
I107	41
I108	42
I109	43
I110	44
I111	45
I112	46
I113	47
I114	48
I115	49
I116	50
I117	51
I118	52
I119	53
I120	54
I121	55
I122	56
I123	57
I124	58
I125	59
I126	60
I127	61
I128	62
I129	63
I130	64
I131	65
I132	66
I133	67
I134	68
I135	69
I136	70
I137	71
I138	72
I139	73
I140	74
I141	75
I142	76
I143	77
I144	78
I145	79
I146	80
I147	81
I148	82
I149	83
I150	84
I151	85
I152	86
I153	87
I154	88
I155	89
I156	90
I157	91
I158	92
I159	93
I160	94
I161	95
I162	96
I163	97
I164	98
I165	99
I166	100
I167	101
I168	102
I169	103
I170	104
I171	105
I172	106
I173	107
I174	108
I175	109
I176	110
I177	111
I178	112
I179	113
I180	114
I181	115
I182	116
I183	117
I184	118
I185	119
I186	120
I187	121
I188	122
I189	123
I190	124
I191	125
I192	126
I193	127
I194	128
I195	129
I196	130
I197	131
I198	132
I199	133
I200	134
I201	135
I202	136
I203	137
I204	138
I205	139
I206	140
I207	141
I208	142
I209	143
I210	144
I211	145
I212	146
I213	147
I214	148
I215	149
I216	150
I217	151
I218	152
I219	153
I220	154
I221	155
I222	156
I223	157
I224	158
I225	159
I226	160
I227	161
I228	162
I229	163
I230	164
I231	165
I232	166
I233	167
I234	168
I235	169
I236	170
I237	171
I238	172
I239	173
I240	174
I241	175
I242	176
I243	177
I244	178
I245	179
I246	180
I247	181
I248	182
I249	183
I250	184
I251	185
I252	186
I253	187
I254	188
I255	189
I256	190
I257	191
I258	192
I259	193
I260	194
I261	195
I262	196
I263	197
I264	198
I265	199
I266	200
I267	201
I268	202
I269	203
I270	204
I271	205
I272	206
I273	207
I274	208
I275	209
I276	210
I277	211
I278	212
I279	213
I280	214
I281	215
I282	216
I283	217
I284	218
I285	219
I286	220
I287	221
I288	222
I289	223
I290	224
I291	225
I292	226
I293	227
I294	228
I295	229
I296	230
I297	231
I298	232
I299	233
I300	234
I301	235
I302	236
I303	237
I304	238
I305	239
I306	240
I307	241
I308	242
I309	243
I310	244
I311	245
I312	246
I313	247
I314	248
I315	249
I316	250
I317	251
I318	252
I319	253
I320	254
I321	255
I322	256
I323	257
I324	258
I325	259
I326	260
I327	261
I328	262
I329	263
I330	264
I331	265
I332	266
I333	267
I334	268
I335	269
I336	270
I337	271
I338	272
I339	273
I340	274
I341	275
I342	276
I343	277
I344	278
I345	279
I346	280
I347	281
I348	282
I349	283
I350	284
I351	285
I352	286
I353	287
I354	288
I355	289
I356	290
I357	291
I358	292
I359	293
I360	294
I361	295
I362	296
I363	297
I364	298
I365	299
I366	300
I367	301
I368	302
I369	303
I370	304
I371	305
I372	306
I373	307
I374	308
I375	309
I376	310
I377	311
I378	312
I379	313
I380	314
I381	315
I382	316
I383	317
I384	318
I385	319
I386	320
I387	321
I388	322
I389	323
I390	324
I391	325
I392	326
I393	327
I394	328
I395	329
I396	330
I397	331
I398	332
I399	333
I400	334
I401	335
I402	336
I403	337
I404	338
I405	339
I406	340
I407	341
I408	342
I409	343
I410	344
I411	345
I412	346
I413	347
I414	348
I415	349
I416	350
I417	351
I418	352
I419	353
I420	354
I421	355
I422	356
I423	357
I424	358
I425	359
I426	360
I427	361
I428	362
I429	363
I430	364
I431	365
I432	366
I433	367
I434	368
I435	369
I436	370
I437	371
I438	372
I439	373
I440	374
I441	375
I442	376
I443	377
I444	378
I445	379
I446	380
I447	381
I448	382
I449	383
I450	384
I451	385
I452	386
I453	387
I454	388
I455	389
I456	390
I457	391
I458	392
I459	393
I460	394
I461	395
I462	396
I463	397
I464	398
I465	399
I466	400
I467	401
I468	402
I469	403
I470	404
I471	405
I472	406
I473	407
I474	408
I475	409
I476	410
I477	411
I478	412
I479	413
I480	414
I481	415
I482	416
I483	417
I484	418
I485	419
I486	420
I487	421
I488	422
I489	423
I490	424
I491	425
I492	426
I493	427
I494	428
I495	429
I496	430
I497	431
I498	432
I499	433
I500	434</





SATCOY ELEMENTARY SCHOOL
760 JAZMIN AVENUE
SCALE: 1" = 80' 0"



























State of California
Division of Occupational Safety and Health
Certified Asbestos Consultant

Kevin R Riley

Name

Certification No. **17-5871**

Expires on **2/15/2026**

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq of the Business and Professions Code

