



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school is following all recommended remediation to help reduce children's exposure to lead in drinking water.

School District: Auburn

School Name: Arthur Jacobsen Elementary

School Code: 5082

School Address: 29205 132nd Ave Southeast, Auburn Washington 98092

Number of Samples Collected: 72

Date Collected: 06/07/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25164	other	other		<1	07/03/2019	06737, 6:37 AM
25165	FirstDraw	Tap	Health Room	<1	07/03/2019	
25166	FirstDraw	Bubbler	Room 107	<1	07/03/2019	Left Sink
25167	FirstDraw	Tap	Room 107	<1	07/03/2019	Left Sink
25168	FirstDraw	Bubbler	Room 107	<1	07/03/2019	Right Sink
25169	FirstDraw	Tap	Room 107	<1	07/03/2019	Right Sink
25170	FirstDraw	Bubbler	Room 109	<1	07/03/2019	Left Sink, Small amount of black slime on bubbler
25171	FirstDraw	Tap	Room 109	<1	07/03/2019	Left Sink, No aerator
25172	FirstDraw	Bubbler	Room 109	<1	07/03/2019	Right Sink, Some mineral depositson bubbler
25173	FirstDraw	Tap	Room 109	<1	07/03/2019	Right Sink
25174	FirstDraw	Bubbler	Outside Gym	<1	07/03/2019	Left
25175	FirstDraw	Bubbler	Outside Gym	<1	07/03/2019	Right
25176	FirstDraw	Tap	Room 112 B in Library	3	07/03/2019	
25177	FirstDraw	Tap	Room 117	<1	07/03/2019	Music Room
25178	FirstDraw	Tap	Room 118	<1	07/03/2019	Mineral deposits in aerator
25179	FirstDraw	Tap	Kitchen, 2-Sink compartment near back	<1	07/03/2019	Left Tap, Used this morning
25180	FirstDraw	Tap	Kitchen, 2-Sink compartment near back	<1	07/03/2019	Right Tap

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25181	FirstDraw	Bubbler	Outside Maintenance Office (Room 123)	<1	07/03/2019	Left
25182	FirstDraw	Bubbler	Outside Maintenance Office (Room 123)	<1	07/03/2019	Right
25183	FirstDraw	Bubbler	Room 135	<1	07/03/2019	
25184	FirstDraw	Tap	Room 135	<1	07/03/2019	
25185	FirstDraw	Bubbler	Room 137	<1	07/03/2019	Some mineral deposits on bubbler
25186	FirstDraw	Tap	Room 137	<1	07/03/2019	
25187	FirstDraw	Bubbler	Room 139	<1	07/03/2019	
25188	FirstDraw	Tap	Room 139	<1	07/03/2019	
25189	FirstDraw	Bubbler	Room 141	<1	07/03/2019	
25190	FirstDraw	Tap	Room 141	<1	07/03/2019	
25191	FirstDraw	Bubbler	Next to Room 145	<1	07/03/2019	Left
25192	FirstDraw	Bubbler	Next to Room 145	<1	07/03/2019	Right
25193	FirstDraw	Bubbler	Room 145	<1	07/03/2019	
25194	FirstDraw	Tap	Room 145	<1	07/03/2019	
25195	FirstDraw	Bubbler	Room 146	<1	07/03/2019	
25196	FirstDraw	Tap	Room 146	<1	07/03/2019	
25197	FirstDraw	other	Portable 2 (Room 902)	<1	07/03/2019	
25198	FirstDraw	Bubbler	Room 144	<1	07/03/2019	Some mineral deposits on bubbler
25199	FirstDraw	Tap	Room 144	<1	07/03/2019	
25200	FirstDraw	Bubbler	Room 138	<1	07/03/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25201	FirstDraw	Tap	Room 138	<1	07/03/2019	Tap Drips
25202	FirstDraw	Bubbler	Room 136	<1	07/03/2019	
25203	FirstDraw	Tap	Room 136	<1	07/03/2019	
25204	FirstDraw	Bubbler	Room 134	<1	07/03/2019	Mineral deposits on bubbler
25205	FirstDraw	Tap	Room 134	<1	07/03/2019	Mineral deposits and rust on aerator
25206	FirstDraw	Bubbler	Room 132	<1	07/03/2019	
25207	FirstDraw	Tap	Room 132	1	07/03/2019	
25208	FirstDraw	Bubbler	Near 2nd Floor Elevators	<1	07/03/2019	Left
25209	FirstDraw	Bubbler	Near 2nd Floor Elevators	<1	07/03/2019	Right
25210	FirstDraw	Bubbler	Room 205	<1	07/03/2019	Mineral deposits on bubbler
25211	FirstDraw	Tap	Room 205	3	07/03/2019	
25212	FirstDraw	Bubbler	Room 207	<1	07/03/2019	
25213	FirstDraw	Tap	Room 207	<1	07/03/2019	Mineral deposits in and around aerator
25214	FirstDraw	Bubbler	Room 209	<1	07/03/2019	
25215	FirstDraw	Tap	Room 209	<1	07/03/2019	
25216	FirstDraw	Bubbler	Room 211	<1	07/03/2019	Mineral deposits on bubbler
25217	FirstDraw	Tap	Room 211	<1	07/03/2019	
25218	FirstDraw	Bubbler	Room 213	<1	07/03/2019	
25219	FirstDraw	Tap	Room 213	<1	07/03/2019	
25220	FirstDraw	Bubbler	Near Room 217 (End of Hallway on 2nd Floor)	<1	07/03/2019	Left

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
25221	FirstDraw	Bubbler	Near Room 217 (End of Hallway on 2nd Floor)	<1	07/03/2019	Right
25222	FirstDraw	Bubbler	Room 217	<1	07/03/2019	Mineral deposits on bubbler
25223	FirstDraw	Tap	Room 217	<1	07/03/2019	
25224	FirstDraw	Bubbler	Room 218	<1	07/03/2019	
25225	FirstDraw	Tap	Room 218	1	07/03/2019	
25226	FirstDraw	Bubbler	Room 216	<1	07/03/2019	
25227	FirstDraw	Tap	Room 216	<1	07/03/2019	
25228	FirstDraw	Bubbler	Room 212	<1	07/03/2019	
25229	FirstDraw	Tap	Room 212	<1	07/03/2019	
25230	FirstDraw	Bubbler	Room 210	<1	07/03/2019	
25231	FirstDraw	Tap	Room 210	<1	07/03/2019	
25232	FirstDraw	Bubbler	Room 208	<1	07/03/2019	
25233	FirstDraw	Tap	Room 208	<1	07/03/2019	
25234	FirstDraw	Bubbler	Room 206	<1	07/03/2019	
25235	FirstDraw	Tap	Room 206	<1	07/03/2019	