

Lead in Water Issues								
Action Level = 0.015								
	School	Location	Sink / Fountain	Lead Level	Action	Notified	Date of Remediation Completion	Notes
1	Armstrong	health room	sink	0.016	Shut down; correctly labeled	1/9/20	1/16/20	Appropriate signage/labeling on 1/9/20. Sinks taken out of service on 1/16/20.
2	Armstrong	room 124	sink	0.215	Shut down; correctly labeled	1/9/20	1/16/20	Appropriate signage/labeling on 1/9/20. Sinks taken out of service on 1/16/20.
3	Armstrong	room 127	sink	0.101	Shut down; correctly labeled	1/9/20	1/16/20	Appropriate signage/labeling on 1/9/20. Sinks taken out of service on 1/16/20.
4	Armstrong	basement coat room	left sink	0.205	Shut down; correctly labeled	1/9/20	1/16/20	Appropriate signage/labeling on 1/9/20. Sinks taken out of service on 1/16/20.
5	Armstrong	basement coat room	right sink	0.2	Shut down; correctly labeled	1/9/20	1/16/20	Appropriate signage/labeling on 1/9/20. Sinks taken out of service on 1/16/20.
6	Bancroft	Room 101	sink	0.017	Sink was already turned off, but not labeled; labeled on 1/9/20	3/4/19	1/9/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted action, immediate review, and compliance.
7	Bancroft	Health room 212	sink	0.03	Shut down; correctly labeled	1/9/20	1/17/20	Action taken upon receiving testing results. Appropriate signage posted on 1/9/20. Sink turned off on 1/17/20.
8	Bancroft	room 211	sink	0.022	Shut down; correctly labeled	1/9/20	1/17/20	Action taken upon receiving testing results. Appropriate signage posted on 1/9/20. Sink turned off on 1/17/20.
9	Bancroft	cafeteria	left sink	0.018	Left active for washing hands and dishes; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Left message for principal on 1/16/20. Spoke to principal on 1/17/20.
10	McNichols	Gym Boys' bathroom	fountain	0.056	Fountain was off, but not labeled; labeled on 1/9/20	3/4/19	1/9/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted action, immediate review, and compliance.
11	McNichols	4th grade - yellow wall	sink	0.016	Shut down; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Sink was already turned off when inspected on 1/17/20.
12	McNichols	Computer lab	right sink	0.093	Shut down; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Sink was already turned off when inspected on 1/17/20.
13	McNichols	Gym, girls' restroom	left sink	0.052	Shut down; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Sink was already turned off when inspected on 1/17/20.
14	McNichols	1st grade (brown section)	sink	0.607	sink shut off; correctly labeled	1/13/20	1/21/20	Appropriate signage posted on 1/14/20. Unable to access the shutoff valve. District carpenter and building maintenance contacted on 1/21/20 about getting the sink turned off. Sink has been turned off.
15	McNichols	Library, Classroom (peach wall)	sink	0.0149	Not above action level, but will be taken out of service on 1/21/20	1/20/20	1/21/20	Notified by Guzek Associates on 1/20/20 that the lead level was not above the required action level, but close enough that the sink should be taken out of service or labeled. It was taken out of service on 1/21/20.

16	Northeast	Home Ec Room	sink 1	0.017	Shut down; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Sink was already turned off when inspected on 1/17/20.
17	Northeast	Home Ec Room	sink 4	0.015	Shut down; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Sink was already turned off when inspected on 1/17/20.
18	Northeast	Home Ec Room	sink 5	0.027	Shut down; correctly labeled	1/9/20	1/9/20	Appropriate signage posted on 1/9/20. Sink was already turned off when inspected on 1/17/20.
19	Northeast	Basement cafeteria	sink	0.021	Left active for washing hands; correctly labeled	1/14/20	1/14/20	Appropriate signage posted on 1/14/20.
20	Prescott	Room 101	fountain	0.018 (Dec 2018 test result) 0.026 (Dec 2019 test result)	Fountain was on and not labeled; turned off and labeled on 1/9/20	3/4/19	1/9/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted action, immediate review, and compliance. Fountain was testing again in December of 2019, still showing an elevated lead level of 0.026.
21	Prescott	room 218	sink	0.021	Shut down; correctly labeled	1/14/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
22	Prescott	room 204	sink	0.022	Shut down; correctly labeled	1/14/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
23	Prescott	room 205	fountain	0.079	Shut down; correctly labeled	1/14/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
24	Prescott	room 205	sink	0.056	Shut down; correctly labeled	1/14/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
25	Prescott	room 104	sink	0.18	Active; correctly labeled; will be out of service on 1/31/20	1/14/20	1/14/20	Appropriate signage posted on 1/14/20. Despite attempts, unable to turn off the sink on 1/17/20. Plumbing contractor contacted on 1/21/20 to get the sink turned off. Contractor will be shutting off the main water supply to the school to get a new valve installed after school on 1/31/20. This sink will then be removed from service.
26	Prescott	basement health room	sink	0.045	sink shut off; correctly labeled	1/14/20	1/21/20	Appropriate signage posted on 1/14/20. Unable to shut off sink on 1/17/20. Plumbing contractor contacted on 1/21/20 about getting the sink turned off. Sink successfully removed from service on 1/21/20.
27	Prescott	Teachers' Lounge	sink	0.005	turned off on 1/17/20	1/17/20	1/17/20	Building administration asked that the sink in the teachers' lounge be taken out of service, stating the belief that the sink had a high lead content. Thirty second flush test results from March of 2019 does not report this sink as having a high lead level. Updated testing information from Guzak received in an email on 1/14/20 does not report this sink as having a high lead content. In the final report, issued on 1/20/20, it listed this sink as having a acceptable lead content of 0.005.
28	Prescott	Basement hallway	fountain	0.0139	Not above action level, but will be taken out of service on 1/21/20	1/20/20	1/21/20	Notified by Guzek on 1/20/20 that the lead level was not above the required action level, but close enough that the fountain should be taken out of service or labeled. It was taken out of service on 1/21/20.

29	Scranton	Training room	sink	0.022	Sink was initially off and turned back on by maintenance staff in December of 2019. It wasn't labeled. Sink turned off on 1/9/20. After receiving updated, low lead level results on 1/17/20, sink put back into service.	3/4/19	1/9/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted action, immediate review, and compliance. Per Guzek on 1/17/20, in testing that was conducted in Dec. 2019, the sink did not have an unacceptable lead content.
30	Stadium	concession stand near main office	sink	0.128	Turned off on 1/17/20; correctly labeled	1/13/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
31	Stadium	Visitors Stand, West Locker Room	cooler fill sink	0.0577	Turned off on 1/17/20; correctly labeled	1/13/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
32	Stadium	Visitors Stand Locker Room (Blue Walls), coaches office restroom	sink	0.0551	Turned off on 1/17/20; correctly labeled	1/13/20	1/17/20	Appropriate signage posted on 1/14/20. Sink turned off on 1/17/20.
33	Whittier	1st Floor, Kitchen, 2 Bay Sink	left sink	0.0162	Left active for washing hands and dishes; correctly labeled	1/13/20	1/14/20	Appropriate signage posted on 1/14/20.
34	WSIS	Auditorium hall	fountain	0.017	Fountain was off and labeled when inspected on 1/9/20	3/4/19	1/9/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted an immediate review for compliance. Appropriate action was already taken and signage was already posted when inspected on 1/9/20.
35	WSIS	Medical office exam room	sink	0.029	On 1/9/20, left active for washing hands, sink was already labeled correctly when inspected on 1/9/20. Sink turned off on 1/17/20.	3/4/19	1/17/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted action, immediate review, and compliance. Signage was already posted when inspected on 1/9/20. Sink turned off on 1/17/20.
36	WSIS	Main office	sink	0.028	left active for washing hands, labeled correctly when inspected on 1/9/20	3/4/19	1/9/20	Report predates current administration. Unsure of action plan at that time. Advised on 1/9/20 to check 2018 report by Guzek for compliance. This prompted action immediate review and compliance. Appropriate signage was already posted when inspected on 1/9/20. Unable to shut off on 1/17/20, as the sink does not have a shutoff valve. Students do not have access.
37	WSIS	Band Room, Girl's (faculty) Restroom	sink	0.569	sink shut off; correctly labeled	1/13/20	1/21/20	Appropriate signage posted on 1/14/20. Clarity was needed on which specific sink. On 1/20/20, we were informed by that this sink is not in the girls' restroom. It is located in the women's faculty restroom in the music area. It was taken out of service on 1/21/20.

38	WSIS	Band Room	sink	0.0798	sink shut off; correctly labeled	1/13/20	1/21/20	Appropriate signage posted on 1/14/20. On 1/17/20, the cold side was turned off. The hot side could not be turned off as the shutoff valve isn't accessible. Plumbing contractor was contacted on 1/21/20 about getting the hot side turned off. Contractor found a shut off valve in the ceiling and was able to turn off.
----	------	-----------	------	--------	----------------------------------	---------	---------	---