EMSL Analytical, Inc.
200 Route 130 North, Cinnaminson, NJ 08077
Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn: **Tim Popp**
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057
Phone: (856) 840-8800
Fax: (856) 840-8815

8/30/2021

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 8/24/2021. The results are tabulated on the attached data pages for the following client designated project:

21-356 John Hydock Elementary School 19 Locust Avenue, Columbus, NJ

The reference number for these samples is EMSL Order #012109610. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Phillip Worby, Environmental Chemistry
Laboratory Director

The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.
NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

EMSL Analytical, Inc.
200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (856) 303-2500 / (856) 858-4571
http://www.EMSL.com EnvChemistry2@emsl.com

EMSL Order:	012109610
CustomerID:	TTIE54
CustomerPO:	033409
ProjectID:	

Attn: **Tim Popp**
TTI Environmental Inc.
1253 North Church Street
Moorestown, NJ 08057

Phone: (856) 840-8800
Fax: (856) 840-8815
Received: 8/24/2021 12:35 PM

Project: **21-356 John Hydock Elementary School 19 Locust Avenue, Columbus, NJ**

Analytical Results

Client Sample Description WDL01-01 BOILER ROOM ***Collected:*** 8/24/2021 7:01:00 AM ***Lab ID:*** *012109610-0001*

Method	*Parameter*	*Result*	*RL*	*Units*	*Prep Date & Analyst*	*Analysis Date & Analyst*
METALS						
200.8	Lead	24.5	1.00	µg/L	8/27/2021 JW	8/27/2021 19:57 JW

Client Sample Description WDL01-01 CORRIDOR C101 ***Collected:*** 8/24/2021 7:01:00 AM ***Lab ID:*** *012109610-0002*

Method	*Parameter*	*Result*	*RL*	*Units*	*Prep Date & Analyst*	*Analysis Date & Analyst*
METALS						
200.8	Lead	ND	1.00	µg/L	8/27/2021 JW	8/27/2021 20:03 JW

Definitions:

MDL - method detection limit
J - Result was below the reporting limit, but at or above the MDL
ND - indicates that the analyte was not detected at the reporting limit
RL - Reporting Limit (Analytical)
D - Dilution Sample required a dilution which was used to calculate final results