SAMPLE NAME	SAMPLE LOCATION	DATE COLLECTED	RESULT	QUALIFIER	UNIT	REPORTING LIMIT	Immediate Remedial Response	Long-Term Remedial Response
IR-15-1-MR-DWC-P-01R	Water Fountain w/Cooler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-SS-01R	Water Fountain w/Cooler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-F-01R	Water Fountain w/Cooler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-P-02C	Water Fountain w/Cooler b Men's Room	12/23/2022	0.0009	J	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-SS-02C	Water Fountain w/Cooler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-F-02C	Water Fountain w/Cooler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-WBF-P-03	Water Bottle Filler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-WBF-SS-03	Water Fountain w/Cooler by Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-WBF-F-03	Water Fountain w/Cooler Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-Obando-WBF-P-04	Water Bottle Filler - Obando's Classroom	12/23/2022	0.0033		mg/L	0.0020	NA	NA
IR-15-1-Obando-WBF-SS-04	Water Bottle Filler - Obando's Classroom	12/23/2022	0.002	J	mg/L	0.0020	NA	NA
IR-15-1-Obando-WBF-F-04	Water Bottle Filler - Obando's Classroom	12/23/2022	0.0018	J	mg/L	0.0020	NA	NA
IR-15-1-NR-CF-P-05	Faucet in Nurses Room	12/23/2022	0.01		mg/L	0.0020	Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample	Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Replace Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
IR-15-1-NR-CF-F-05	Faucet in Nurses Room	12/23/2022	0.002		mg/L	0.0020	NA	NA
IR-15-1-NRB-BF-P-06	Faucet in Nurses Bathroom	12/23/2022	0.0022		mg/L	0.0020	NA	NA
IR-15-1-NRB-BF-F-06	Faucet in Nurses Bathroom	12/23/2022	0.00086	J	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-P-07	Water Fountain w/Cooler Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-SS-07	Water Fountain w/Cooler Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-MR-DWC-F-07	Water Fountain w/Cooler Men's Room	12/23/2022	0.002	U	mg/L	0.0020	NA	NA
IR-15-1-Cafe-WBF-P-08	Water Bottle Filler in Cafeteria	12/23/2022	0.0018	J	mg/L	0.0020	NA	NA
IR-15-1-Cafe-WBF-SS-08	Water Bottle Filler in Cafeteria	12/23/2022	0.0069		mg/L	0.0020	NA	NA
IR-15-1-Cafe-WBF-F-08	Water Bottle Filler in Cafeteria	12/23/2022	0.0082		mg/L	0.0020	Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample	Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Replace Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
IR-15-1-Kit-KF-P-09	Faucet in Kitchen	12/23/2022	0.071		mg/L	0.0020	Shut off/disconnect outlet, Post "Not for Drinking/Cooking at outlet, Provide Filters at Problem Tap, Continuous Daily/Weekly Flushing, Provide Bottle Water, Resample	Follow Immediate Remedial Response and Resample. If High Levels Remain follow the Long-Term Remedial Response: Provide Filters, Replace Problem Outlet, Replace Pipe, Reconfigure Plumbing, Resample
IR-15-1-Kit-KF-F-09	Faucet in Kitchen	12/23/2022	0.0031		mg/L	0.0020	NA	NA
IR-15-1-Kit-KF-P-10	Faucet in Kitchen	12/23/2022	0.0018	J	mg/L	0.0020	NA	NA
IR-15-1-Kit-KF-F-10	Faucet in Kitchen	12/23/2022	0.0013	J	mg/L	0.0020	NA	NA
IR-15-1-Kit-KF-P-11	Faucet in Kitchen	12/23/2022	0.0031		mg/L	0.0020	NA	NA
IR-15-1-Kit-KF-F-11	Faucet in Kitchen	12/23/2022	0.002	U	mg/L	0.0020	NA	NA

Key - Sample Name	
P	Primary Sample
SS	Sequential Sample
F	Flush Sample

Key - Qualifier	
U	Not Detected in Laboratory Analysis
J	Result is Between Laboratory Detection Limit & Laboratory Reporting Limit