

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-
Individual Canister Results

Canister ID# :	2704186	Test Start :	11/03/2020 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:27
Location :	1st FL = Rm 28 BL	Received:	11/06/2020 @ 13:40
Radon Level :	0.1 pCi/L	Analyzed:	11/09/2020 @ 09:30
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2704488	Test Start :	11/03/2020 @ 06:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:40
Location :	1st FL = Resource Rm B4	Received:	11/06/2020 @ 13:40
Radon Level :	0.7 pCi/L	Analyzed:	11/09/2020 @ 10:15
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2707290	Test Start :	11/03/2020 @ 06:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:45
Location :	1st FL = Rm 24 BL	Received:	11/06/2020 @ 13:40
Radon Level :	0.1 pCi/L	Analyzed:	11/09/2020 @ 09:30
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2710027	Test Start :	11/03/2020 @ 06:12
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:13
Location :	1st FL = Rm 158	Received:	11/06/2020 @ 13:40
Radon Level :	0.5 pCi/L	Analyzed:	11/06/2020 @ 16:53
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2756329	Test Start :	11/03/2020 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:32
Location :	1st FL = Rm 26 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.7 pCi/L	Analyzed:	11/09/2020 @ 09:57
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2756346	Test Start :	11/03/2020 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:06
Location :	1st FL = Media Ctr. 1	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/09/2020 @ 10:21
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-
Individual Canister Results

Canister ID# : 2756348
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Off. Mgr.
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:00
Test Stop : 11/05/2020 @ 06:04
Received: 11/06/2020 @ 13:39
Analyzed: 11/06/2020 @ 16:45

Canister ID# : 2756352
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 10 Music
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:37
Test Stop : 11/05/2020 @ 06:38
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:45

Canister ID# : 2756398
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 137
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:41
Test Stop : 11/05/2020 @ 06:42
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:36

Canister ID# : 2756420
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 1
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 05:56
Test Stop : 11/05/2020 @ 06:04
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:57

Canister ID# : 2756421
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 136
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:42
Test Stop : 11/05/2020 @ 06:43
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:30

Canister ID# : 2756425
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 8
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:46
Test Stop : 11/05/2020 @ 06:46
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:49

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2756516	Test Start :	11/03/2020 @ 06:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:49
Location :	1st FL = Stage	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/06/2020 @ 16:54
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2756517	Test Start :	11/03/2020 @ 06:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:45
Location :	1st FL = Rm 24	Received:	11/06/2020 @ 13:40
Radon Level :	0.9 pCi/L	Analyzed:	11/06/2020 @ 16:28
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2756520	Test Start :	11/03/2020 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:27
Location :	1st FL = Rm 28	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/09/2020 @ 09:49
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2756532	Test Start :	11/03/2020 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:23
Location :	1st FL = Rm 30 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/09/2020 @ 09:02
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2756534	Test Start :	11/03/2020 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:51
Location :	1st FL = Rm 6 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/06/2020 @ 16:45
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2756536	Test Start :	11/03/2020 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:27
Location :	1st FL = Rm 20	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/09/2020 @ 10:14
Error for Measurement is: $\pm$	0.3 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-
Individual Canister Results

Canister ID# : 2756537
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Staff B.R.
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:35
Test Stop : 11/05/2020 @ 06:36
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:37

Canister ID# : 2756538
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 13
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:29
Test Stop : 11/05/2020 @ 06:29
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:45

Canister ID# : 2756540
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 19
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:20
Test Stop : 11/05/2020 @ 06:23
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:30

Canister ID# : 2756543
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 25
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:35
Test Stop : 11/05/2020 @ 06:44
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:54

Canister ID# : 2756544
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Principals Off.
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:03
Test Stop : 11/05/2020 @ 06:06
Received: 11/06/2020 @ 13:39
Analyzed: 11/06/2020 @ 16:37

Canister ID# : 2756570
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Media Ctr. 3
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:06
Test Stop : 11/05/2020 @ 06:09
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:28

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2756575	Test Start :	11/03/2020 @ 06:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:54
Location :	1st FL = Rm 4 BL	Received:	11/06/2020 @ 13:40
Radon Level :	0.1 pCi/L	Analyzed:	11/09/2020 @ 09:21
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2756577	Test Start :	11/03/2020 @ 06:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:49
Location :	1st FL = Stage BL	Received:	11/06/2020 @ 13:40
Radon Level :	0.1 pCi/L	Analyzed:	11/09/2020 @ 09:49
Error for Measurement is: ±	0.1 pCi/L		

Canister ID# :	2756579	Test Start :	11/03/2020 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:32
Location :	1st FL = Rm 26 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.5 pCi/L	Analyzed:	11/06/2020 @ 16:54
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2756583	Test Start :	11/03/2020 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:34
Location :	1st FL = Rm 11	Received:	11/06/2020 @ 13:40
Radon Level :	0.7 pCi/L	Analyzed:	11/09/2020 @ 10:21
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2756584	Test Start :	11/03/2020 @ 06:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:45
Location :	1st FL = Rm 9	Received:	11/06/2020 @ 13:40
Radon Level :	0.5 pCi/L	Analyzed:	11/06/2020 @ 17:36
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2756598	Test Start :	11/03/2020 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:23
Location :	1st FL = Rm 30 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/06/2020 @ 16:28
Error for Measurement is: ±	0.2 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2756601
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 15
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:12
Test Stop : 11/05/2020 @ 06:13
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:28

Canister ID# : 2756603
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 7
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:48
Test Stop : 11/05/2020 @ 06:48
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:36

Canister ID# : 2756604
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 12
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:31
Test Stop : 11/05/2020 @ 06:31
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:37

Canister ID# : 2756605
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 4
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:54
Test Stop : 11/05/2020 @ 06:54
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:28

Canister ID# : 2756611
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 6 DP
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:49
Test Stop : 11/05/2020 @ 06:51
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:28

Canister ID# : 2756612
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Media Ctr. 2
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:05
Test Stop : 11/05/2020 @ 06:08
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 16:53

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havnear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2756613	Test Start :	11/03/2020 @ 06:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:48
Location :	1st FL = Gym 2 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/06/2020 @ 16:54
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2756616	Test Start :	11/03/2020 @ 06:56
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:56
Location :	1st FL = Rm 3	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/06/2020 @ 16:54
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2756627	Test Start :	11/03/2020 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:16
Location :	1st FL = Rm 14	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/06/2020 @ 16:28
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2756629	Test Start :	11/03/2020 @ 06:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:53
Location :	1st FL = Cafeteria 2 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.2 pCi/L	Analyzed:	11/09/2020 @ 09:20
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2765195	Test Start :	11/03/2020 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:13
Location :	1st FL = Rm 160/159	Received:	11/06/2020 @ 13:40
Radon Level :	0.5 pCi/L	Analyzed:	11/09/2020 @ 10:14
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2765220	Test Start :	11/03/2020 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:14
Location :	1st FL = Rm 157/156	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/09/2020 @ 10:21
Error for Measurement is: ±	0.3 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2815868	Test Start :	11/03/2020 @ 06:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:47
Location :	1st FL = Gym 1	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/09/2020 @ 09:47
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2815873	Test Start :	11/03/2020 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:09
Location :	1st FL = Rm 17	Received:	11/06/2020 @ 13:40
Radon Level :	0.3 pCi/L	Analyzed:	11/09/2020 @ 09:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2815877	Test Start :	11/03/2020 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:26
Location :	1st FL = Rm 29	Received:	11/06/2020 @ 13:40
Radon Level :	0.7 pCi/L	Analyzed:	11/06/2020 @ 17:17
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2815878	Test Start :	11/03/2020 @ 05:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:03
Location :	1st FL = Main Office	Received:	11/06/2020 @ 13:39
Radon Level :	0.7 pCi/L	Analyzed:	11/06/2020 @ 17:09
Error for Measurement is: $\pm$	0.2 pCi/L		

Canister ID# :	2815879	Test Start :	11/03/2020 @ 06:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:11
Location :	1st FL = Rm 16	Received:	11/06/2020 @ 13:40
Radon Level :	0.4 pCi/L	Analyzed:	11/09/2020 @ 09:49
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2815883	Test Start :	11/03/2020 @ 06:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:53
Location :	1st FL = Cafeteria 2 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/09/2020 @ 09:21
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-
Individual Canister Results

Canister ID# : 2815885
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 32
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:23
Test Stop : 11/05/2020 @ 06:28
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 10:31

Canister ID# : 2815927
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 33-B
Radon Level : 20.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/03/2020 @ 10:00
Test Stop : 11/05/2020 @ 11:00
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 17:09

Canister ID# : 2815939
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 5
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:52
Test Stop : 11/05/2020 @ 06:52
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:28

Canister ID# : 2815946
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 18
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:19
Test Stop : 11/05/2020 @ 06:22
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:58

Canister ID# : 2816013
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 21 Computer
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:47
Test Stop : 11/05/2020 @ 06:50
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 10:31

Canister ID# : 2816014
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 27
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:26
Test Stop : 11/05/2020 @ 06:27
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 10:31

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-
Individual Canister Results

Canister ID# : 2816016
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Gym 2 DP
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:42
Test Stop : 11/05/2020 @ 06:48
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 10:21

Canister ID# : 2816022
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 33-A
Radon Level : 17.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/03/2020 @ 10:00
Test Stop : 11/05/2020 @ 11:00
Received: 11/06/2020 @ 13:40
Analyzed: 11/06/2020 @ 17:18

Canister ID# : 2816027
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Health Rm
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:04
Test Stop : 11/05/2020 @ 06:07
Received: 11/06/2020 @ 13:39
Analyzed: 11/09/2020 @ 09:28

Canister ID# : 2816032
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Cafeteria 1
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 11/03/2020 @ 06:51
Test Stop : 11/05/2020 @ 06:53
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:21

Canister ID# : 2816038
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm 161 BL
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 11/03/2020 @ 06:56
Test Stop : 11/05/2020 @ 06:57
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:10

Canister ID# : 2816041
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Computer Rm
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/03/2020 @ 06:07
Test Stop : 11/05/2020 @ 06:09
Received: 11/06/2020 @ 13:40
Analyzed: 11/09/2020 @ 09:58

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havnear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2817644	Test Start :	11/03/2020 @ 06:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 07:00
Location :	1st FL = Rm 2 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.3 pCi/L	Analyzed:	11/09/2020 @ 09:10
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2817645	Test Start :	11/03/2020 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:25
Location :	1st FL = E. Common Area	Received:	11/06/2020 @ 13:40
Radon Level :	0.3 pCi/L	Analyzed:	11/09/2020 @ 09:58
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2817648	Test Start :	11/03/2020 @ 06:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:08
Location :	1st FL = Staff W.R.	Received:	11/06/2020 @ 13:40
Radon Level :	0.1 pCi/L	Analyzed:	11/09/2020 @ 11:07
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2817649	Test Start :	11/03/2020 @ 06:56
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:57
Location :	1st FL = Rm 161	Received:	11/06/2020 @ 13:40
Radon Level :	0.2 pCi/L	Analyzed:	11/09/2020 @ 09:49
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2817997	Test Start :	11/03/2020 @ 06:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 07:00
Location :	1st FL = Rm 2 DP	Received:	11/06/2020 @ 13:40
Radon Level :	0.6 pCi/L	Analyzed:	11/09/2020 @ 10:15
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2818000	Test Start :	11/03/2020 @ 06:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/05/2020 @ 06:23
Location :	1st FL = Rm 31	Received:	11/06/2020 @ 13:40
Radon Level :	0.3 pCi/L	Analyzed:	11/09/2020 @ 09:57
Error for Measurement is: ±	0.3 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/06/2020

Bryan Hogan / Ron Havniear
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Howard E.S.
Test Location: 286 Mace Road
Medford, OR 97501-
Individual Canister Results

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201