PC2110250266

RTCA RADON TESTING CORPORATION OF AMERICA

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2704206	Test Start :	10/18/2021 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:18
Location :	1st FL=Staff Break Rm DP	Received:	10/25/2021 @ 14:37
Radon Level :	0.4 pCi/L	Analyzed:	10/27/2021 @ 08:45
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2707277	Test Start :	10/18/2021 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:16
Location :	1st FL = Gym 3 BL	Received:	10/25/2021 @ 14:37
Radon Level :	0.2 pCi/L	Analyzed:	10/26/2021 @ 12:00
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2707282	Test Start :	10/18/2021 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:19
Location :	1st FL=Large Rm	Received:	10/25/2021 @ 14:37
Radon Level :	2.4 pCi/L	Analyzed:	10/26/2021 @ 14:03
EAST OF BREAK ROOM			
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2707382	Test Start :	10/18/2021 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:15
Location :	1st FL = Room 3 BL	Received:	10/25/2021 @ 14:38
Radon Level :	1.1 pCi/L	Analyzed:	10/26/2021 @ 16:15
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2707419	Test Start :	10/18/2021 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:17
Location :	1st FL = Room 11	Received:	10/25/2021 @ 14:38
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 16:29
Error for Measurement is: ±	0.7 pCi/L		

Canister ID# :	2708544	Test Start :	10/18/2021 @ 06:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:17
Location :	1st FL = Room 2 DP	Received:	10/25/2021 @ 14:38
Radon Level :	1.2 pCi/L	Analyzed:	10/27/2021 @ 08:58

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Error for Measurement is: ± 0.6 pCi/L

Canister ID# : 2710014
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 7
Radon Level : 1.8 pCi/L
Error for Measurement is: ± 0.6 pCi/L

Test Start : 10/18/2021 @ 06:17
Test Stop : 10/20/2021 @ 06:25
Received: 10/25/2021 @ 14:38
Analyzed: 10/26/2021 @ 14:03

Canister ID# : 2756328
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 8
Radon Level : 1.9 pCi/L
Error for Measurement is: ± 0.6 pCi/L

Test Start : 10/18/2021 @ 06:15
Test Stop : 10/20/2021 @ 06:23
Received: 10/25/2021 @ 14:38
Analyzed: 10/26/2021 @ 16:36

Canister ID# : 2756345
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Large Rm BL
Radon Level : 0.1 pCi/L
EAST OF BREAK ROOM

Error for Measurement is: ± 7.8 pCi/L

Test Start : 10/18/2021 @ 06:16
Test Stop : 10/20/2021 @ 06:20
Received: 10/25/2021 @ 14:37
Analyzed: 10/26/2021 @ 14:52

Canister ID# : 2756350
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 16
Radon Level : 25.0 pCi/L
Error for Measurement is: ± 1.0 pCi/L

Test Start : 10/18/2021 @ 06:29
Test Stop : 10/20/2021 @ 06:30
Received: 10/25/2021 @ 14:37
Analyzed: 10/26/2021 @ 14:20

Canister ID# : 2756401
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Ctr 1
Radon Level : 2.1 pCi/L
Error for Measurement is: ± 0.7 pCi/L

Test Start : 10/18/2021 @ 06:27
Test Stop : 10/20/2021 @ 06:29
Received: 10/25/2021 @ 14:37
Analyzed: 10/26/2021 @ 14:22

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546
2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2756424	Test Start :	10/18/2021 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:14
Location :	1st FL = Room 15	Received:	10/25/2021 @ 14:37
Radon Level :	0.5 pCi/L	Analyzed:	10/26/2021 @ 14:20
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2756573	Test Start :	10/18/2021 @ 06:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:31
Location :	1st FL = Room 15	Received:	10/25/2021 @ 14:37
Radon Level :	36.6 pCi/L	Analyzed:	10/27/2021 @ 08:45
Error for Measurement is: ±	1.2 pCi/L		

Canister ID# :	2756609	Test Start :	10/18/2021 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:22
Location :	1st FL = Stage (E)	Received:	10/25/2021 @ 14:37
Radon Level :	0.5 pCi/L	Analyzed:	10/26/2021 @ 14:22
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2756619	Test Start :	10/18/2021 @ 06:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:11
Location :	1st FL = Room 14 DP	Received:	10/25/2021 @ 14:37
Radon Level :	0.4 pCi/L	Analyzed:	10/27/2021 @ 08:44
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2765209	Test Start :	10/18/2021 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:16
Location :	1st FL=Staff Work Rm DP	Received:	10/25/2021 @ 14:37
Radon Level :	1.3 pCi/L	Analyzed:	10/26/2021 @ 16:36
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2765215	Test Start :	10/18/2021 @ 06:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:14
Location :	1st FL=Principal's Office	Received:	10/25/2021 @ 14:37
Radon Level :	0.6 pCi/L	Analyzed:	10/26/2021 @ 14:52
Error for Measurement is: ±	0.6 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2765259	Test Start :	10/18/2021 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:21
Location :	1st FL=Small Rm	Received:	10/25/2021 @ 14:37
Radon Level :	1.1 pCi/L	Analyzed:	10/26/2021 @ 13:49

EAST OF BREAK ROOM

Error for Measurement is: ± 0.6 pCi/L

Canister ID# :	2765302	Test Start :	10/18/2021 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:28
Location :	1st FL=Media Ctr 2 DP	Received:	10/25/2021 @ 14:37
Radon Level :	1.2 pCi/L	Analyzed:	10/27/2021 @ 08:44

Error for Measurement is: ± 0.6 pCi/L

Canister ID# :	2765636	Test Start :	10/18/2021 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:15
Location :	1st FL = Room 13	Received:	10/25/2021 @ 14:38
Radon Level :	1.5 pCi/L	Analyzed:	10/26/2021 @ 14:22

Error for Measurement is: ± 0.7 pCi/L

Canister ID# :	2765642	Test Start :	10/18/2021 @ 06:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:16
Location :	1st FL = Room 12 DP	Received:	10/25/2021 @ 14:38
Radon Level :	1.4 pCi/L	Analyzed:	10/26/2021 @ 13:50

Error for Measurement is: ± 0.5 pCi/L

Canister ID# :	2765782	Test Start :	10/18/2021 @ 06:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:29
Location :	1st FL = Room 14	Received:	10/25/2021 @ 14:37
Radon Level :	0.2 pCi/L	Analyzed:	10/26/2021 @ 14:54

Error for Measurement is: ± 0.6 pCi/L

Canister ID# :	2765784	Test Start :	10/18/2021 @ 06:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:19
Location :	1st FL = Gym 1	Received:	10/25/2021 @ 14:37
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 13:50

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Error for Measurement is: ± 0.6 pCi/L

Canister ID# :	2765801	Test Start :	10/18/2021 @ 06:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:35
Location :	1st FL = Media (108)	Received:	10/25/2021 @ 14:38
Radon Level :	2.0 pCi/L	Analyzed:	10/27/2021 @ 08:58
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2815861	Test Start :	10/18/2021 @ 06:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:09
Location :	1st FL = Cafeteria	Received:	10/25/2021 @ 14:37
Radon Level :	1.9 pCi/L	Analyzed:	10/26/2021 @ 14:20
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2815862	Test Start :	10/18/2021 @ 05:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:12
Location :	1st FL = Room 5	Received:	10/25/2021 @ 14:38
Radon Level :	2.1 pCi/L	Analyzed:	10/26/2021 @ 14:22
Error for Measurement is: ±	0.7 pCi/L		

Canister ID# :	2815864	Test Start :	10/18/2021 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:14
Location :	1st FL = Room 15 BL	Received:	10/25/2021 @ 14:37
Radon Level :	0.1 pCi/L	Analyzed:	10/27/2021 @ 08:58
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	2815865	Test Start :	10/18/2021 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:28
Location :	1st FL=Media Ctr 2 DP	Received:	10/25/2021 @ 14:37
Radon Level :	3.7 pCi/L	Analyzed:	10/26/2021 @ 16:15
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2815870	Test Start :	10/18/2021 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:32
Location :	1st FL=Work Rm	Received:	10/25/2021 @ 14:37
Radon Level :	2.0 pCi/L	Analyzed:	10/26/2021 @ 14:03
Error for Measurement is: ±	0.6 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2815928	Test Start :	10/18/2021 @ 05:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:12
Location :	1st FL=Office BL	Received:	10/25/2021 @ 14:37
Radon Level :	0.1 pCi/L	Analyzed:	10/26/2021 @ 14:52
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2815929	Test Start :	10/18/2021 @ 06:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:16
Location :	1st FL = Room 12 DP	Received:	10/25/2021 @ 14:38
Radon Level :	0.7 pCi/L	Analyzed:	10/26/2021 @ 16:29
Error for Measurement is: ±	0.7 pCi/L		

Canister ID# :	2815937	Test Start :	10/18/2021 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:16
Location :	1st FL = Gym 2	Received:	10/25/2021 @ 14:37
Radon Level :	1.1 pCi/L	Analyzed:	10/26/2021 @ 14:37
Error for Measurement is: ±	0.7 pCi/L		

Canister ID# :	2815938	Test Start :	10/18/2021 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:21
Location :	1st FL = Room 9 DP	Received:	10/25/2021 @ 14:38
Radon Level :	1.6 pCi/L	Analyzed:	10/27/2021 @ 08:45
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2816012	Test Start :	10/18/2021 @ 06:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:11
Location :	1st FL = Room 14 DP	Received:	10/25/2021 @ 14:37
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 15:08
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2816017	Test Start :	10/18/2021 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:15
Location :	1st FL = Room 3	Received:	10/25/2021 @ 14:38
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 15:27
Error for Measurement is: ±	0.7 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2816019	Test Start :	10/18/2021 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:23
Location :	1st FL = Room 8 BL	Received:	10/25/2021 @ 14:38
Radon Level :	0.4 pCi/L	Analyzed:	10/26/2021 @ 15:09
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2816026	Test Start :	10/18/2021 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:19
Location :	1st FL = Room 10 BL	Received:	10/25/2021 @ 14:38
Radon Level :	0.1 pCi/L	Analyzed:	10/26/2021 @ 16:29
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2816034	Test Start :	10/18/2021 @ 05:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:13
Location :	1st FL = Room 6	Received:	10/25/2021 @ 14:38
Radon Level :	1.3 pCi/L	Analyzed:	10/27/2021 @ 08:44
Error for Measurement is: ±	0.7 pCi/L		

Canister ID# :	2816036	Test Start :	10/18/2021 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:18
Location :	1st FL=Staff Break Rm DP	Received:	10/25/2021 @ 14:37
Radon Level :	1.3 pCi/L	Analyzed:	10/26/2021 @ 16:36
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2816037	Test Start :	10/18/2021 @ 06:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:17
Location :	1st FL = Room 2 DP	Received:	10/25/2021 @ 14:38
Radon Level :	1.5 pCi/L	Analyzed:	10/27/2021 @ 08:58
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2816045	Test Start :	10/18/2021 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:27
Location :	1st FL=Custodial Off.	Received:	10/25/2021 @ 14:37
Radon Level :	3.3 pCi/L	Analyzed:	10/26/2021 @ 16:29
Error for Measurement is: ±	0.7 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2110250266

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2817647	Test Start :	10/18/2021 @ 05:57
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:11
Location :	1st FL=Office	Received:	10/25/2021 @ 14:37
Radon Level :	0.8 pCi/L	Analyzed:	10/26/2021 @ 16:50
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2817859	Test Start :	10/18/2021 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:21
Location :	1st FL = Room 9 DP	Received:	10/25/2021 @ 14:38
Radon Level :	2.6 pCi/L	Analyzed:	10/26/2021 @ 12:00
Error for Measurement is: ±	0.7 pCi/L		

Canister ID# :	2817985	Test Start :	10/18/2021 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:33
Location :	1st FL=Storage Rm	Received:	10/25/2021 @ 14:38
Radon Level :	2.2 pCi/L	Analyzed:	10/26/2021 @ 15:27
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2817989	Test Start :	10/18/2021 @ 06:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:10
Location :	1st FL = Cafeteria	Received:	10/25/2021 @ 14:37
Radon Level :	0.5 pCi/L	Analyzed:	10/26/2021 @ 15:27
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2817992	Test Start :	10/18/2021 @ 06:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:13
Location :	1st FL=Health Rm	Received:	10/25/2021 @ 14:37
Radon Level :	0.7 pCi/L	Analyzed:	10/26/2021 @ 14:52
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2817995	Test Start :	10/18/2021 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:16
Location :	1st FL=Staff Work Rm DP	Received:	10/25/2021 @ 14:37
Radon Level :	0.6 pCi/L	Analyzed:	10/26/2021 @ 13:49
Error for Measurement is: ±	0.5 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

PC2110250266

RTCA RADON TESTING CORPORATION OF AMERICA

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Ruch Elementary School
Test Location: 156 Upper Applegate Road
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2817998	Test Start :	10/18/2021 @ 05:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:12
Location :	1st FL = Room 4	Received:	10/25/2021 @ 14:38
Radon Level :	0.8 pCi/L	Analyzed:	10/26/2021 @ 14:52
Error for Measurement is:	± 0.5 pCi/L		

Canister ID# :	2818002	Test Start :	10/18/2021 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/20/2021 @ 06:19
Location :	1st FL = Room 10	Received:	10/25/2021 @ 14:38
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 13:50
Error for Measurement is:	± 0.5 pCi/L		

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability , collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or it's consultants based on RTCA-provided results.

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com