

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2901023	Test Start :	04/04/2022 @ 07:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:31
Location :	1st FL=A-301	Received:	04/11/2022 @ 10:27
Radon Level :	13.0 pCi/L	Analyzed:	04/12/2022 @ 09:15
Error for Measurement is: ±	0.8 pCi/L		

Canister ID# :	2916960	Test Start :	04/04/2022 @ 07:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:04
Location :	1st FL=A-304	Received:	04/11/2022 @ 10:27
Radon Level :	21.1 pCi/L	Analyzed:	04/12/2022 @ 08:56
Error for Measurement is: ±	0.9 pCi/L		

Canister ID# :	2917643	Test Start :	04/04/2022 @ 07:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:02
Location :	1st FL=A-302	Received:	04/11/2022 @ 10:27
Radon Level :	19.9 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: ±	0.9 pCi/L		

Canister ID# :	2918196	Test Start :	04/04/2022 @ 07:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:03
Location :	1st FL=A-303	Received:	04/11/2022 @ 10:27
Radon Level :	19.5 pCi/L	Analyzed:	04/12/2022 @ 09:10
Error for Measurement is: ±	0.8 pCi/L		

Canister ID# :	2987628	Test Start :	04/04/2022 @ 07:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:12
Location :	1st FL=Custodial Off. DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 10:31
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2988042	Test Start :	04/04/2022 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:32
Location :	1st FL=A-133 Off.N	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: ±	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989189	Test Start :	04/04/2022 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:50
Location :	1st FL=E-111#2 Metals	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 08:22
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989191	Test Start :	04/04/2022 @ 06:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:29
Location :	1st FL=E-102 BLANK	Received:	04/11/2022 @ 10:27
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 08:56
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989192	Test Start :	04/04/2022 @ 07:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:03
Location :	1st FL=Gym 3	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/12/2022 @ 09:50
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989194	Test Start :	04/04/2022 @ 07:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:10
Location :	1st FL=Gym 7	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 11:05
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989195	Test Start :	04/04/2022 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:26
Location :	1st FL=E-101	Received:	04/11/2022 @ 10:26
Radon Level :	0.1 pCi/L	Analyzed:	04/11/2022 @ 10:48
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2989198	Test Start :	04/04/2022 @ 06:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:16
Location :	1st FL=A-151	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 08:39
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989201	Test Start :	04/04/2022 @ 06:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:29
Location :	1st FL=Media Ctr 5	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 10:29
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989204	Test Start :	04/04/2022 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:41
Location :	1st FL=C-110	Received:	04/11/2022 @ 10:28
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 15:17
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989206	Test Start :	04/04/2022 @ 06:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:43
Location :	1st FL=C-112	Received:	04/11/2022 @ 10:28
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 08:41
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989208	Test Start :	04/04/2022 @ 06:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:45
Location :	1st FL=C-115	Received:	04/11/2022 @ 10:28
Radon Level :	0.8 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989209	Test Start :	04/04/2022 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:37
Location :	1st FL=C-105	Received:	04/11/2022 @ 10:28
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 10:32
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989210	Test Start :	04/04/2022 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:15
Location :	1st FL=Cafeteria 4	Received:	04/11/2022 @ 10:26
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 08:56
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989211	Test Start :	04/04/2022 @ 06:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:19
Location :	1st FL=A-153	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 10:06
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989214	Test Start :	04/04/2022 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:24
Location :	1st FL=D-109 CTE DP	Received:	04/11/2022 @ 10:26
Radon Level :	0.1 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989216	Test Start :	04/04/2022 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:33
Location :	1st FL=E-103 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 09:34
Error for Measurement is: $\pm$	0.7 pCi/L		

Canister ID# :	2989217	Test Start :	04/04/2022 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:17
Location :	1st FL=A-109 Off.D	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/12/2022 @ 09:11
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989220	Test Start :	04/04/2022 @ 06:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:52
Location :	1st FL=C-119	Received:	04/11/2022 @ 10:28
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 10:06
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989223	Test Start :	04/04/2022 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:30
Location :	1st FL=Media Ctr 3	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/11/2022 @ 10:45
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989225	Test Start :	04/04/2022 @ 06:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:44
Location :	1st FL=C-114	Received:	04/11/2022 @ 10:28
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 11:19
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989226	Test Start :	04/04/2022 @ 06:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:40
Location :	1st FL=E-104 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:16
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989227	Test Start :	04/04/2022 @ 06:43
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:44
Location :	1st FL=E-108#1 Band	Received:	04/11/2022 @ 10:27
Radon Level :	0.8 pCi/L	Analyzed:	04/12/2022 @ 09:50
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989230	Test Start :	04/04/2022 @ 06:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:29
Location :	1st FL=E-102	Received:	04/11/2022 @ 10:26
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 08:39
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989231	Test Start :	04/04/2022 @ 07:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:04
Location :	1st FL=Gym 4	Received:	04/11/2022 @ 10:27
Radon Level :	1.1 pCi/L	Analyzed:	04/12/2022 @ 09:31
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989233	Test Start :	04/04/2022 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:20
Location :	1st FL=A-154	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 09:10
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989234	Test Start :	04/04/2022 @ 14:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 14:53
Location :	1st FL=C-120	Received:	04/11/2022 @ 10:28
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 09:27
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989237	Test Start :	04/04/2022 @ 06:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:31
Location :	1st FL=Media Ctr NTS DP	Received:	04/11/2022 @ 10:28
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:32
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989238	Test Start :	04/04/2022 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:24
Location :	1st FL=Media Ctr 1	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/11/2022 @ 15:14
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989239	Test Start :	04/04/2022 @ 07:05
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:06
Location :	1st FL=Gym 5	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 11:19
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989243	Test Start :	04/04/2022 @ 06:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:42
Location :	1st FL=C-111	Received:	04/11/2022 @ 10:28
Radon Level :	0.2 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989246	Test Start :	04/04/2022 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:49
Location :	1st FL=C-117 DP	Received:	04/11/2022 @ 10:28
Radon Level :	0.9 pCi/L	Analyzed:	04/12/2022 @ 09:35
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989248	Test Start :	04/04/2022 @ 06:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:51
Location :	1st FL=E-112#1 Auto	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 08:41
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989249	Test Start :	04/04/2022 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:33
Location :	1st FL=E-103 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 10:31
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989250	Test Start :	04/04/2022 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:50
Location :	1st FL=E-111#1 Metals	Received:	04/11/2022 @ 10:27
Radon Level :	0.2 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989251	Test Start :	04/04/2022 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:16
Location :	1st FL=Cafeteria 3	Received:	04/11/2022 @ 10:26
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 15:17
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989254	Test Start :	04/04/2022 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:28
Location :	1st FL=Media Ctr 4	Received:	04/11/2022 @ 10:27
Radon Level :	1.3 pCi/L	Analyzed:	04/12/2022 @ 10:10
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989257	Test Start :	04/04/2022 @ 06:57
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:59
Location :	1st FL=A-148	Received:	04/11/2022 @ 10:27
Radon Level :	1.1 pCi/L	Analyzed:	04/11/2022 @ 11:22
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989261	Test Start :	04/04/2022 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:22
Location :	1st FL=A-156 DP	Received:	04/11/2022 @ 10:27
Radon Level :	1.0 pCi/L	Analyzed:	04/11/2022 @ 11:22
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2989262	Test Start :	04/04/2022 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:20
Location :	1st FL=Theater 2	Received:	04/11/2022 @ 10:26
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 15:14
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989263	Test Start :	04/04/2022 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:33
Location :	1st FL=C-101	Received:	04/11/2022 @ 10:28
Radon Level :	0.2 pCi/L	Analyzed:	04/12/2022 @ 10:16
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989268	Test Start :	04/04/2022 @ 06:52
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:53
Location :	1st FL=E-112#2 Auto	Received:	04/11/2022 @ 10:27
Radon Level :	0.9 pCi/L	Analyzed:	04/12/2022 @ 10:18
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989270	Test Start :	04/04/2022 @ 06:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:40
Location :	1st FL=C-109 DP	Received:	04/11/2022 @ 10:28
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 11:05
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2989274	Test Start :	04/04/2022 @ 06:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:36
Location :	1st FL=E-105 Music	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989285	Test Start :	04/04/2022 @ 06:34
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:38
Location :	1st FL=C-106	Received:	04/11/2022 @ 10:28
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 10:47
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989286	Test Start :	04/04/2022 @ 06:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:21
Location :	1st FL=A-155	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 15:17
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989289	Test Start :	04/04/2022 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:47
Location :	1st FL=C-116	Received:	04/11/2022 @ 10:28
Radon Level :	1.0 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989292	Test Start :	04/04/2022 @ 06:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:22
Location :	1st FL=A-156 DP	Received:	04/11/2022 @ 10:27
Radon Level :	1.0 pCi/L	Analyzed:	04/11/2022 @ 11:22
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989295	Test Start :	04/04/2022 @ 06:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:39
Location :	1st FL=C-107	Received:	04/11/2022 @ 10:28
Radon Level :	1.8 pCi/L	Analyzed:	04/12/2022 @ 09:35
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989296	Test Start :	04/04/2022 @ 06:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:59
Location :	1st FL=Gym 1	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989297	Test Start :	04/04/2022 @ 06:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:39
Location :	1st FL=C-108	Received:	04/11/2022 @ 10:28
Radon Level :	0.8 pCi/L	Analyzed:	04/11/2022 @ 14:13
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989299	Test Start :	04/04/2022 @ 07:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:16
Location :	1st FL=Gym Off.A BL	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/12/2022 @ 09:11
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989300	Test Start :	04/04/2022 @ 06:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:34
Location :	1st FL=C-102	Received:	04/11/2022 @ 10:28
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989301	Test Start :	04/04/2022 @ 06:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:31
Location :	1st FL=Media Ctr NTS DP	Received:	04/11/2022 @ 10:28
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 10:06
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989302	Test Start :	04/04/2022 @ 06:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:36
Location :	1st FL=C-104	Received:	04/11/2022 @ 10:28
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 11:19
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989303	Test Start :	04/04/2022 @ 06:50
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:50
Location :	1st FL=C-118	Received:	04/11/2022 @ 10:28
Radon Level :	1.0 pCi/L	Analyzed:	04/11/2022 @ 10:47
Error for Measurement is: $\pm$	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989307	Test Start :	04/04/2022 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:24
Location :	1st FL=Media Ctr 2	Received:	04/11/2022 @ 10:27
Radon Level :	1.1 pCi/L	Analyzed:	04/11/2022 @ 11:22
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989312	Test Start :	04/04/2022 @ 07:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:12
Location :	1st FL=Custodial Off. DP	Received:	04/11/2022 @ 10:27
Radon Level :	1.0 pCi/L	Analyzed:	04/12/2022 @ 09:15
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989313	Test Start :	04/04/2022 @ 06:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:17
Location :	1st FL=A-152	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/11/2022 @ 10:29
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989320	Test Start :	04/04/2022 @ 06:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:34
Location :	1st FL=C-103	Received:	04/11/2022 @ 10:28
Radon Level :	0.8 pCi/L	Analyzed:	04/11/2022 @ 11:05
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989357	Test Start :	04/04/2022 @ 06:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:44
Location :	1st FL=C-114 BL	Received:	04/11/2022 @ 10:28
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 10:10
Error for Measurement is: $\pm$	0.3 pCi/L		

Canister ID# :	2989359	Test Start :	04/04/2022 @ 06:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:21
Location :	1st FL=A-155 BL	Received:	04/11/2022 @ 10:27
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 09:31
Error for Measurement is: $\pm$	0.2 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989941	Test Start :	04/04/2022 @ 06:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:58
Location :	1st FL=A-145	Received:	04/11/2022 @ 10:27
Radon Level :	0.8 pCi/L	Analyzed:	04/12/2022 @ 10:18
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989942	Test Start :	04/04/2022 @ 06:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:52
Location :	1st FL=A-118 Off.W	Received:	04/11/2022 @ 10:27
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989943	Test Start :	04/04/2022 @ 06:53
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:57
Location :	1st FL=A-144	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 08:39
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989945	Test Start :	04/04/2022 @ 06:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:16
Location :	1st FL=A-105 Off.B	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 10:31
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989946	Test Start :	04/04/2022 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:24
Location :	1st FL=D-109 CTE DP	Received:	04/11/2022 @ 10:26
Radon Level :	0.1 pCi/L	Analyzed:	04/11/2022 @ 11:19
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989947	Test Start :	04/04/2022 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:14
Location :	1st FL=Main Off. 2 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:10
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989949	Test Start :	04/04/2022 @ 07:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:25
Location :	1st FL=Gym Off.C	Received:	04/11/2022 @ 10:27
Radon Level :	0.2 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989951	Test Start :	04/04/2022 @ 06:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:32
Location :	1st FL=A-135 Off.O	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 10:48
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989952	Test Start :	04/04/2022 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:40
Location :	1st FL=E-105.1	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 14:59
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989954	Test Start :	04/04/2022 @ 06:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:51
Location :	1st FL=A-116 Off.V	Received:	04/11/2022 @ 10:27
Radon Level :	0.8 pCi/L	Analyzed:	04/12/2022 @ 08:56
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989955	Test Start :	04/04/2022 @ 07:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:01
Location :	1st FL=A-149	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 10:47
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989957	Test Start :	04/04/2022 @ 06:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:44
Location :	1st FL=E-108#2 Band	Received:	04/11/2022 @ 10:27
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 09:50
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989959	Test Start :	04/04/2022 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:55
Location :	1st FL=A-126 Panther Ctr	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:18
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989962	Test Start :	04/04/2022 @ 06:37
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:36
Location :	1st FL=A-112 Off.T	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 10:45
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989965	Test Start :	04/04/2022 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:19
Location :	1st FL=A-113 Off.F	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:06
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989967	Test Start :	04/04/2022 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:27
Location :	1st FL=A-119 Off.I	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 11:11
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2989968	Test Start :	04/04/2022 @ 06:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:16
Location :	1st FL=A-107 Off.C	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 14:13
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989974	Test Start :	04/04/2022 @ 06:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:35
Location :	1st FL=A-108 Off.R	Received:	04/11/2022 @ 10:27
Radon Level :	0.2 pCi/L	Analyzed:	04/11/2022 @ 10:29
Error for Measurement is: ±	0.3 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989975	Test Start :	04/04/2022 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:19
Location :	1st FL=Theater 1	Received:	04/11/2022 @ 10:26
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 14:13
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989978	Test Start :	04/04/2022 @ 07:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:18
Location :	1st FL=Gym Off.B	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/12/2022 @ 10:32
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989980	Test Start :	04/04/2022 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:33
Location :	1st FL=Activities Rm Off.Q	Received:	04/11/2022 @ 10:27
Radon Level :	0.8 pCi/L	Analyzed:	04/11/2022 @ 14:59
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989981	Test Start :	04/04/2022 @ 06:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:55
Location :	1st FL=A-141 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989984	Test Start :	04/04/2022 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:20
Location :	1st FL=A-115 Off.G	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 09:10
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2989987	Test Start :	04/04/2022 @ 06:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:29
Location :	1st FL=Media Ctr BL	Received:	04/11/2022 @ 10:28
Radon Level :	0.1 pCi/L	Analyzed:	04/12/2022 @ 08:41
Error for Measurement is: $\pm$	0.8 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2989988	Test Start :	04/04/2022 @ 06:12
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:18
Location :	1st FL=A-111 Off.E	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 09:50
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2989992	Test Start :	04/04/2022 @ 06:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:15
Location :	1st FL=A-103 Off.A	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 09:27
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2989994	Test Start :	04/04/2022 @ 06:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:53
Location :	1st FL=A-120 Off.X	Received:	04/11/2022 @ 10:27
Radon Level :	1.0 pCi/L	Analyzed:	04/12/2022 @ 09:27
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2989996	Test Start :	04/04/2022 @ 06:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:27
Location :	1st FL=A-121 Off.J	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 09:15
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2989998	Test Start :	04/04/2022 @ 06:43
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:53
Location :	1st FL=A-122 Off.Y	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:10
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2989999	Test Start :	04/04/2022 @ 06:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:40
Location :	1st FL=C-109 DP	Received:	04/11/2022 @ 10:28
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 10:47
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990001	Test Start :	04/04/2022 @ 07:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:14
Location :	1st FL=Gym Off.A	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 11:05
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2990002	Test Start :	04/04/2022 @ 07:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:01
Location :	1st FL=A-150	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 15:17
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990003	Test Start :	04/04/2022 @ 06:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:13
Location :	1st FL=Main Off. 1	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 09:27
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990004	Test Start :	04/04/2022 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:32
Location :	1st FL=Health Rm Off.P	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 09:36
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990006	Test Start :	04/04/2022 @ 07:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:26
Location :	1st FL=Gym Off.D	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/11/2022 @ 11:02
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990007	Test Start :	04/04/2022 @ 06:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:56
Location :	1st FL=A-143	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 08:41
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990009	Test Start :	04/04/2022 @ 06:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:54
Location :	1st FL=A-124 Off.Z	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990012	Test Start :	04/04/2022 @ 06:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:58
Location :	1st FL=A-146	Received:	04/11/2022 @ 10:27
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 09:10
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990049	Test Start :	04/04/2022 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:29
Location :	1st FL=A-127 Off.L	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 09:31
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2990054	Test Start :	04/04/2022 @ 06:36
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:36
Location :	1st FL=A-110 Off.S	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 09:11
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2990055	Test Start :	04/04/2022 @ 06:56
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:59
Location :	1st FL=A-147	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 09:35
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990056	Test Start :	04/04/2022 @ 07:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:28
Location :	1st FL=Gym Off.E	Received:	04/11/2022 @ 10:27
Radon Level :	0.9 pCi/L	Analyzed:	04/12/2022 @ 09:34
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990061	Test Start :	04/04/2022 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:51
Location :	1st FL=A-114 Off.U	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 10:32
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990062	Test Start :	04/04/2022 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:49
Location :	1st FL=C-117 DP	Received:	04/11/2022 @ 10:28
Radon Level :	0.4 pCi/L	Analyzed:	04/12/2022 @ 08:55
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990066	Test Start :	04/04/2022 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:25
Location :	1st FL=New Off.H	Received:	04/11/2022 @ 10:27
Radon Level :	0.7 pCi/L	Analyzed:	04/12/2022 @ 08:39
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990148	Test Start :	04/04/2022 @ 07:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:09
Location :	1st FL=Gym 6	Received:	04/11/2022 @ 10:27
Radon Level :	1.1 pCi/L	Analyzed:	04/12/2022 @ 09:31
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990151	Test Start :	04/04/2022 @ 06:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:40
Location :	1st FL=E-104 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.1 pCi/L	Analyzed:	04/11/2022 @ 14:13
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2990155	Test Start :	04/04/2022 @ 06:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:55
Location :	1st FL=A-141 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/11/2022 @ 10:45
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990169	Test Start :	04/04/2022 @ 07:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 07:01
Location :	1st FL=Gym 2	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 10:45
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2990205	Test Start :	04/04/2022 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:28
Location :	1st FL=A-128 Off.K	Received:	04/11/2022 @ 10:27
Radon Level :	0.3 pCi/L	Analyzed:	04/11/2022 @ 10:29
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2990485	Test Start :	04/04/2022 @ 06:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:15
Location :	1st FL=Cafeteria 1	Received:	04/11/2022 @ 10:26
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 09:11
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990497	Test Start :	04/04/2022 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:14
Location :	1st FL=Main Off. 2 DP	Received:	04/11/2022 @ 10:27
Radon Level :	0.6 pCi/L	Analyzed:	04/12/2022 @ 10:18
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990507	Test Start :	04/04/2022 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:23
Location :	1st FL=D-108 Culinary	Received:	04/11/2022 @ 10:26
Radon Level :	0.2 pCi/L	Analyzed:	04/11/2022 @ 10:31
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990508	Test Start :	04/04/2022 @ 06:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	04/06/2022 @ 06:30
Location :	1st FL=A-129 Off.M	Received:	04/11/2022 @ 10:27
Radon Level :	0.5 pCi/L	Analyzed:	04/12/2022 @ 09:15
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 04/11/2022

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Room 214
Medford, OR 97501-

Client: South High School
Test Location: 1551 Cunningham Avenue
Medford, OR 97501-

Individual Canister Results

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201