


INSPECTION CERTIFICATION for Saint Paul Public Schools -- Gordon Parks High School

STATEMENT OF BUILDING ACCESS

On behalf of Saint Paul Public Schools for Gordon Parks High School, I certify that I have provided access to all areas within the building to IEA's inspector identified below for the purpose of inspecting for asbestos-containing building materials (ACBM) as mandated by 40 CFR 763.85, "Inspections and Reinspections."


Additionally, I have discussed any concerns I have regarding identified or non-identified ACBM within this building.


Signature

8/3/18
Date

INSPECTOR

As mandated by 40 CFR 763.85, "Inspections and Reinspections," I certify that I have inspected all accessible areas in Gordon Parks High School for the purpose of identifying and assessing asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Inspector. A copy of my certification/accreditation is attached.


Signature
K. E. M. R.
Print Name

8/3/18
Date of Inspection
I13620
State Certification/Accreditation Number

MANAGEMENT PLANNER

I certify that I have reviewed all of the inspection data for Gordon Parks High School and have appropriately provided assessments and response actions for identified asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Management Planner. A copy of my certification/accreditation is attached.


Signature
M. H. Lindberg
Print Name

9/11/18
Date of Review
AH3874
State Certification/Accreditation Number

Inspector State Certification/Accreditation



K Peterson

Director, Env. Health Div.

mn ASBESTOS
DEPARTMENT OF HEALTH INSPECTOR

Certified by:

State of Minnesota
Department of Health

Expires: 09/27/2018

Kennedy E Peterson
523 Ramsey St
Hastings, MN 55033

No AI13620 Issued: 10/09/2017

Management Planner State Certification/Accreditation



K Peterson

Director, Env. Health Div.

mn ASBESTOS
DEPARTMENT OF HEALTH MANAGEMENT
PLANNER

Certified by:

State of Minnesota
Department of Health

Expires: 08/02/2019

Matthew A Lindberg
11816 Ghia St NE
Blaine, MN 55449

No AM3896 Issued: 08/14/2018

Chart A - Immediate Response Situations

The following is a list of those events that contain damaged asbestos material and should be considered to be potential hazards. It is imperative that the following immediate response situations are corrected as soon as possible but no later than six months from the date of this inspection to avoid increased risk of exposure to airborne asbestos fibers. The District should take extra precaution to ensure that properly trained personnel use appropriate techniques to implement these responses.

Following is an explanation of the Immediate Response Action Codes identified in this report.

EPA ASSESSMENT CATEGORY	RESPONSE ACTION
1 = Damaged or significantly damaged TSI ACM. 2 = Damaged friable surfacing ACM. 3 = Significantly damaged friable surfacing ACM. 4 = Damaged or significantly damaged friable miscellaneous ACM. 5 = ACBM w/potential for damage. 6 = ACBM w/potential for significant damage. 7 = Any remaining friable ACBM or friable suspected ACBM.	A = Clean-up ACM debris. B = Encapsulate slight damage on TSI (i.e. puncture hole or exposed ends of pipe cover). C = Patch TSI and/or repair ACM cover. D = Enclose or protect accessible sections w/protective barrier. E = Remove section of damaged ACM. F = Remove ACM and replace with non-ACM. G = Isolate area until repaired/removed. H = Encapsulate slight damage. I = Remove and replace damaged or loose tile section (s). J = Monitor condition of material(s).

IEA	IEA		Estimated	Estimated	EPA	Immediate	
Event	Material Type	Location	Amount	Amount of	Assess.	Response	
No.			Total	Damage		Action	Comments

There were no immediate response actions identified during the inspection of this building.