

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2987414	Test Start :	11/14/2023 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 06:58
Location :	101 The Hub 1	Received:	11/21/2023 @ 09:26
Radon Level :	0.8 pCi/L	Analyzed:	11/21/2023 @ 09:38
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2987490	Test Start :	11/14/2023 @ 06:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 06:59
Location :	101 The Hub 2	Received:	11/21/2023 @ 09:26
Radon Level :	0.3 pCi/L	Analyzed:	11/21/2023 @ 09:38
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2987474	Test Start :	11/14/2023 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:00
Location :	101 The Hub 3	Received:	11/21/2023 @ 09:26
Radon Level :	0.6 pCi/L	Analyzed:	11/21/2023 @ 14:06
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2987422	Test Start :	11/14/2023 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:01
Location :	101 The Hub 4	Received:	11/21/2023 @ 09:26
Radon Level :	0.4 pCi/L	Analyzed:	11/21/2023 @ 15:19
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2987459	Test Start :	11/14/2023 @ 06:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:02
Location :	101 The Hub 5	Received:	11/21/2023 @ 09:26
Radon Level :	0.3 pCi/L	Analyzed:	11/21/2023 @ 14:00
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2987438	Test Start :	11/14/2023 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:03
Location :	101 The Hub 6	Received:	11/21/2023 @ 09:26
Radon Level :	1.0 pCi/L	Analyzed:	11/21/2023 @ 15:02
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2987461
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 7
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:26
Test Stop : 11/16/2023 @ 07:03
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:26

Canister ID# : 2987484
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 8
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:27
Test Stop : 11/16/2023 @ 07:04
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:02

Canister ID# : 2987328
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 9
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:28
Test Stop : 11/16/2023 @ 07:05
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:39

Canister ID# : 2987416
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 10
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:29
Test Stop : 11/16/2023 @ 07:06
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:07

Canister ID# : 2987363
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 11
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:30
Test Stop : 11/16/2023 @ 07:07
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:04

Canister ID# : 2987405
Canister Type : Charcoal Canister 3 inch
Location : 134
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:30
Test Stop : 11/16/2023 @ 07:11
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:06

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2987382
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 12
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:31
Test Stop : 11/16/2023 @ 07:08
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:19

Canister ID# : 2987475
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 13
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:32
Test Stop : 11/16/2023 @ 07:09
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:19

Canister ID# : 2987401
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 14 DP
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:33
Test Stop : 11/16/2023 @ 07:11
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:20

Canister ID# : 2987432
Canister Type : Charcoal Canister 3 inch
Location : 101 The Hub 14 DP
Radon Level : 0.5 pCi/L

Test Start : 11/14/2023 @ 06:33
Test Stop : 11/16/2023 @ 07:11
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:59

Average of Side by Side Canisters 0.4 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2987284
Canister Type : Charcoal Canister 3 inch
Location : 103
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:34
Test Stop : 11/16/2023 @ 07:12
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:00

Canister ID# : 2987465
Canister Type : Charcoal Canister 3 inch
Location : 104
Radon Level : 0.5 pCi/L

Test Start : 11/14/2023 @ 06:35
Test Stop : 11/16/2023 @ 07:13
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:04

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2987452
Canister Type : Charcoal Canister 3 inch
Location : 128
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:40
Test Stop : 11/16/2023 @ 07:05
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:59

Canister ID# : 2989267
Canister Type : Charcoal Canister 3 inch
Location : 129
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:44
Test Stop : 11/16/2023 @ 07:07
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:33

Canister ID# : 2987503
Canister Type : Charcoal Canister 3 inch
Location : 130
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:48
Test Stop : 11/16/2023 @ 07:09
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:56

Canister ID# : 2985787
Canister Type : Charcoal Canister 3 inch
Location : 132
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 06:50
Test Stop : 11/16/2023 @ 07:11
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:06

Canister ID# : 2987451
Canister Type : Charcoal Canister 3 inch
Location : 136
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 06:53
Test Stop : 11/16/2023 @ 07:12
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:06

Canister ID# : 2987476
Canister Type : Charcoal Canister 3 inch
Location : 138
Radon Level : 1.1 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:00
Test Stop : 11/16/2023 @ 07:14
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:59

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2987450
Canister Type : Charcoal Canister 3 inch
Location : 108
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:02
Test Stop : 11/16/2023 @ 07:14
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:39

Canister ID# : 2987444
Canister Type : Charcoal Canister 3 inch
Location : 109
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:03
Test Stop : 11/16/2023 @ 07:15
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:02

Canister ID# : 2987506
Canister Type : Charcoal Canister 3 inch
Location : 111
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:04
Test Stop : 11/16/2023 @ 07:16
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:56

Canister ID# : 2987455
Canister Type : Charcoal Canister 3 inch
Location : 137
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:05
Test Stop : 11/16/2023 @ 07:13
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:33

Canister ID# : 2987407
Canister Type : Charcoal Canister 3 inch
Location : 112 DP
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:05
Test Stop : 11/16/2023 @ 07:18
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:04

Canister ID# : 2989236
Canister Type : Charcoal Canister 3 inch
Location : 112 DP
Radon Level : 0.3 pCi/L

Test Start : 11/14/2023 @ 07:05
Test Stop : 11/16/2023 @ 07:18
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:50

Average of Side by Side Canisters 0.4 pCi/L

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2987464
Canister Type : Charcoal Canister 3 inch
Location : 113-A
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:06
Test Stop : 11/16/2023 @ 07:19
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:00

Canister ID# : 2987502
Canister Type : Charcoal Canister 3 inch
Location : 139
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 11/14/2023 @ 07:07
Test Stop : 11/16/2023 @ 07:15
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:50

Canister ID# : 2987398
Canister Type : Charcoal Canister 3 inch
Location : 113-B
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 11/14/2023 @ 07:07
Test Stop : 11/16/2023 @ 07:20
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:20

Canister ID# : 2987390
Canister Type : Charcoal Canister 3 inch
Location : 140
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:08
Test Stop : 11/16/2023 @ 07:15
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:52

Canister ID# : 2987300
Canister Type : Charcoal Canister 3 inch
Location : 113-C
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:08
Test Stop : 11/16/2023 @ 07:21
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:56

Canister ID# : 2987415
Canister Type : Charcoal Canister 3 inch
Location : 142
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:09
Test Stop : 11/16/2023 @ 07:16
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:50

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2987446
Canister Type : Charcoal Canister 3 inch
Location : 114
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:09
Test Stop : 11/16/2023 @ 07:22
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:59

Canister ID# : 2987387
Canister Type : Charcoal Canister 3 inch
Location : 114 BLANK
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:10
Test Stop : 11/16/2023 @ 07:23
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:20

Canister ID# : 2987458
Canister Type : Charcoal Canister 3 inch
Location : 141
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 11/14/2023 @ 07:11
Test Stop : 11/16/2023 @ 07:17
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:09

Canister ID# : 2987420
Canister Type : Charcoal Canister 3 inch
Location : 117
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:11
Test Stop : 11/16/2023 @ 07:24
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:07

Canister ID# : 2987413
Canister Type : Charcoal Canister 3 inch
Location : 118 DP
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:12
Test Stop : 11/16/2023 @ 07:26
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:07

Canister ID# : 2987507
Canister Type : Charcoal Canister 3 inch
Location : 118 DP
Radon Level : 0.5 pCi/L

Test Start : 11/14/2023 @ 07:12
Test Stop : 11/16/2023 @ 07:26
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:19

Average of Side by Side Canisters 0.6 pCi/L

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2987481
Canister Type : Charcoal Canister 3 inch
Location : 143
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:13
Test Stop : 11/16/2023 @ 07:18
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 09:38

Canister ID# : 2987424
Canister Type : Charcoal Canister 3 inch
Location : 144
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:14
Test Stop : 11/16/2023 @ 07:18
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 09:38

Canister ID# : 2987429
Canister Type : Charcoal Canister 3 inch
Location : 119 Café 1
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:14
Test Stop : 11/16/2023 @ 07:27
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:33

Canister ID# : 2915700
Canister Type : Charcoal Canister 3 inch
Location : 145
Radon Level : 22.4 pCi/L
Error for Measurement is: $\pm$ 0.8 pCi/L

Test Start : 11/14/2023 @ 07:15
Test Stop : 11/16/2023 @ 07:20
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:56

Canister ID# : 2987491
Canister Type : Charcoal Canister 3 inch
Location : 119 Café 2
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 11/14/2023 @ 07:15
Test Stop : 11/16/2023 @ 07:28
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 14:07

Canister ID# : 2987500
Canister Type : Charcoal Canister 3 inch
Location : 123
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:16
Test Stop : 11/16/2023 @ 07:21
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 15:02

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2987421	Test Start :	11/14/2023 @ 07:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:29
Location :	120	Received:	11/21/2023 @ 09:26
Radon Level :	0.5 pCi/L	Analyzed:	11/21/2023 @ 15:03
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2987434	Test Start :	11/14/2023 @ 07:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:30
Location :	121	Received:	11/21/2023 @ 09:26
Radon Level :	0.6 pCi/L	Analyzed:	11/21/2023 @ 14:00
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2987391	Test Start :	11/14/2023 @ 07:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:31
Location :	122	Received:	11/21/2023 @ 09:26
Radon Level :	0.3 pCi/L	Analyzed:	11/21/2023 @ 13:52
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2987393	Test Start :	11/14/2023 @ 07:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:22
Location :	124 DP	Received:	11/21/2023 @ 09:26
Radon Level :	0.6 pCi/L	Analyzed:	11/21/2023 @ 15:20
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2987482	Test Start :	11/14/2023 @ 07:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:22
Location :	124 DP	Received:	11/21/2023 @ 09:26
Radon Level :	0.6 pCi/L	Analyzed:	11/21/2023 @ 13:52

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: $\pm$ 0.6 pCi/L

Canister ID# :	2987436	Test Start :	11/14/2023 @ 07:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	11/16/2023 @ 07:24
Location :	125 Break Rm	Received:	11/21/2023 @ 09:26
Radon Level :	0.8 pCi/L	Analyzed:	11/21/2023 @ 14:04

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 11/21/2023

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Innovation Academy
Test Location: 1321 Center Drive
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2987395
Canister Type : Charcoal Canister 3 inch
Location : 125 Break Rm BLANK
Radon Level : 0.1 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:23
Test Stop : 11/16/2023 @ 07:24
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:52

Canister ID# : 2987326
Canister Type : Charcoal Canister 3 inch
Location : 127 Greenhouse Off.
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 11/14/2023 @ 07:28
Test Stop : 11/16/2023 @ 07:30
Received: 11/21/2023 @ 09:26
Analyzed: 11/21/2023 @ 13:50

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201