

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# : 2756580
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Comp. Rm. Off.1
Radon Level : 1.1 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:19
Test Stop : 10/21/2021 @ 06:36
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:38

Canister ID# : 2756625
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 6
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:10
Test Stop : 10/21/2021 @ 06:33
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:20

Canister ID# : 2765264
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 23
Radon Level : 30.4 pCi/L
Error for Measurement is: $\pm$ 1.0 pCi/L

Test Start : 10/19/2021 @ 06:40
Test Stop : 10/21/2021 @ 06:47
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 15:09

Canister ID# : 2815951
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Work Rm
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:23
Test Stop : 10/21/2021 @ 06:37
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:52

Canister ID# : 2817993
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Comp. Rm. Off.2
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:21
Test Stop : 10/21/2021 @ 06:37
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:22

Canister ID# : 2818003
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 22
Radon Level : 28.2 pCi/L
Error for Measurement is: $\pm$ 0.9 pCi/L

Test Start : 10/19/2021 @ 06:41
Test Stop : 10/21/2021 @ 06:48
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 14:35

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# : 2913339
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 14
Radon Level : 1.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:37
Test Stop : 10/21/2021 @ 06:48
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 14:22

Canister ID# : 2913341
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Stage DP
Radon Level : 1.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:41
Test Stop : 10/21/2021 @ 06:50
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 16:15

Canister ID# : 2913344
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Ctr. Desk
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:04
Test Stop : 10/21/2021 @ 06:31
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:35

Canister ID# : 2913345
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Computer Rm
Radon Level : 1.1 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:17
Test Stop : 10/21/2021 @ 06:36
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:21

Canister ID# : 2913377
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 15
Radon Level : 1.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:30
Test Stop : 10/21/2021 @ 06:46
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 16:28

Canister ID# : 2913378
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 4 DP
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 10/19/2021 @ 06:18
Test Stop : 10/21/2021 @ 06:38
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:27



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2913380	Test Start :	10/19/2021 @ 05:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:29
Location :	1st FL=Gym West Wall	Received:	10/25/2021 @ 14:42
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 14:21
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2913665	Test Start :	10/19/2021 @ 05:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:29
Location :	1st FL=Cafeteria DP	Received:	10/25/2021 @ 14:41
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 14:22
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2913673	Test Start :	10/19/2021 @ 06:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:40
Location :	1st FL = Room 17	Received:	10/25/2021 @ 14:41
Radon Level :	1.7 pCi/L	Analyzed:	10/26/2021 @ 15:11
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2913707	Test Start :	10/19/2021 @ 06:00
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:30
Location :	1st FL=Rm 20 East Cnt.	Received:	10/25/2021 @ 14:41
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 14:37
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2913708	Test Start :	10/19/2021 @ 06:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:35
Location :	1st FL=Gym North Wall	Received:	10/25/2021 @ 14:42
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 16:14
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2913758	Test Start :	10/19/2021 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:45
Location :	1st FL=Rm 13 S. Cnt. DP	Received:	10/25/2021 @ 14:42
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 16:37
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# : 2916013
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Gym N. Wall BL
Radon Level : 0.1 pCi/L
Error for Measurement is: $\pm$ No Result

Test Start : 10/19/2021 @ 06:11
Test Stop : 10/21/2021 @ 06:35
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 15:09

Canister ID# : 2916014
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 1
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:30
Test Stop : 10/21/2021 @ 06:48
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:28

Canister ID# : 2916018
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Music Rm N. DP
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 10/19/2021 @ 06:04
Test Stop : 10/21/2021 @ 06:37
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 15:11

Canister ID# : 2916026
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Gym East Wall
Radon Level : 1.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:09
Test Stop : 10/21/2021 @ 06:33
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 14:55

Canister ID# : 2916029
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 5
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 10/19/2021 @ 06:22
Test Stop : 10/21/2021 @ 06:40
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:28

Canister ID# : 2916036
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 3 Storage
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:28
Test Stop : 10/21/2021 @ 06:44
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:14

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2916040	Test Start :	10/19/2021 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:49
Location :	1st FL=Break Rm	Received:	10/25/2021 @ 14:41
Radon Level :	0.6 pCi/L	Analyzed:	10/26/2021 @ 15:11
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2916043	Test Start :	10/19/2021 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:45
Location :	1st FL=Rm 13 S. Cnt. DP	Received:	10/25/2021 @ 14:42
Radon Level :	1.1 pCi/L	Analyzed:	10/26/2021 @ 14:38
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2916055	Test Start :	10/19/2021 @ 06:08
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:38
Location :	1st FL=Rm 9 East Wall	Received:	10/25/2021 @ 14:42
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 14:38
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2916942	Test Start :	10/19/2021 @ 06:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:33
Location :	1st FL=Rm 21 East Cnt.	Received:	10/25/2021 @ 14:42
Radon Level :	1.3 pCi/L	Analyzed:	10/26/2021 @ 14:55
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2916962	Test Start :	10/19/2021 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:36
Location :	1st FL = Room 7 BL	Received:	10/25/2021 @ 14:41
Radon Level :	0.4 pCi/L	Analyzed:	10/26/2021 @ 16:37
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2917594	Test Start :	10/19/2021 @ 06:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:40
Location :	1st FL = Room 17 BL	Received:	10/25/2021 @ 14:41
Radon Level :	0.3 pCi/L	Analyzed:	10/26/2021 @ 14:39
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# : 2917604
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Gym South Wall
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 10/19/2021 @ 06:03
Test Stop : 10/21/2021 @ 06:31
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 16:37

Canister ID# : 2917610
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 19 DP
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 10/19/2021 @ 06:33
Test Stop : 10/21/2021 @ 06:42
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:21

Canister ID# : 2917634
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 16
Radon Level : 1.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:26
Test Stop : 10/21/2021 @ 06:39
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:52

Canister ID# : 2917644
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Ctr. Off.2
Radon Level : 1.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 10/19/2021 @ 06:12
Test Stop : 10/21/2021 @ 06:33
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:03

Canister ID# : 2918204
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Stage DP
Radon Level : 1.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:41
Test Stop : 10/21/2021 @ 06:50
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 16:15

Canister ID# : 2918240
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 7
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:14
Test Stop : 10/21/2021 @ 06:35
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:28

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# : 2918250
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 2
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:25
Test Stop : 10/21/2021 @ 06:42
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:27

Canister ID# : 2918256
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 8
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:13
Test Stop : 10/21/2021 @ 06:40
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 14:39

Canister ID# : 2918257
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Ctr. Off.3
Radon Level : 1.5 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 10/19/2021 @ 06:14
Test Stop : 10/21/2021 @ 06:34
Received: 10/25/2021 @ 14:41
Analyzed: 10/27/2021 @ 08:44

Canister ID# : 2918266
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Ctr. Shelf
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 10/19/2021 @ 06:07
Test Stop : 10/21/2021 @ 06:32
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 14:21

Canister ID# : 2918267
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Room 11
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 06:16
Test Stop : 10/21/2021 @ 06:41
Received: 10/25/2021 @ 14:42
Analyzed: 10/26/2021 @ 14:38

Canister ID# : 2918268
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Principal's Office
Radon Level : 1.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 10/19/2021 @ 05:59
Test Stop : 10/21/2021 @ 06:29
Received: 10/25/2021 @ 14:41
Analyzed: 10/26/2021 @ 16:14



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2918277	Test Start :	10/19/2021 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:42
Location :	1st FL = Room 19 DP	Received:	10/25/2021 @ 14:41
Radon Level :	1.1 pCi/L	Analyzed:	10/26/2021 @ 16:37
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2918280	Test Start :	10/19/2021 @ 06:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:37
Location :	1st FL=Music Rm N. DP	Received:	10/25/2021 @ 14:42
Radon Level :	1.2 pCi/L	Analyzed:	10/26/2021 @ 14:35
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2918281	Test Start :	10/19/2021 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:43
Location :	1st FL = Room 12	Received:	10/25/2021 @ 14:42
Radon Level :	0.8 pCi/L	Analyzed:	10/26/2021 @ 16:50
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2918283	Test Start :	10/19/2021 @ 05:59
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:29
Location :	1st FL=Cafeteria DP	Received:	10/25/2021 @ 14:41
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 14:35
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2918287	Test Start :	10/19/2021 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:43
Location :	1st FL = Room 3	Received:	10/25/2021 @ 14:41
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 15:11
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2918288	Test Start :	10/19/2021 @ 06:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:41
Location :	1st FL = Room 18	Received:	10/25/2021 @ 14:41
Radon Level :	0.9 pCi/L	Analyzed:	10/26/2021 @ 16:27
Error for Measurement is: ±	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2918298	Test Start :	10/19/2021 @ 06:02
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:30
Location :	1st FL=Health Office	Received:	10/25/2021 @ 14:41
Radon Level :	0.8 pCi/L	Analyzed:	10/26/2021 @ 16:27
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2918300	Test Start :	10/19/2021 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:38
Location :	1st FL = Room 4 DP	Received:	10/25/2021 @ 14:41
Radon Level :	0.8 pCi/L	Analyzed:	10/26/2021 @ 14:39
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2918301	Test Start :	10/19/2021 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:42
Location :	1st FL = Room 10	Received:	10/25/2021 @ 14:42
Radon Level :	0.7 pCi/L	Analyzed:	10/26/2021 @ 14:52
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2918302	Test Start :	10/19/2021 @ 06:09
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:32
Location :	1st FL=Media Ctr. Off. 1	Received:	10/25/2021 @ 14:41
Radon Level :	1.3 pCi/L	Analyzed:	10/26/2021 @ 14:22
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2918304	Test Start :	10/19/2021 @ 05:57
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:28
Location :	1st FL=Main Office	Received:	10/25/2021 @ 14:41
Radon Level :	1.1 pCi/L	Analyzed:	10/26/2021 @ 14:39
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2918305	Test Start :	10/19/2021 @ 06:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:31
Location :	1st FL=Staff Work Rm	Received:	10/25/2021 @ 14:41
Radon Level :	1.0 pCi/L	Analyzed:	10/26/2021 @ 16:14
Error for Measurement is: $\pm$	0.5 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 10/25/2021

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
815 South Oakdale Avenue
Medford, OR 97501-

Client: Jacksonville Elementary School
Test Location: 655 Hueners Lane
Jacksonville, OR 97530-

Individual Canister Results

Canister ID# :	2918308	Test Start :	10/19/2021 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	10/21/2021 @ 06:35
Location :	1st FL=Media Ctr. Off.4	Received:	10/25/2021 @ 14:41
Radon Level :	1.3 pCi/L	Analyzed:	10/26/2021 @ 15:09
Error for Measurement is: $\pm$	0.5 pCi/L		

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201