EXISTING SITE & BUILDING ASSESSMENT

- FINISH FLOOR ELEVATION ARE TOO LOW
- SITE DRAINS TO THE SOUTHEAST
- STRUCTURAL CHANGES WOULD BE DIFFICULT DUE TO FOUNDATION
- MECHANICAL SYSTEMS ARE AT THE END OF ESTIMATED MEDIAN SERVICE LIFE
- KITCHEN IS TOO SMALL & EQUIPMENT IS DUE FOR REPLACEMENT









SITE WORKSHOP



GROUP 1



GROUP 2



GROUP 3

PREFERRED OPTIONS



PUEBLO ELEMENTARY
GROUP 1 OVERALL SITE PLAN

bws ARCHITECTS



PUEBLO ELEMENTARY
GROUP 2 OVERALL SITE PLAN

bws ARCHITECTS



PUEBLO ELEMENTARY
GROUP 3 OVERALL SITE PLAN


bws ARCHITECTS



PUEBLO ELEMENTARY
OPTION 4 OVERALL SITE PLAN

bws ARCHITECTS






PUEBLO ELEMENTARY
OVERALL SITE PLANS

bws ARCHITECTS

LET'S HEAR FROM YOU



DO YOU LIKE THE DIRECTION THE PROJECT IS HEADING?


2022
2023
A S O N D J F M A M J J A S O N D J F M A M J J A
DESIGN + CONSTRUCTION
SCHEMATIC DESIGN
DESIGN DEVELOPMENT
CONSTRUCTION DOCUMENTS
PERMITTING + GMP
PERMITTING
CONSTRUCTION
CONSTRUCTION
OWNER FIT

SCHEDULE

QUESTIONS & WRAP-UP



THANK YOU