

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2990198
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 27
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:08
Test Stop : 03/07/2024 @ 06:41
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:40

Canister ID# : 2990171
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 29
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:10
Test Stop : 03/07/2024 @ 06:42
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:37

Canister ID# : 2987411
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Main Office
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:12
Test Stop : 03/07/2024 @ 06:40
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:16

Canister ID# : 2990177
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 31
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:12
Test Stop : 03/07/2024 @ 06:43
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:10

Canister ID# : 2990180
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 22
Radon Level : 1.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:13
Test Stop : 03/07/2024 @ 06:40
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:05

Canister ID# : 2989188
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Principal's Office
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:14
Test Stop : 03/07/2024 @ 06:41
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 09:28



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990189	Test Start :	03/05/2024 @ 06:14
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:48
Location :	1st FL=Room 33	Received:	03/11/2024 @ 10:15
Radon Level :	0.5 pCi/L	Analyzed:	03/12/2024 @ 09:31
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2987410	Test Start :	03/05/2024 @ 06:15
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:41
Location :	1st FL=Health Rm	Received:	03/11/2024 @ 10:15
Radon Level :	0.6 pCi/L	Analyzed:	03/11/2024 @ 13:37
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990225	Test Start :	03/05/2024 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:42
Location :	1st FL=Room 20 DP	Received:	03/11/2024 @ 10:15
Radon Level :	1.3 pCi/L	Analyzed:	03/12/2024 @ 09:28
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2990501	Test Start :	03/05/2024 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:42
Location :	1st FL=Room 20 DP	Received:	03/11/2024 @ 10:15
Radon Level :	1.5 pCi/L	Analyzed:	03/12/2024 @ 09:31

Average of Side by Side Canisters 1.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990197	Test Start :	03/05/2024 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:48
Location :	1st FL=Room 33 BL	Received:	03/11/2024 @ 10:15
Radon Level :	0.5 pCi/L	Analyzed:	03/11/2024 @ 12:01
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2990208	Test Start :	03/05/2024 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:43
Location :	1st FL=Room 18	Received:	03/11/2024 @ 10:15
Radon Level :	0.8 pCi/L	Analyzed:	03/11/2024 @ 13:37

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2989205
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 07 DP
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/05/2024 @ 06:18
Test Stop : 03/07/2024 @ 06:44
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 10:12

Canister ID# : 2989207
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 07 DP
Radon Level : 0.6 pCi/L

Test Start : 03/05/2024 @ 06:18
Test Stop : 03/07/2024 @ 06:44
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 10:12

Average of Side by Side Canisters 0.5 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2990223
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 34
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:18
Test Stop : 03/07/2024 @ 06:49
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 09:31

Canister ID# : 2990204
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 17
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/05/2024 @ 06:19
Test Stop : 03/07/2024 @ 06:44
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:02

Canister ID# : 2990196
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 09
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/05/2024 @ 06:20
Test Stop : 03/07/2024 @ 06:45
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 09:31

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990494	Test Start :	03/05/2024 @ 06:20
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:45
Location :	1st FL=Room 19	Received:	03/11/2024 @ 10:15
Radon Level :	1.2 pCi/L	Analyzed:	03/11/2024 @ 13:37
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990207	Test Start :	03/05/2024 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:46
Location :	1st FL=Room 11	Received:	03/11/2024 @ 10:15
Radon Level :	0.1 pCi/L	Analyzed:	03/12/2024 @ 09:53
Error for Measurement is: ±	0.8 pCi/L		

Canister ID# :	2990219	Test Start :	03/05/2024 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:47
Location :	1st FL=Stage	Received:	03/11/2024 @ 10:15
Radon Level :	0.5 pCi/L	Analyzed:	03/11/2024 @ 12:01
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	2990229	Test Start :	03/05/2024 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:50
Location :	1st FL=Room 35	Received:	03/11/2024 @ 10:15
Radon Level :	0.6 pCi/L	Analyzed:	03/12/2024 @ 15:24
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990188	Test Start :	03/05/2024 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:47
Location :	1st FL=Room 13	Received:	03/11/2024 @ 10:15
Radon Level :	0.1 pCi/L	Analyzed:	03/11/2024 @ 11:40
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	2990481	Test Start :	03/05/2024 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:52
Location :	1st FL=Modular 1 DP	Received:	03/11/2024 @ 10:15
Radon Level :	0.4 pCi/L	Analyzed:	03/11/2024 @ 11:18
Error for Measurement is: ±	0.4 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990493	Test Start :	03/05/2024 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:52
Location :	1st FL=Modular 1 DP	Received:	03/11/2024 @ 10:15
Radon Level :	0.5 pCi/L	Analyzed:	03/11/2024 @ 11:16

Average of Side by Side Canisters 0.5 pCi/L

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	2990183	Test Start :	03/05/2024 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:48
Location :	1st FL=Gym 1	Received:	03/11/2024 @ 10:15
Radon Level :	1.4 pCi/L	Analyzed:	03/11/2024 @ 12:10

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	2990170	Test Start :	03/05/2024 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:49
Location :	1st FL=Room 12	Received:	03/11/2024 @ 10:15
Radon Level :	0.7 pCi/L	Analyzed:	03/12/2024 @ 09:52

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990487	Test Start :	03/05/2024 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:53
Location :	1st FL=Modular 2	Received:	03/11/2024 @ 10:15
Radon Level :	0.5 pCi/L	Analyzed:	03/11/2024 @ 11:40

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990162	Test Start :	03/05/2024 @ 06:27
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:54
Location :	1st FL=Modular 3	Received:	03/11/2024 @ 10:15
Radon Level :	0.7 pCi/L	Analyzed:	03/11/2024 @ 11:37

Error for Measurement is: $\pm$ 0.3 pCi/L

Canister ID# :	2990211	Test Start :	03/05/2024 @ 06:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:55
Location :	1st FL=Modular 4	Received:	03/11/2024 @ 10:15
Radon Level :	0.3 pCi/L	Analyzed:	03/11/2024 @ 12:29

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2990232
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Gym 2
Radon Level : 1.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/05/2024 @ 06:29
Test Stop : 03/07/2024 @ 06:49
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 09:52

Canister ID# : 2989288
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 10
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:29
Test Stop : 03/07/2024 @ 06:50
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:19

Canister ID# : 2990503
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 10 BL
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:29
Test Stop : 03/07/2024 @ 06:50
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:21

Canister ID# : 2990222
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Gym 3
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:30
Test Stop : 03/07/2024 @ 06:50
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:02

Canister ID# : 2990490
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Modular 5
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:30
Test Stop : 03/07/2024 @ 06:56
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:40

Canister ID# : 2990156
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Modular 5 BL
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:30
Test Stop : 03/07/2024 @ 06:56
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:19

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2990185
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Gym 4
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:31
Test Stop : 03/07/2024 @ 06:51
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:10

Canister ID# : 2990486
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Modular 6
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:32
Test Stop : 03/07/2024 @ 06:57
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 10:07

Canister ID# : 2990064
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 06
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 03/05/2024 @ 06:33
Test Stop : 03/07/2024 @ 09:52
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:21

Canister ID# : 2990220
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Staff Work Rm
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:35
Test Stop : 03/07/2024 @ 06:52
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:10

Canister ID# : 2990500
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Staff Work Rm 3
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:36
Test Stop : 03/07/2024 @ 06:52
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:16

Canister ID# : 2987479
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 14
Radon Level : 1.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:36
Test Stop : 03/07/2024 @ 06:55
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:40

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# : 2990492
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 32
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.3 pCi/L

Test Start : 03/05/2024 @ 06:36
Test Stop : 03/07/2024 @ 06:57
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:05

Canister ID# : 2990165
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Cafeteria 1
Radon Level : 0.6 pCi/L
FOUND ON FLOOR UPSIDE DOWN

Test Start : 03/05/2024 @ 06:38
Test Stop : 03/07/2024 @ 06:53
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:07

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2990209
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 30 DP
Radon Level : 0.4 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:38
Test Stop : 03/07/2024 @ 06:58
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:01

Canister ID# : 2990224
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 30 DP
Radon Level : 0.5 pCi/L

Test Start : 03/05/2024 @ 06:38
Test Stop : 03/07/2024 @ 06:58
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 10:10

Average of Side by Side Canisters 0.5 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 2989273
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Media Ctr. 1
Radon Level : 1.7 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:39
Test Stop : 03/07/2024 @ 06:56
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:18

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2987472	Test Start :	03/05/2024 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:57
Location :	1st FL=Media Ctr. 2	Received:	03/11/2024 @ 10:15
Radon Level :	1.5 pCi/L	Analyzed:	03/12/2024 @ 10:07
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990234	Test Start :	03/05/2024 @ 06:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:54
Location :	1st FL=Cafeteria 2	Received:	03/11/2024 @ 10:15
Radon Level :	0.4 pCi/L	Analyzed:	03/12/2024 @ 10:12
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2989232	Test Start :	03/05/2024 @ 06:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:59
Location :	1st FL=Room 21	Received:	03/11/2024 @ 10:15
Radon Level :	1.4 pCi/L	Analyzed:	03/12/2024 @ 09:33
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990166	Test Start :	03/05/2024 @ 06:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 07:00
Location :	1st FL=Room 28	Received:	03/11/2024 @ 10:15
Radon Level :	0.4 pCi/L	Analyzed:	03/12/2024 @ 10:12
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990161	Test Start :	03/05/2024 @ 06:43
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:56
Location :	1st FL=Staff Break Rm DP	Received:	03/11/2024 @ 10:15
Radon Level :	0.9 pCi/L	Analyzed:	03/12/2024 @ 09:52
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990226	Test Start :	03/05/2024 @ 06:43
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 06:56
Location :	1st FL=Staff Break Rm DP	Received:	03/11/2024 @ 10:15
Radon Level :	0.9 pCi/L	Analyzed:	03/11/2024 @ 11:18

Average of Side by Side Canisters 0.9 pCi/L

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# : 2990182
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 23
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:43
Test Stop : 03/07/2024 @ 07:00
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 10:12

Canister ID# : 2990184
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 26
Radon Level : 1.5 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:43
Test Stop : 03/07/2024 @ 07:02
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:18

Canister ID# : 2990178
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Custodian Off.
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/05/2024 @ 06:45
Test Stop : 03/07/2024 @ 06:57
Received: 03/11/2024 @ 10:15
Analyzed: 03/12/2024 @ 09:53

Canister ID# : 2989218
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 25
Radon Level : 0.9 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:45
Test Stop : 03/07/2024 @ 07:01
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 13:37

Canister ID# : 2990164
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 24
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/05/2024 @ 06:45
Test Stop : 03/07/2024 @ 07:03
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 11:37

Canister ID# : 2987362
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Room 41
Radon Level : 19.9 pCi/L
Error for Measurement is: $\pm$ 0.7 pCi/L

Test Start : 03/05/2024 @ 06:46
Test Stop : 03/07/2024 @ 06:59
Received: 03/11/2024 @ 10:15
Analyzed: 03/11/2024 @ 12:07

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/11/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: Jefferson E.S.
Test Location: 333 Holmes Avenue
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2987498	Test Start :	03/05/2024 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/07/2024 @ 07:00
Location :	1st FL=Room 42	Received:	03/11/2024 @ 10:15
Radon Level :	20.2 pCi/L	Analyzed:	03/12/2024 @ 09:53
Error for Measurement is: $\pm$	0.8 pCi/L		

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201