

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990174	Test Start :	03/18/2024 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:16
Location :	1st FL = Main Off. DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 11:42
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990199	Test Start :	03/18/2024 @ 06:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:16
Location :	1st FL = Main Off. DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 11:59

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: ± 0.6 pCi/L

Canister ID# :	2990482	Test Start :	03/18/2024 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:36
Location :	1st FL = Band Rm. 1	Received:	03/26/2024 @ 10:04
Radon Level :	0.3 pCi/L	Analyzed:	03/26/2024 @ 10:39
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990200	Test Start :	03/18/2024 @ 06:17
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:37
Location :	1st FL = Band Rm. 2	Received:	03/26/2024 @ 10:04
Radon Level :	0.9 pCi/L	Analyzed:	03/26/2024 @ 14:39
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990146	Test Start :	03/18/2024 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:20
Location :	1st FL = Rm. 107 DP	Received:	03/26/2024 @ 10:04
Radon Level :	1.4 pCi/L	Analyzed:	03/28/2024 @ 11:59
Error for Measurement is: ±	0.8 pCi/L		

Canister ID# :	2990491	Test Start :	03/18/2024 @ 06:18
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:20
Location :	1st FL = Rm. 107 DP	Received:	03/26/2024 @ 10:04
Radon Level :	1.1 pCi/L	Analyzed:	03/26/2024 @ 10:41

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist

NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Average of Side by Side Canisters 1.3 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 2990236
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Band Rm. Off.B
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.4 pCi/L

Test Start : 03/18/2024 @ 06:19
Test Stop : 03/20/2024 @ 06:37
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:39

Canister ID# : 2990483
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Band Rm. Off.A
Radon Level : 1.3 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:19
Test Stop : 03/20/2024 @ 06:38
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 13:15

Canister ID# : 2990210
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Health Rm
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:20
Test Stop : 03/20/2024 @ 06:20
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:41

Canister ID# : 2990213
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = NTS Off.
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:20
Test Stop : 03/20/2024 @ 06:21
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 13:12

Canister ID# : 2990150
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Asst. Principal
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:22
Test Stop : 03/20/2024 @ 06:22
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 11:42

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990203	Test Start :	03/18/2024 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:22
Location :	1st FL = Conf. Rm. A	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 10:40
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2990154	Test Start :	03/18/2024 @ 06:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:23
Location :	1st FL = Rm. 108	Received:	03/26/2024 @ 10:04
Radon Level :	0.3 pCi/L	Analyzed:	03/26/2024 @ 11:22
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990167	Test Start :	03/18/2024 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:23
Location :	1st FL = Conf. Rm. B	Received:	03/26/2024 @ 10:04
Radon Level :	0.4 pCi/L	Analyzed:	03/26/2024 @ 11:42
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990173	Test Start :	03/18/2024 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:23
Location :	1st FL = Rm. 108 BL	Received:	03/26/2024 @ 10:04
Radon Level :	0.8 pCi/L	Analyzed:	03/26/2024 @ 11:06
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2989213	Test Start :	03/18/2024 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:23
Location :	1st FL = SRO/Tech.	Received:	03/26/2024 @ 10:04
Radon Level :	0.3 pCi/L	Analyzed:	03/26/2024 @ 11:59
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	4883560	Test Start :	03/18/2024 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:39
Location :	1st FL = Rm. 110 DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 11:22
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	4883595	Test Start :	03/18/2024 @ 06:23
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:39
Location :	1st FL = Rm. 110 DP	Received:	03/26/2024 @ 10:04
Radon Level :	1.2 pCi/L	Analyzed:	03/26/2024 @ 11:55

Average of Side by Side Canisters 0.9 pCi/L

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	4883599	Test Start :	03/18/2024 @ 06:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:40
Location :	1st FL = Rm. 110 Off.	Received:	03/26/2024 @ 10:04
Radon Level :	0.8 pCi/L	Analyzed:	03/26/2024 @ 11:57

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990504	Test Start :	03/18/2024 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:25
Location :	1st FL = Cafeteria 2	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 10:41

Error for Measurement is: $\pm$ 0.4 pCi/L

Canister ID# :	2990488	Test Start :	03/18/2024 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:25
Location :	1st FL = Counselor Off.	Received:	03/26/2024 @ 10:04
Radon Level :	1.0 pCi/L	Analyzed:	03/26/2024 @ 11:55

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990214	Test Start :	03/18/2024 @ 06:25
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:25
Location :	1st FL = Principal's Off.	Received:	03/26/2024 @ 10:04
Radon Level :	0.9 pCi/L	Analyzed:	03/26/2024 @ 14:21

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990217	Test Start :	03/18/2024 @ 06:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:26
Location :	1st FL = Cafeteria 3	Received:	03/26/2024 @ 10:04
Radon Level :	1.0 pCi/L	Analyzed:	03/26/2024 @ 10:46

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 2990160
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Off. Mgr. Off.
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:26
Test Stop : 03/20/2024 @ 06:26
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:41

Canister ID# : 2990149
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm. 111
Radon Level : 0.1 pCi/L
Error for Measurement is: $\pm$ 0.2 pCi/L

Test Start : 03/18/2024 @ 06:26
Test Stop : 03/20/2024 @ 06:42
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:39

Canister ID# : 4883592
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm. 111 BL
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:26
Test Stop : 03/20/2024 @ 06:42
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 13:12

Canister ID# : 2990158
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Vice Princ. Off.
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:27
Test Stop : 03/20/2024 @ 06:27
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 13:15

Canister ID# : 2990168
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Main Conf. Rm
Radon Level : 1.0 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:28
Test Stop : 03/20/2024 @ 06:28
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 11:04

Canister ID# : 2990195
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm. 112
Radon Level : 0.5 pCi/L
Error for Measurement is: $\pm$ 0.7 pCi/L

Test Start : 03/18/2024 @ 06:28
Test Stop : 03/20/2024 @ 06:43
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 12:01

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990499	Test Start :	03/18/2024 @ 06:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:29
Location :	1st FL = Dean 1	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 10:39
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990761	Test Start :	03/18/2024 @ 06:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:30
Location :	1st FL = SRO	Received:	03/26/2024 @ 10:04
Radon Level :	0.7 pCi/L	Analyzed:	03/26/2024 @ 12:01
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990172	Test Start :	03/18/2024 @ 06:29
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:44
Location :	1st FL = Rm. 113	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 11:20
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990228	Test Start :	03/18/2024 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:32
Location :	1st FL = Rm. 100	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 14:21
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990186	Test Start :	03/18/2024 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:32
Location :	1st FL = Rm. 100 BL	Received:	03/26/2024 @ 10:04
Radon Level :	0.1 pCi/L	Analyzed:	03/26/2024 @ 11:34
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990235	Test Start :	03/18/2024 @ 06:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:46
Location :	1st FL = Lrg.Group Rm.1	Received:	03/26/2024 @ 10:04
Radon Level :	0.1 pCi/L	Analyzed:	03/26/2024 @ 11:42
Error for Measurement is: ±	0.9 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990233	Test Start :	03/18/2024 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:37
Location :	1st FL = Gold Gym 1	Received:	03/26/2024 @ 10:04
Radon Level :	1.4 pCi/L	Analyzed:	03/26/2024 @ 14:41
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990484	Test Start :	03/18/2024 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:37
Location :	1st FL = Gold Gym 2	Received:	03/26/2024 @ 10:04
Radon Level :	0.9 pCi/L	Analyzed:	03/26/2024 @ 11:18
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990191	Test Start :	03/18/2024 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:47
Location :	1st FL=Lrg.Grp. Rm.2 DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 12:01
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2990201	Test Start :	03/18/2024 @ 06:33
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:47
Location :	1st FL=Lrg.Grp. Rm.2 DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 11:39

Average of Side by Side Canisters 0.5 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# :	2990163	Test Start :	03/18/2024 @ 06:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:36
Location :	1st FL = Rm. 102	Received:	03/26/2024 @ 10:04
Radon Level :	0.2 pCi/L	Analyzed:	03/26/2024 @ 11:43
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990495	Test Start :	03/18/2024 @ 06:35
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:37
Location :	1st FL = Gold Gym 3	Received:	03/26/2024 @ 10:04
Radon Level :	1.4 pCi/L	Analyzed:	03/26/2024 @ 13:12

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 2990152
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Gold Gym 4
Radon Level : 1.2 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:35
Test Stop : 03/20/2024 @ 06:38
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 14:39

Canister ID# : 2990175
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Staff Mgt. Off.
Radon Level : 0.2 pCi/L
Error for Measurement is: $\pm$ 0.7 pCi/L

Test Start : 03/18/2024 @ 06:35
Test Stop : 03/20/2024 @ 06:50
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 11:59

Canister ID# : 2990194
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm. 101
Radon Level : 0.1 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:36
Test Stop : 03/20/2024 @ 06:36
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 12:01

Canister ID# : 2990218
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Student Mgt.Rm.
Radon Level : 2.2 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:36
Test Stop : 03/20/2024 @ 06:49
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:46

Canister ID# : 4883617
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Staff Work Rm
Radon Level : 0.6 pCi/L
Error for Measurement is: $\pm$ 0.7 pCi/L

Test Start : 03/18/2024 @ 06:37
Test Stop : 03/20/2024 @ 06:51
Received: 03/26/2024 @ 10:04
Analyzed: 03/28/2024 @ 11:59

Canister ID# : 2990159
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Weight Rm
Radon Level : 2.2 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:38
Test Stop : 03/20/2024 @ 06:41
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:40

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990176	Test Start :	03/18/2024 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:39
Location :	1st FL = Rm. 103 DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.3 pCi/L	Analyzed:	03/26/2024 @ 11:43
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990480	Test Start :	03/18/2024 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:39
Location :	1st FL = Rm. 103 DP	Received:	03/26/2024 @ 10:04
Radon Level :	0.9 pCi/L	Analyzed:	03/26/2024 @ 11:57

Average of Side by Side Canisters 0.6 pCi/L

Error for Measurement is: ± 0.5 pCi/L

Canister ID# :	2990202	Test Start :	03/18/2024 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:51
Location :	1st FL = Staff Library	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 13:12
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	4883520	Test Start :	03/18/2024 @ 06:39
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:52
Location :	1st FL = Custodial Off.	Received:	03/26/2024 @ 10:04
Radon Level :	0.3 pCi/L	Analyzed:	03/26/2024 @ 14:39
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2987492	Test Start :	03/18/2024 @ 06:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:53
Location :	1st FL = Rm. 120-A	Received:	03/26/2024 @ 10:04
Radon Level :	26.4 pCi/L	Analyzed:	03/26/2024 @ 11:06
Error for Measurement is: ±	1.0 pCi/L		

Canister ID# :	2990231	Test Start :	03/18/2024 @ 06:41
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:41
Location :	1st FL = Rm. 104	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 11:39

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Error for Measurement is: $\pm$ 0.5 pCi/L

Canister ID# : 2990505
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Black Gym 1
Radon Level : 0.3 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:41
Test Stop : 03/20/2024 @ 06:44
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 11:18

Canister ID# : 2987471
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm. 120-B
Radon Level : 26.5 pCi/L
Error for Measurement is: $\pm$ 1.1 pCi/L

Test Start : 03/18/2024 @ 06:41
Test Stop : 03/20/2024 @ 06:54
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:40

Canister ID# : 2990212
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Black Gym 2
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:42
Test Stop : 03/20/2024 @ 06:44
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 14:39

Canister ID# : 2990153
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Black Gym 3
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.6 pCi/L

Test Start : 03/18/2024 @ 06:43
Test Stop : 03/20/2024 @ 06:44
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 11:24

Canister ID# : 2990206
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Black Gym 4
Radon Level : 0.7 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:43
Test Stop : 03/20/2024 @ 06:44
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 10:59

Canister ID# : 2990181
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Rm. 105
Radon Level : 0.8 pCi/L
Error for Measurement is: $\pm$ 0.5 pCi/L

Test Start : 03/18/2024 @ 06:44
Test Stop : 03/20/2024 @ 06:44
Received: 03/26/2024 @ 10:04
Analyzed: 03/26/2024 @ 13:10

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	4883591	Test Start :	03/18/2024 @ 06:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:54
Location :	Bsmt = South End	Received:	03/26/2024 @ 10:04
Radon Level :	0.7 pCi/L	Analyzed:	03/26/2024 @ 11:24
Error for Measurement is: $\pm$	0.7 pCi/L		

Canister ID# :	4883505	Test Start :	03/18/2024 @ 06:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:55
Location :	Bsmt = North End	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 11:34
Error for Measurement is: $\pm$	0.4 pCi/L		

Canister ID# :	2990496	Test Start :	03/18/2024 @ 06:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:46
Location :	1st FL = Media Ctr. 1	Received:	03/26/2024 @ 10:04
Radon Level :	0.7 pCi/L	Analyzed:	03/26/2024 @ 11:59
Error for Measurement is: $\pm$	0.6 pCi/L		

Canister ID# :	2990187	Test Start :	03/18/2024 @ 06:46
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:46
Location :	1st FL = Media Ctr. 2	Received:	03/26/2024 @ 10:04
Radon Level :	0.2 pCi/L	Analyzed:	03/26/2024 @ 11:37
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990216	Test Start :	03/18/2024 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:47
Location :	1st FL = Media Ctr. Off.A	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 14:43
Error for Measurement is: $\pm$	0.5 pCi/L		

Canister ID# :	2990227	Test Start :	03/18/2024 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:49
Location :	1st FL = Wrestling Rm. 1	Received:	03/26/2024 @ 10:04
Radon Level :	0.4 pCi/L	Analyzed:	03/26/2024 @ 11:06
Error for Measurement is: $\pm$	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

Canister ID# :	2990230	Test Start :	03/18/2024 @ 06:47
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:49
Location :	1st FL = Wrestling Rm. 2	Received:	03/26/2024 @ 10:04
Radon Level :	1.0 pCi/L	Analyzed:	03/26/2024 @ 14:43
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990190	Test Start :	03/18/2024 @ 06:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:48
Location :	1st FL = Media Ctr. Off. B	Received:	03/26/2024 @ 10:04
Radon Level :	0.5 pCi/L	Analyzed:	03/26/2024 @ 11:20
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990489	Test Start :	03/18/2024 @ 06:48
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:49
Location :	1st FL = Wrestling Rm.	Received:	03/26/2024 @ 10:04
Radon Level :	1.1 pCi/L	Analyzed:	03/26/2024 @ 10:46
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	2990498	Test Start :	03/18/2024 @ 06:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:49
Location :	1st FL = Media Ctr. Video	Received:	03/26/2024 @ 10:04
Radon Level :	0.6 pCi/L	Analyzed:	03/26/2024 @ 14:41
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990179	Test Start :	03/18/2024 @ 06:51
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:54
Location :	1st FL = Staff Break Rm	Received:	03/26/2024 @ 10:04
Radon Level :	0.7 pCi/L	Analyzed:	03/26/2024 @ 10:59
Error for Measurement is: ±	0.5 pCi/L		

Canister ID# :	2990192	Test Start :	03/18/2024 @ 06:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/20/2024 @ 06:54
Location :	1st FL = Rm. 106	Received:	03/26/2024 @ 10:04
Radon Level :	0.3 pCi/L	Analyzed:	03/26/2024 @ 11:06
Error for Measurement is: ±	0.6 pCi/L		

*Andreas C. George*

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

Site Radon Inspection Report

Date : 03/26/2024

Mr. Seth Barry
MEDFORD SCHOOL DISTRICT
900 Kenyon Street
Medford, OR 97501-

Client: McLoughlin M.S.
Test Location: 320 West 2nd Street
Medford, OR 97501-

Individual Canister Results

The results indicate that at least one testing device registered at or above the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends mitigation if the average of two short-term tests taken in the lowest level of the building suitable for occupancy show radon levels that are equal to or greater than 4.0 pCi/L.

For information on how to reduce radon levels in your home, please review the EPA booklet: Consumer's Guide to Radon Reduction (www.epa.gov/radon/pdfs/consguid.pdf) and contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free 1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability, collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or its consultants based on RTCA-provided results.



Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201