Lead in School Drinking Water Report

Stanwood Elementary School

Date(s) collected: 2024-05-01
Date(s) analyzed: 2024-05-14

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
391705	Main Building	Sink	Speech	1 of 1	Tap	center	46
391699	Main Building	Sink	Rm19	1 of 1	Tap	center	39
391206	Main Building	Sink	Rm26	1 of 1	Tap	center	30
391198	Main Building	Sink	Rm16	1 of 1	Tap	center	19
391700	Main Building	Sink	Rm21	1 of 2 lower	Tap	center	18
391202	Main Building	Sink	Rm22	2 of 2 higher	Tap	center	15
391706	Main Building	Sink	Rm27	1 of 1	Tap	center	14
391701	Main Building	Sink	Rm22	1 of 2 lower	Tap	center	13
391205	Main	Sink	Psych	1 of 1	Tap	center	11

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
	Building						
391211	Main Building	Sink	Nurse	1 of 1	Tap	center	11
391697	Main Building	Sink	Behavior	1 of 1	Tap	center	10
391704	Main Building	Sink	Rm23	2 of 2 higher	Tap	center	9
391201	Main Building	Sink	Rm21	2 of 2 higher	Tap	center	8
391710	Main Building	Sink	Rm35	1 of 1	Tap	center	6
391196	Main Building	Sink	Rm12	1 of 1	Tap	center	5
391200	Main Building	Sink	Rm20	1 of 1	Tap	center	5
391711	Main Building	Sink	Kitchen	1 of 1 Food prep	Tap	center	5
391197	Main Building	Sink	Rm14	1 of 1	Tap	center	4
391204	Main Building	Sink	Rm23	1 of 2 lower	Tap	center	4
391708	Main Building	Sink	Rm31	1 of 1	Tap	center	4
391195	Main Building	Sink	Rm10	1 of 1	Tap	center	3
391199	Main Building	Sink	Rm18	1 of 1	Tap	center	3
391209	Main Building	Sink	Rm32	1 of 1	Tap	center	3
391696	Main Building	Sink	Rm13	1 of 1	Tap	center	3
391698	Main Building	Sink	Rm17	1 of 1	Tap	center	3
391208	Main Building	Sink	Rm30	1 of 1	Tap	center	2
391210	Main	Sink	Rm34	1 of 1	Tap	center	2

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
391695	Building Main Building	Sink	Rm11	1 of 1	Tap	center	2
391707	Main Building	Sink	Rm29	1 of 1	Tap	center	2
391709	Main Building	Sink	Rm33	1 of 1	Tap	center	2
391203	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Rm21-23	2 of 2	Water Fountain	right	<1
391207	Main Building	Sink	Rm28	1 of 1	Tap	center	<1
391212	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Outside Gym	1 of 2	Water Fountain	left	<1
391213	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Outside Gym	2 of 2	Water Bottle Filler	right	<1
391702	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Rm21-23	1 of 2	Water Fountain	left	<1
391703	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Rm21-23	2 of 2	Water Bottle Filler	right	<1
391712	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Outside Gym	2 of 2	Water Fountain	right	<1

EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures,

multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: **leadfreekids@doh.wa.gov**