Bradford Elementary

Sample ID	Sample Date	Sample Time	Fixture Type	Cadmium (ppb)	Copper (ppb)	Iron (ppb)	Lead (ppb)	Zinc (ppb)	Location	Action
BRFD1	11/14/2017	6:19 AM	SC-1S	<1.00	109	<0.50	76.3	3420	Backflow Tap 1	Replacing backflow
BRFD2	11/14/2017	6:24 AM	SC-1M	<1.00	175	<0.50	17.1	157	Backflow Tap 2	Replacing backflow
BRFD3	11/14/2017	6:27 AM	DFS	<1.00	462	<0.50	2.40	385	Basement hallway near cafeteria	No Action Taken
BRFD4-L	11/14/2017	6:29 AM	KSF	<1.00	249	<0.50	1.58	234	Kitchen sink	No Action Taken
BRFD4-R	11/14/2017	6:30 AM	KSF	<1.00	434	<0.50	1.24	549	Kitchen sink	No Action Taken
BRFD5	11/14/2017	6:31 AM	TL	<1.00	288	<0.50	<1.00	488	Basement teachers lounge sink	No Action Taken
BRFD6	11/14/2017	6:34 AM	DFS	<1.00	525	<0.50	<1.00	176	West main level hallway	No Action Taken
BRFD7	11/14/2017	6:35 AM	KSF	<1.00	199	<0.50	<1.00	364	Main level Media Center	No Action Taken
BRFD8	11/14/2017	6:36 AM	DFS	<1.00	195	<0.50	<1.00	10.3	Kindegarten vestibule	No Action Taken
BRFD9	11/14/2017	6:37 AM	DFS	<1.00	47.2	<0.50	<1.00	1.38	Main foyer	No Action Taken
BRFD10	11/14/2017	6:38 AM	DFS	<1.00	62.5	<0.50	<1.00	2.16	Main foyer	No Action Taken
BRFD11	11/14/2017	6:39 AM	DFS	<1.00	332	<0.50	<1.00	377	South hallway main level	No Action Taken
SL 15SEC	11/14/2017	6:00AM	M	<1.00	23.9	<0.50	<1.00	22.3	Meter	No Action Taken
SL 45SEC	11/14/2017	6:00AM	M	<1.00	14.8	<0.50	<1.00	14.6	Meter	No Action Taken

Fixture Type: DFS - Drinking Fountain with single faucet, DFD - Drinking Fountain with double faucet, *SC - Service Connection Tap; KS - Kitchen Sink; TL - Teachers Lounge Sink

* Service Coonection Tap is not a point for consumption water