Facilities Liaison Report

October 10, 2024

- We seeded the lower sports fields.



- Weed Guards were installed under the baseball fence.



- Turf Track and Court came out to do Gmax testing on the stadium field and groom it. They added 350#s of rubber infield material. Otherwise no issues reported.

- PVIS locker room and kitchen floor drains were backing up about every two weeks. It was determined there is a large belly in the pipe under the floor that was filled with sludge. We brought a jet/vac company in to break up and remove the sludge. So far no new backups.

- Dustin was able to replace some PVIS drinking fountains. The challenge of it was finding a fountain that had a water supply line shutoff valve that would function, and have a drain line that wasn't collapsed in the floor.

THEN…



NOW…



- On September 26, Athletics had to cancel a soccer game due to excessive mud on the walking path to the lower fields. This occurred from the contractor grading around the old sewer and new pump station. When I reached out to Lobar they said they were not contractually obligated to maintain a driveway in that area after the pump station was installed. It was my contention that the contractor ruined the area by doing adjacent work so they should at least put it back to the condition that it was. There was another soccer game planned for the 27th. With all of the rain, Lobar did not have an excavation crew in to do the work. We called the local quarry and had 73 tons of stone delivered. Pat graded it, in time for that evening's soccer game.

THEN…



NOW…

