



Village of Fairport Harbor

220 Third Street, Fairport Harbor, Ohio 44077

Phone: 440-352-3620

FairportHarbor.org

November 11, 2024

FAIRPORT HARBOR SCH BD
329 VINE STREET
FAIRPORT HARBOR, OH 44077-5741

RE: Notification of Lead Status Unknown (Unknown) Service Line

Service Address:	HARDING HIGH SCHOOL
Account Number:	03-00440-00

Dear Water System Consumer:

The Village of Fairport Harbor is the public water system (PWS) responsible for providing drinking water to this location. This notification is being sent because this home or building has a **lead status unknown** service line. This means that your service line material is unknown and may be lead, galvanized requiring replacement, or a non-lead material. A service line is a pipe that connects the water main to the building.

What Does This Mean?

Under the authority of the Safe Drinking Water Act, the US Environmental Protection Agency (EPA) requires us to notify water consumers who are served by a lead status unknown service line. A lead status unknown service line is where the service line material is not known to be lead, galvanized requiring replacement, or a non-lead service line, and there is no documented evidence supporting the material classification.

What are the Health Effects of Lead?

There is no safe level of lead in drinking water. Exposure to lead in drinking water can cause serious health effects in all age groups, especially pregnant people, infants (both formula-fed and breastfed), and young children. Some of the health effects to infants and children include decreases in IQ and attention span. Lead exposure can also result in new or worsened learning and behavior problems. The children of persons who are exposed to lead before or during pregnancy may be at increased risk of these harmful health effects. Adults have increased risks of heart disease, high blood pressure, and kidney or nervous system problems. Contact your health care provider for more information about your risks.

What Can I Do to Reduce Exposure to Lead if Found in My Drinking Water?

- **Do not boil water to remove lead.** Boiling water will not reduce lead.
- **Flush your tap if it has been unused for 6 or more hours.** Lead levels increase over time as water sits in lead-containing plumbing materials. Regular water usage in your home or building can reduce lead levels in drinking water. When water has not been used for 6

hours or more, homes and buildings served by lead or a galvanized requiring replacement service lines should be flushed until you note a temperature change, then flush for one more minute.

- **Use cold water for cooking, drinking, and preparing baby formula.** Do not cook with, drink, or make baby formula from your hot water tap. Lead dissolves more easily in hot water. Always use cold water and heat if needed.
- **Use an ANSI certified lead filter.** Filters certified to the ANSI/NSF 53 standard for lead removal can be effective at reducing lead levels in water.
- **Regularly clean your faucet aerators.** Over time, particles containing lead can build up on the inside of aerator screens. Cleaning aerators regularly will help eliminate this source of lead.
- **For pregnant persons, infants, and young children.** Some populations such as pregnant persons, infants, and young children may be more at risk from the harmful effects of lead. These populations may consider taking extra precautions if their home is served by a lead or galvanized requiring replacement service line. These extra precautions may include having their drinking water analyzed for lead, using an alternative source of water (such as bottled water), or utilizing a filter certified to ANSI/NSF 53 standard for lead removal.
- **Replace lead containing plumbing fixtures.** Many old faucets, valves and other plumbing fixtures may contain lead. Identify if your building's plumbing fixtures contain lead, and replace them when appropriate.
- **You may wish to have your child's blood tested for lead.** Your local county health department can be reached for additional assistance.
- You may wish to test your water for lead. To request this, contact Village Hall at 440-352-3620 for more information.

What is Village of Fairport Harbor PWS Doing?

Your Source Water Treatment Facility uses an orthophosphate to help keep lead levels in the distribution system at a minimum. This is done by coating the pipes to minimize corrosion. If a lead service line is located, either during a main break or as part of regular line maintenance, it will be replaced with an appropriate material.

What can you do About Your Lead Status Unknown Service Line?

You can call the Village of Fairport Harbor Water Department at (440)-352-3620 to schedule an in person, inspection of the exposed line materials in the home.

For More Information, Please Contact: 440-352-3620, visit U.S. EPA's website at www.epa.gov/lead, or visit Ohio EPA's Learn About Lead website. For information about other lead exposure, please visit the Ohio Department of Health's Childhood Lead Poisoning website.

Please share this information with all the other people in this home or building, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.



Village of Fairport Harbor

220 Third Street, Fairport Harbor, Ohio 44077

Phone: 440-352-3620

FairportHarbor.org

November 11, 2024

FAIRPORT PUBLIC LIBRARY
329 VINE STREET
FAIRPORT HARBOR, OH 44077-5741

RE: Notification of Lead Status Unknown (Unknown) Service Line

Service Address:	329 VINE
Account Number:	03-00460-00

Dear Water System Consumer:

The Village of Fairport Harbor is the public water system (PWS) responsible for providing drinking water to this location. This notification is being sent because this home or building has a **lead status unknown** service line. This means that your service line material is unknown and may be lead, galvanized requiring replacement, or a non-lead material. A service line is a pipe that connects the water main to the building.

What Does This Mean?

Under the authority of the Safe Drinking Water Act, the US Environmental Protection Agency (EPA) requires us to notify water consumers who are served by a lead status unknown service line. A lead status unknown service line is where the service line material is not known to be lead, galvanized requiring replacement, or a non-lead service line, and there is no documented evidence supporting the material classification.

What are the Health Effects of Lead?

There is no safe level of lead in drinking water. Exposure to lead in drinking water can cause serious health effects in all age groups, especially pregnant people, infants (both formula-fed and breastfed), and young children. Some of the health effects to infants and children include decreases in IQ and attention span. Lead exposure can also result in new or worsened learning and behavior problems. The children of persons who are exposed to lead before or during pregnancy may be at increased risk of these harmful health effects. Adults have increased risks of heart disease, high blood pressure, and kidney or nervous system problems. Contact your health care provider for more information about your risks.

What Can I Do to Reduce Exposure to Lead if Found in My Drinking Water?

- ***Do not boil water to remove lead.*** Boiling water will not reduce lead.
- ***Flush your tap if it has been unused for 6 or more hours.*** Lead levels increase over time as water sits in lead-containing plumbing materials. Regular water usage in your home or building can reduce lead levels in drinking water. When water has not been used for 6

hours or more, homes and buildings served by lead or a galvanized requiring replacement service lines should be flushed until you note a temperature change, then flush for one more minute.

- **Use cold water for cooking, drinking, and preparing baby formula.** Do not cook with, drink, or make baby formula from your hot water tap. Lead dissolves more easily in hot water. Always use cold water and heat if needed.
- **Use an ANSI certified lead filter.** Filters certified to the ANSI/NSF 53 standard for lead removal can be effective at reducing lead levels in water.
- **Regularly clean your faucet aerators.** Over time, particles containing lead can build up on the inside of aerator screens. Cleaning aerators regularly will help eliminate this source of lead.
- **For pregnant persons, infants, and young children.** Some populations such as pregnant persons, infants, and young children may be more at risk from the harmful effects of lead. These populations may consider taking extra precautions if their home is served by a lead or galvanized requiring replacement service line. These extra precautions may include having their drinking water analyzed for lead, using an alternative source of water (such as bottled water), or utilizing a filter certified to ANSI/NSF 53 standard for lead removal.
- **Replace lead containing plumbing fixtures.** Many old faucets, valves and other plumbing fixtures may contain lead. Identify if your building's plumbing fixtures contain lead, and replace them when appropriate.
- **You may wish to have your child's blood tested for lead.** Your local county health department can be reached for additional assistance.
- You may wish to test your water for lead. To request this, contact Village Hall at 440-352-3620 for more information.

What is Village of Fairport Harbor PWS Doing?

Your Source Water Treatment Facility uses an orthophosphate to help keep lead levels in the distribution system at a minimum. This is done by coating the pipes to minimize corrosion. If a lead service line is located, either during a main break or as part of regular line maintenance, it will be replaced with an appropriate material.

What can you do About Your Lead Status Unknown Service Line?

You can call the Village of Fairport Harbor Water Department at (440)-352-3620 to schedule an in person, inspection of the exposed line materials in the home.

For More Information, Please Contact: 440-352-3620, visit U.S. EPA's website at www.epa.gov/lead, or visit Ohio EPA's Learn About Lead website. For information about other lead exposure, please visit the Ohio Department of Health's Childhood Lead Poisoning website.

Please share this information with all the other people in this home or building, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.



Village of Fairport Harbor

220 Third Street, Fairport Harbor, Ohio 44077

Phone: 440-352-3620

FairportHarbor.org

November 11, 2024

FAIRPORT HARBOR SCH BD
329 VINE STREET
FAIRPORT HARBOR, OH 44077-5741

RE: Notification of Lead Status Unknown (Unknown) Service Line

Service Address:	602 PLUM
Account Number:	03-00480-00

Dear Water System Consumer:

The Village of Fairport Harbor is the public water system (PWS) responsible for providing drinking water to this location. This notification is being sent because this home or building has a **lead status unknown** service line. This means that your service line material is unknown and may be lead, galvanized requiring replacement, or a non-lead material. A service line is a pipe that connects the water main to the building.

What Does This Mean?

Under the authority of the Safe Drinking Water Act, the US Environmental Protection Agency (EPA) requires us to notify water consumers who are served by a lead status unknown service line. A lead status unknown service line is where the service line material is not known to be lead, galvanized requiring replacement, or a non-lead service line, and there is no documented evidence supporting the material classification.

What are the Health Effects of Lead?

There is no safe level of lead in drinking water. Exposure to lead in drinking water can cause serious health effects in all age groups, especially pregnant people, infants (both formula-fed and breastfed), and young children. Some of the health effects to infants and children include decreases in IQ and attention span. Lead exposure can also result in new or worsened learning and behavior problems. The children of persons who are exposed to lead before or during pregnancy may be at increased risk of these harmful health effects. Adults have increased risks of heart disease, high blood pressure, and kidney or nervous system problems. Contact your health care provider for more information about your risks.

What Can I Do to Reduce Exposure to Lead if Found in My Drinking Water?

- **Do not boil water to remove lead.** Boiling water will not reduce lead.
- **Flush your tap if it has been unused for 6 or more hours.** Lead levels increase over time as water sits in lead-containing plumbing materials. Regular water usage in your home or building can reduce lead levels in drinking water. When water has not been used for 6

hours or more, homes and buildings served by lead or a galvanized requiring replacement service lines should be flushed until you note a temperature change, then flush for one more minute.

- **Use cold water for cooking, drinking, and preparing baby formula.** Do not cook with, drink, or make baby formula from your hot water tap. Lead dissolves more easily in hot water. Always use cold water and heat if needed.
- **Use an ANSI certified lead filter.** Filters certified to the ANSI/NSF 53 standard for lead removal can be effective at reducing lead levels in water.
- **Regularly clean your faucet aerators.** Over time, particles containing lead can build up on the inside of aerator screens. Cleaning aerators regularly will help eliminate this source of lead.
- **For pregnant persons, infants, and young children.** Some populations such as pregnant persons, infants, and young children may be more at risk from the harmful effects of lead. These populations may consider taking extra precautions if their home is served by a lead or galvanized requiring replacement service line. These extra precautions may include having their drinking water analyzed for lead, using an alternative source of water (such as bottled water), or utilizing a filter certified to ANSI/NSF 53 standard for lead removal.
- **Replace lead containing plumbing fixtures.** Many old faucets, valves and other plumbing fixtures may contain lead. Identify if your building's plumbing fixtures contain lead, and replace them when appropriate.
- **You may wish to have your child's blood tested for lead.** Your local county health department can be reached for additional assistance.
- You may wish to test your water for lead. To request this, contact Village Hall at 440-352-3620 for more information.

What is Village of Fairport Harbor PWS Doing?

Your Source Water Treatment Facility uses an orthophosphate to help keep lead levels in the distribution system at a minimum. This is done by coating the pipes to minimize corrosion. If a lead service line is located, either during a main break or as part of regular line maintenance, it will be replaced with an appropriate material.

What can you do About Your Lead Status Unknown Service Line?

You can call the Village of Fairport Harbor Water Department at (440)-352-3620 to schedule an in person, inspection of the exposed line materials in the home.

For More Information, Please Contact: 440-352-3620, visit U.S. EPA's website at www.epa.gov/lead, or visit Ohio EPA's Learn About Lead website. For information about other lead exposure, please visit the Ohio Department of Health's Childhood Lead Poisoning website.

Please share this information with all the other people in this home or building, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.



Village of Fairport Harbor

220 Third Street, Fairport Harbor, Ohio 44077

Phone: 440-352-3620

FairportHarbor.org

November 11, 2024

EAST STREET BALL FIELDS
329 VINE ST
FAIRPORT HARBOR, OH 44077-5741

RE: Notification of Lead Status Unknown (Unknown) Service Line

Service Address:	EAST BALL FIELDS
Account Number:	03-00270-00

Dear Water System Consumer:

The Village of Fairport Harbor is the public water system (PWS) responsible for providing drinking water to this location. This notification is being sent because this home or building has a **lead status unknown** service line. This means that your service line material is unknown and may be lead, galvanized requiring replacement, or a non-lead material. A service line is a pipe that connects the water main to the building.

What Does This Mean?

Under the authority of the Safe Drinking Water Act, the US Environmental Protection Agency (EPA) requires us to notify water consumers who are served by a lead status unknown service line. A lead status unknown service line is where the service line material is not known to be lead, galvanized requiring replacement, or a non-lead service line, and there is no documented evidence supporting the material classification.

What are the Health Effects of Lead?

There is no safe level of lead in drinking water. Exposure to lead in drinking water can cause serious health effects in all age groups, especially pregnant people, infants (both formula-fed and breastfed), and young children. Some of the health effects to infants and children include decreases in IQ and attention span. Lead exposure can also result in new or worsened learning and behavior problems. The children of persons who are exposed to lead before or during pregnancy may be at increased risk of these harmful health effects. Adults have increased risks of heart disease, high blood pressure, and kidney or nervous system problems. Contact your health care provider for more information about your risks.

What Can I Do to Reduce Exposure to Lead if Found in My Drinking Water?

- **Do not boil water to remove lead.** Boiling water will not reduce lead.
- **Flush your tap if it has been unused for 6 or more hours.** Lead levels increase over time as water sits in lead-containing plumbing materials. Regular water usage in your home or building can reduce lead levels in drinking water. When water has not been used for 6

hours or more, homes and buildings served by lead or a galvanized requiring replacement service lines should be flushed until you note a temperature change, then flush for one more minute.

- **Use cold water for cooking, drinking, and preparing baby formula.** Do not cook with, drink, or make baby formula from your hot water tap. Lead dissolves more easily in hot water. Always use cold water and heat if needed.
- **Use an ANSI certified lead filter.** Filters certified to the ANSI/NSF 53 standard for lead removal can be effective at reducing lead levels in water.
- **Regularly clean your faucet aerators.** Over time, particles containing lead can build up on the inside of aerator screens. Cleaning aerators regularly will help eliminate this source of lead.
- **For pregnant persons, infants, and young children.** Some populations such as pregnant persons, infants, and young children may be more at risk from the harmful effects of lead. These populations may consider taking extra precautions if their home is served by a lead or galvanized requiring replacement service line. These extra precautions may include having their drinking water analyzed for lead, using an alternative source of water (such as bottled water), or utilizing a filter certified to ANSI/NSF 53 standard for lead removal.
- **Replace lead containing plumbing fixtures.** Many old faucets, valves and other plumbing fixtures may contain lead. Identify if your building's plumbing fixtures contain lead, and replace them when appropriate.
- **You may wish to have your child's blood tested for lead.** Your local county health department can be reached for additional assistance.
- You may wish to test your water for lead. To request this, contact Village Hall at 440-352-3620 for more information.

What is Village of Fairport Harbor PWS Doing?

Your Source Water Treatment Facility uses an orthophosphate to help keep lead levels in the distribution system at a minimum. This is done by coating the pipes to minimize corrosion. If a lead service line is located, either during a main break or as part of regular line maintenance, it will be replaced with an appropriate material.

What can you do About Your Lead Status Unknown Service Line?

You can call the Village of Fairport Harbor Water Department at (440)-352-3620 to schedule an in person, inspection of the exposed line materials in the home.

For More Information, Please Contact: 440-352-3620, visit U.S. EPA's website at www.epa.gov/lead, or visit Ohio EPA's Learn About Lead website. For information about other lead exposure, please visit the Ohio Department of Health's Childhood Lead Poisoning website.

Please share this information with all the other people in this home or building, especially those who may not have received this notice directly (for example, people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.