

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:		1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
		2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
		3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
		4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
5 CAD #:	B1A	Air Cell Pipe Insulation 1923 Original Building	THROUGHOUT 1923 ORIGINAL BUILDING	100 Lin Ft	N	40 CH	5
Comments: INACCESSIBLE FOR REMOVAL. ASSUMED PRESENT ABOVE PLASTER CEILING FOR RADIATORS.					Sample #: 207-P-2A		
6 CAD #:	A1A	Mudded Pipe Joints on Air Cell Insulation 1923 Original Building	THROUGHOUT 1923 ORIGINAL BUILDING	20 Joints	N	40 CH	5
Comments: INACCESSIBLE FOR REMOVAL. ASSUMED PRESENT ABOVE PLASTER CEILING FOR RADIATORS.					Sample #: 207-P-1A		
10 CAD #:	X0A	Miscellaneous Material Pipe/Valve Flange Gaskets	1923 ORIGINAL BUILDING BOILER ROOM 0100	40 Sq Ft	N	ASSUMED	5
Comments: INACCESSIBLE. APPROXIMATELY FORTY (40) FLANGES.					Sample #:		
15 CAD #:	X1A	Miscellaneous Material 6" Red Quarry Tile	1923 ORIGINAL BUILDING SOUTHEAST STAIRWELL	250 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
21 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1971 Addition	ROOM 1115	3 Joints	N	3 CH	5
Comments: ONE (1) ABOVE CEILING BY SINK & TWO (2) INACCESSIBLE FOR REMOVAL IN CHASE BY SINK.					Sample #: 500-JJT-29		
25 CAD #:	V0A	Sink Undercoating Black	ROOM 1115	10 Sq Ft	N	5-20 CH	5
Comments: ONE (1) SINK.					Sample #: 2001-1504-CC2		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
28 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 1115	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
30 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1971 Addition	ROOM 1116	2 Joints	N	3 CH	5
Comments: INACCESSIBLE FOR REMOVAL. ASSUME PRESENT IN CHASE FOR SINK.					Sample #: 500-JJT-25		
34 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 1116	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
35 CAD #:	V0A	Sink Undercoating Black	ROOM 1116	10 Sq Ft	N	5-20 CH	5
Comments: ONE (1) SINK.					Sample #:		
39 CAD #:	K2L	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown Streaks	ROOM 1114	900 Sq Ft	N	3 CH (TILE), 7 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #: 091310-ML-06		
40 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 1114	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
41 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 1114	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
47 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1923)	ROOM 1114 STORAGE	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
48 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 1113	120 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
49 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 1113	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
50 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1923)	ROOM 1112	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
51 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 1112	48 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
55 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 1110	4 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
56 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 1110	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
57 CAD #:	X0M	Miscellaneous Material Thin Metal Frame Tackboard Adhesive	ROOM 1110	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
58 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1110A	30 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: CRACKED TILE AT ENTRY.					Sample #: 2001-01136-3		
63 CAD #:	X0M	Miscellaneous Material Thin Metal Frame Tackboard Adhesive	ROOM 1109	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
77 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1004B	25 Sq Ft	N	5 CH (TILE ONLY)	5
Comments:					Sample #:		
79 CAD #:	X1A	Miscellaneous Material 6" Red Quarry Tile	1923 ORIGINAL BUILDING SOUTHWEST STAIRWELL	250 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
90 CAD #:	X0M	Miscellaneous Material Thin Metal Frame Tackboard Adhesive	ROOM 1102	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
92 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1102	620 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: UNDER CARPET. BROWN ADHESIVE.					Sample #: 100510-ML-06		
96 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1103	250 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: UNDER CARPET.					Sample #:		
97 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 1103	70 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
101 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1104 STORAGE	100 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: TILE WORN WHERE CHAIR WAS ONCE LOCATED. RECOMMEND SEALING WITH WAX. MONITOR.					Sample #:		
105 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1105	120 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: UNDER CARPET.					Sample #:		
110 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1106	110 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: UNDER CARPET.					Sample #:		
111 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 1106	24 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
115 CAD #:	K0C	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Streaks	ROOM 1107	90 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: UNDER CARPET. NEED SPECIAL KEY.					Sample #:		
117 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 1107	24 Sq Ft	N	ASSUMED	5
Comments: NEED SPECIAL KEY.					Sample #:		
130 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	1ST FLOOR NORTH HALLWAY 1200	150 Sq Ft	N	ASSUMED	5
Comments: MULTIPLE CHIPS THROUGHOUT. SEALED WITH WAX.					Sample #:		
131 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Streaks	1971 ADDITION GYMNASIUM 1207	4800 Sq Ft	N	3-10 CH (MASTIC ONLY)	5
Comments: INCLUDES PATCHED TILES.					Sample #: 100510-ML-10; 2001-01136-1		
163 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 2101 (LOUNGE)	220 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
165 CAD #:	X0J	Miscellaneous Material McQuay AHU Tar Gaskets	1971 ADDITION ROOM 2102 MECHANICAL	10 Sq Ft	N	12 CH	5
Comments:					Sample #: 100510-ML-23		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
167 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray	1923 ORIGINAL BUILDING 2ND FLOOR HALLWAY 2100	450 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: SOME CRACKING OUTSIDE ROOMS 2108, 2109 & 2114. CHIPPED OUTSIDE ROOM 2102. SEALED WITH WAX.					Sample #: 2001-01136-2		
168 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Black	1923 ORIGINAL BUILDING 2ND FLOOR HALLWAY 2100	450 Sq Ft	N	3 CH (TILE ONLY)	5
Comments: SOME CRACKING OUTSIDE ROOMS 2108, 2109 & 2114. CHIPPED OUTSIDE ROOM 2102. SEALED WITH WAX.					Sample #:		
169 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 2103	620 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
170 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 2103	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
171 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 2103	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
173 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 2104	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
174 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 2104	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
178 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 2105	120 Sq Ft	N	ASSUMED	5
Comments: MOST BEHIND WHITEBOARDS.					Sample #:		
179 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 2105	15 Sq Ft	N	ASSUMED	5
Comments: MOST BEHIND WHITEBOARDS.					Sample #:		
181 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 2108	120 Sq Ft	N	ASSUMED	5
Comments: MOST BEHIND WHITEBOARDS.					Sample #:		
182 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 2108	15 Sq Ft	N	ASSUMED	5
Comments: MOST BEHIND WHITEBOARDS.					Sample #:		
183 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 2107	100 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
184 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 2107A	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
187 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 2112A	150 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
189 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 2109	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
190 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 2109	15 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
191 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 2114	620 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
192 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 2114	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
193 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 2114	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD & CORKBOARD.					Sample #:		
196 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Streaks	HALLWAY OUTSIDE ROOMS 2113 & 2116	15 Sq Ft	N	3-10 CH (MASTIC ONLY)	5
Comments: CRACKED BY DOORS W/EXPOSED MASTIC BY ROOM 2116. RECOMMEND SEALING WITH WAX.					Sample #:		
197 CAD #:	X0P	Miscellaneous Material Wired Window Glazing	HALLWAY OUTSIDE ROOMS 2113 & 2116	2 Sq Ft	N	4 CH	5
Comments:					Sample #: 080315BV-06		
198 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1971 Addition	ROOM 2113	2 Joints	N	3 CH	5
Comments: INACCESSIBLE FOR REMOVAL. ASSUMED PRESENT IN CHASE BY SINK.					Sample #: 500-JJT-20		
201 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 2113	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
202 CAD #:	V0A	Sink Undercoating Black	ROOM 2113	10 Sq Ft	N	5-20 CH	5
Comments: ONE (1) SINK.					Sample #:		
203 CAD #:	A4B	Mudded Pipe Joints on Fiberglass Insulation 1971 Addition	ROOM 2116	2 Joints	N	3 CH	5
Comments: INACCESSIBLE FOR REMOVAL. ASSUMED PRESENT IN CHASE BY SINK.					Sample #:		
206 CAD #:	V0A	Sink Undercoating Black	ROOM 2116	10 Sq Ft	N	5-20 CH	5
Comments: ONE (1) SINK.					Sample #:		
208 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 2116	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
209 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Streaks	HALLWAY OUTSIDE ROOMS 3111 & 3114	15 Sq Ft	N	3-10 CH (MASTIC ONLY)	5
Comments: CRACKED BY DOORS W/EXPOSED MASTIC BY ROOM 3114. RECOMMEND SEALING WITH WAX.					Sample #:		
210 CAD #:	X0P	Miscellaneous Material Wired Window Glazing	HALLWAY OUTSIDE ROOMS 3111 & 3114	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
212 CAD #:	V0A	Sink Undercoating Black	ROOM 3111	10 Sq Ft	N	5-20 CH	5
Comments: ONE (1) SINK.					Sample #:		
215 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 3111	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
218 CAD #:	V0A	Sink Undercoating Black	ROOM 3114	10 Sq Ft	N	5-20 CH	5
Comments: ONE (1) SINK.					Sample #: 2001-1901-JL-16		
221 CAD #:	X0G	Miscellaneous Material Corkboard Adhesive (1971)	ROOM 3114	40 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
224 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Gray	1923 ORIGINAL BUILDING 3RD FLOOR HALLWAY 3100	425 Sq Ft	N	5 CH (TILE ONLY)	5
Comments: SCRATCHED THROUGHOUT. RECOMMEND KEEPING TILE SEALED W/WAX.					Sample #:		
225 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Black	1923 ORIGINAL BUILDING 3RD FLOOR HALLWAY 3100	425 Sq Ft	N	3 CH (TILE ONLY)	5
Comments: SCRATCHED THROUGHOUT. RECOMMEND KEEPING TILE SEALED W/WAX.					Sample #: 100510-ML-05		
228 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 4102	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
230 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3112	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
231 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3112	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
233 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3107	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS & CORKBOARDS.					Sample #:		
234 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3107	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
238 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 3110	150 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
239 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3110	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
240 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3110	5 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
243 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3106	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
244 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3106	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
245 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1923)	ROOM 3103	620 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
246 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3103	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
247 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3103	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
251 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 4101	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
254 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3101	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
255 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3101	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS AND NEW CORKBOARDS.					Sample #:		
256 CAD #:	X0C	Miscellaneous Material Corkboard Adhesive (1923)	ROOM 3102	120 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
257 CAD #:	X0D	Miscellaneous Material Slate Chalkboard Adhesive (1923)	ROOM 3102	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS AND NEW CORKBOARDS.					Sample #:		