

1305 Prosperity Avenue, Saint Paul, MN 55106

Chart C - All Materials List

The following list contains all events observed by the inspector, whether or not they actually contained asbestos, and are grouped by homogeneous area (material type).

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
D1A	Boiler Gaskets Boiler #1					Total Amount - 2 Sq Ft
	19	BOILER ROOM 0110	NONE DETECTED	031709-MA-17		2 Sq Ft
D1B	Boiler Gaskets Boiler #2					Total Amount - 4 Sq Ft
	21	BOILER ROOM 0110	NONE DETECTED	031709-MA-18		4 Sq Ft
D2A	Interior Boiler Insulation Interior Refractory (Boiler #1)					Total Amount - 40 Sq Ft
	20	BOILER ROOM 0110	ASSUMED			40 Sq Ft
D2B	Interior Boiler Insulation Interior Refractory (Boiler #2)					Total Amount - 25 Sq Ft
	22	BOILER ROOM 0110	ASSUMED			25 Sq Ft
F2A	Exterior Duct Insulation Black Tar on Seams					Total Amount - 20 Sq Ft
	27	ENTRANCE HALLWAY TO BOILER ROOM	NONE DETECTED	2001-1501-C1-5		5 Sq Ft
	31	BASEMENT HALLWAY OUTSIDE BOILER ROOM	NONE DETECTED			10 Sq Ft
	33	BASEMENT STORAGE 0102 & ROOM 0103	NONE DETECTED	2001-1501-C1-3, 4		5 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
I1A	1' x 1' Acoustical Ceiling Tile Pegboard (1952)					Total Amount - 2200 Sq Ft
	40	GYMNASIUM 1108	NONE DETECTED	206D7A		2200 Sq Ft
I2A	2' x 2' Acoustical Ceiling Tile Grubs w/Pin Holes					Total Amount - 1305 Sq Ft
	26	ENTRANCE HALLWAY TO BOILER ROOM	NONE DETECTED	031709-MA-11		125 Sq Ft
	30	BASEMENT HALLWAY OUTSIDE BOILER ROOM	NONE DETECTED			80 Sq Ft
	34	BASEMENT CUSTODIAN OFFICE 0104	NONE DETECTED			500 Sq Ft
	67	BOYS' RESTROOM 1110	NONE DETECTED			300 Sq Ft
	69	GIRLS' RESTROOM 1112	NONE DETECTED			300 Sq Ft
I2B	2' x 2' Acoustical Ceiling Tile Bumps w/Pin Holes					Total Amount - 12000 Sq Ft
	2	THROUGHOUT BUILDING	NONE DETECTED	031709-MA-23; 542-12	MA-23: STAFF LOUNGE. 542-12: COACHES' OFFICE.	12000 Sq Ft
I2C	2' x 2' Acoustical Ceiling Tile Vinyl-Covered Sheetrock (1995)					Total Amount - 500 Sq Ft
	53	KITCHEN 1104	NSM			500 Sq Ft
I2D	2' x 2' Acoustical Ceiling Tile Bumps with Pin Holes (2016)					Total Amount - 17500 Sq Ft
	92	THROUGHOUT 1956 ADDITION	NEW			12500 Sq Ft
	124	THROUGHOUT 1995 ADDITION	NEW			5000 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
J3A	Miscellaneous Cementitious Material Black Window Sill (1952)					Total Amount - 268 Sq Ft
	58	ROOM 1102	NONE DETECTED			34 Sq Ft
	63	ROOM 1101	NONE DETECTED			34 Sq Ft
	71	ROOM 1202	NONE DETECTED			8 Sq Ft
	73	ROOM 1201	NONE DETECTED			12 Sq Ft
	74	ROOM 1204	NONE DETECTED			45 Sq Ft
	78	ROOM 1203	NONE DETECTED			45 Sq Ft
	82	ROOM 1206	NONE DETECTED			45 Sq Ft
	86	ROOM 1205	NONE DETECTED	031709-MA-27	MA-27: ROOM 1208 (SINCE REMOVED).	45 Sq Ft
K2A	12" x 12" Vinyl Floor Tile & Mastic White w/Multi-Colored Smudges					Total Amount - 2000 Sq Ft
	5	THROUGHOUT BUILDING	NONE DETECTED	031709-MA-21; 542-16	MA-21: GYMNASIUM OFFICE. 542-16: CAFETERIA.	2000 Sq Ft
K2B	12" x 12" Vinyl Floor Tile & Mastic Beige Mottle					Total Amount - 2200 Sq Ft
	42	GYMNASIUM 1108	NONE DETECTED	031709-MA-14		2200 Sq Ft
K2C	12" x 12" Vinyl Floor Tile & Mastic Maroon w/Multi-Colored Smudges					Total Amount - 100 Sq Ft
	6	THROUGHOUT BUILDING	NONE DETECTED	542-19	542-19: 1952 ORIGINAL BUILDING HALLWAY.	100 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
K2E	12" x 12" Vinyl Floor Tile & Mastic Gray w/Multi-Colored Smudges					Total Amount - 200 Sq Ft
7	THROUGHOUT BUILDING	NONE DETECTED	542-17	542-17: CAFETERIA.	200 Sq Ft	
K2F	12" x 12" Vinyl Floor Tile & Mastic Teal w/Multi-Colored Smudges					Total Amount - 200 Sq Ft
8	THROUGHOUT BUILDING	NONE DETECTED	542-13	542-13: 1952 ORIGINAL BUILDING HALLWAY.	200 Sq Ft	
K3A	Miscellaneous Flooring 24" x 24" Gray w/Specks (2013)					Total Amount - 10000 Sq Ft
9	THROUGHOUT BUILDING	NEW			10000 Sq Ft	
K3B	Miscellaneous Flooring 2' x 2' Beige w/Specks (2013)					Total Amount - 10000 Sq Ft
10	THROUGHOUT BUILDING	NEW			10000 Sq Ft	
L0A	Flexible Duct Connector Brown Canvas					Total Amount - 28 Sq Ft
23	BOILER ROOM 0110	NONE DETECTED	2001-1504-BC2		24 Sq Ft	
45	STAGE 1106	NONE DETECTED			4 Sq Ft	
M0A	Plaster 1952 Original Building					Total Amount - 6000 Sq Ft
17	THROUGHOUT 1952 ORIGINAL BUILDING	NONE DETECTED	031709-MA-13, 24, 42, 43, 44; 2001-1501-C1-1; 542-9	MA-13: GYMNASIUM OFFICE. MA024: HALLWAY BY ROOM 1208. MA-42: ROOM 1101. MA-43: HALLWAY BY ROOM 1204. MA-44: ROOM 1102. C1-1: ROOM 0104 KITCHEN. 542-9: 1ST FLOOR HALLWAY.	6000 Sq Ft	

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
M0B	Plaster Exterior Soffit	Total Amount - 1000 Sq Ft				
	15	THROUGHOUT BUILDING	NONE DETECTED	072815BV-03-07`	BV-03-07: EXTERIOR.	1000 Sq Ft
N0A	Drywall/Joint Compound	Total Amount - 10000 Sq Ft				
	1	THROUGHOUT BUILDING	NONE DETECTED	031709-MA-40; 542-14	MA-40: STAFF LOUNGE. 542-14: 1995 ADDITION FAN ROOM.	10000 Sq Ft
P0A	Fire Doors Wood Composite - Weldwood	Total Amount - 60 Sq Ft				
	28	ENTRANCE HALLWAY TO BOILER ROOM	20 CH	031709-MA-19		40 Sq Ft
	29	CUSTODIAL OFFICE 0109	20 CH			20 Sq Ft
P0B	Fire Doors Wood - 1 Hr Rating (Algoma)	Total Amount - 80 Sq Ft				
	52	CAFETERIA 1103	ASSUMED			80 Sq Ft
P0C	Fire Doors Wood w/White Interior (No Tag)	Total Amount - 20 Sq Ft				
	44	GYMNASIUM STORAGE 1105	10 CH, 5 AM	031709-MA-12		20 Sq Ft
P0D	Fire Doors Wood - 1 Hr Rating (Algoma)	Total Amount - 60 Sq Ft				
	36	BASEMENT GENERATOR ROOM 0106	NEW			20 Sq Ft
	37	BASEMENT ELECTRICAL ROOM 0105	NEW			20 Sq Ft
	135	MECHANICAL ROOM 1116	NEW			20 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
Q0A	Carpet Adhesive 2' x 2' Purple, Green & Yellow Carpet (2013)					Total Amount - 6000 Sq Ft
	3	THROUGHOUT BUILDING	NEW			6000 Sq Ft
Q0B	Carpet Adhesive Blue w/Green & Purple Carpet (2013)					Total Amount - 6000 Sq Ft
	4	THROUGHOUT BUILDING	NEW			6000 Sq Ft
Q0C	Carpet Adhesive Blue, Gray & Red Carpet					Total Amount - 500 Sq Ft
	104	ROOM 1304	NEW			500 Sq Ft
R0B	Baseboard/Mopboard Adhesive 4" Blue/Gray Baseboard					Total Amount - 100 Sq Ft
	11	THROUGHOUT BUILDING	NONE DETECTED	031709-MA-26	MA-26: MEDIA CENTER.	100 Sq Ft
R0C	Baseboard/Mopboard Adhesive 4" Black Baseboard (New Straight)					Total Amount - 100 Sq Ft
	12	THROUGHOUT BUILDING	NONE DETECTED	033109-MA-02	MA-02: MEDIA CENTER.	100 Sq Ft
S0A	Wood Floor Felt / Vapor Barrier 1952 Original Building (Elevated)					Total Amount - 320 Sq Ft
	47	STAGE 1106	ASSUMED			320 Sq Ft
T0A	Light Cord Insulation White					Total Amount - 18 Lin Ft
	43	GYMNASIUM 1108	ASSUMED			12 Lin Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	46	STAGE 1106	ASSUMED			6 Lin Ft
VOA	Sink Undercoating Gray					Total Amount - 12 Sq Ft
	38	BASEMENT CUSTODIAL OFFICE KITCHEN 0108	NONE DETECTED	031709-MA-07		4 Sq Ft
	59	ROOM 1102	NONE DETECTED			4 Sq Ft
	64	ROOM 1101	NONE DETECTED			4 Sq Ft
VOB	Sink Undercoating Gray (1956)					Total Amount - 24 Sq Ft
	97	ROOM 1301	NONE DETECTED			4 Sq Ft
	100	ROOM 1302	NONE DETECTED	031709-MA-36		4 Sq Ft
	103	ROOM 1303	NONE DETECTED			4 Sq Ft
	107	ROOM 1304	NONE DETECTED			4 Sq Ft
	110	ROOM 1305	NONE DETECTED			4 Sq Ft
	113	ROOM 1306	NONE DETECTED			4 Sq Ft
VOC	Sink Undercoating Gray (1995)					Total Amount - 8 Sq Ft
	131	MEDIA CENTER OFFICE 1014	NONE DETECTED	031709-MA-38	MA-38: STAFF LOUNGE (SINCE REMOVED).	4 Sq Ft
	132	NURSE'S ROOM 1002	NONE DETECTED			4 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
V0D	Sink Undercoating Gray (2013)					Total Amount - 20 Sq Ft
	75	ROOM 1204	NEW			5 Sq Ft
	79	ROOM 1203	NEW			5 Sq Ft
	83	ROOM 1206	NEW			5 Sq Ft
	87	ROOM 1205	NEW			5 Sq Ft
W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A					Total Amount - 550 Sq Ft
	41	GYMNASIUM 1108	3 CH	031709-MA-15, 20	MA-15: ROOM 1101 (SINCE REMOVED). MA-20: ROOM 1102 (SINCE REMOVED).	550 Sq Ft
X0A	Miscellaneous Material Black Tar Coating on Ceiling					Total Amount - 2500 Sq Ft
	18	BOILER ROOM 0110	NONE DETECTED	031709-MA-01		2500 Sq Ft
X0B	Miscellaneous Material Brown Mastic on Walls					Total Amount - 12 Sq Ft
	24	BOILER ROOM 0110	NONE DETECTED	031709-MA-03		12 Sq Ft
X0D	Miscellaneous Material Corkboard Adhesive (1952)					Total Amount - 152 Sq Ft
	35	BASEMENT CUSTODIAN OFFICE 0104	NONE DETECTED	031709-MA-06		40 Sq Ft
	51	HALLWAY 1100	NONE DETECTED			32 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	57	ROOM 1102	NONE DETECTED			40 Sq Ft
	62	ROOM 1101	NONE DETECTED			40 Sq Ft
X0F	Miscellaneous Material Radiator Chase Fiberglass w/Black Layer (1952)					Total Amount - 1000 Sq Ft
	56	THROUGHOUT 1952 ORIGINAL BUILDING CLASSROOMS	NONE DETECTED	542-104	104: ROOM 1205.	1000 Sq Ft
X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1956)					Total Amount - 60 Sq Ft
	95	ROOM 1301	8 CH			10 Sq Ft
	98	ROOM 1302	8 CH			10 Sq Ft
	101	ROOM 1303	8 CH			10 Sq Ft
	105	ROOM 1304	8 CH	112812MV-02	MV-02: ROOM 1304.	10 Sq Ft
	108	ROOM 1305	8 CH			10 Sq Ft
	111	ROOM 1306	8 CH			10 Sq Ft
X0H	Miscellaneous Material Metal Frame Corkboard Adhesive (1956)					Total Amount - 50 Sq Ft
	96	ROOM 1301	5 CH			10 Sq Ft
	99	ROOM 1302	5 CH			10 Sq Ft
	102	ROOM 1303	5 CH			R Sq Ft
	106	ROOM 1304	5 CH	112812MV-03	MV-03: ROOM 1304.	10 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	109	ROOM 1305	5 CH			10 Sq Ft
	112	ROOM 1306	5 CH			10 Sq Ft
XOI	Miscellaneous Material Wired Window Glaze					Total Amount - 20 Sq Ft
	122	THROUGHOUT 1995 ADDITION	NONE DETECTED	031709-MA-39	MA-39: ROOM 1308.	20 Sq Ft
XOK	Miscellaneous Material Black Dampproofing (1995)					Total Amount - 2000 Sq Ft
	123	THROUGHOUT 1995 ADDITION	NONE DETECTED	031709-MA-41	1956 ADDITION TUNNEL.	2000 Sq Ft
XOL	Miscellaneous Material Radiator Chase Fiberglass w/Black Layer (1956)					Total Amount - 800 Sq Ft
	93	THROUGHOUT 1956 ADDITION CLASSROOMS	NONE DETECTED	033109-MA-04	MA-04: ROOM 1306.	800 Sq Ft
XOM	Miscellaneous Material Residual Countertop Adhesive					Total Amount - 14 Sq Ft
	72	ROOM 1202	NONE DETECTED	020912-BF-01	BF-01: ROOM 1202.	14 Sq Ft
XOO	Miscellaneous Material Carpet Tackboard Adhesive					Total Amount - 170 Sq Ft
	50	HALLWAY 1100	ASSUMED			170 Sq Ft
XOP	Miscellaneous Material Interior Window Glazing					Total Amount - 6 Sq Ft
	94	THROUGHOUT 1956 ADDITION CLASSROOMS	4 CH	072815BV-01	BV-01: ROOM 1301.	6 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X0Q	Miscellaneous Material Exterior Window Caulking					Total Amount - 70 Sq Ft
	14	THROUGHOUT BUILDING	NONE DETECTED	072815BV-02	BV-02: ROOM 1205.	70 Sq Ft
X0R	Miscellaneous Material Milkboard Adhesive					Total Amount - 250 Sq Ft
	55	KITCHEN 1104	ASSUMED			250 Sq Ft
X0S	Miscellaneous Material Red Firestop (1995)					Total Amount - 20 Sq Ft
	136	MECHANICAL ROOM 1116	NEW			20 Sq Ft
X0T	Miscellaneous Material Metal Frame Corkboard Adhesive (1995)					Total Amount - 40 Sq Ft
	114	ROOM 1307	NEW			10 Sq Ft
	116	ROOM 1308	NEW			10 Sq Ft
	118	ROOM 1309	NEW			10 Sq Ft
	120	ROOM 1312	NEW			10 Sq Ft
X0U	Miscellaneous Material Metal Frame Chalkboard Adhesive (1995)					Total Amount - 40 Sq Ft
	115	ROOM 1307	NEW			10 Sq Ft
	117	ROOM 1308	NEW			10 Sq Ft
	119	ROOM 1309	NEW			10 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	121	ROOM 1312	NEW			10 Sq Ft
X0V	Miscellaneous Material Red Fire Stop					Total Amount - 100 Sq Ft
	16	THROUGHOUT BUILDING	NONE DETECTED	053024BV-01, 02	BV-01,02: MECHANICAL ROOM 1116.	100 Sq Ft
X1A	Miscellaneous Material 1" Beige Ceramic Floor Tile System					Total Amount - 40 Sq Ft
	32	BASEMENT RESTROOM 0101	ASSUMED			40 Sq Ft
X1B	Miscellaneous Material 6" Tan Quarry Tile					Total Amount - 160 Sq Ft
	39	STAIRWELL 0199A	ASSUMED			160 Sq Ft
X1C	Miscellaneous Material 2" Gray Ceramic Floor Tile System (1995)					Total Amount - 50 Sq Ft
	48	RESTROOM 1113	NEW			50 Sq Ft
X1D	Miscellaneous Material 4" White Ceramic Wall Tile System (1995)					Total Amount - 200 Sq Ft
	49	RESTROOM 1113	NEW			150 Sq Ft
	133	NURSE'S ROOM 1002 RESTROOM	NEW			50 Sq Ft
X1E	Miscellaneous Material 6" Gray Quarry Tile (1995)					Total Amount - 600 Sq Ft
	54	KITCHEN 1104	NEW			600 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X1F	Miscellaneous Material 1" Gray Ceramic Floor Tile System					Total Amount - 360 Sq Ft
	60	RESTROOM 1102B	ASSUMED			20 Sq Ft
	66	RESTROOM 1101B	ASSUMED			40 Sq Ft
	68	BOYS' RESTROOM 1110	ASSUMED			300 Sq Ft
X1G	Miscellaneous Material 1" Blue Ceramic Floor Tile System					Total Amount - 300 Sq Ft
	70	GIRLS' RESTROOM 1112	ASSUMED			300 Sq Ft
X1H	Miscellaneous Material 2" Beige Ceramic Floor Tile System (2013)					Total Amount - 200 Sq Ft
	76	ROOM 1204 RESTROOM	NEW			50 Sq Ft
	80	ROOM 1203 RESTROOM	NEW			50 Sq Ft
	84	ROOM 1206 RESTROOM	NEW			50 Sq Ft
	88	ROOM 1205 RESTROOM	NEW			50 Sq Ft
X1I	Miscellaneous Material 4" White Ceramic Wall Tile System (2013)					Total Amount - 460 Sq Ft
	61	RESTROOM 1102B	NEW			40 Sq Ft
	65	RESTROOM 1101B	NEW			20 Sq Ft
	77	ROOM 1204 RESTROOM	NEW			100 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	81	ROOM 1203 RESTROOM	NEW			100 Sq Ft
	85	ROOM 1206 RESTROOM	NEW			100 Sq Ft
	89	ROOM 1205 RESTROOM	NEW			100 Sq Ft
X1J	Miscellaneous Material Multi-Sized Green Ceramic Floor Tile System					Total Amount - 165 Sq Ft
	90	BOYS' RESTROOM 1210	ASSUMED			165 Sq Ft
X1K	Miscellaneous Material Multi-Sized Yellow Ceramic Floor Tile System					Total Amount - 145 Sq Ft
	91	GIRLS' RESTROOM 1211	ASSUMED			145 Sq Ft
X1L	Miscellaneous Material 6" Tan Quarry Tile (1995)					Total Amount - 285 Sq Ft
	125	ENTRANCE 1299A	NEW			200 Sq Ft
	126	ENTRANCE 1200A	NEW			85 Sq Ft
X1M	Miscellaneous Material 2" Tan Ceramic Floor Tile System (1995)					Total Amount - 150 Sq Ft
	127	RESTROOM 1213	NEW			50 Sq Ft
	129	RESTROOM 1214	NEW			50 Sq Ft
	134	NURSE'S ROOM 1002 RESTROOM	NEW			50 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X1N	Miscellaneous Material 1" Black w/Multi-Colored Mosaic Ceramic Wall Tile System (1995)					Total Amount - 100 Sq Ft
	128	RESTROOM 1213	NEW			50 Sq Ft
	130	RESTROOM 1214	NEW			50 Sq Ft
Y0A	Miscellaneous Material Old Metal Window Glazing					Total Amount - 2 Sq Ft
	25	BOILER ROOM 0110	<1 CH	031709-MA-02		2 Sq Ft
Y0K	Miscellaneous Material Tan w/Red & White Marble-Look Sheet Vinyl (20XX)					Total Amount - 360 Sq Ft
	13	THROUGHOUT BUILDING	NEW			360 Sq Ft



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427
Tel/Fax: (763) 449-4922 / (763) 449-4924
<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352404872

Customer ID: IFEA50

Customer PO:

Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Project: 202410449 Early Childhood Hub East

Phone: (763) 315-7927

Fax: (763) 315-7920

Received Date: 05/31/2024 8:55 AM

Analysis Date: 06/03/2024

Collected Date:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Non-Asbestos

Asbestos

Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
053024BV-01 352404872-0001	Mechanical 1116 - Red Fire Stop	Red Non-Fibrous Homogeneous	5% Glass	95.0% Non-fibrous (Other)	None Detected
053024BV-02 352404872-0002	Mechanical 1116 - Red Fire Stop	Red Non-Fibrous Homogeneous	5% Glass	95.0% Non-fibrous (Other)	None Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 06/03/2024 11:06:49



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352404872

Customer ID: IFEA50

Customer PO:

Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Project: 202410449 Early Childhood Hub East

Phone: (763) 315-7927

Fax: (763) 315-7920

Received Date: 05/31/2024 8:55 AM

Analysis Date: 06/03/2024

Collected Date:

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 05/31/2024

Sample Receipt Time: 8:55 AM

Analysis Completed Date: 06/03/2024

Analysis Completed Time: 11:01 AM

Analyst(s):

Michael Craigmile PLM (2)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 06/03/2024 11:06:49



9201 West Broadway North, Suite 600
Brooklyn Park, MN 55445
(763) 315-7900
1-800-233-9513

352404872

CHAIN OF CUSTODY

Page 1 of 1

Shaded Areas are for
Laboratory Use Only!

Client # _____ Project # 202410449

Building Name Early Childhood Hub East

Client St. Paul Public Schools

Project Name _____

Address _____

Contact Person _____

IEA Project Manager _____

Other Information _____

Verbal results to _____

Phone, Fax No. or E-Mail _____

TAT (circle) 6 hr 24 hr 48 hr 72 hr 96 hr Specify

Verbal results relayed to _____

Verbal results relayed by _____

Date _____

Time _____

Analysis location: ☐ On Site ☐ Lab ☐ Regional Office ☒ Other EWL

Matrix type

Analysis requested

Filter type

Sample #	Work Area or Phase #	Sample Description/Location	Sample type or Material code	Volume	Air	Bulk	Dust	PCM	PLM	TEM	Other	MCE	.8 um	.45 um
053024BV-01 -02		Red Fire Stop - Mechanical 1116 11	TTP		☐	☒	☐	☐	☒	☐		☐	☐	☐
					☐	☒	☐	☐	☒	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐