

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:		1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
		2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
		3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
		4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
12 CAD #:	T0A	Light Cord Insulation	THROUGHOUT 1964 ORIGINAL BUILDING	500 Lin Ft	N	50 CH	5
Comments: ORIGINAL FLUORESCENT LIGHTS.					Sample #: 2001-01104-5		
15 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	BOILER ROOM (1101)	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
16 CAD #:	J2A	Transite Piping/Ducting 1964 Original Building	1964 ORIGINAL BUILDING TUNNEL SYSTEM	1500 Sq Ft	N	30 CH	5
Comments: FIFTY (50) AT PENETRATIONS. VISIBLE W/I TUNNEL. ESTIMATED UNDER CONCRETE SLAB.					Sample #: M2045-1A		
17 CAD #:	P0A	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	TUNNEL SYSTEM	10 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. BOILER ROOM ACCESS.					Sample #:		
19 CAD #:	X0A	Miscellaneous Material Tan Penetration Putty	1964 ORIGINAL BUILDING TUNNEL SYSTEM	50 Sq Ft	N	25 CH	5
Comments: SEALING HVAC SYSTEM CONNECTIONS FROM METAL TO TRANSITE DUCTING.					Sample #: M2045-3A, B, C		
27 CAD #:	K3A	Miscellaneous Flooring Black Flooring Mastic	ROOM 1104	10 Sq Ft	N	5 CH	5
Comments: ASSUMED PRESENT AT PERIMETER EDGES.					Sample #: 110508ML-23		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
30 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1104	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
31 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	ROOM 1104 RESTROOM	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
35 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1105	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
36 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	ROOM 1105 RESTROOM	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
40 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1106	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
41 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	ROOM 1106 RESTROOM	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
42 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1964 Original Building	STAGE (1108)	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
43 CAD #:	X1B	Miscellaneous Material 8" Purple Quarry Tile System	RESTROOM 1113 NEAR ROOM 1106	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
62 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	NURSE'S OFFICE/SICK ROOM RESTROOM	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
63 CAD #:	X0B	Miscellaneous Material Tan Adhesive Puck	GIRLS' HAND WASHING/DRINKING FOUNTAIN CHASE EAST OF ROOM 1317	10 Sq Ft	N	5 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR.					Sample #: 110508ML-01		
64 CAD #:	X0C	Miscellaneous Material Black Adhesive Puck	GIRLS' HAND WASHING/DRINKING FOUNTAIN CHASE EAST OF ROOM 1317	10 Sq Ft	N	25 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR.					Sample #: 110508ML-02		
65 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	GIRLS' RESTROOM EAST OF ROOM 1317	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
66 CAD #:	X0B	Miscellaneous Material Tan Adhesive Puck	BOYS' HAND WASHING/DRINKING FOUNTAIN CHASE EAST OF ROOM 1316	10 Sq Ft	N	5 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR.					Sample #:		
67 CAD #:	X0C	Miscellaneous Material Black Adhesive Puck	BOYS' HAND WASHING/DRINKING FOUNTAIN CHASE EAST OF ROOM 1316	10 Sq Ft	N	25 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR.					Sample #:		
68 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	BOYS' RESTROOM EAST OF ROOM 1316	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
71 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1320	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
73 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1317	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
75 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1317	2 Sq Ft	N	4 CH	5
Comments:					Sample #: 110508ML-32		
78 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1316	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
79 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1316	2 Sq Ft	N	4 CH	5
Comments: ESTIMATED BEHIND GRAY GLAZING.					Sample #:		
83 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1315	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARD.					Sample #:		
84 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1315	2 Sq Ft	N	4 CH	5
Comments: ESTIMATED UNDER BLACK GLAZING.					Sample #:		
88 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1314	20 Sq Ft	N	ASSUMED	5
Comments: UNDER WHITEBOARDS.					Sample #:		
93 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1312	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
100 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1310	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
101 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1310	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
104 CAD #:	X1B	Miscellaneous Material 8" Purple Quarry Tile System	RESTROOM 1310A	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
106 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1313	15 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
108 CAD #:	J2B	Transite Piping/Ducting 1966 Addition	1966 ADDITION WEST TUNNEL SYSTEM	90 Sq Ft	N	ASSUMED	5
Comments: VISIBLE AT PENETRATIONS. ASSUMED UNDER CONCRETE SLAB.					Sample #:		
112 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1301	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
116 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1303	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARD.					Sample #:		
120 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1304	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARD.					Sample #:		
125 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1305	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
129 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1322	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARD.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
130 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1322	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
134 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1321	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS:					Sample #:		
135 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1321	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
139 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1324	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS:					Sample #:		
140 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1324	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
144 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1323	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS:					Sample #:		
145 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1323	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
149 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1326	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS:					Sample #:		
150 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1326	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
154 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1325	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS:					Sample #:		
155 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1325	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
158 CAD #:	X0B	Miscellaneous Material Tan Adhesive Puck	BOYS' HAND WASHING/DRINKING FOUNTAIN CHASE WEST OF ROOM 1330	10 Sq Ft	N	5 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR:					Sample #:		
159 CAD #:	X0C	Miscellaneous Material Black Adhesive Puck	BOYS' HAND WASHING/DRINKING FOUNTAIN CHASE WEST OF ROOM 1330	10 Sq Ft	N	25 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR:					Sample #:		
160 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	BOYS' RESTROOM WEST OF ROOM 1330	144 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
161 CAD #:	X0B	Miscellaneous Material Tan Adhesive Puck	GIRLS' HAND WASHING/DRINKING FOUNTAIN CHASE WEST OF ROOM 1329	10 Sq Ft	N	5 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR:					Sample #:		
162 CAD #:	X0C	Miscellaneous Material Black Adhesive Puck	GIRLS' HAND WASHING/DRINKING FOUNTAIN CHASE WEST OF ROOM 1329	10 Sq Ft	N	25 CH	5
Comments: VISIBLE FROM CHASE & TUNNEL. ADHESIVE IS PEELING OFF WALL. MONITOR:					Sample #:		
163 CAD #:	X1A	Miscellaneous Material 6" Brown Quarry Tile System	GIRLS' RESTROOM WEST OF ROOM 1329	144 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
166 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1330	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
167 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1330	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
170 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1329	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
172 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1329	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
176 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1332	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
179 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1332	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARD.					Sample #:		
181 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1331	40 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS WEST SIDE OF ROOM.					Sample #:		
182 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1331	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
187 CAD #:	X0G	Miscellaneous Material Metal Frame Chalkboard Adhesive (1964)	ROOM 1334	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
188 CAD #:	X0I	Miscellaneous Material Wired Side Light Window Glaze (1964)	ROOM 1334	2 Sq Ft	N	4 CH	5
Comments:					Sample #:		
192 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1335	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
196 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1336	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
200 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive (1966)	ROOM 1337	20 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		
203 CAD #:	J2B	Transite Piping/Ducting 1966 Addition	1966 ADDITION EAST TUNNEL SYSTEM	90 Sq Ft	N	ASSUMED	5
Comments: VISIBLE AT PENETRATIONS. ASSUMED UNDER CONCRETE SLAB.					Sample #:		
222 CAD #:	X0O	Miscellaneous Material Metal Frame Chalkboard Adhesive (1996)	THROUGHOUT 1996 ADDITION	120 Sq Ft	N	ASSUMED	5
Comments: UNDER NEW WHITEBOARDS.					Sample #:		