Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: *Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.*

EPA ASSESSMENT CATEGORIES:

1 = Damaged or significantly damaged TSI ACM
2 = Damaged friable surfacing ACM
3 = Significantly damaged friable surfacing ACM
4 = Damaged or significantly damaged friable miscellaneous ACM
5 = ACBM with potential for damage
6 = ACBM with potential for significant damage
7 = Remaining friable ACBM or friable suspect ACBM

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
9 CAD #:	B1A	Air Cell Pipe Insulation 1925 Original Building	TUNNEL (1200A) NEAR BOILER ROOM	6 Lin Ft	Y	40 CH	1
Comments: VISIBLE IN CHASE UNDER 1925 ORIGINAL BUILDING GIRLS' RESTROOM NEAR TUNNEL ENTRANCE. INACCESSIBLE FOR REPAIR/REMOVAL.					Sample #: 2001-1501-AQ-7, 8, 9		
12 CAD #:	X1A	Miscellaneous Material 6" x 6" Red/Brown Ceramic Floor Tile System	2000 HALLWAY	300 Sq Ft	N	ASSUMED	5
Comments: NEAR STAIRWELL 2099A.					Sample #:		
13 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 2206	750 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
14 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1925)	ROOM 2206	15 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARD.					Sample #:		
15 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 2203	750 Sq Ft	N	ASSUMED	5
Comments: UNDER K2M & K2O.					Sample #:		
16 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1925)	ROOM 2203	5 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		

© 2024 Institute for Environmental Assessment, Inc. All Rights Reserved.

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
22 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 3203	750 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
23 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1925)	ROOM 3203	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
24 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 3201	750 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
25 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1925)	ROOM 3201	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
27 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	1925 ORIGINAL BUILDING 3RD FLOOR STAIRWELL 4099A	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
29 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 4203	200 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
30 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 4204	750 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
31 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1925)	ROOM 4204	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
34 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 4201	750 Sq Ft	N	ASSUMED	5
Comments: UNDER CARPET.					Sample #:		
35 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1925)	ROOM 4201	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
43 CAD #:	X1B	Miscellaneous Material 4" Brown Ceramic Baseboard System	THROUGHOUT 1971 ADDITION	500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
51 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/White Swirls	NORTHEAST STAIRWELL FROM GROUND FLOOR TO 1ST FLOOR	50 Sq Ft	N	10 CH	5
Comments: ON LANDING BETWEEN 1ST & 2ND FLOORS.					Sample #:		
55 CAD #:	X1A	Miscellaneous Material 6" x 6" Red/Brown Ceramic Floor Tile System	KITCHEN AREA & STORAGE ROOMS	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
59 CAD #:	P0B	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	KITCHEN STORAGE 1112	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. LABEL PAINTED					Sample #:		
61 CAD #:	P0B	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	LAUNDRY AREAS 1111A, 1113 & HALLWAY	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
64 CAD #:	P0B	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	CUSTODIAL SLOP SINK NEXT TO KITCHEN LOCKER ROOM	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
67 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	ROOM 1106	300 Sq Ft	N	10 CH (TILE), 20 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #: 428-15		
71 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/White Swirls	NORTHWEST STAIRWELL FROM GROUND FLOOR TO 1ST FLOOR	60 Sq Ft	N	10 CH	5
Comments: LANDING BETWEEN GROUND & FIRST FLOOR. 3 CORNERS CHIPPED BY STAIRS.					Sample #: 428-14		
75 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	ROOM 1105	800 Sq Ft	N	10 CH (TILE), 20 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
76 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 1105	20 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND WHITEBOARD.					Sample #:		
78 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	ROOM 1105A (RESTROOM)	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
79 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	ROOM 1104	800 Sq Ft	N	10 CH (TILE), 20 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #:		
80 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 1104	10 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND WHITEBOARD.					Sample #:		
82 CAD #:	X1D	Miscellaneous Material 2" x 2" Beige Ceramic Floor Tile System	ROOM 1104A (RESTROOM)	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
83 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Cream w/Beige Smudges	ROOM 1103	700 Sq Ft	N	5 CH (TILE), 10 CH (MASTIC)	5
Comments: CHIPPED NEAR CENTER OF ROOM & AT OUTDOOR WALL NEAR CARPET. CRACKING AT NORTHWEST CORNER.					Sample #: 120808ML-26; 1501-AQ-19		
85 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 1103	20 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND WHITEBOARD.					Sample #:		
86 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	ROOM 1103A RESTROOM	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
87 CAD #:	X0F	Miscellaneous Material Coating on outside of Elevator Car	ELEVATOR TA17	300 Sq Ft	N	5 CH	5
Comments:					Sample #: 2402541-1		
90 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	CUSTODIAL STORAGE 1101	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
92 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	CUSTODIAL STORAGE 1202	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. DAMAGED EDGE BOTTOM OUTSIDE BY HINGE - CAN SEE WHITE STYROFOAM, MONITOR.					Sample #:		
95 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	GYMNASIUM STORAGE 1203	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
99 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	STORAGE ROOMS 1204/1205	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS. 1204 DOOR HAS LARGE CHIP ON INSIDE EDGE. 1205 DOOR HAS SMALL CHIP ON OUTSIDE EDGE. CORE NOT EXPOSED. MONITOR.					Sample #:		
104 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	BOYS' RESTROOM 1207	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
105 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	GIRLS' RESTROOM 1206	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
106 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	STORAGE 1208A	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR					Sample #:		
111 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	GIRLS' LOCKER ROOM 1211	220 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
112 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	BOYS' LOCKER ROOM 1214	220 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
117 CAD #:	X1E	Miscellaneous Material 1" x 1" Blue Ceramic Floor Tile System	POOL 1114	1500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
119 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	POOL OFFICE 1213	150 Sq Ft	N	10 CH (TILE), 20 CH (MASTIC)	5
Comments: INCLUDES REPLACEMENT TILES BY POOL ENTRANCE DOOR.					Sample #:		
120 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	POOL OFFICE 1213 RESTROOM	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
121 CAD #:	K2A	12" x 12" Vinyl Floor Tile & Mastic Light Brown w/Brown & Beige Smudges	POOL OFFICE FILTER ROOM 1213B	30 Sq Ft	N	10 CH (TILE), 20 CH (MASTIC)	5
Comments:					Sample #: 2001-1501-AQ-17		
122 CAD #:	P0B	Fire Doors Metal - 1.5 Hr Rating (Underwriter's Laboratories)	POOL TUNNEL 0114	60 Sq Ft	N	ASSUMED	5
Comments: THREE (3) DOORS. TWO (2) AT ENTRANCE & ONE (1) STORED.					Sample #:		
133 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	NURSE'S OFFICE 2202 RESTROOM	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
135 CAD #:	X1C	Miscellaneous Material 1" x 1" Green/Brown/White Ceramic Floor Tile System	BOYS' AND GIRLS' RESTROOM NEXT TO ROOM 2103	500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
137 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2103	15 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND WHITEBOARD.					Sample #:		
138 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2103	1 Sq Ft	N	10 CH	5
Comments:					Sample #: 120808ML-12		
139 CAD #:	V0B	Sink Undercoating Black	ROOM 2103	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #: 120808ML-13		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
141 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2104	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
142 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2104	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
143 CAD #:	V0B	Sink Undercoating Black	ROOM 2104	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
145 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2105	10 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND WHITEBOARD.					Sample #:		
146 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2105	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
147 CAD #:	V0B	Sink Undercoating Black	ROOM 2105	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
149 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2106	10 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND WHITEBOARD.					Sample #:		
150 CAD #:	V0B	Sink Undercoating Black	ROOM 2106	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
156 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2107	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
157 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2107	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
158 CAD #:	V0B	Sink Undercoating Black	ROOM 2107	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
160 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2108	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
161 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2108	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
162 CAD #:	V0B	Sink Undercoating Black	ROOM 2108	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
164 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2109	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
165 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2109	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
166 CAD #:	V0B	Sink Undercoating Black	ROOM 2109	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
168 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2110	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
169 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2110	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
170 CAD #:	V0B	Sink Undercoating Black	ROOM 2110	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
177 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2207	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.					Sample #:		
178 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2207	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
179 CAD #:	V0B	Sink Undercoating Black	ROOM 2207	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
181 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2208	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.					Sample #:		
182 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 2208	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
183 CAD #:	V0B	Sink Undercoating Black	ROOM 2208	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
184 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 2211	15 Sq Ft	N	ASSUMED	5
Comments: MOST BEHIND WHITEBOARD.					Sample #:		
185 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Cream w/Beige Smudges	STORAGE ROOM 2211A	100 Sq Ft	N	5 CH (TILE), 10 CH (MASTIC)	5
Comments:					Sample #:		
186 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Cream w/Beige Smudges	STORAGE ROOM 2211B	100 Sq Ft	N	5 CH (TILE), 10 CH (MASTIC)	5
Comments: SCRAPED TILE. MONITOR.					Sample #:		
187 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	ENTRANCE 2200B TO ROOM 2213	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
188 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Cream w/Beige Smudges	ROOM 2214	170 Sq Ft	N	5 CH (TILE), 10 CH (MASTIC)	5
Comments: RUG COVERS MOST OF ROOM. CORNER OF TILE MISSING BY COUNTER LEFT OF DOOR.					Sample #:		
190 CAD #:	K2B	12" x 12" Vinyl Floor Tile & Mastic Cream w/Beige Smudges	ROOM 2212	170 Sq Ft	N	5 CH (TILE), 10 CH (MASTIC)	5
Comments: SMALL GOUGE BY LARGE CABINETS.					Sample #:		
191 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	STUDIO ROOM 2213	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
197 CAD #:	X1E	Miscellaneous Material 1" x 1" Blue Ceramic Floor Tile System	RESTROOMS 3101 & 3102	500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
203 CAD #:	P0E	Fire Doors Wood - 1 Hr Rating (Underwriter's Laboratories)	2ND FLOOR STAIRWELL 3299D	40 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
208 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3206	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
209 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3206	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
211 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3103	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
212 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3103	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
213 CAD #:	V0B	Sink Undercoating Black	ROOM 3103	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
215 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3104	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
216 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3104	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
217 CAD #:	V0B	Sink Undercoating Black	ROOM 3104	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
219 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3105	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
220 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3105	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
221 CAD #:	V0B	Sink Undercoating Black	ROOM 3105	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
223 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3106	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
224 CAD #:	V0B	Sink Undercoating Black	ROOM 3106	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
229 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3107	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
230 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3107	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
231 CAD #:	V0B	Sink Undercoating Black	ROOM 3107	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
233 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3108	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
234 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3108	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
235 CAD #:	V0B	Sink Undercoating Black	ROOM 3108	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
237 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3109	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
238 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3109	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
239 CAD #:	V0B	Sink Undercoating Black	ROOM 3109	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
241 CAD #:	X0A	Miscellaneous Material Metal Frame Chalkboard Adhesive (1971)	ROOM 3110	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
242 CAD #:	X0B	Miscellaneous Material Wired Window Glaze (1971)	ROOM 3110	1 Sq Ft	N	10 CH	5
Comments:					Sample #:		
243 CAD #:	V0B	Sink Undercoating Black	ROOM 3110	5 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		