

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:		1 = Damaged or significantly damaged TSI ACM 2 = Damaged friable surfacing ACM 3 = Significantly damaged friable surfacing ACM 4 = Damaged or significantly damaged friable miscellaneous ACM		5 = ACBM with potential for damage 6 = ACBM with potential for significant damage 7 = Remaining friable ACBM or friable suspect ACBM			
IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assessment Category
11 CAD #:	D2A	Interior Boiler Insulation Burner Refractory	BOILER ROOM 0300	4 Sq Ft	N	ASSUMED	5
Comments: TWO (2) BOILERS.					Sample #:		
20 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Cream w/Brown Streaks	MECHANICAL ROOM 0301	20 Sq Ft	N	3 CH (MASTIC)	5
Comments: TILE ONLY. STORED ON SHELF IN SOUTHEAST CORNER.					Sample #:		
23 CAD #:	X00	Miscellaneous Material Black Dampproofing	MECHANICAL ROOM 0301	1000 Sq Ft	N	ASSUMED	5
Comments: ON WALLS AND CEILING.					Sample #:		
31 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	THROUGHOUT 1925 ORIGINAL BUILDING	5000 Sq Ft	N	ASSUMED	5
Comments: ALL ELEVATED.					Sample #:		
32 CAD #:	X1C	Miscellaneous Material 6" X 6" Red Quarry Tile System	1925 ORIGINAL BUILDING ENTRANCES	500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
33 CAD #:	K2F	12" x 12" Vinyl Floor Tile & Mastic Cream w/Brown Streaks	1925 ORIGINAL BUILDING 1ST FLOOR HALLWAY	800 Sq Ft	N	3 CH (MASTIC)	5
Comments:					Sample #:	310-TB5-A, B, C	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
37 CAD #:	X0M	Miscellaneous Material Stone Panel Adhesive (1925)	BOYS' RESTROOM 1302	20 Sq Ft	N	ASSUMED	5
Comments: WEST OF ROOM 1304.					Sample #:		
39 CAD #:	X2B	Miscellaneous Material 4" X 4" Beige Ceramic Wall Tile System	STAFF RESTROOM 1202 ACROSS FROM MAIN OFFICE 1001	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
40 CAD #:	X1B	Miscellaneous Material 1" Beige & Blue Ceramic Floor Tile System	STAFF RESTROOM 1202 ACROSS FROM MAIN OFFICE 1001	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
57 CAD #:	K3A	Miscellaneous Flooring Brown Stair Treads	1925 ORIGINAL BUILDING NORTHEAST STAIRWELL 1299A	30 Sq Ft	N	3 CH (TREAD ONLY)	5
Comments: ONE (1) CHIPPED AT TOP STAIR LOWER RISER.					Sample #: 121708ML-37		
66 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 2205A	240 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
67 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Cream w/White Streaks	ROOMS 2207 & 2208	720 Sq Ft	N	8 CH (TILE), 3 CH (MASTIC)	5
Comments: WEARING FROM CHAIR CASTERS AT TEACHER'S DESK. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #: 121708ML-57		
72 CAD #:	S0A	Wood Floor Felt / Vapor Barrier 1925 Original Building	ROOM 2206A	240 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
84 CAD #:	X0M	Miscellaneous Material Stone Panel Adhesive (1925)	STAFF RESTROOM 3203 SOUTH OF 1925 ORIGINAL BUILDING STAIRWELL	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
88 CAD #:	J3B	Miscellaneous Cementitious Material Black Fume Hood Base	ROOM 3202	6 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
92 CAD #:	X0M	Miscellaneous Material Stone Panel Adhesive (1925)	BOYS' RESTROOM 3302	20 Sq Ft	N	ASSUMED	5
Comments: WEST OF ROOM 3306.					Sample #:		
95 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1937 Addition	THROUGHOUT 1937 ADDITION	5000 Sq Ft	N	ASSUMED	5
Comments: ALL ELEVATED.					Sample #:		
98 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	CAFETERIA 1102	1025 Sq Ft	N	10 CH	5
Comments: MOST ABOVE CEILING.					Sample #: 121708ML-10		
102 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 1006	2 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
112 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1307	18 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
115 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1309	8 Sq Ft	N	ASSUMED	5
Comments: BEHIND METAL SHELIVING.					Sample #:		
116 CAD #:	X0K	Miscellaneous Material Thin Metal Frame Corkboard Adhesive	ROOM 1308	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
117 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1308	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
118 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 1308	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
121 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1313	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARD.					Sample #:		
122 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 1313	3 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
124 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1310	50 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
126 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1315	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARD.					Sample #:		
127 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 1315	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
129 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 1312	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARD.					Sample #:		
130 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 1312	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
132 CAD #:	X2B	Miscellaneous Material 4" X 4" Beige Ceramic Wall Tile System	RESTROOM 1314B	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
133 CAD #:	X1D	Miscellaneous Material 2" X 2" Taupe Ceramic Floor Tile System	RESTROOM 1314B	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
138 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2312	50 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARD.					Sample #:		
139 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2312	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
141 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2313	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
142 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2313	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
144 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2310	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
145 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2310	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
147 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2311	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
148 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2311	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
150 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2308	80 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
151 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2308	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
153 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2309	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
154 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2309	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
156 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2306	60 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
157 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2306	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
159 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 2307	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
160 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2307	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
161 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2303	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
162 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 2305	5 Sq Ft	N	ASSUMED	5
Comments: ACCESS THROUGH ROOM 2303.					Sample #:		
163 CAD #:	X0N	Miscellaneous Material Stone Panel Adhesive (1937)	BOYS' RESTROOM 2304	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
164 CAD #:	X0N	Miscellaneous Material Stone Panel Adhesive (1937)	GIRLS' RESTROOM 2102	40 Sq Ft	N	ASSUMED	5
Comments: ACROSS FROM CLASSROOM 2102.					Sample #:		
170 CAD #:	B2B	Millboard Pipe Insulation 1937 Addition	AUDITORIUM 2104	160 Lin Ft	N	ASSUMED	5
Comments: ESTIMATED IN DECORATIVE PLASTER SOFFIT AT CEILING & IN WALL CHASES.					Sample #:		
171 CAD #:	A2B	Mudded Pipe Joints on Millboard Insulation 1937 Addition	AUDITORIUM 2104	20 Joints	N	ASSUMED	5
Comments: ESTIMATED IN DECORATIVE PLASTER SOFFIT AT CEILING & IN WALL CHASES.					Sample #:		
173 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	AUDITORIUM 2104	600 Sq Ft	N	10 CH	5
Comments:					Sample #: 121708ML-71		
174 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	AUDITORIUM 2104	8 Sq Ft	N	ASSUMED	5
Comments: TWO (2) BOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
175 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	AUDITORIUM STORAGE 2105	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
176 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	AUDITORIUM STORAGE 2107	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
178 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 3103	3 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
181 CAD #:	X0N	Miscellaneous Material Stone Panel Adhesive (1937)	GIRLS' RESTROOM 3101	40 Sq Ft	N	ASSUMED	5
Comments: ACROSS FROM ROOM 3104.					Sample #:		
184 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3303	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
185 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 3303	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
187 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3306	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
188 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	ROOM 3306	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
190 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3305	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
192 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3308	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
194 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3307	110 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
196 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3310	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
198 CAD #:	W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A	ROOM 3312	205 Sq Ft	N	10 CH	5
Comments: ABOVE CEILING.					Sample #: 121708ML-56		
200 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3312	60 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
202 CAD #:	X0H	Miscellaneous Material Corkboard Adhesive (1937)	ROOM 3309	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
205 CAD #:	X0L	Miscellaneous Material Wood Frame Corkboard Adhesive (1937)	STAIRWELL 1399A	10 Sq Ft	N	ASSUMED	5
Comments: THREE (3) BOARDS. ONE (1) ON EACH LANDING.					Sample #:		
206 CAD #:	X0K	Miscellaneous Material Thin Metal Frame Corkboard Adhesive	OFFICE 3399	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
221 CAD #:	S0C	Wood Floor Felt / Vapor Barrier On Grade (1965)	1965 ADDITION GYMNASIUM 0401	6000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
222 CAD #:	R0L	Baseboard/Mopboard Adhesive 4" Black Angled Baseboard	1965 ADDITION GYMNASIUM 0401	600 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
224 CAD #:	X0J	Miscellaneous Material Metal Frame Corkboard Adhesive (1965)	1965 ADDITION GYMNASIUM ENTRANCES	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
226 CAD #:	X1E	Miscellaneous Material 1" X 1" Light Gray Ceramic Floor Tile System (1965)	THROUGHOUT 1965 LOCKER ROOM AREAS	1500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
227 CAD #:	A4C	Mudded Pipe Joints on Fiberglass Insulation 1965 Addition	CHASE WALLS FOR BOYS' & GIRLS' SHOWERS	20 Joints	N	ASSUMED	5
Comments: ESTIMATED. PARTIALLY VISIBLE FROM ROOM 0409. INACCESSIBLE FOR REMOVAL.					Sample #:		
228 CAD #:	A4C	Mudded Pipe Joints on Fiberglass Insulation 1965 Addition	BOYS' LOCKER ROOM TOILET/URINAL PIPE CHASE	3 Joints	N	ASSUMED	5
Comments: VISIBLE FROM ROOM 0409. INACCESSIBLE FOR REMOVAL.					Sample #:		
229 CAD #:	X1F	Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System (1965)	RESTROOMS 0407 & 0410	500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
232 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1965)	FLIGHT SIMULATOR ROOM 0408	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
233 CAD #:	X0J	Miscellaneous Material Metal Frame Corkboard Adhesive (1965)	FLIGHT SIMULATOR ROOM 0408	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
235 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1965)	ROOM 0406	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
244 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	TRAINING ROOM (1402)	1500 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments:					Sample #: 315-16		
246 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	AUXILIARY GYMNASIUM (1420)	1000 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments:					Sample #:		
248 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	CLASSROOM 1422	500 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments:					Sample #:		
250 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	ROOM 1403	1100 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments: MULTIPLE DENTS AND CHIPS THROUGHOUT. SEALED WITH WAX.					Sample #: 2001-1501 AP15		
251 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	STORAGE ROOM 1403A	150 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments:					Sample #:		
253 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	ROOM 1405	1100 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments: PIECE OF TILE MISSING WITH MASTIC EXPOSED BY SINK.					Sample #:		
254 CAD #:	X0I	Miscellaneous Material Metal Frame Chalkboard Adhesive (1965)	ROOM 1405	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
255 CAD #:	X0J	Miscellaneous Material Metal Frame Corkboard Adhesive (1965)	ROOM 1405	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
256 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	STORAGE ROOM 1405A	150 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments: REPLACEMENT TILES ALONG NORTH WALL.					Sample #:		
258 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	ROOM 1407	1100 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments:					Sample #:		
259 CAD #:	X0J	Miscellaneous Material Metal Frame Corkboard Adhesive (1965)	ROOM 1407	60 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
260 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	STORAGE 1407A	150 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments: PARTIALLY UNDER BLUE CARPET.					Sample #:		
262 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	ROOM 1409	1100 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments: SMALL CHIP 10' FROM ENTRANCE. SEALED WITH WAX.					Sample #:		
263 CAD #:	X0J	Miscellaneous Material Metal Frame Corkboard Adhesive (1965)	ROOM 1409	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
264 CAD #:	K0F	9" x 9" Vinyl Floor Tile & Mastic White w/Gray Streaks	ROOM 1409A	150 Sq Ft	N	8 CH (TILE), 15 CH (MASTIC)	5
Comments:					Sample #:		
265 CAD #:	X1F	Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System (1965)	1965 ADDITION RESTROOMS 1404 & 1408	500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		