



## **INSPECTION CERTIFICATION for Saint Paul Public Schools -- Area Learning Center**

### **STATEMENT OF BUILDING ACCESS**

On behalf of Saint Paul Public Schools for Area Learning Center, I certify that I have provided access to all areas within the building to IEA's inspector identified below for the purpose of inspecting for asbestos-containing building materials (ACBM) as mandated by 40 CFR 763.85, "Inspections and Reinspections."


Additionally, I have discussed any concerns I have regarding identified or non-identified ACBM within this building.


  
Signature

  
Date of Inspection

### **INSPECTOR**

As mandated by 40 CFR 763.85, "Inspections and Reinspections," I certify that I have inspected all accessible areas in Area Learning Center for the purpose of identifying and assessing asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Inspector. A copy of my certification/accreditation is attached.

  
Signature  
Grant Gervais  
Print Name

  
Date of Inspection  
AZ15101  
State Certification/Accreditation Number

### **MANAGEMENT PLANNER**

I certify that I have reviewed all of the inspection data for Area Learning Center and have appropriately provided assessments and response actions for identified asbestos-containing building materials. I have completed an EPA-approved course and all appropriate refresher courses and am an accredited AHERA Management Planner. A copy of my certification/accreditation is attached.

  
Signature  
Matt Lindberg  
Print Name

  
Date of Review  
Am389C  
State Certification/Accreditation Number

## Inspector State Certification/Accreditation

---



**m** ASBESTOS  
DEPARTMENT OF HEALTH INSPECTOR

Certified by:

State of Minnesota  
Department of Health

**Expires: 05/16/2025**

**Grant O. Gervais**  
**1031 13th Ave Se**  
**Minneapolis, MN 55414**

*SPH*  
Director, Env. Health Div.

No AI15101

Issued: 06/06/2024

## Management Planner State Certification/Accreditation

---



**m** ASBESTOS  
DEPARTMENT OF HEALTH MANAGEMENT

Certified by: **PLANNER**

State of Minnesota  
Department of Health

**Expires: 08/02/2025**

**Matt A Lindberg**  
**11816 Ghia St NE**  
**Blaine, MN 55449**

*SPH*  
Director, Env. Health Div.

No AM3896

Issued: 08/20/2024

## Chart A - Immediate Response Situations

The following is a list of those events that contain damaged asbestos material and should be considered to be potential hazards. It is imperative that the following immediate response situations are corrected as soon as possible but no later than six months from the date of this inspection to avoid increased risk of exposure to airborne asbestos fibers. The district should take extra precaution to ensure that properly trained personnel use appropriate techniques to implement these responses.

Following is an explanation of the immediate Response Action codes identified in this report.

| EPA ASSESSMENT CATEGORY                                         | RESPONSE ACTION                                                     |
|-----------------------------------------------------------------|---------------------------------------------------------------------|
| 1 = Damaged or significantly damaged TSI ACM.                   | A = Cleanup ACM debris.                                             |
| 2 = Damaged friable surfacing ACM.                              | B = Encapsulate slight damage on TSI.                               |
| 3 = Significantly damaged friable surfacing ACM.                | C = Patch TSI and/or repair ACM cover.                              |
| 4 = Damaged or significantly damaged friable miscellaneous ACM. | D = Enclose or protect accessible sections with protective barrier. |
| 5 = ACBM with potential for damage.                             | E = Remove section of damaged ACM.                                  |
| 6 = ACBM with potential for significant damage.                 | F = Remove ACM and replace with non-ACM.                            |
| 7 = Remaining friable ACBM or friable suspected ACBM.           | G = Isolate area until repaired/removed.                            |
|                                                                 | H = Encapsulate slight damage.                                      |
|                                                                 | I = Remove and replace damaged or loose tile section.               |
|                                                                 | J = Monitor condition of material(s).                               |

| IEA Event No. | Material Type | Material Id/Desc | Location | Estimated Amount Total | Estimated Amount of Damage | EPA Assess. | Immediate Response Action | Comments |
|---------------|---------------|------------------|----------|------------------------|----------------------------|-------------|---------------------------|----------|
|---------------|---------------|------------------|----------|------------------------|----------------------------|-------------|---------------------------|----------|

There were no damaged materials identified during the inspection of this building.