

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:		1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
		2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
		3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
		4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
11 CAD #:	B2A	Millboard Pipe Insulation 1963 Original Building	THROUGHOUT 1963 ORIGINAL BUILDING	200 Lin Ft	N	10 CH	5
Comments: INACCESSIBLE. INSIDE WALLS. AMOUNT ESTIMATED. FOR DRINKING FOUNTAINS, LOCKER ROOM FIXTURES, ETC.					Sample #: ACB450-AB-01		
12 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1963 Original Building	THROUGHOUT 1963 ORIGINAL BUILDING	50 Joints	N	30 CH	5
Comments: INACCESSIBLE. INSIDE WALLS. AMOUNT ESTIMATED. FOR DRINKING FOUNTAINS, LOCKER ROOM FIXTURES, ETC.					Sample #:		
13 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	THROUGHOUT 1963 ORIGINAL BUILDING	75 Joints	N	35 CH	5
Comments: INACCESSIBLE. INSIDE WALLS. AMOUNT ESTIMATED.					Sample #: 2001-1501-JN-04		
20 CAD #:	X1A	Miscellaneous Material 1" X 1" Blue Ceramic Floor Tile System	BOYS' PHY ED LOCKER ROOM 0306	800 Sq Ft	N	ASSUMED	5
Comments: RESTROOM & SHOWER AREAS.					Sample #:		
25 CAD #:	X1A	Miscellaneous Material 1" X 1" Blue Ceramic Floor Tile System	BOYS' LOCKER ROOM OFFICE 0307 RESTROOM	20 Sq Ft	N	ASSUMED	5
Comments: SHOWER AREA.					Sample #:		
28 CAD #:	X0C	Miscellaneous Material Pipe/Valve Flange Gaskets	POOL MECHANICAL ROOM 0311	3 Sq Ft	N	55 CH	5
Comments: THREE (3) OLD GASKETS. ACCESS THROUGH UNMARKED DOOR NEXT TO EXIT #13.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
31 CAD #:	X1A	Miscellaneous Material 1" X 1" Blue Ceramic Floor Tile System	GIRLS' PHY ED LOCKER ROOM 0301	540 Sq Ft	N	ASSUMED	5
Comments: SHOWER & RESTROOM AREAS.					Sample #:		
33 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	GIRLS' PHY ED LOCKER ROOM OFFICE 0302	6 Sq Ft	N	5 CH	5
Comments:					Sample #:		
34 CAD #:	X1B	Miscellaneous Material 1" X 1" Gray/Blue/White Pool Ceramic Tile System	POOL AREA 0305	4000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
35 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 0304A	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
37 CAD #:	X1C	Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System	GIRLS' VARSITY LOCKER ROOM 0401	315 Sq Ft	N	ASSUMED	5
Comments: SHOWER & RESTROOM AREAS.					Sample #:		
39 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	GIRLS' VARSITY LOCKER ROOM OFFICE 0402	4 Sq Ft	N	5 CH	5
Comments:					Sample #:		
40 CAD #:	X1C	Miscellaneous Material 1" X 1" Beige Ceramic Floor Tile System	GIRLS' VARSITY LOCKER ROOM OFFICE 0402 RESTROOM	20 Sq Ft	N	ASSUMED	5
Comments: SHOWER AREA.					Sample #:		
42 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 0216D	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
53 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	ROOM 0216	660 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
55 CAD #:	J3A	Miscellaneous Cementitious Material Black Table Tops w/Metal Legs	ROOM 0218 (CERAMICS CLASSROOM)	20 Sq Ft	N	20 CH	5
Comments: TWO (2) TABLES. CHIPPED CORNERS.					Sample #:		
57 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0218 (CERAMICS CLASSROOM)	10 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD IN SOUTHWEST CORNER.					Sample #:		
58 CAD #:	V0A	Sink Undercoating Black	ROOM 0217A (KILN AREA)	5 Sq Ft	N	6 CH	5
Comments: ONE (1) SINK.					Sample #: 021610-MA-09		
62 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0217	25 Sq Ft	N	5 CH	5
Comments:					Sample #:		
63 CAD #:	J1A	Cementitious Panels Gray Panels	ROOM 0215C (BACK CORNER)	1 Sq Ft	N	ASSUMED	5
Comments: ROUND POTTERY WHEELS IN STORAGE LOCKER #2.					Sample #:		
64 CAD #:	J3A	Miscellaneous Cementitious Material Black Table Tops w/Metal Legs	ROOM 0215A (ART STORAGE)	20 Sq Ft	N	20 CH	5
Comments: TWO (2) TABLES.					Sample #:		
66 CAD #:	P0C	Fire Doors Metal Jacket -1.5 Hr Rating (Underwriters Laboratories)	MECHANICAL ROOM 0215A	50 Sq Ft	N	ASSUMED	5
Comments: TWO (2) DOORS.					Sample #:		
70 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0215	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
74 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0214	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
78 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	ROOM 0212 (WEIGHT ROOM)	8 Sq Ft	N	ASSUMED	5
Comments: ASSUMED PRESENT BEHIND NEW MIRRORS ON NORTH WALL.					Sample #:		
82 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0211 (WOOD SHOP CLASSROOM)	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		
84 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0208 (WOOD SHOP)	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
88 CAD #:	B2A	Millboard Pipe Insulation 1963 Original Building	RESTROOM 0206 PIPE CHASE	30 Lin Ft	N	10 CH	5
Comments: VISIBLE FROM ABOVE CEILING IN RESTROOM. INACCESSIBLE FOR REMOVAL.					Sample #:		
89 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1963 Original Building	RESTROOM 0206 PIPE CHASE	4 Joints	N	30 CH	5
Comments: VISIBLE FROM ABOVE CEILING IN RESTROOM. INACCESSIBLE FOR REMOVAL.					Sample #:		
90 CAD #:	B3B	Pre-Formed Pipe Insulation Water Lines	RESTROOM 0206 PIPE CHASE	30 Lin Ft	N	ASSUMED	5
Comments: VISIBLE FROM ABOVE CEILING IN RESTROOM. INACCESSIBLE FOR REMOVAL OR SAMPLING. SAMPLE 01 WAS ANALYZED AS "NONE DETECTED", BUT TWO (2) ADDITIONAL SAMPLES ARE REQUIRED TO CONFIRM.					Sample #: 072512MA-01		
91 CAD #:	A3B	Mudded Pipe Joints on Pre-formed Insulation Water Lines	RESTROOM 0206 PIPE CHASE	6 Joints	N	20 CH	5
Comments: VISIBLE FROM ABOVE CEILING IN RESTROOM. INACCESSIBLE FOR REMOVAL.					Sample #: 072512MA-02		
92 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 0205	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
96 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 0204	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		
113 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1299D	1000 Sq Ft	N	ASSUMED	5
Comments: SIXTEEN (16) REPLACEMENT TILES AT LOWER LEVEL ENTRANCE.					Sample #:		
120 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1201	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: REPLACEMENT TILES IN SOUTHEAST CORNER. CHIPPED TILE 10' FROM ENTRANCE. WEAR AT TEACHER'S DESK, RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
121 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1201	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
122 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1201	15 Sq Ft	N	5 CH	5
Comments:					Sample #:		
123 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1207	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: CHIPPED TILE IN NORTHWEST CORNER UNDER TEACHER'S DESK. REPLACEMENT TILES IN SOUTHWEST CORNER. WEAR AT TEACHER'S DESK, RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
124 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1209	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILE PIECES MISSING BETWEEN 1209 & 1211A OFFICE. REPLACEMENT TILES BY EAST WALL.					Sample #:		
127 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1211/1211A	380 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments:					Sample #:		
128 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1211/1211A	8 Sq Ft	N	5 CH	5
Comments:					Sample #:		
129 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 1204	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
131 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1213	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: REPLACEMENT TILES AT TEACHER'S DESK. CHIPS AND GOUGES THROUGHOUT.					Sample #:		
132 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1213	10 Sq Ft	N	5 CH	5
Comments: ASSUMED PRESENT BEHIND TACKBOARD.					Sample #:		
133 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1213	15 Sq Ft	N	5 CH	5
Comments:					Sample #:		
135 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1208	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON WEST WALL.					Sample #:		
136 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1208	10 Sq Ft	N	5 CH	5
Comments:					Sample #:		
138 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1215	5 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
139 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1215	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
140 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1299E	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
142 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1212	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: ONE (1) TILE MISSING BY EAST WALL.					Sample #:		
143 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1212	6 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON WEST WALL.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
144 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1212	20 Sq Ft	N	5 CH	5
Comments: THREE (3) BOARDS.					Sample #:		
147 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1214	420 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
148 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1214	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
149 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1219	1350 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: INCLUDES MATERIAL UNDER 12" TILES. TABLES & CHAIRS SCRATCHING FLOOR TILE. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
151 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1219	10 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON NORTH WALL.					Sample #:		
152 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1219	10 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON SOUTH WALL.					Sample #:		
154 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1219 OFFICE & STORAGE ROOMS (1219A, B & C)	460 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: WORN FROM CHAIR CASTERS IN ROOM 1219C, RECOMMEND CHAIR MAT.					Sample #: 021610-MA-39		
155 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1218	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
156 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1218	15 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON WEST WALL COVERED WITH TACKBOARD.					Sample #:		
157 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1218	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
158 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1221	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILE WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
159 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1221	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
163 CAD #:	B2A	Millboard Pipe Insulation 1963 Original Building	RESTROOM ACROSS FROM 1221	10 Lin Ft	N	10 CH	5
Comments: ASSUMED PRESENT IN NARROW PART OF CHASE. INACCESSIBLE W/O DEMOLITION.					Sample #:		
164 CAD #:	A2A	Mudded Pipe Joints on Millboard Insulation 1963 Original Building	RESTROOM ACROSS FROM 1221	4 Joints	N	30 CH	5
Comments: ASSUMED PRESENT IN NARROW PART OF CHASE. INACCESSIBLE W/O DEMOLITION.					Sample #: 207W-4A, 6A		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
165 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1499F	2000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
172 CAD #:	S0A	Wood Floor Felt / Vapor Barrier On-Grade (1963)	ROOM 1302 (CLAIR MCMANN GYMNASIUM)	12000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
173 CAD #:	X1I	Miscellaneous Material 1" X 1" White Ceramic Floor Tile System	ROOM 1302 (CLAIR MCMANN GYMNASIUM)	25 Sq Ft	N	ASSUMED	5
Comments: AT DRINKING FOUNTAINS.					Sample #:		
174 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1302 (CLAIR MCMANN GYMNASIUM)	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD. SOUTH ENTRANCE.					Sample #:		
175 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1399G	700 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
176 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1399H	700 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
177 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	STORAGE 1305	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
181 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	THROUGHOUT KITCHEN AREA	2000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
183 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	KITCHEN CUSTODIAL CLOSET 1413	25 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
184 CAD #:	X0B	Miscellaneous Material Adhesive for Yellow Milkboard	KITCHEN STORAGE 1403	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
185 CAD #:	X0B	Miscellaneous Material Adhesive for Yellow Milkboard	KITCHEN DISHWASHING AREA	100 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
186 CAD #:	B3A	Pre-Formed Pipe Insulation 1963 Original Building - Heating Lines	KITCHEN BREAK AREA 1409	8 Lin Ft	N	60 AM	5
Comments: IN WALL CHASE AT BOTTOM OF STAIRS. INACCESSIBLE FOR REMOVAL. RECOMMEND VERIFICATION SAMPLING IF POSSIBLE.					Sample #: 207W1A		
187 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	KITCHEN BREAK AREA 1409	310 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILE CRACKING AT ENTRANCE.					Sample #:		
188 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1399I	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
190 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 1306	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
192 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1399J	600 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
194 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL HALLWAY 1309A	30 Sq Ft	N	ASSUMED	5
Comments: AT SLOP SINK.					Sample #:		
196 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	CUSTODIAL BREAK ROOM 1311	1 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
199 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ENGINEER'S OFFICE 1310	8 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
200 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1499K	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
206 CAD #:	X1K	Miscellaneous Material 1" X 1" Gray w/White & Blue Accents Ceramic Floor Tile System	1996 ADDITION FIELDHOUSE RESTROOMS	432 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
208 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1963)	AUDITORIUM STAGE 1504	2000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
211 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	AUDITORIUM LOBBY 1501	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD. NORTH WALL, EAST END.					Sample #:		
218 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 1010B	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
222 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1017	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD PRESENT BEHIND WOOD PANEL ON EAST WALL.					Sample #:		
223 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1017	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
225 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1018	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
227 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1099B	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
229 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	NURSE'S OFFICE ROOM 1019	275 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: WEARING UNDER CHAIRS W/WHEELS. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
231 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	NURSE'S OFFICE ROOM 1019	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
232 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	NURSE'S OFFICE ROOM 1020	225 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
233 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	NURSE'S OFFICE ROOM 1020	1 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
234 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	NURSE'S OFFICE ROOM 1020A	30 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: <u>PIECE MISSING NEAR ENTRANCE.</u>					Sample #:		
235 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	NURSE'S OFFICE RESTROOM 1020B	48 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: <u>REPLACEMENT TILES AT TOILET & SINK.</u>					Sample #:		
236 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	NURSE'S OFFICE RESTROOM 1020B	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
238 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	NURSE'S OFFICE ROOM 1021	187 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments:					Sample #:		
239 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	NURSE'S OFFICE ROOM 1021	1 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
240 CAD #:	K0B	9" x 9" Vinyl Floor Tile & Mastic Brown w/Dark Brown & Beige Streaks	RESTROOM 1021A	45 Sq Ft	N	5 CH (MASTIC ONLY)	5
Comments:					Sample #:	021610-MA-41	
242 CAD #:	R0F	Baseboard/Mopboard Adhesive 4" Dark Brown Baseboard	STORAGE 1021B AND RESTROOM	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
245 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	CLINIC AREA 1022	6 Sq Ft	N	5 CH	5
Comments: <u>ONE (1) BOARD.</u>					Sample #:		
247 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	CLINIC AREA 1026	4 Sq Ft	N	5 CH	5
Comments: <u>ONE (1) BOARD.</u>					Sample #:		
248 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1102	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: <u>CHIPPED TILE IN SW CORNER. WEARING UNDER TEACHER'S CHAIR, RECOMMEND CHAIR MAT. SEALED WITH WAX.</u>					Sample #:		
249 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1102	5 Sq Ft	N	5 CH	5
Comments: <u>ONE (1) BOARD.</u>					Sample #:		
250 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1102	15 Sq Ft	N	5 CH	5
Comments: <u>TWO (2) BOARDS.</u>					Sample #:		
251 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1101	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: <u>WEARING & SCRATCHING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT. SEALED WITH WAX.</u>					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
252 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1101	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
253 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1104	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON EAST WALL.					Sample #:		
254 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1104	20 Sq Ft	N	5 CH	5
Comments: FOUR (4) BOARDS.					Sample #:		
257 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1103	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILES COMING LOOSE DOWN MIDDLE OF ROOM. REPLACEMENT TILES AT ENTRANCES & WINDOWS. WEARING UNDER TEACHER'S DESK. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
258 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1103	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
259 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1103	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
261 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1105/1103A	420 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TWO (2) ROOMS. WEARING UNDER CHAIRS. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
262 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1105	3 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
263 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1107	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: SMALL CHIP AT ENTRANCE. TILE IS WORN. RECOMMEND SEALING WITH WAX.					Sample #:		
264 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 1106	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
265 CAD #:	X1D	Miscellaneous Material 6" X 6" Tan Quarry Tile System	STAIRWELL 1199C	1000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
267 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1109	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
271 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 1113	750 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: WEARING UNDER DESKS & CHAIRS. RECOMMEND CHAIR MAT. SEALED WITH WAX.					Sample #:		
272 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1113	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
273 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1113	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
280 CAD #:	B2A	Millboard Pipe Insulation 1963 Original Building	LIBRARY 1110	80 Lin Ft	N	10 CH	5
Comments: INACCESSIBLE ABOVE PLASTER CEILING.					Sample #:		
281 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	LIBRARY 1110	80 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD, PAINTED WHITE. ON SOUTH WALL BETWEEN 1114 & 1116.					Sample #:		
288 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 1119	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
289 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 1119	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
297 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2203	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
299 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2203	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
300 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	CUSTODIAL CLOSET 2204	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
302 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2206	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
304 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2205	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
305 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2205	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
307 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2208	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
308 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2208	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
309 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2207	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
310 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2208	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
312 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2207	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
313 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2207	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
314 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2210	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
317 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2210	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
318 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2210	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
319 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2209	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
321 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2209	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
322 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2209	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
326 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2211	30 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS ON NORTH WALL. THREE (3) BOARDS ON EAST WALL.					Sample #:		
329 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2218	10 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD ON SOUTH WALL. ONE (1) BOARD ON NORTH WALL BETWEEN TACKBOARDS COVERED WITH PAPER.					Sample #:		
330 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2218	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
331 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2220	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
333 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2220	6 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
335 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	2ND FLOOR TEACHERS' LOUNGE 2222	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
342 CAD #:	X1M	Miscellaneous Material 6" X 6" Red Quarry Tile System	ROOM 2213	1750 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
343 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2213	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD. BEHIND WHITEBOARD.					Sample #:		
344 CAD #:	X0A	Miscellaneous Material Milkboard Adhesive	ROOM 2213	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
345 CAD #:	X1M	Miscellaneous Material 6" X 6" Red Quarry Tile System	STORAGE ROOM 2213A	72 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
347 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	STAFF RESTROOM NEAR STORAGE 2302	3 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
351 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 2409 (BAND) & ASSOCIATED ROOMS	1200 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: BLACK MASTIC ONLY REMAINS ON WOOD FLOORS UNDER NEWER CARPETING AT AT SOUTH END OF ROOM 2409 AND SOUTH END ASSOCIATED ROOMS.					Sample #: 2001-1501-JN02		
352 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2409 (BAND)	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
353 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2409 (BAND)	15 Sq Ft	N	5 CH	5
Comments: THREE (3) BOARDS.					Sample #:		
354 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	BAND OFFICE 2418	4 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
355 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	ROOM 2402 (CHOIR) & ASSOCIATED ROOMS	1200 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: BLACK MASTIC ONLY REMAINS ON WOOD FLOORS UNDER NEWER CARPETING AT AT NORTH END OF ROOM 2409 AND NORTH END ASSOCIATED ROOMS.					Sample #:		
356 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2402 (CHOIR)	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
357 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2402 (CHOIR)	8 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
358 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	CHOIR OFFICE 2407	4 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
359 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2401	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
361 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2401	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
363 CAD #:	A3C	Mudded Pipe Joints on Pre-formed Insulation Kalo	AREA ABOVE BAND & CHOIR AREAS	2 Joints	N	8 CH	5
Comments: TWO (2) ROOF DRAINS. LIMITED VISIBILITY. ACCESS FROM WALL HATCH IN WEST PENTHOUSE.					Sample #: 071816-BF-4, 5, 6		
365 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2420	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
367 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2421	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
369 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2422	15 Sq Ft	N	5 CH	5
Comments: THREE (3) BOARDS.					Sample #:		
370 CAD #:	X0S	Miscellaneous Material Adhesive for Metal Framed Green Chalkboard	ROOM 2422	4 Sq Ft	N	ASSUMED	5
Comments: ONE (1) BOARD.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
372 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2423	15 Sq Ft	N	5 CH	5
Comments: THREE (3) BOARDS.					Sample #:		
374 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2424	7 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
375 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2102	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
377 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2102	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
378 CAD #:	X0T	Miscellaneous Material Wood Frame Tackboard Adhesive	ROOM 2102	6 Sq Ft	N	ASSUMED	5
Comments: ONE (1) BOARD.					Sample #:		
382 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	HALLWAY 2501 OFF AUDITORIUM BALCONY	600 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: TILE MISSING AT ENTRANCE TO 2502. SEALED WITH WAX.					Sample #:		
383 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	WOMEN'S STAFF RESTROOM NEAR ROOM 2425	1 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
385 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	ROOM 2425	2 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
387 CAD #:	J1B	Cementitious Panels Window Panels	ROOM 2426	30 Sq Ft	N	ASSUMED	5
Comments: THREE (3) PANELS. PAINTED WHITE.					Sample #:		
388 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2426	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
389 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	ROOM 2427 (STAGE)	10 Sq Ft	N	ASSUMED	5
Comments: SIX (6) MIRRORS.					Sample #:		
391 CAD #:	K0A	9" x 9" Vinyl Floor Tile & Mastic Light Brown w/White Streaks	DRESSING ROOMS 2506 & 2508 & HALLWAY 2505 OFF OF WEST STAGE MEZZANINE	200 Sq Ft	N	3-8 CH (TILE), NONE DETECTED (MASTIC)	5
Comments: ACCESSIBLE FROM STAGE LADDER OR 2ND FLOOR HALLWAY. CHIPPED IN 2506. SEALED WITH WAX.					Sample #: 021017-BF-1		
392 CAD #:	X0R	Miscellaneous Material Tan Mirror Adhesive (Thin Metal Frame)	DRESSING ROOMS 2506 & 2508 & HALLWAY 2505 OFF OF WEST STAGE MEZZANINE	15 Sq Ft	N	ASSUMED	5
Comments: TEN (10) MIRRORS.					Sample #:		
393 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	NORTHEAST STAIRWELL 2299H	2 Joints	N	35 CH	5
Comments: INSIDE WALL. VISIBLE THROUGH UNIVENT. INACCESSIBLE.					Sample #:		
400 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2108	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
402 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2108	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD BEHIND WHITEBOARD.					Sample #:		
403 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2108	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
406 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2103	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		
407 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2103	5 Sq Ft	N	5 CH	5
Comments:					Sample #:		
412 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2110	12 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
422 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2112	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
424 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2112	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #: 060713-BF-2, 4		
425 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2112	30 Sq Ft	N	5 CH	5
Comments: ALSO SAMPLED IN ROOM 1009 (060713-BF-1) & 2201 (060713-BF-5). ANALYZED AS "NONE DETECTED" IN ROOM 2201. TWO (2) BOARDS.					Sample #: 060713-BF-1, 3, 5		
426 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2114	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
429 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2114	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
430 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2114	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
434 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2107	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
440 CAD #:	A4A	Mudded Pipe Joints on Fiberglass Insulation 1963 Original Building	ROOM 2111	2 Joints	N	35 CH	5
Comments: INSIDE UNIVENT.					Sample #:		
443 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2111	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
444 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2111	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
448 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2113	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
449 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2113	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
463 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2118	20 Sq Ft	N	5 CH	5
Comments: FOUR (4) BOARDS.					Sample #:		
465 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2115	8 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
468 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2115	15 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
471 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2120	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD. BEHIND WHITEBOARDS.					Sample #: 060713-BF-6		
472 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2120	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
479 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2120B	6 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		
483 CAD #:	X0G	Miscellaneous Material Metal Framed Chalkboard Adhesive -Black	ROOM 2122	10 Sq Ft	N	5 CH	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
484 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2122	5 Sq Ft	N	5 CH	5
Comments: ONE (1) BOARD.					Sample #:		
491 CAD #:	X0M	Miscellaneous Material Tackboard Adhesive	ROOM 2117	10 Sq Ft	N	5 CH	5
Comments: TWO (2) BOARDS.					Sample #:		