

LEAP High School

Inspection Date: 8/9/2024

740 York Avenue, Saint Paul, MN 55106

Chart C - All Materials List

The following list contains all events observed by the inspector, whether or not they actually contained asbestos, and are grouped by homogeneous area (material type).

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
D1A	Boiler Gaskets Synthetic	Total Amount - 10 Sq Ft				
	25	BOILER ROOM (0001)	NONE DETECTED	101508-MV-6		10 Sq Ft
D2A	Interior Boiler Insulation Interior Refractory	Total Amount - 100 Sq Ft				
	26	BOILER ROOM (0001)	ASSUMED			100 Sq Ft
H1A	Sprayed-On Structural Fireproofing Gray, Fluffy Cellulose	Total Amount - 40000 Sq Ft				
	1	THROUGHOUT BUILDING	NONE DETECTED	101508MV-27	ROOM 1111.	40000 Sq Ft
H1B	Sprayed-On Structural Fireproofing Green w/Blue Cellulose	Total Amount - 5030 Sq Ft				
	44	ROOM 2301	NONE DETECTED	101508MV-28		30 Sq Ft
	53	THROUGHOUT 3RD FLOOR	NONE DETECTED			5000 Sq Ft
I2A	2' x 2' Acoustical Ceiling Tile Light Texture w/Revealed Edge	Total Amount - 15000 Sq Ft				
	4	THROUGHOUT BUILDING	NONE DETECTED	101508MV-13	OFFICE.	15000 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
I3A	2' x 4' Ceiling Tile Pockmarks & Pin Holes	Total Amount - 50000 Sq Ft				
5	THROUGHOUT BUILDING	NONE DETECTED	101508MV-18	ROOM 2314.	50000 Sq Ft	
I3B	2' x 4' Ceiling Tile Vinyl-Coated Sheetrock	Total Amount - 930 Sq Ft				
28	KITCHEN (1105J)	NSM			680 Sq Ft	
30	SMALL KITCHEN 1105C	NSM			160 Sq Ft	
50	ROOM 2313	NSM			90 Sq Ft	
K1A	Sheet Vinyl Flooring & Adhesive Blue Marbled	Total Amount - 1444 Sq Ft				
39	ROOM 2109	ASSUMED			784 Sq Ft	
43	ROOM 2113	ASSUMED			660 Sq Ft	
K2A	12" x 12" Vinyl Floor Tile & Mastic White w/Black & Gray Smudges	Total Amount - 20000 Sq Ft				
8	THROUGHOUT BUILDING	NONE DETECTED	101508MV-23		20000 Sq Ft	
K2B	12" x 12" Vinyl Floor Tile & Mastic Yellow Mottle (2023)	Total Amount - 1000 Sq Ft				
9	THROUGHOUT BUILDING	NEW			1000 Sq Ft	
K2C	12" x 12" Vinyl Floor Tile & Mastic Seagreen Mottle (2023)	Total Amount - 2000 Sq Ft				
10	THROUGHOUT BUILDING	NEW			2000 Sq Ft	

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
K2D	12" x 12" Vinyl Floor Tile & Mastic Blue Mottle (2023)					Total Amount - 2000 Sq Ft
	11	THROUGHOUT BUILDING	NEW			2000 Sq Ft
K2E	12" x 12" Vinyl Floor Tile & Mastic Purple Mottle (2023)					Total Amount - 1000 Sq Ft
	12	THROUGHOUT BUILDING	NEW			1000 Sq Ft
K2F	12" x 12" Vinyl Floor Tile & Mastic White w/Gray Smudges (2023)					Total Amount - 750 Sq Ft
	13	THROUGHOUT BUILDING	NEW			750 Sq Ft
K3A	Miscellaneous Flooring Gray Stair Treads w/Raised Circles					Total Amount - 3000 Sq Ft
	32	STAIRWELL 1302 NEAR LOADING DOCK	ASSUMED			2000 Sq Ft
	35	STAIRWELL FROM 1ST FLOOR LOBBY TO 2ND FLOOR LOBBY 2102	ASSUMED			1000 Sq Ft
L0A	Flexible Duct Connector Black Vinyl					Total Amount - 2 Sq Ft
	33	ELEVATOR EQUIPMENT ROOM 1301	NSM			2 Sq Ft
M0A	Plaster 1911 Original Building Columns					Total Amount - 300 Sq Ft
	23	LOWER LEVEL MECHANICAL ROOM & STORAGE	NONE DETECTED	101508MV-1, 2, 3	1: ROOM 0002. 2: ROOM 0001. 3: ROOM 0001A.	300 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
M0B	Plaster 1911 Original Building Walls & Ceiling	Total Amount - 50000 Sq Ft				
2	THROUGHOUT BUILDING	NONE DETECTED	101508-MV-5, 7, 20, 24, 25, 26; 501-V-7	5: ROOM 0002. 7: ROOM 1201. 20: ROOM 2323. 24: ROOM 3201. 25: STAIRS BY ROOM 2103. 26: ROOM 3400. V-7: BASEMENT RESTROOM.	50000 Sq Ft	
N0A	Drywall/Joint Compound 2000 Installation	Total Amount - 50000 Sq Ft				
3	THROUGHOUT BUILDING	NONE DETECTED	101508MV-15	HALLWAY 124.	50000 Sq Ft	
P0A	Fire Doors Metal - 1.5 Hr Rating (Warnock Hersey)	Total Amount - 60 Sq Ft				
27	BOILER ROOM (0001)	NEW			40 Sq Ft	
34	ELEVATOR EQUIPMENT ROOM 1301	NEW			20 Sq Ft	
Q0A	Carpet Adhesive Purple and Blue Hues w/Multi Color Carpet (1997 Installation)	Total Amount - 15000 Sq Ft				
6	THROUGHOUT BUILDING	NONE DETECTED	101508MV-21	ROOM 2113.	15000 Sq Ft	
Q0B	Carpet Adhesive Gray, Blue, Navy Blue Streaks Carpet Squares (2023)	Total Amount - 500 Sq Ft				
7	MEDIA CENTER	NEW			500 Sq Ft	
R0A	Baseboard/Mopboard Adhesive Silver Baseboard	Total Amount - 5000 Sq Ft				
14	THROUGHOUT BUILDING	NONE DETECTED	101508MV-8	HALLWAY BY ROOM 1127.	5000 Sq Ft	

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
ROB	Baseboard/Mopboard Adhesive 4" Navy Baseboard					Total Amount - 110 Sq Ft
	40	ROOM 2109	ASSUMED			60 Sq Ft
	42	ROOM 2113	ASSUMED			50 Sq Ft
T0A	Light Cord Insulation White Wiring for Light Fixture					Total Amount - 200 Lin Ft
	15	THROUGHOUT BUILDING	NONE DETECTED	101508MV-11	ROOM 4311.	200 Lin Ft
T0B	Light Cord Insulation Black Light Fixture Wire					Total Amount - 200 Lin Ft
	16	THROUGHOUT BUILDING	NONE DETECTED	101508MV-22	ROOM 2107C.	200 Lin Ft
VOA	Sink Undercoating Black					Total Amount - 200 Sq Ft
	17	THROUGHOUT BUILDING	NONE DETECTED	101508MV-12	ROOM 1107.	200 Sq Ft
VOB	Sink Undercoating Smooth White					Total Amount - 6 Sq Ft
	41	ROOM 2109	ASSUMED			6 Sq Ft
W1A	1' x 1' Ceiling Tile Adhesive Dark Brown					Total Amount - 177 Sq Ft
	36	MAIN OFFICE AREA	NONE DETECTED	101508MV-14		50 Sq Ft
	38	ROOM 2109	NONE DETECTED			15 Sq Ft
	52	ROOM 2004	NONE DETECTED			2 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	54	ROOM 3400 & ASSOCIATED OFFICES	NONE DETECTED	101508MV-10	OFFICE 3406.	100 Sq Ft
	55	ROOM 3201	NONE DETECTED			10 Sq Ft
W1B	1' x 1' Ceiling Tile Adhesive Light Tan					Total Amount - 174 Sq Ft
	37	ROOM 2108	NONE DETECTED	101508MV-17		25 Sq Ft
	45	HALLWAY OUTSIDE ROOM 2317	NONE DETECTED			30 Sq Ft
	46	ROOM 2317	NONE DETECTED	101508MV-19		40 Sq Ft
	47	ROOM 2318	NONE DETECTED			4 Sq Ft
	48	ROOM 2315	NONE DETECTED			40 Sq Ft
	49	ROOM 2316	NONE DETECTED			25 Sq Ft
	51	ROOM 2314	NONE DETECTED			10 Sq Ft
X0A	Miscellaneous Material Tan Caulk					Total Amount - 10 Sq Ft
	24	LOWER LEVEL STORAGE (0001A)	4 CH	101508MV-4		10 Sq Ft
X0B	Miscellaneous Material Tan Sheetrock Adhesive					Total Amount - 200 Sq Ft
	22	THROUGHOUT LOWER LEVEL	NONE DETECTED	101508MV-9	HALLWAY BY ROOM 1115.	200 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X0C	Miscellaneous Material Red Fire Stop	Total Amount - 300 Sq Ft				
18	THROUGHOUT BUILDING	NONE DETECTED	101508MV-16	HALLWAY 124.	300 Sq Ft	
X0D	Miscellaneous Material Gray Duct Caulk	Total Amount - 200 Sq Ft				
19	THROUGHOUT BUILDING	NONE DETECTED	101508MV-29	ROOM 0002.	200 Sq Ft	
X0F	Miscellaneous Material Black Table Tops (Wood)	Total Amount - 160 Sq Ft				
56	ROOM 4207	NSM			160 Sq Ft	
X1A	Miscellaneous Material 4" X 8" Quarry Tile System	Total Amount - 4660 Sq Ft				
20	THROUGHOUT BUILDING RESTROOMS	ASSUMED			4000 Sq Ft	
29	KITCHEN (1105J)	ASSUMED			500 Sq Ft	
31	SMALL KITCHEN 1105C	ASSUMED			160 Sq Ft	
X1B	Miscellaneous Material 4" X 8" Blue Ceramic Wall Tile System	Total Amount - 15000 Sq Ft				
21	THROUGHOUT BUILDING RESTROOMS	NONE DETECTED	06112024JA-01, 02	JA-01: ROOM 4118. JA-02: ROOM 3026.	15000 Sq Ft	



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427
Tel/Fax: (763) 449-4922 / (763) 449-4924
<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352405235

Customer ID: IFEA50

Customer PO:

Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Project: 202410572 LEAP H.S.

Phone: (763) 315-7927

Fax: (763) 315-7920

Received Date: 06/11/2024 11:00 AM

Analysis Date: 06/12/2024

Collected Date:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
06112024JA-01 Ceramic Tile 352405235-0001	Rm 4118 - Tile/Grout/Adhesive	Brown/Blue Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
06112024JA-01 Grout 352405235-0001A	Rm 4118 - Tile/Grout/Adhesive	White Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
06112024JA-01 Adhesive 352405235-0001B	Rm 4118 - Tile/Grout/Adhesive	Tan Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
06112024JA-02 Ceramic Tile 352405235-0002	Rm 3026 - Tile/Grout/Adhesive	Brown/Blue Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
06112024JA-02 Grout 352405235-0002A	Rm 3026 - Tile/Grout/Adhesive	White Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected
06112024JA-02 Adhesive 352405235-0002B	Rm 3026 - Tile/Grout/Adhesive	Tan Non-Fibrous Homogeneous		100.0% Non-fibrous (Other)	None Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 06/12/2024 11:39:38



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427

Tel/Fax: (763) 449-4922 / (763) 449-4924

<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352405235

Customer ID: IFEA50

Customer PO:

Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445

Project: 202410572 LEAP H.S.

Phone: (763) 315-7927

Fax: (763) 315-7920

Received Date: 06/11/2024 11:00 AM

Analysis Date: 06/12/2024

Collected Date:

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 06/11/2024

Sample Receipt Time: 11:00 AM

Analysis Completed Date: 06/12/2024

Analysis Completed Time: 11:38 AM

Analyst(s):

Louis Miller PLM (6)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 06/12/2024 11:39:38



9201 West Broadway North, Suite 600
Brooklyn Park, MN 55445
(763) 315-7900
1-800-233-9513

352405235

CHAIN OF CUSTODY

Page 1 of 1

Order ID: 352405235

Client # _____		Project # <u>202410572</u>		Building Name <u>LEAP H.S.</u>		Shaded Areas are for Laboratory Use Only!								
Client <u>St. Paul Public Schools</u>		Project Name _____		Contact Person _____										
Address _____		IEA Project Manager <u>Brenda F.</u>		Other Information _____										
Verbal results to <u>Emma S.</u>		Phone, Fax No. or E-Mail <u>IEA Lab</u>		TAT (circle) 6 hr <u>24 hr</u> 48 hr 72 hr 96 hr Specify										
Verbal results relayed to _____		Verbal results relayed by _____		Date _____		Time _____								
Analysis location: ☐ On Site ☐ Lab ☐ Regional Office ☐ Other _____						Matrix type		Analysis requested		Filter type				
Sample #	Work Area or Phase #	Sample Description/Location	Sample type or Material code	Volume	Air	Bulk	Dust	PCM	PLM	TEM	Other	MCE	8 um	5 um
<u>06120245A-01</u>		<u>Tile/Grout/Adhesive - Rm 4118</u>	<u>XIB</u>	<u>7 TYP</u>	☐	☒	☐	☐	☒	☐		☐	☐	☐
<u>-02</u>		<u>" " - Rm 3026</u>	<u>XIB</u>		☐	☒	☐	☐	☒	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐								