

1041 Marion Street, Saint Paul, MN 55117

Chart C - All Materials List

The following list contains all events observed by the inspector, whether or not they actually contained asbestos, and are grouped by homogeneous area (material type).

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
A4A		Mudded Pipe Joints on Fiberglass Insulation Associated w/Hard Fiberglass				Total Amount - 77 Joints
	35	TUNNEL SOUTH OF UNEXCAVATED AREA	NONE DETECTED	030410ML-06	ML-06: UNEXCAVATED AREA OFF OF AHU MECHANICAL ROOM 0035 (SINCE REMOVED).	4 Joints
	39	TUNNEL NORTH OF UNEXCAVATED AREA	NONE DETECTED	2001-1501-GQC-4, 6	GQC-4: HALLWAY BY COMPUTER ROOM SOUTHWEST CORNER (SINCE REMOVED). GQC-6: BOILER ROOM SOUTHWEST CORNER (SINCE REMOVED).	5 Joints
	87	MECHANICAL ROOM 1035	NONE DETECTED			1 Joints
	105	ROOM 1034	NONE DETECTED			2 Joints
	123	ROOM 0121	NONE DETECTED	030410ML-04		10 Joints
	133	TITLE 1 RECEPTION 0111	NONE DETECTED	030410ML-05	ML-05: UPPER ELEVATOR LOBBY.	15 Joints
	140	THROUGHOUT TITLE 1 EAST OFFICES & HALLWAYS	NONE DETECTED			40 Joints
A4B		Mudded Pipe Joints on Fiberglass Insulation Foil/Canvas Wrap (1971)				Total Amount - 239 Joints
	36	TUNNEL SOUTH OF UNEXCAVATED AREA	NONE DETECTED			2 Joints

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	41	ELEVATED WALKING TUNNEL SOUTH OF AHU ROOM 0035	NONE DETECTED	030410ML-02		16 Joints
	69	AREA OUTSIDE ROOM 0009	NONE DETECTED	2001-1501-GQ5	GQ5: TOWARDS TUNNEL ENTRANCE	20 Joints
	71	AREA 0008	NONE DETECTED			20 Joints
	77	1978 ADDITION GYMNASIUM STORAGE 1066	NONE DETECTED			4 Joints
	84	ROOM 1026	NONE DETECTED	030410ML-03		8 Joints
	88	MECHANICAL ROOM 1035	NONE DETECTED			30 Joints
	148	BASEMENT MECHANICAL ROOM 0056	NONE DETECTED			40 Joints
	151	HALLWAY 1202	NONE DETECTED			1 Joints
	164	BAND INSTRUMENT STORAGE 1221	NONE DETECTED			4 Joints
	192	MEN'S LOCKER ROOM 1115	NONE DETECTED	072324ML-02, 03, 04	ML-02,03: ROOM 1118 (SINCE REMOVED). ML-04: LOCKER ROOM SHOWER AREA.	8 Joints
	194	MEN'S LOCKER ROOM SHOWER 1121	NONE DETECTED			10 Joints
	197	BOYS' RESTROOM 1122	NONE DETECTED			9 Joints
	198	MAINTENANCE ROOM 1123	NONE DETECTED			4 Joints
	206	MECHANICAL ROOM 1063	NONE DETECTED			6 Joints
	209	ROOM 1130	NONE DETECTED			7 Joints
	266	GYMNASIUM 2120	NONE DETECTED			12 Joints

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	305	HALLWAY 3221	NONE DETECTED			20 Joints
	307	ROOM 3215	NONE DETECTED			1 Joints
	311	STORAGE ROOM 3218	NONE DETECTED			3 Joints
	312	STORAGE ROOM 3219	NONE DETECTED	030410ML-01		3 Joints
	313	ROOM 3220	NONE DETECTED			2 Joints
	345	MEDIA CENTER 3110	NONE DETECTED			2 Joints
	347	MECHANICAL ROOM 3114	NONE DETECTED			7 Joints
A4C	Mudded Pipe Joints on Fiberglass Insulation Foil/Canvas (Title 1)					Total Amount - 127 Joints
	116	HALLWAY FROM ROOM 0120 TO RECEPTION	NONE DETECTED			20 Joints
	120	ROOM 0119	NONE DETECTED			6 Joints
	124	ROOM 0121	NONE DETECTED	030410ML-08		20 Joints
	134	TITLE 1 RECEPTION 0111	NONE DETECTED			40 Joints
	137	TITLE 1 CUSTODIAL CLOSET 0112	NONE DETECTED	030410ML-07		1 Joints
	141	THROUGHOUT TITLE 1 EAST OFFICES & HALLWAYS	NONE DETECTED	030410ML-09		40 Joints

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
B1A	Air Cell Pipe Insulation 1926 Original Building					Total Amount - 2 Lin Ft
	34	SMALL TUNNEL SECTION OFF OF TUNNEL SOUTH OF UNEXCAVATED AREA	80 CH	207C2A	UNEXCAVATED AREA OFF OF AHU MECHANICAL ROOM 0035 (SINCE REMOVED).	1 Lin Ft
	38	SMALL TUNNEL SECTION OFF OF TUNNEL NORTH OF UNEXCAVATED AREA	80 CH	207C-2A		1 Lin Ft
B4A	Fiberglass Thermal Pipe Insulation Hard Fiberglass					Total Amount - 1000 Lin Ft
	2	THROUGHOUT BUILDING	NONE DETECTED	207C18A, ACB450AM-A6, 7	BOILER ROOM (SINCE REMOVED).	1000 Lin Ft
D1C	Boiler Gaskets Cleaver Brooks (2002)					Total Amount - 10 Sq Ft
	25	BOILER ROOM 0030	NONE DETECTED	030410ML-12		10 Sq Ft
E1A	Stack Gasket Fume Hood Exhaust					Total Amount - 2 Sq Ft
	199	MAINTENANCE ROOM 1123	45 CH	030410ML-16		1 Sq Ft
	211	ROOM 1131	45 CH			1 Sq Ft
G1A	Sprayed-On Acoustical Finish White Texture					Total Amount - 260 Sq Ft
	132	TITLE 1 RECEPTION 0111	NONE DETECTED	030410ML-17, 19		110 Sq Ft
	138	TITLE 1 ENTRANCE 0138	NONE DETECTED	030410ML-18		150 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
H1B	Sprayed-On Structural Fireproofing Off-White					Total Amount - 27070 Sq Ft
	27	CRAWL SPACE ABOVE BOILER ROOM	NONE DETECTED			2000 Sq Ft
	28	MECHANICAL ROOM 0031	NONE DETECTED			1000 Sq Ft
	29	ELECTRICAL ROOM 0032	NONE DETECTED	030410ML-21		500 Sq Ft
	30	AREA 0036	NONE DETECTED			1000 Sq Ft
	31	AHU MECHANICAL ROOM 0035 NEAR BOILER ROOM	NONE DETECTED			50 Sq Ft
	53	ELEVATOR LOBBY 0002 AT NORTHEAST CORNER OF CAFETERIA	NONE DETECTED			400 Sq Ft
	56	ELEVATOR MACHINE ROOM 0006	NONE DETECTED			700 Sq Ft
	70	MECHANICAL ROOM 0010	NONE DETECTED			650 Sq Ft
	73	ELEVATOR MACHINE ROOM 0006	NONE DETECTED			220 Sq Ft
	74	FIRE SPRINKLER EQUIPMENT ROOM 0021	NONE DETECTED			400 Sq Ft
	82	MAINTENANCE ROOM 1059	NONE DETECTED	030410ML-20		100 Sq Ft
	94	NURSE'S ROOM 1012	NONE DETECTED			200 Sq Ft
	96	NURSE'S RESTROOM	NONE DETECTED			100 Sq Ft
	98	NURSE'S OFFICE 1014	NONE DETECTED			100 Sq Ft
	174	BOYS' RESTROOM 1208	NONE DETECTED			300 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	175	STAFF RESTROOM 1206	NONE DETECTED			40 Sq Ft
	186	1ST FLOOR COMMONS 1100	NONE DETECTED			2500 Sq Ft
	187	COMPUTER ROOM 1110	NONE DETECTED			700 Sq Ft
	188	ROOM 1111 OFF ROOM 1110	NONE DETECTED	030410ML-23		400 Sq Ft
	200	HALLWAY 1127	NONE DETECTED			600 Sq Ft
	201	RECEIVING 1128	NONE DETECTED			100 Sq Ft
	202	RESTROOM 1125	NONE DETECTED			30 Sq Ft
	204	ROOM 1126	NONE DETECTED			60 Sq Ft
	220	ROOM 2058	NONE DETECTED			50 Sq Ft
	228	ELECTRICAL ROOM 2061	NONE DETECTED			100 Sq Ft
	230	ROOM 2130	NONE DETECTED			2000 Sq Ft
	232	STORAGE ROOM 2131	NONE DETECTED			100 Sq Ft
	234	MECHANICAL ROOM 2133	NONE DETECTED			1400 Sq Ft
	235	STORAGE ROOM 2134	NONE DETECTED			100 Sq Ft
	240	HALLWAY 2100 OUTSIDE ROOMS 2106-2110	NONE DETECTED			1000 Sq Ft
	241	ROOM 2106	NONE DETECTED	030410ML-26		1200 Sq Ft
	242	ROOM 2107	NONE DETECTED			140 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	243	ROOM 2108	NONE DETECTED			130 Sq Ft
	244	ROOM 2110	NONE DETECTED			1200 Sq Ft
	269	STAIRWELL 2124 OFF GYMNASIUM	NONE DETECTED			360 Sq Ft
	271	GYMNASIUM OFFICE 2132	NONE DETECTED	030410ML-24		200 Sq Ft
	280	ROOM 2206	NONE DETECTED			200 Sq Ft
	284	ROOM 2208	NONE DETECTED			400 Sq Ft
	325	BOYS' RESTROOM 3208	NONE DETECTED			200 Sq Ft
	326	STAFF RESTROOM 3206	NONE DETECTED	030410ML-25		100 Sq Ft
	336	HALLWAY 3100	NONE DETECTED			1000 Sq Ft
	342	THROUGHOUT MEDIA CENTER & ASSOCIATED ROOMS	NONE DETECTED			4000 Sq Ft
	352	ROOM 3051	NONE DETECTED	030410ML-22		1000 Sq Ft
	354	ELECTRICAL ROOM 3053	NONE DETECTED			40 Sq Ft
H1C	Sprayed-On Structural Fireproofing Light Blue					Total Amount - 7781 Sq Ft
	83	MAINTENANCE ROOM 1059	NONE DETECTED			1 Sq Ft
	147	STAIRWELL 1058 (BY MUSIC)	NONE DETECTED	030410ML-27		300 Sq Ft
	150	HALLWAY 1202	NONE DETECTED			410 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	153	OFFICE 1213	NONE DETECTED	030410ML-28		200 Sq Ft
	154	ROOM 1215	NONE DETECTED	030410ML-33		360 Sq Ft
	157	ROOM 1216	NONE DETECTED			750 Sq Ft
	161	HALLWAY 1219	NONE DETECTED	030410ML-29		40 Sq Ft
	165	HALLWAY 1225	NONE DETECTED			50 Sq Ft
	168	STORAGE ROOM 1222	NONE DETECTED			80 Sq Ft
	169	ROOM 1217	NONE DETECTED			250 Sq Ft
	170	ROOM 1218	NONE DETECTED			90 Sq Ft
	262	HALLWAY/LOBBY 2115	NONE DETECTED			1500 Sq Ft
	263	GYMNASIUM ENTRANCE 2115B	NONE DETECTED			200 Sq Ft
	264	GYMNASIUM STORAGE ROOM 2122	NONE DETECTED	030410ML-30		200 Sq Ft
	273	GYMNASIUM MECHANICAL ROOM 2121	NONE DETECTED			100 Sq Ft
	274	GYMNASIUM ENTRANCE 2115A	NONE DETECTED			200 Sq Ft
	291	HALLWAY 2209 OUTSIDE ROOMS 2215-2220	NONE DETECTED			200 Sq Ft
	293	ROOM 2220	NONE DETECTED			500 Sq Ft
	295	ROOM 2217	NONE DETECTED			200 Sq Ft
	297	ROOM 2218	NONE DETECTED	030410ML-31		200 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	300	ROOM 2215	NONE DETECTED			350 Sq Ft
	334	ROOM 3113	NONE DETECTED			300 Sq Ft
	343	THROUGHOUT MEDIA CENTER & ASSOCIATED ROOMS	NONE DETECTED			500 Sq Ft
	346	MECHANICAL ROOM 3114	NONE DETECTED	030410ML-32		500 Sq Ft
	349	COMPUTER ROOM 3115	NONE DETECTED			300 Sq Ft
H1D	Sprayed-On Structural Fireproofing Tan					Total Amount - 3155 Sq Ft
	86	MECHANICAL ROOM 1035	NONE DETECTED	030410ML-34		60 Sq Ft
	104	ROOM 1034	NONE DETECTED	030410ML-35		400 Sq Ft
	109	OFFICE 1033	NONE DETECTED			75 Sq Ft
	110	OFFICE 1036	NONE DETECTED			70 Sq Ft
	112	STORAGE ROOM 1031	NONE DETECTED			50 Sq Ft
	114	THROUGHOUT BASEMENT TITLE 1 AREA	NONE DETECTED	030410ML-36, 37, 38	ML-36: ROOM 122. ML-37: OFFICE SOUTH OF ROOM 135. ML-38: ROOM 121.	2500 Sq Ft
I1A	1' x 1' Acoustical Ceiling Tile Pegboard					Total Amount - 1320 Sq Ft
	216	ROOM 2063	NONE DETECTED	13590 28A;207C6A		400 Sq Ft
	221	ROOM 2058	NONE DETECTED	13590 28B		720 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	374	ROOM 3016	NONE DETECTED	13590 29A		200 Sq Ft
I2D	2' x 2' Acoustical Ceiling Tile Lightly Textured w/Revealed Edge					Total Amount - 8200 Sq Ft
	5	THROUGHOUT BUILDING	NONE DETECTED	030410ML-40	ML-40: MAIN OFFICE RECEPTION 1005.	8200 Sq Ft
I2E	2' x 2' Acoustical Ceiling Tile Fissures w/Gouges & Pin Holes					Total Amount - 22200 Sq Ft
	6	THROUGHOUT BUILDING	NONE DETECTED	030410ML-42; 207C25A	ML-42: ROOM 3058. 207C25A: ROOM 2217.	22200 Sq Ft
I2F	2' x 2' Acoustical Ceiling Tile Dents w/Pin Holes					Total Amount - 2100 Sq Ft
	118	ROOM 0120	NONE DETECTED			140 Sq Ft
	125	ROOM 0121	NONE DETECTED			500 Sq Ft
	135	TITLE 1 RECEPTION 0111	NONE DETECTED			900 Sq Ft
	142	ROOM 0122	NONE DETECTED	030410ML-51		440 Sq Ft
	144	ROOM 0127	NONE DETECTED			120 Sq Ft
I2G	2' x 2' Acoustical Ceiling Tile Sandpaper Texture					Total Amount - 1000 Sq Ft
	7	THROUGHOUT BUILDING	NONE DETECTED	030410ML-50	ML-50: HALLWAY 1112.	1000 Sq Ft
I2H	2' x 2' Acoustical Ceiling Tile Small Grubs w/Pockmarks & Nail Holes					Total Amount - 260 Sq Ft
	260	ROOM 2030	NONE DETECTED	13590 23B		260 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
I2I	2' x 2' Acoustical Ceiling Tile Fissures & Pin Holes					Total Amount - 1900 Sq Ft
	115	THROUGHOUT BASEMENT TITLE 1 AREA	NONE DETECTED	030410ML-41		1900 Sq Ft
I2J	2' x 2' Acoustical Ceiling Tile Rough Texture w/Revealed Edges (202x)					Total Amount - 1500 Sq Ft
	106	ROOM 1034	NEW			1500 Sq Ft
I3A	2' x 4' Ceiling Tile Widthwise Fissures, Gouges & Pin Holes					Total Amount - 3652 Sq Ft
	44	CAFETERIA 0045	NONE DETECTED	207C8A; 13590-32A, 32B		192 Sq Ft
	57	NORTHWEST ENTRANCE 101 TO CAFETERIA	NONE DETECTED			160 Sq Ft
	65	KITCHEN OFFICE 0047	NONE DETECTED			120 Sq Ft
	155	ROOM 1215	NONE DETECTED			1100 Sq Ft
	158	ROOM 1216	NONE DETECTED			1500 Sq Ft
	162	HALLWAY 1219	NONE DETECTED			220 Sq Ft
	166	HALLWAY 1225	NONE DETECTED	030410ML-43		360 Sq Ft
I3C	2' x 4' Ceiling Tile Dents w/Pin Holes					Total Amount - 1325 Sq Ft
	54	ELEVATOR LOBBY 0002 AT NORTHEAST CORNER OF CAFETERIA	NONE DETECTED			130 Sq Ft
	171	ROOM 1218	NONE DETECTED			200 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	189	ROOM 1111 OFF ROOM 1110	NONE DETECTED			290 Sq Ft
	236	STORAGE ROOM 2134	NONE DETECTED	030410ML-44		60 Sq Ft
	265	GYMNASIUM STORAGE ROOM 2122	NONE DETECTED			230 Sq Ft
	270	STAIRWELL 2124 OFF GYMNASIUM	NONE DETECTED			260 Sq Ft
	276	DATA CLOSET 2205	NONE DETECTED			85 Sq Ft
	341	DATA CLOSET 3121 OFF OF ROOM 3201	NONE DETECTED			70 Sq Ft
I3D	2' x 4' Ceiling Tile Vinyl-Covered Cellulose					Total Amount - 900 Sq Ft
	59	KITCHEN 0046	NONE DETECTED	030410ML-45		800 Sq Ft
	61	KITCHEN STORAGE ROOM 0050	NONE DETECTED			50 Sq Ft
	63	KITCHEN LOCKER ROOM 0048	NONE DETECTED			50 Sq Ft
I3E	2' x 4' Ceiling Tile Vinyl-Coated Sheetrock					Total Amount - 1375 Sq Ft
	47	CAFETERIA STORAGE 0053	NSM			320 Sq Ft
	203	RESTROOM 1125	NSM			60 Sq Ft
	214	GIRLS' LOCKER ROOM 1151	NSM			880 Sq Ft
	327	STAFF RESTROOM 3206	NSM			115 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
I3F	2' x 4' Ceiling Tile Textured Panel Look w/Revealed Edge		Total Amount - 8000 Sq Ft			
3	THROUGHOUT BUILDING	NONE DETECTED	030410ML-46	ML-46: ROOM 1110.	8000 Sq Ft	
I3G	2' x 4' Ceiling Tile Textured w/Revealed Edge		Total Amount - 2000 Sq Ft			
4	THROUGHOUT BUILDING	NONE DETECTED	030410ML-47	ML-47: HALLWAY 1100.	2000 Sq Ft	
I3H	2' x 4' Ceiling Tile Pock Marks & Pin Holes		Total Amount - 1350 Sq Ft			
301	ROOM 2215	NONE DETECTED	030410ML-48		1350 Sq Ft	
I3I	2' x 4' Ceiling Tile Smooth Cloth (2021)		Total Amount - 2600 Sq Ft			
43	CAFETERIA 0045	NEW			2600 Sq Ft	
J3A	Miscellaneous Cementitious Material Black Sills (1930)		Total Amount - 106 Sq Ft			
51	STAIRWELL LANDING 0055 AT SOUTHWEST CORNER OF CAFETERIA	NONE DETECTED			4 Sq Ft	
173	ROOM 1211	NONE DETECTED			10 Sq Ft	
179	ROOM 1207	NONE DETECTED			10 Sq Ft	
182	ROOM 1203	NONE DETECTED			10 Sq Ft	
283	ROOM 2207	NONE DETECTED	030410ML-52		10 Sq Ft	
285	STAIRWELL 2210	NONE DETECTED			4 Sq Ft	

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	288	ROOM 2211	NONE DETECTED			10 Sq Ft
	317	ROOM 3214	NONE DETECTED			4 Sq Ft
	320	ROOM 3207	NONE DETECTED			10 Sq Ft
	321	ROOM 3209	NONE DETECTED			2 Sq Ft
	324	ROOM 3205	NONE DETECTED			10 Sq Ft
	331	ROOM 3203	NONE DETECTED			10 Sq Ft
	333	ROOM 3112	NONE DETECTED			12 Sq Ft
J3B	Miscellaneous Cementitious Material Black Science Table Top					Total Amount - 15 Sq Ft
	247	ROOM 2005	NONE DETECTED	030410ML-53		15 Sq Ft
J3C	Miscellaneous Cementitious Material Fume Hood Base					Total Amount - 30 Sq Ft
	251	ROOM 2015	NONE DETECTED	030410ML-54		30 Sq Ft
J3D	Miscellaneous Cementitious Material Epoxy Resin Science Table Top					Total Amount - 245 Sq Ft
	252	ROOM 2015	NSM			225 Sq Ft
	303	ROOM 2215	NSM			20 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
J3E	Miscellaneous Cementitious Material Fume Hood Panels				Total Amount - 30 Sq Ft	
	304	ROOM 2215	NONE DETECTED	030410ML-55		30 Sq Ft
K1A	Sheet Vinyl Flooring & Adhesive Yellow & Green Terrazzo-Look				Total Amount - 60 Sq Ft	
	128	TITLE 1 MEN'S RESTROOM 0115	18 CH	030410ML-56		30 Sq Ft
	130	TITLE 1 WOMEN'S RESTROOM 0113	18 CH			30 Sq Ft
K2C	12" x 12" Vinyl Floor Tile & Mastic Beige Mottle				Total Amount - 280 Sq Ft	
	58	NORTHWEST ENTRANCE 101 TO CAFETERIA	NONE DETECTED	030410ML-60		160 Sq Ft
	227	ROOM 2052 RESTROOM	NONE DETECTED			60 Sq Ft
	239	ROOM 2050 RESTROOM	NONE DETECTED			60 Sq Ft
K2D	12" x 12" Vinyl Floor Tile & Mastic Brown w/Black Specks				Total Amount - 3610 Sq Ft	
	62	KITCHEN STORAGE ROOM 0050	NONE DETECTED	030410ML-61		50 Sq Ft
	152	HALLWAY 1202	NONE DETECTED			910 Sq Ft
	163	HALLWAY 1219	NONE DETECTED			220 Sq Ft
	167	HALLWAY 1225	NONE DETECTED			390 Sq Ft
	213	ROOMS 1139 & 1140	NONE DETECTED			160 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	294	ROOM 2220	NONE DETECTED			1700 Sq Ft
	296	ROOM 2217	NONE DETECTED			100 Sq Ft
	298	ROOM 2218	NONE DETECTED			80 Sq Ft
K2E	12" x 12" Vinyl Floor Tile & Mastic White w/Black Smudges					Total Amount - 170 Sq Ft
	64	KITCHEN LOCKER ROOM 0048	NONE DETECTED			50 Sq Ft
	66	KITCHEN OFFICE 0047	NONE DETECTED	352-JJT-34		120 Sq Ft
K2F	12" x 12" Vinyl Floor Tile & Mastic Light Blue Mottle					Total Amount - 7050 Sq Ft
	45	CAFETERIA 0045	NONE DETECTED	030410ML-63		3800 Sq Ft
	48	CAFETERIA STORAGE 0053	NONE DETECTED			350 Sq Ft
	308	ROOM 3215	NONE DETECTED			1300 Sq Ft
	314	ROOM 3220	NONE DETECTED			1600 Sq Ft
K2G	12" x 12" Vinyl Floor Tile & Mastic Light Gray w/Black & White Specks					Total Amount - 8697 Sq Ft
	55	ELEVATOR LOBBY 0002 AT NORTHEAST CORNER OF CAFETERIA	NONE DETECTED			290 Sq Ft
	78	HALLWAYS 1050 & 1060	NONE DETECTED			1400 Sq Ft
	79	MAINTENANCE ROOM 1055	NONE DETECTED			12 Sq Ft
	80	ROOM 1064	NONE DETECTED			820 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	85	ROOM 1062	NONE DETECTED			820 Sq Ft
	90	MAINTENANCE ROOM 1016	NONE DETECTED			25 Sq Ft
	91	ELECTRICAL ROOM 1029	NONE DETECTED			25 Sq Ft
	95	NURSE'S ROOM 1012	NONE DETECTED			160 Sq Ft
	99	NURSE'S OFFICE 1014	NONE DETECTED			100 Sq Ft
	101	WORK/TESTING ROOM 1028	NONE DETECTED			25 Sq Ft
	107	ROOM 1034	NONE DETECTED			280 Sq Ft
	111	OFFICE 1036	NONE DETECTED			140 Sq Ft
	113	STORAGE ROOM 1031	NONE DETECTED			100 Sq Ft
	160	SOUTH ENTRANCE 1214	NONE DETECTED			115 Sq Ft
	172	ROOM 1218	NONE DETECTED			200 Sq Ft
	190	ROOM 1111 OFF ROOM 1110	NONE DETECTED			190 Sq Ft
	191	HALLWAY 1112	NONE DETECTED			670 Sq Ft
	205	HALLWAY 1061	NONE DETECTED			240 Sq Ft
	208	HALLWAY 1164	NONE DETECTED			590 Sq Ft
	219	ROOM 2063	NONE DETECTED			50 Sq Ft
	224	ROOM 2058	NONE DETECTED			50 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	225	HALLWAY 2059	NONE DETECTED			720 Sq Ft
	229	ELECTRICAL ROOM 2061	NONE DETECTED			50 Sq Ft
	233	STORAGE ROOM 2131	NONE DETECTED			100 Sq Ft
	237	STORAGE ROOM 2134	NONE DETECTED			60 Sq Ft
	238	ROOM 2050	NONE DETECTED			75 Sq Ft
	272	GYMNASIUM OFFICE 2132	NONE DETECTED			140 Sq Ft
	277	ROOM 2203	NONE DETECTED			50 Sq Ft
	289	MAINTENANCE ROOM 2212	NONE DETECTED			150 Sq Ft
	292	HALLWAY 2209 OUTSIDE ROOMS 2215-2220	NONE DETECTED			340 Sq Ft
	306	HALLWAY 3221	NONE DETECTED			340 Sq Ft
	335	ROOM 3113	NONE DETECTED			50 Sq Ft
	350	ROOM 3120	NONE DETECTED	030410ML-64		170 Sq Ft
	351	ROOM 3119	NONE DETECTED			100 Sq Ft
	353	ROOM 3051	NONE DETECTED			50 Sq Ft
K2H	12" x 12" Vinyl Floor Tile & Mastic Tan w/Brown & White Smudges					Total Amount - 600 Sq Ft
	42	STAIRWELL 0004 AT SOUTHEAST CORNER OF CAFETERIA	NONE DETECTED	030410ML-65		600 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
K2I	12" x 12" Vinyl Floor Tile & Mastic Dark Blue w/Blue & Light Blue Specks					Total Amount - 1000 Sq Ft
8	THROUGHOUT BUILDING	NONE DETECTED	030410ML-66	ML-66: HALLWAY NEAR ROOM 2005.	1000 Sq Ft	
K2J	12" x 12" Vinyl Floor Tile & Mastic Blue w/Dark Blue & White Specks					Total Amount - 1000 Sq Ft
9	THROUGHOUT BUILDING	NONE DETECTED	030410ML-67	ML-67: HALLWAY NEAR AUDITORIUM.	1000 Sq Ft	
K2K	12" x 12" Vinyl Floor Tile & Mastic Green w/Light Green & White Specks					Total Amount - 2000 Sq Ft
10	THROUGHOUT BUILDING	NONE DETECTED	030410ML-68	ML-68: ROOM 1110.	2000 Sq Ft	
K2L	12" x 12" Vinyl Floor Tile & Mastic Yellow w/Light Yellow & White Specks					Total Amount - 2000 Sq Ft
11	THROUGHOUT BUILDING	NONE DETECTED	030410ML-69	ML-68: ROOM 3115.	2000 Sq Ft	
K2N	12" x 12" Vinyl Floor Tile & Mastic Tan w/Brown & White Streaks					Total Amount - 30 Sq Ft
89	MECHANICAL ROOM 1035	2 CH (TILE), 8 CH (MASTIC)	030410ML-70		30 Sq Ft	
K2O	12" x 12" Vinyl Floor Tile & Mastic Purple w/Gray & White Specks					Total Amount - 1900 Sq Ft
12	THROUGHOUT BUILDING	NONE DETECTED	030410ML-71	ML-71: HALLWAY NEAR ROOM 1113.	1000 Sq Ft	
215	ROOM 1150	NONE DETECTED			900 Sq Ft	

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
K2P	12" x 12" Vinyl Floor Tile & Mastic Tan Mottle w/Beige Smudges					Total Amount - 2260 Sq Ft
	250	ROOM 2015	NONE DETECTED			880 Sq Ft
	253	STORAGE 2014	NONE DETECTED	030410ML-72		80 Sq Ft
	254	HALLWAY 2018 OUTSIDE ROOM 2027	NONE DETECTED			50 Sq Ft
	257	ROOM 2028	NONE DETECTED			990 Sq Ft
	261	ROOM 2030	NONE DETECTED			260 Sq Ft
K2Q	12" x 12" Vinyl Floor Tile & Mastic Tan w/Brown Specks					Total Amount - 540 Sq Ft
	310	ROOM 3216	3 CH (TILE)8 CH (MASTIC)	030410ML-73		540 Sq Ft
K2R	12" x 12" Vinyl Floor Tile & Mastic Light Gray w/Gray & White Smudges					Total Amount - 1350 Sq Ft
	302	ROOM 2215	NONE DETECTED	030410ML-74		1350 Sq Ft
K3A	Miscellaneous Flooring Tan w/Brown Marbling					Total Amount - 80 Sq Ft
	159	SOUTH ENTRANCE 1214	NONE DETECTED	030410ML-75		80 Sq Ft
K3B	Miscellaneous Flooring 2' x 6' Green					Total Amount - 55 Sq Ft
	290	AUDITORIUM BALCONY 2045 OFF HALLWAY 2214	NONE DETECTED	030410ML-76		55 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
K3C	Miscellaneous Flooring Gray Rubber Floor					Total Amount - 3000 Sq Ft
76	1978 ADDITION GYMNASIUM 1065	NONE DETECTED	032210ML-01			3000 Sq Ft
K3D	Miscellaneous Flooring Gray Rubber Flooring (2023)					Total Amount - 5500 Sq Ft
267	GYMNASIUM 2120	NEW				5500 Sq Ft
L0A	Flexible Duct Connector White, Coarsely Woven					Total Amount - 38 Sq Ft
33	AHU MECHANICAL ROOM 0035 NEAR BOILER ROOM	NONE DETECTED	030410ML-57			38 Sq Ft
L0B	Flexible Duct Connector White Woven (1930)					Total Amount - 6 Sq Ft
184	1930 ADDITION MECHANICAL ROOM 1200	NONE DETECTED	030410ML-58			6 Sq Ft
L0C	Flexible Duct Connector White Woven (1926)					Total Amount - 1 Sq Ft
337	WEST PENTHOUSE MECHANICAL ROOM	NONE DETECTED	030410ML-59			1 Sq Ft
M0A	Plaster 1926 Original Building					Total Amount - 50000 Sq Ft
23	THROUGHOUT 1926 ORIGINAL BUILDING	NONE DETECTED	030410ML-97, 98, 99, 100, 101, 102; 510X1	ML-97: ROOM 1050. ML-98: ROOM 2057. ML-99: ROOM 2052. ML-100: HALLWAY NEAR ROOM 1051. ML-101: HALLWAY NEAR ROOM 3005. ML-102: MECHANICAL ROOM 1063.		50000 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
M0B	Plaster 1930 Addition	Total Amount - 15000 Sq Ft				
	67	THROUGHOUT 1930 ADDITION	NONE DETECTED	030410ML-103, 104, 105, 106; 352-JJT-30, 32; 2001-1501-G11	ML-103: HALLWAY 2201. ML-104: ROOM 3205. ML-105: ROOM 1211. ML-106: ROOM 1200.	15000 Sq Ft
M0C	Plaster 1971 Addition	Total Amount - 800 Sq Ft				
	72	THROUGHOUT 1971 ADDITION	NONE DETECTED	030410ML-107, 108, 109; 352-JJT-24	ML-107,108: BOYS' LOCKER ROOM. ML-109: SOUTH ENTRANCE 1214.	800 Sq Ft
N0A	Drywall/Joint Compound	Total Amount - 30000 Sq Ft				
	1	THROUGHOUT BUILDING	NONE DETECTED	352-JJT-8, 22; 2001-1501-G11, G13; ACB450AMA-10		30000 Sq Ft
P0A	Fire Doors Metal - 1-1/2 Hr Rating (Trussbilt)	Total Amount - 80 Sq Ft				
	75	FIRE SPRINKLER EQUIPMENT ROOM 0021	ASSUMED			20 Sq Ft
	149	BASEMENT MECHANICAL ROOM 0056	ASSUMED			20 Sq Ft
	193	MECHANICAL ROOM 1119	ASSUMED			20 Sq Ft
	348	MECHANICAL ROOM 3114	ASSUMED			20 Sq Ft
P0B	Fire Doors Composite - 1-1/2 Hr Rating (Eggers)	Total Amount - 160 Sq Ft				
	119	ROOM 0120	NONE DETECTED			20 Sq Ft
	121	ROOM 0119	NONE DETECTED			20 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	122	ROOM 0118	NONE DETECTED			20 Sq Ft
	127	ROOM 0121	NONE DETECTED			40 Sq Ft
	129	TITLE 1 MEN'S RESTROOM 0115	NONE DETECTED			20 Sq Ft
	131	TITLE 1 WOMEN'S RESTROOM 0113	NONE DETECTED			20 Sq Ft
	143	ROOM 0122	NONE DETECTED	030410ML-77		20 Sq Ft
POC	Fire Doors Wood - 1 Hr Rating (Marshfield)					Total Amount - 20 Sq Ft
	50	CAFETERIA STORAGE 0053	NEW			20 Sq Ft
POD	Fire Doors Wood - 1.5 Hr Rating (Warnock Hersey)					Total Amount - 20 Sq Ft
	52	STAIRWELL/LANDING 0055 AT SOUTHWEST CORNER OF CAFETERIA	NEW			20 Sq Ft
Q0A	Carpet Adhesive Gray, Dark Gray & Tan Carpet Squares					Total Amount - 15000 Sq Ft
	13	THROUGHOUT BUILDING	NONE DETECTED	030410ML-78	ML-78: ROOM 1005.	15000 Sq Ft
Q0B	Carpet Adhesive Blue Berber Carpet					Total Amount - 600 Sq Ft
	100	AUDITORIUM 1045	NONE DETECTED	030410ML-79		600 Sq Ft
Q0C	Carpet Adhesive Red w/Multi-Colored Berber Carpet					Total Amount - 8000 Sq Ft
	14	THROUGHOUT BUILDING	NONE DETECTED	030410ML-80	ML-80: OFFICE 1213.	8000 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
Q0D	Carpet Adhesive Blue, Tan & Red Berber Carpet					Total Amount - 1870 Sq Ft
	117	HALLWAY FROM ROOM 0120 TO RECEPTION	NONE DETECTED			230 Sq Ft
	212	ROOM 1071	NONE DETECTED			900 Sq Ft
	309	ROOM 3216	NONE DETECTED	030410ML-73		540 Sq Ft
	366	ROOM 3002	NONE DETECTED			200 Sq Ft
Q0E	Carpet Adhesive Blue, Gray & Green Circle Pattern Carpet Squares					Total Amount - 3980 Sq Ft
	218	ROOM 2063	NONE DETECTED			850 Sq Ft
	223	ROOM 2058	NONE DETECTED			670 Sq Ft
	226	ROOM 2052	NONE DETECTED	030410ML-81		1000 Sq Ft
	231	ROOM 2130	NONE DETECTED			1400 Sq Ft
	340	ROOM 3201	NONE DETECTED			60 Sq Ft
Q0F	Carpet Adhesive Gray w/Tan and Black Square Pattern (202x)					Total Amount - 1500 Sq Ft
	108	ROOM 1034 AND OFFICE	NEW			1500 Sq Ft
Q0G	Carpet Adhesive Dark Brown w/Cream and Black Lined Squares (202x)					Total Amount - 750 Sq Ft
	185	ROOM 1113	NEW			750 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
Q0H	Carpet Adhesive Black, Gray, Cream Letters Pattern (202x)					Total Amount - 2000 Sq Ft
	344	THROUGHOUT MEDIA CENTER & ASSOCIATED ROOMS	NEW			2000 Sq Ft
R0A	Baseboard/Mopboard Adhesive 4" Brown Baseboard					Total Amount - 200 Sq Ft
	15	THROUGHOUT BUILDING	NONE DETECTED	13299-4; 13590 24B		200 Sq Ft
R0C	Baseboard/Mopboard Adhesive 4" Blue Baseboard					Total Amount - 60 Sq Ft
	46	CAFETERIA 0045	NONE DETECTED	030410ML-82		50 Sq Ft
	49	CAFETERIA STORAGE 0053	NONE DETECTED			10 Sq Ft
R0D	Baseboard/Mopboard Adhesive 4" Dark Gray Baseboard					Total Amount - 1000 Sq Ft
	16	THROUGHOUT BUILDING	NONE DETECTED	030410ML-83	ML-83: HALLWAY NEAR ROOM 2052.	1000 Sq Ft
R0E	Baseboard/Mopboard Adhesive 6" Gray Baseboard					Total Amount - 20 Sq Ft
	210	ROOM 1130	NEW			20 Sq Ft
R0F	Baseboard/Mopboard Adhesive 4" Black Baseboard (20XX)					Total Amount - 100 Sq Ft
	17	THROUGHOUT BUILDING	NEW			100 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
R0G	Baseboard/Mopboard Adhesive 4" Black (2023)					Total Amount - 150 Sq Ft
	268	GYMNASIUM 2120	NEW			150 Sq Ft
S0A	Wood Floor Felt / Vapor Barrier Elevated (1926)					Total Amount - 17000 Sq Ft
	24	THROUGHOUT 1926 ORIGINAL BUILDING	ASSUMED			17000 Sq Ft
S0B	Wood Floor Felt / Vapor Barrier Elevated (1930)					Total Amount - 7000 Sq Ft
	68	THROUGHOUT 1930 ADDITION	ASSUMED			7000 Sq Ft
VOA	Sink Undercoating Pink					Total Amount - 14 Sq Ft
	81	ROOM 1064	5 CH	030410ML-84		4 Sq Ft
	126	ROOM 0121	5 CH			4 Sq Ft
	146	ROOM 0131	5 CH			6 Sq Ft
V0B	Sink Undercoating Gray					Total Amount - 106 Sq Ft
	20	THROUGHOUT BUILDING	NONE DETECTED	030410ML-85, 86	ML-85: ROOM 1110. ML-86: ML-86: ROOM 2220 (SINCE REMOVED).	106 Sq Ft
W1A	1' x 1' Ceiling Tile Adhesive Associated w/I1A					Total Amount - 330 Sq Ft
	217	ROOM 2063	NONE DETECTED	030410ML-39		100 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	222	ROOM 2058	NONE DETECTED			180 Sq Ft
	375	ROOM 3016	NONE DETECTED			50 Sq Ft
X0A	Miscellaneous Material AHU Seam Putty					Total Amount - 50 Sq Ft
	32	AHU MECHANICAL ROOM 0035 NEAR BOILER ROOM	NONE DETECTED	030410ML-87		40 Sq Ft
	183	1930 ADDITION MECHANICAL ROOM 1200	NONE DETECTED			10 Sq Ft
X0B	Miscellaneous Material Red Fire Stop					Total Amount - 200 Sq Ft
	18	THROUGHOUT BUILDING	NONE DETECTED	030410ML-88	ML-88: EAST PENTHOUSE.	200 Sq Ft
X0C	Miscellaneous Material Gray Duct Caulk					Total Amount - 200 Sq Ft
	19	THROUGHOUT BUILDING	NONE DETECTED	030410ML-89	ML-89: EAST PENTHOUSE.	200 Sq Ft
X0D	Miscellaneous Material Gray AHU Seam Caulk					Total Amount - 2 Sq Ft
	207	MECHANICAL ROOM 1063	NONE DETECTED	030410ML-90		2 Sq Ft
X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)					Total Amount - 240 Sq Ft
	177	ROOM 1207	ASSUMED			10 Sq Ft
	180	ROOM 1203	ASSUMED			15 Sq Ft
	278	ROOM 2203	ASSUMED			80 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	281	ROOM 2207	ASSUMED			80 Sq Ft
	286	ROOM 2211	ASSUMED			20 Sq Ft
	318	ROOM 3207	ASSUMED			10 Sq Ft
	322	ROOM 3205	ASSUMED			10 Sq Ft
	329	ROOM 3203	ASSUMED			15 Sq Ft
X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)					Total Amount - 311 Sq Ft
	178	ROOM 1207	ASSUMED			32 Sq Ft
	181	ROOM 1203	ASSUMED			64 Sq Ft
	282	ROOM 2207	ASSUMED			20 Sq Ft
	287	ROOM 2211	ASSUMED			90 Sq Ft
	319	ROOM 3207	ASSUMED			35 Sq Ft
	323	ROOM 3205	ASSUMED			35 Sq Ft
	330	ROOM 3203	ASSUMED			35 Sq Ft
X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)					Total Amount - 180 Sq Ft
	245	ROOM 2005	ASSUMED			25 Sq Ft
	255	ROOM 2027	ASSUMED			15 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	259	ROOM 2028	ASSUMED			5 Sq Ft
	355	ROOM 3063	ASSUMED			10 Sq Ft
	358	ROOM 3058	ASSUMED			5 Sq Ft
	360	ROOM 3054	ASSUMED			20 Sq Ft
	362	ROOM 3052	ASSUMED			20 Sq Ft
	364	ROOM 3050	ASSUMED			20 Sq Ft
	369	ROOM 3005	ASSUMED			20 Sq Ft
	372	ROOM 3015	ASSUMED			20 Sq Ft
	376	ROOM 3027	ASSUMED			10 Sq Ft
	379	ROOM 3028	ASSUMED			10 Sq Ft
X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)					Total Amount - 861 Sq Ft
	246	ROOM 2005	ASSUMED			30 Sq Ft
	256	ROOM 2027	ASSUMED			32 Sq Ft
	258	ROOM 2028	ASSUMED			20 Sq Ft
	356	ROOM 3063	ASSUMED			75 Sq Ft
	357	ROOM 3060	ASSUMED			24 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	359	ROOM 3058	ASSUMED			15 Sq Ft
	361	ROOM 3054	ASSUMED			110 Sq Ft
	363	ROOM 3052	ASSUMED			110 Sq Ft
	365	ROOM 3050	ASSUMED			110 Sq Ft
	370	ROOM 3005	ASSUMED			110 Sq Ft
	373	ROOM 3015	ASSUMED			110 Sq Ft
	377	ROOM 3027	ASSUMED			35 Sq Ft
	380	ROOM 3028	ASSUMED			40 Sq Ft
	382	ROOM 3030	ASSUMED			40 Sq Ft
X0I	Miscellaneous Material Science Table Top Insert					Total Amount - 15 Sq Ft
	248	ROOM 2005	NONE DETECTED	030410ML-91		15 Sq Ft
X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive					Total Amount - 30 Sq Ft
	156	ROOM 1215	ASSUMED			20 Sq Ft
	315	ROOM 3220	ASSUMED			10 Sq Ft
X0K	Miscellaneous Material Tar Paper at Concrete Ceiling					Total Amount - 40 Sq Ft
	37	TUNNEL SOUTH OF UNEXCAVATED AREA	NONE DETECTED	030410ML-92		20 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	40	TUNNEL NORTH OF UNEXCAVATED AREA	NONE DETECTED			20 Sq Ft
XOL	Miscellaneous Material Old Window Glaze					Total Amount - 2 Sq Ft
	367	EAST PENTHOUSE MECHANICAL ROOM	NONE DETECTED	030410ML-93		2 Sq Ft
XOM	Miscellaneous Material Old Window Glaze (1926)					Total Amount - 1 Sq Ft
	338	WEST PENTHOUSE MECHANICAL ROOM	NONE DETECTED	030410ML-94		1 Sq Ft
XON	Miscellaneous Material White Blown-In Mineral Wool					Total Amount - 4000 Sq Ft
	339	1930 ADDITION ATTIC	NONE DETECTED	030410ML-95		4000 Sq Ft
XOO	Miscellaneous Material Gray Blown-In Mineral Wool					Total Amount - 8000 Sq Ft
	368	1926 ORIGINAL BUILDING ATTIC	NONE DETECTED	030410ML-96		8000 Sq Ft
XOP	Miscellaneous Material Pipe/Valve Flange Gaskets & Packings					Total Amount - 40 Sq Ft
	26	BOILER ROOM 0030	ASSUMED			40 Sq Ft
XOQ	Miscellaneous Material Stone Panel Adhesive					Total Amount - 64 Sq Ft
	176	GIRLS' RESTROOM 1204	ASSUMED			14 Sq Ft
	249	GIRLS' RESTROOM 2008	ASSUMED			14 Sq Ft
	279	STAFF RESTROOM 2204	ASSUMED			4 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
	316	ROOM 3213	ASSUMED			4 Sq Ft
	328	GIRLS' RESTROOM 3204	ASSUMED			14 Sq Ft
	371	GIRLS' RESTROOM 3008	ASSUMED			14 Sq Ft
X0R	Miscellaneous Material Gray w/White Streaks Countertop					Total Amount - 8 Sq Ft
	381	ROOM 3028	NONE DETECTED	081815BV-02	BV-02: ROOM 3028.	8 Sq Ft
X0S	Miscellaneous Material Thin Metal Frame Corkboard Adhesive					Total Amount - 60 Sq Ft
	332	ROOM 3112	NONE DETECTED	081815BV-01	BV-01: HALLWAY 3003.	40 Sq Ft
	378	HALLWAY 3003 OUTSIDE ROOM 3028	NONE DETECTED			20 Sq Ft
X0T	Miscellaneous Material Gray Stair Tread (20XX)					Total Amount - 500 Sq Ft
	22	THROUGHOUT BUILDING STAIRWELLS	NEW			500 Sq Ft
X0U	Miscellaneous Material Interior/Exterior Window Caulk					Total Amount - 40 Sq Ft
	102	THROUGHOUT 1979 ADDITION	NONE DETECTED	052120-BF-1, 3	BF-1,3: TITLE 1.	40 Sq Ft
X0V	Miscellaneous Material Interior/Exterior Window Glazing Compound					Total Amount - 30 Sq Ft
	103	THROUGHOUT 1979 ADDITION	NONE DETECTED	052120-BF-2, 4	BF-2,4: TITLE 1.	30 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X1A	Miscellaneous Material 6" Red Quarry Tile					Total Amount - 800 Sq Ft
60	KITCHEN 0046		ASSUMED			800 Sq Ft
X1B	Miscellaneous Material 2" x 6" White Ceramic Wall Tile System (20XX)					Total Amount - 4000 Sq Ft
21	THROUGHOUT BUILDING RESTROOMS		NEW			4000 Sq Ft
X1C	Miscellaneous Material 12" Light Gray Ceramic Floor Tile System					Total Amount - 98 Sq Ft
93	ADULT RESTROOM 1018		NEW			50 Sq Ft
97	NURSE'S RESTROOM		NEW			48 Sq Ft
X1D	Miscellaneous Material 6" Brown Quarry Tile					Total Amount - 500 Sq Ft
136	TITLE 1 RECEPTION 0111		ASSUMED			500 Sq Ft
X1E	Miscellaneous Material 6" Light Gray Ceramic Floor Tile System (20XX)					Total Amount - 100 Sq Ft
145	ROOM 0131		NEW			100 Sq Ft
X1F	Miscellaneous Material 1" Light Brown Ceramic Floor Tile System					Total Amount - 170 Sq Ft
195	MEN'S LOCKER ROOM SHOWER 1121		NEW			170 Sq Ft

Homogeneous Area ID Code (Material Type)	IEA Event No.	Location	% Asbestos	Sample No.	Sample Location	Estimated Total Amount
X1G	Miscellaneous Material 1" x 2" Brown & Beige Ceramic Floor Tile System					Total Amount - 240 Sq Ft
	196	BOYS' RESTROOM 1122	NEW			200 Sq Ft
	299	ROOM 2218 RESTROOM	NEW			40 Sq Ft
X1H	Miscellaneous Material 6" Red Quarry Tile					Total Amount - 200 Sq Ft
	275	1930 ADDITION STAIRWELL/ENTRY 2200	ASSUMED			200 Sq Ft
X1I	Miscellaneous Material 4" X 2" Beige Ceramic Wall Tile System					Total Amount - 160 Sq Ft
	92	ADULT RESTROOM 1018	NEW			160 Sq Ft
X1K	Miscellaneous Material 8" X 8" Gray w/Black Specks Ceramic Floor Tile System (20xx)					Total Amount - 125 Sq Ft
	139	TITLE 1 RESTROOMS BY 0136	NEW			125 Sq Ft



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427
Tel/Fax: (763) 449-4922 / (763) 449-4924
<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352406771
Customer ID: IFEA50
Customer PO:
Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445
Project: 202410273 - Wellstone Elem.

Phone: (763) 315-7927
Fax: (763) 315-7920
Received Date: 07/23/2024 1:50 PM
Analysis Date: 07/24/2024
Collected Date: 07/23/2024

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
072324ML-02 352406771-0001	Rm 118 - Mudded Fitting on Fiberglass - A4B	Gray/Various Non-Fibrous Homogeneous	20% Glass 10% Wollastonite	70.0% Non-fibrous (Other)	None Detected
072324ML-03 352406771-0002	Rm 118 - Mudded Fitting on Fiberglass - A4B	Gray/Various Non-Fibrous Homogeneous	10% Synthetic 20% Glass 10% Wollastonite	60.0% Non-fibrous (Other)	None Detected
072324ML-04 Yellow Material 352406771-0003	Boys Locker Shower - Mudded Fitting on Fiberglass - A4B	Yellow Fibrous Homogeneous	95% MinWool	5.0% Non-fibrous (Other)	None Detected
072324ML-04 Gray Material 352406771-0003A	Boys Locker Shower - Mudded Fitting on Fiberglass - A4B	Gray Non-Fibrous Homogeneous	20% Glass 10% Wollastonite	70.0% Non-fibrous (Other)	None Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 07/24/2024 13:00:22



EMSL Analytical, Inc.

3410 Winnetka Avenue North New Hope, MN 55427
Tel/Fax: (763) 449-4922 / (763) 449-4924
<http://www.EMSL.com> / minneapolislab@emsl.com

EMSL Order: 352406771
Customer ID: IFEA50
Customer PO:
Project ID:

Attention: Emma Squires-Sperling
Inst. For Environmental Assessment
9201 West Broadway
Suite 600
Brooklyn Park, MN 55445
Project: 202410273 - Wellstone Elem.

Phone: (763) 315-7927
Fax: (763) 315-7920
Received Date: 07/23/2024 1:50 PM
Analysis Date: 07/24/2024
Collected Date: 07/23/2024

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk materials via EPA/600 (0513) Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date: 07/23/2024
Analysis Completed Date: 07/24/2024

Sample Receipt Time: 1:50 PM
Analysis Completed Time: 11:40 AM

Analyst(s):

Michael Craigmile PLM (4)

Samples Reviewed and approved by:

Rachel Travis, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. New Hope, MN NVLAP Lab Code 200019-0; Colorado AL-24478

Initial report from: 07/24/2024 13:00:22



9201 West Broadway North, Suite 600
Brooklyn Park, MN 55445
(763) 315-7900
1-800-233-9513

6771

CHAIN OF CUSTODY

Page 1 of 1

Order ID: 352406771

Client # _____		Project # <u>202410273</u>		Building Name <u>Wellstone Elem.</u>		Shaded Areas are for Laboratory Use Only!								
Client <u>Saint Paul Public Schools</u>		Project Name _____		Contact Person _____										
Address _____		IEA Project Manager _____		Other Information _____										
Verbal results to <u>Enn. Squines</u>		Phone, Fax No. or E-Mail _____		TAT (circle) 6 hr <u>24 hr</u> 48 hr 72 hr 96 hr Specify										
Verbal results relayed to _____		Verbal results relayed by _____		Date _____		Time _____								
Analysis location: ☐ On Site ☐ Lab ☐ Regional Office ☒ Other <u>EMS L</u>				Matrix type		Analysis requested		Filter type						
Sample #	Work Area or Phase #	Sample Description/Location	Sample type or Material code	Volume	Air	Bulk	Dust	PCM	PLM	TEM	Other	MCE	.8 um	.45 um
072324ML-02	R 1118	Muddled Fitting on Fiberglass	A4B		☐	☒	☐	☐	☒	☐		☐	☐	☐
03	" "	" "	A4B		☐	☒	☐	☐	☒	☐		☐	☐	☐
04	Boys Locker Shower	" "	A4B	Analyze muddled insulation only	☐	☒	☐	☐	☒	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐
					☐	☐	☐	☐	☐	☐		☐	☐	☐ </