

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
24 CAD #:	S0A	Wood Floor Felt / Vapor Barrier Elevated (1926)	THROUGHOUT 1926 ORIGINAL BUILDING	17000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
26 CAD #:	X0P	Miscellaneous Material Pipe/Valve Flange Gaskets & Packings	BOILER ROOM 0030	40 Sq Ft	N	ASSUMED	5
Comments: APPROXIMATELY FORTY (40) GASKETS.					Sample #:		
34 CAD #:	B1A	Air Cell Pipe Insulation 1926 Original Building	SMALL TUNNEL SECTION OFF OF TUNNEL SOUTH OF UNEXCAVATED AREA	1 Lin Ft	Y	80 CH	1
Comments: DEBRIS IN TUNNEL SECTION. INACCESSIBLE FOR CLEAN-UP. LABELED "CAUTION".					Sample #: 207C2A		
38 CAD #:	B1A	Air Cell Pipe Insulation 1926 Original Building	SMALL TUNNEL SECTION OFF OF TUNNEL NORTH OF UNEXCAVATED AREA	1 Lin Ft	Y	80 CH	1
Comments: DEBRIS IN TUNNEL SECTION. INACCESSIBLE FOR CLEAN-UP. LABELED "CAUTION".					Sample #: 207C-2A		
60 CAD #:	X1A	Miscellaneous Material 6" Red Quarry Tile	KITCHEN 0046	800 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
68 CAD #:	S0B	Wood Floor Felt / Vapor Barrier Elevated (1930)	THROUGHOUT 1930 ADDITION	7000 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
75 CAD #:	P0A	Fire Doors Metal - 1-1/2 Hr Rating (Trussbilt)	FIRE SPRINKLER EQUIPMENT ROOM 0021	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
81 CAD #:	V0A	Sink Undercoating Pink	ROOM 1064	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #: 030410ML-84		
89 CAD #:	K2N	12" x 12" Vinyl Floor Tile & Mastic Tan w/Brown & White Streaks	MECHANICAL ROOM 1035	30 Sq Ft	N	2 CH (TILE), 8 CH (MASTIC)	5
Comments: ACCESS INSIDE ROOM 1026. ONE (1) CHIPPED TILE AT PIPE PENETRATION & ONE CHIPPED TILE NEAR DOOR AT ENTRANCE.					Sample #: 030410ML-70		
126 CAD #:	V0A	Sink Undercoating Pink	ROOM 0121	4 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
128 CAD #:	K1A	Sheet Vinyl Flooring & Adhesive Yellow & Green Terrazzo-Look	TITLE 1 MEN'S RESTROOM 0115	30 Sq Ft	N	18 CH	5
Comments: ADHESIVE ANALYZED AS "NONE DETECTED".					Sample #: 030410ML-56		
130 CAD #:	K1A	Sheet Vinyl Flooring & Adhesive Yellow & Green Terrazzo-Look	TITLE 1 WOMEN'S RESTROOM 0113	30 Sq Ft	N	18 CH	5
Comments: ADHESIVE ANALYZED AS "NONE DETECTED". SOME WEAR UNDERNEATH TOILET. MONITOR.					Sample #:		
136 CAD #:	X1D	Miscellaneous Material 6" Brown Quarry Tile	TITLE 1 RECEPTION 0111	500 Sq Ft	N	ASSUMED	5
Comments: INCLUDES ENTRY 0138 & STAIRWELL NEAR ENTRY.					Sample #:		
146 CAD #:	V0A	Sink Undercoating Pink	ROOM 0131	6 Sq Ft	N	5 CH	5
Comments: ONE (1) SINK.					Sample #:		
149 CAD #:	P0A	Fire Doors Metal - 1-1/2 Hr Rating (Trussbilt)	BASEMENT MECHANICAL ROOM 0056	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
156 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 1215	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
176 CAD #:	X0Q	Miscellaneous Material Stone Panel Adhesive	GIRLS' RESTROOM 1204	14 Sq Ft	N	ASSUMED	5
Comments: RESTROOM STALLS.					Sample #:		
177 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 1207	10 Sq Ft	N	ASSUMED	5
Comments: COVERED W/WHITEBOARD.					Sample #:		
178 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 1207	32 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
180 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 1203	15 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED W/WHITEBOARD.					Sample #:		
181 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 1203	64 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
193 CAD #:	P0A	Fire Doors Metal - 1-1/2 Hr Rating (Trussbilt)	MECHANICAL ROOM 1119	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR. NORTHWEST CORNER OF MEN'S LOCKER ROOM.					Sample #:		
199 CAD #:	E1A	Stack Gasket Fume Hood Exhaust	MAINTENANCE ROOM 1123	1 Sq Ft	N	45 CH	5
Comments:					Sample #: 030410ML-16		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
211 CAD #:	E1A	Stack Gasket Fume Hood Exhaust	ROOM 1131	1 Sq Ft	N	45 CH	5
Comments:					Sample #:		
245 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 2005	25 Sq Ft	N	ASSUMED	5
Comments: SOME COVERED BY WHITEBOARD.					Sample #:		
246 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 2005	30 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
249 CAD #:	X0Q	Miscellaneous Material Stone Panel Adhesive	GIRLS' RESTROOM 2008	14 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
255 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 2027	15 Sq Ft	N	ASSUMED	5
Comments: COVERED BY WHITEBOARD.					Sample #:		
256 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 2027	32 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
258 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 2028	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
259 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 2028	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
275 CAD #:	X1H	Miscellaneous Material 6" Red Quarry Tile	1930 ADDITION STAIRWELL/ENTRY 2200	200 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
278 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 2203	80 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
279 CAD #:	X0Q	Miscellaneous Material Stone Panel Adhesive	STAFF RESTROOM 2204	4 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
281 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 2207	80 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARD.					Sample #:		
282 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 2207	20 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
286 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 2211	20 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
287 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 2211	90 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
310 CAD #:	K2Q	12" x 12" Vinyl Floor Tile & Mastic Tan w/Brown Specks	ROOM 3216	540 Sq Ft	N	3 CH (TILE)8 CH (MASTIC)	5
Comments: UNDER CARPET.					Sample #: 030410ML-73		
315 CAD #:	X0J	Miscellaneous Material Metal Frame Chalkboard Adhesive	ROOM 3220	10 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
316 CAD #:	X0Q	Miscellaneous Material Stone Panel Adhesive	ROOM 3213	4 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
318 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 3207	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
319 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 3207	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
322 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 3205	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
323 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 3205	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
328 CAD #:	X0Q	Miscellaneous Material Stone Panel Adhesive	GIRLS' RESTROOM 3204	14 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
329 CAD #:	X0E	Miscellaneous Material Wood Frame Chalkboard Adhesive (1930)	ROOM 3203	15 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARD.					Sample #:		
330 CAD #:	X0F	Miscellaneous Material Wood Frame Corkboard Adhesive (1930)	ROOM 3203	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
348 CAD #:	P0A	Fire Doors Metal - 1-1/2 Hr Rating (Trussbilt)	MECHANICAL ROOM 3114	20 Sq Ft	N	ASSUMED	5
Comments: ONE (1) DOOR.					Sample #:		
355 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3063	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
356 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3063	75 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
357 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3060	24 Sq Ft	N	ASSUMED	5
Comments: BEHIND CORKBOARD.					Sample #:		
358 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3058	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
359 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3058	15 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
360 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3054	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
361 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3054	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
362 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3052	20 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
363 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3052	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
364 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3050	20 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
365 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3050	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
369 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3005	20 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
370 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3005	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
371 CAD #:	X0Q	Miscellaneous Material Stone Panel Adhesive	GIRLS' RESTROOM 3008	14 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
372 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3015	20 Sq Ft	N	ASSUMED	5
Comments: SOME BEHIND WHITEBOARDS.					Sample #:		
373 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3015	110 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
376 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3027	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
377 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3027	35 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
379 CAD #:	X0G	Miscellaneous Material Wood Frame Chalkboard Adhesive (1926)	ROOM 3028	10 Sq Ft	N	ASSUMED	5
Comments: BEHIND WHITEBOARDS.					Sample #:		
380 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3028	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
382 CAD #:	X0H	Miscellaneous Material Wood Frame Corkboard Adhesive (1926)	ROOM 3030	40 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		