# Lead Sample Test Results and Actions

## CHIEF JOSEPH ELEMENTARY SCHOOL

| Fixture Number | Location | Part of Sampling Plan | Sampling Results (ppm) | Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service | Bin 2 - Lead concentrations equal or greater than 5.0 µg/L up to 15.0 µg/L – fixture must be fixed, replaced or removed from service | Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required. |
|---|---|---|---|---|---|---|
| FX 001 | | No | | | | |
| FX 002 | Office Sink | Yes | 0.0009 | | | No Action Required |
| FX 003 | East Hall Bottle Filler | Yes | 0.0009 | | | No Action Required |
| FX 004 | | No | | | | |
| FX 005 | | No | | | | |
| FX 006 | | No | | | | |
| FX 007 | Rm 1 Sink | Yes | 0.0009 | | | No Action Required |
| FX 008 | | No | | | | |
| FX 009 | | No | | | | |
| FX 010 | Rm 4 Sink | Yes | 0.0009 | | | No Action Required |
| FX 011 | Rm 5 Sink | Yes | 0.001 | | | No Action Required |
| FX 012 | | No | | | | |
| FX 013 | Rm 7 Sink | Yes | 0.0009 | | | No Action Required |
| FX 014 | | No | | | | |
| FX 015 | | No | | | | |
| FX 016 | | No | | | | |
| FX 017 | Rm 11 Sink | Yes | 0.0009 | | | No Action Required |
| FX 018 | | No | | | | |
| FX 019 | | No | | | | |
| FX 020 | | No | | | | |
| FX 021 | Rm 13 Sink | Yes | 0.001 | | | No Action Required |
| FX 022 | | No | | | | |
| FX 023 | RM 15 Sink | Yes | 0.001 | | | No Action Required |
| FX 024 | | No | | | | |
| FX 025 | | No | | | | |
| FX 026 | Rm 18 Sink | Yes | 0.0009 | | | No Action Required |
| FX 027 | RM 19 Sink | Yes | 0.005 | | Must be fixed, replaced or removed | |
| FX 028 | | No | | | | |
| FX 029 | | No | | | | |
| FX 030 | | No | | | | |
| FX 031 | | No | | | | |

# Lead Sample Test Results and Actions

## CHIEF JOSEPH ELEMENTARY SCHOOL

| Fixture Number | Location | Part of Sampling Plan | Sampling Results (ppm) | Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service | Bin 2 - Lead concentrations equal or greater than 5.0 µg/L up to 15.0 µg/L – fixture must be fixed, replaced or removed from service | Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required. |
|---|---|---|---|---|---|---|
| FX 032 | West Hall Bottle Filler | Yes | 0.0009 | | | No Action Required |
| FX 033 | | No | | | | |
| FX 034 | | No | | | | |
| FX 035 | | No | | | | |
| FX 036 | | No | | | | |
| FX 037 | Cafetteria Bottle Filler | Yes | 0.0009 | | | No Action Required |
| FX 038 | | No | | | | |
| FX 039 | | No | | | | |
| FX 040 | | No | | | | |
| FX 041 | | No | | | | |
| FX 042 | Kitchen Sink | Yes | 0.001 | | | No Action Required |
| FX 043 | | No | | | | |
| FX 044 | | No | | | | |
| FX 045 | | No | | | | |
| FX 046 | | No | | | | |
| FX 047 | | No | | | | |
| FX 048 | | No | | | | |
| FX 049 | | No | | | | |