

Lead Sample Test Results and Actions

MORNINGSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L up to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 001		No				
FX 002	Rm A1 fountain	Yes	0.002			No Action Required
FX 003		No				
FX 004		No				
FX 005		No				
FX 006		No				
FX 007		No				
FX 008	Rm K2 fountain	Yes	0.0009			No Action Required
FX 009	Rm A6 Fountain	Yes	0.0009			No Action Required
FX 010		No				
FX 011		No				
FX 012		No				
FX 013		No				
FX 014		No				
FX 015		No				
FX 016	Rm A3 fountain	Yes	0.003			No Action Required
FX 017		No				
FX 018		No				
FX 019		No				
FX 020		No				
FX 021		No				
FX 022		No				
FX 023	Awing Bottle Filler	Yes	0.0009			No Action Required
FX 024		No				
FX 025		No				
FX 026		No				
FX 027	Rm b6 fountain	Yes	0.002			No Action Required
FX 027	Rm B1 fountain	Yes	0.003			No Action Required
FX 028		No				
FX 029		No				
FX 030		No				
FX 031		No				
FX 032		No				
FX 033	Rm B4 fountain	Yes	0.002			No Action Required

Lead Sample Test Results and Actions

MORNINGSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L up to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 034		No				
FX 035		No				
FX 036		No				
FX 037		No				
FX 038		No				
FX 039		No				
FX 040		No				
FX 041		No				
FX 042	Bwing Bottle Filler	Yes	0.0009			No Action Required
FX 043		No				
FX 044		No				
FX 045		No				
FX 046		No				
FX 047		No				
FX 048	Rm C1 Sink	Yes	0.0009			No Action Required
FX 049		No				
FX 050		No				
FX 051		No				
FX 052		No				
FX 053		No				
FX 054		No				
FX 055		No				
FX 056	Rm C4 fountain	Yes	0.003			No Action Required
FX 057		No				
FX 058	Rm C5 fountain	Yes	0.001			No Action Required
FX 059		No				
FX 060		No				
FX 061		No				
FX 062		No				
FX 063		No				
FX 064		No				
FX 065	Cwing Bottle Filler	Yes	0.0009			No Action Required
FX 066		No				
FX 067		No				

Lead Sample Test Results and Actions

MORNINGSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L up to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 068		No				
FX 069		No				
FX 070		No				
FX 071	Cafeteria Low fountain	Yes	0.0009			No Action Required
FX 072		No				
FX 073		No				
FX 074		No				
FX 075		No				