

ITEM ID	FACILITY	FACILITY TYPE	ITEM DESCRIPTION	DISCIPLINE	CLASSIFICATION	PRIORITY	CONSTRUCTION COST	INFLATION +15%	Construction + Inflation	Blank	SOFT COST +25%	TOTAL COST
0007	Administrative Building	Support Facilities	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
0019	Administrative Building	Support Facilities	Replace (6) MZ-CHW AHUs (4 are RTU). Units are 10-20 ton with hot water heat.	Mechanical	HVAC	2	\$ 600,000.00	\$ 90,000.00	\$ 690,000.00			
0026	Administrative Building	Support Facilities	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 556,920.00	\$ 83,538.00	\$ 640,458.00			
0030	Alamo STEAM Academy	Elementary Schools	Open gate on southwest corner of playground. Baseball backstops are rusted and fencing bent up. Ground cover under playground equipment consists of mulch and dirt. Open gates on playground.	Civil	Playground Equipment	2	\$ 34,800.00	\$ 5,220.00	\$ 40,020.00			
0053	Alamo STEAM Academy	Elementary Schools	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 297,655.00	\$ 44,648.25	\$ 342,303.25			
0055	Alamo STEAM Academy	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 595,310.00	\$ 89,296.50	\$ 684,606.50			
0085	Alternative Education Center (AEC)	High Schools ALT	Upgrade secondary electrical distribution equipment.	Electrical	Electrical Distribution	2	\$ 70,000.00	\$ 10,500.00	\$ 80,500.00			
0091	Alternative Education Center (AEC)	High Schools ALT	South ramp into to main building on east side is too steep. Both ramps into temporary building on the east side are too steep. No accessible path to buildings RC-14, RC-15, and RC-16. All ramps going into building on east side are too steep. Ramp into RC-41 is too steep and the cross slope is greater than 2.0%. Sign for ADA parking on east side of parking lot is too short and space is not van accessible. The space also does not have a crosswalk from the aisle to accessible route. ADA parking on west side of parking lot does not meet standards. The aisle is being used as the only access to another area to the parking lot.	Fire & Life Safety	Ramps	2	\$ 91,525.00	\$ 13,728.75	\$ 105,253.75			
0103	Austin Montessori Magnet Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
0121	Austin Montessori Magnet Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0127	Austin Montessori Magnet Elementary School	Elementary Schools	Stairs across from 205 have guards that are not 42 inches high. Recommend renovating guards to 42 inches high and include new continuous handrails.	Fire & Life Safety	Railing (guard rails, handrails, etc.)	2	\$ 1,500.00	\$ 225.00	\$ 1,725.00			
0129	Austin Montessori Magnet Elementary School	Elementary Schools	Stairs at south end of EE hall have guards that are not 42 inches high. Recommend renovating guards to 42 inches high and include new continuous handrails.	Fire & Life Safety	Railing (guard rails, handrails, etc.)	2	\$ 1,500.00	\$ 225.00	\$ 1,725.00			
0130	Austin Montessori Magnet Elementary School	Elementary Schools	Stairs at south end of FF Hall have guards that are not 42 inches high. Recommend renovating guards to 42 inches high and include new continuous handrails.	Fire & Life Safety	Railing (guard rails, handrails, etc.)	2	\$ 1,500.00	\$ 225.00	\$ 1,725.00			

0131	Austin Montessori Magnet Elementary School	Elementary Schools	Curb ramp for ADA parking on east side of south parking lot is too steep and has a cross slope greater than 2.0%; landing at top of curb ramp has a cross slope greater than 2.0%; signage is too short; parking stall to the east is not van accessible. Curb ramp in drop off area of south parking lot is too steep. Cross slope of aisle for ADA parking in south parking lot on west side is greater than 2.0%; curb ramp is too steep on east side; signage is too short and difficult to read behind fence. Not all crosswalks have a curb ramps. Cracking in concrete on east side of building makes the grade change to large to be accessible. No access ramp into temporary building. Curb ramps at entrance to northwest parking are too steep. Sidewalk in this area has a cross slope greater than 2.0%. Slope for aisle for ADA parking in northwest parking lot is too steep; signage is too short.	Fire & Life Safety	Ramps	2	\$ 21,500.00	\$ 3,225.00	\$ 24,725.00			
0179	Blackshear Elementary Magnet School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 463,728.21	\$ 69,559.23	\$ 533,287.44			
0183	Blackshear Elementary Magnet School	Elementary Schools	South temporary building does not have an access ramp. Top ramp into temporary building (RC-62) is too steep. ADA parking in north parking lot has accessible route blocked by dumpsters; aisles are not wide enough to meet standards; signage is not tall enough.	Fire & Life Safety	Ramps	2	\$ 66,750.00	\$ 10,012.50	\$ 76,762.50			
0194	Blanton Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
0213	Blanton Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 263,031.87	\$ 39,454.78	\$ 302,486.65			
0216	Blanton Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
0253	Bonham Middle School	Middle Schools	Replace (3) CWH roof top air conditioning units. Units are 25-45 ton with hot water heat.	Mechanical	HVAC	2	\$ 340,000.00	\$ 51,000.00	\$ 391,000.00			
0255	Bonham Middle School	Middle Schools	Replace (5) packaged roof top air conditioning units. Units are 2-5 ton with gas heat.	Mechanical	HVAC	2	\$ 75,000.00	\$ 11,250.00	\$ 86,250.00			
0256	Bonham Middle School	Middle Schools	Replace (15) electrical distribution panel(s) - 100A-400A.	Electrical	Electrical Distribution	2	\$ 115,000.00	\$ 17,250.00	\$ 132,250.00			
0257	Bonham Middle School	Middle Schools	Replace electrical switchgear (1600A).	Electrical	Electrical Gear	2	\$ 85,000.00	\$ 12,750.00	\$ 97,750.00			
0258	Bonham Middle School	Middle Schools	Replace electrical main switchgear (2500A).	Electrical	Electrical Gear	2	\$ 120,000.00	\$ 18,000.00	\$ 138,000.00			
0261	Bonham Middle School	Middle Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 20,866.00	\$ 3,129.90	\$ 23,995.90			
0263	Bonham Middle School	Middle Schools	Replace sanitary waste and vent system through 80% of the campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 999,182.06	\$ 149,877.31	\$ 1,149,059.37			
0268	Bonham Middle School	Middle Schools	Bleachers for football field do not have ADA access. No accessible exits on north side of the building, with the exception of one near northwest corner leaving auditorium. No ADA parking in west parking lot. Two of the temporary buildings on the west side have ramps. Ramp on southeast corner of the building is too steep and the handrail does not meet standard. No ADA parking in east parking lot, accessible route exists. No curb ramps for crosswalks.	Fire & Life Safety	Ramps	2	\$ 65,405.00	\$ 9,810.75	\$ 75,215.75			
0295	Bowie Middle School	Middle Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 42,873.00	\$ 6,430.95	\$ 49,303.95			

0315	Bowie Middle School	Middle Schools	Replace (2) Carrier 4-pipe AHU's.	Mechanical	HVAC	2	\$ 100,000.00	\$ 15,000.00	\$ 115,000.00			
0319	Bowie Middle School	Middle Schools	Replace (8) Temtrol 4 pipe roof top AHU's.	Mechanical	HVAC	2	\$ 900,000.00	\$ 135,000.00	\$ 1,035,000.00			
0320	Bowie Middle School	Middle Schools	Replace duct system from Temtrol units, including external insulation.	Mechanical	HVAC	2	\$ 800,000.00	\$ 120,000.00	\$ 920,000.00			
0321	Bowie Middle School	Middle Schools	Replace secondary distribution equipment panels, A3, A2, 2-A, and A1.	Electrical	Electrical Distribution	2	\$ 45,000.00	\$ 6,750.00	\$ 51,750.00			
0323	Bowie Middle School	Middle Schools	General Campus - Drinking fountains are not TAS accessible in most corridors, except in remodeled area entry and library. Recommend replacing with hi-lo accessible drinking fountain throughout entire campus.	Plumbing	Electric Drinking Fountains	2	\$ 26,844.00	\$ 4,026.60	\$ 30,870.60			
0324	Bowie Middle School	Middle Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 20,866.00	\$ 3,129.90	\$ 23,995.90			
0326	Bowie Middle School	Middle Schools	Replace sanitary waste and vent system over 80% of the campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 1,268,339.90	\$ 190,250.99	\$ 1,458,590.89			
0331	Bowie Middle School	Middle Schools	Several ADA parking spots have concrete and asphalt creating a change in grade greater than 1/4". Power pole in curb ramp makes it inaccessible. Not all crosswalks have curb ramps. Sidewalk on north side of building near storm drain has a cross slop great	Fire & Life Safety	Ramps	2	\$ 70,500.00	\$ 10,575.00	\$ 81,075.00			
0372	Buice Elementary School	Elementary Schools	Some brick pavers at main entrance are not level or have gaps greater which with settlement could create grade changes than 1/4". Wooden ramp blocking ADA parking in south parking lot. Significant sediment build up in curb ramp for aisle making it inaccessible.	Fire & Life Safety	Ramps	2	\$ 17,500.00	\$ 2,625.00	\$ 20,125.00			
0382	Burleson Elementary School	Elementary Schools	Replace existing metal roof system per District standards (gym).	Building Envelope	Roof Replacement	2	\$ 327,301.79	\$ 49,095.27	\$ 376,397.06			
0401	Burleson Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0403	Burleson Elementary School	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 668,120.00	\$ 100,218.00	\$ 768,338.00			
0413	Burnet Elementary School	Elementary Schools	Rusted baseball backstops. Warped and bent fencing on baseball backstops. Open gates. Ground coverage consists of gravel, mulch and dirt.	Civil	Playground Equipment	2	\$ 34,800.00	\$ 5,220.00	\$ 40,020.00			
0419	Burnet Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
0448	Burnet Elementary School	Elementary Schools	Exist on west side of building has too steep of a ramp. ADA parking on west side of building has an inadequate aisle. Crosswalks do not have curb ramps. Ramps to temporary is too steep and has inappropriate bottom landings or has no ramp at all.	Fire & Life Safety	Ramps	2	\$ 26,250.00	\$ 3,937.50	\$ 30,187.50			
0504	Cameron Dual Language Magnet School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0507	Cameron Dual Language Magnet School	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 755,570.00	\$ 113,335.50	\$ 868,905.50			
0510	Cameron Dual Language Magnet School	Elementary Schools	ADA parking in east parking lot does not have signage. Curb ramp into north entrance of main hall is too steep. Ramp to north entrance to E hall does not meet standards. Most crosswalks do no have curb ramps; existing curb ramps do not meet standards. Ram	Fire & Life Safety	Ramps	2	\$ 21,000.00	\$ 3,150.00	\$ 24,150.00			
0540	Carver Early Education Center	Early Education Centers	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0544	Carver Early Education Center	Early Education Centers	Sidewalk to basketball courts is too steep for a walking path. South ADA parking in southeast parking lot is not van accessible because aisle is not on passenger side; combination of concrete and asphalt in aisle along with potholing makes the aisle non a	Fire & Life Safety	Ramps	2	\$ 9,250.00	\$ 1,387.50	\$ 10,637.50			

0554	Cavazos Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
0576	Cavazos Elementary School	Elementary Schools	Replace (25) electrical distribution panels. Panels are 28-29 years old.	Electrical	Electrical Distribution	2	\$ 190,000.00	\$ 28,500.00	\$ 218,500.00			
0583	Cavazos Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0585	Cavazos Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 296,432.04	\$ 44,464.81	\$ 340,896.85			
0589	Cavazos Elementary School	Elementary Schools	No ADA parking in east parking lot. Wheel stop in east ADA parking in north parking lot: curb ramp to accessible route is not in aisle and is blocked by wheel stop; sediment build up in parking stall. Curb ramp to main entrance is too steep. Cracking in sidewalk on north side of building makes it inaccessible. Curb ramp to north entrance for west wing is too steep. No ramp into temporary building. Curb ramp to entrance on east side of east wing is too steep. Curb ramps in east parking lot are too steep.	Fire & Life Safety	Ramps	2	\$ 43,750.00	\$ 6,562.50	\$ 50,312.50			
0600	Crockett Middle School	Middle Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 42,873.00	\$ 6,430.95	\$ 49,303.95			
0620	Crockett Middle School	Middle Schools	Install DDC controls campus-wide.	Mechanical	Cooling Tower	2	\$ 375,000.00	\$ 56,250.00	\$ 431,250.00			
0622	Crockett Middle School	Middle Schools	Replace (21) Exhaust fans 1550 cfm.	Mechanical	HVAC	2	\$ 32,000.00	\$ 4,800.00	\$ 36,800.00			
0629	Crockett Middle School	Middle Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 20,866.00	\$ 3,129.90	\$ 23,995.90			
0632	Crockett Middle School	Middle Schools	Replace 60% of sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 667,172.52	\$ 100,075.88	\$ 767,248.40			
0636	Crockett Middle School	Middle Schools	No ADA parking in north parking lot. Curb ramp at northeast corner of building is too steep. Bottom landings for ramps into temporary buildings are too steep. Ramps into temporary buildings RC-55 and RC-33 are too steep. Ramp into temporary building RC-130 does not have an appropriate bottom landing. Ramp into temporary building RC-127 does not have an appropriate landing and is too steep. Cracking in sidewalk on west side of building makes it inaccessible. Ramp for temporary building on south side of main building has a cross slope greater than 2.0% and too steep of a bottom landing. Curb ramps for ADA parking in east parking lot are too steep; signs are rusted and need replacing. Not all crosswalks have curb ramps.	Fire & Life Safety	Ramps	2	\$ 81,250.00	\$ 12,187.50	\$ 93,437.50			
0662	Dowling Elementary School	Elementary Schools	Baseball backstop rusted. Ground coverage under playground equipment is either dirt or small gravel.	Civil	Playground Equipment	2	\$ 54,800.00	\$ 8,220.00	\$ 63,020.00			
0667	Dowling Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
0683	Dowling Elementary School	Elementary Schools	Replace (55) packaged roof top air conditioning units. Units are 3 ton with gas heat.	Mechanical	HVAC	2	\$ 825,000.00	\$ 123,750.00	\$ 948,750.00			
0685	Dowling Elementary School	Elementary Schools	Replace Distribution panel M (400A).	Electrical	Electrical Gear	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
0688	Dowling Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			

0690	Dowling Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 278,974.98	\$ 41,846.25	\$ 320,821.23			
0693	Dowling Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 25,000.00	\$ 3,750.00	\$ 28,750.00			
0694	Dowling Elementary School	Elementary Schools	No crosswalks have curb ramps for ADA access. Crown of road appears to make crosswalk too steep to meet TAS standards. ADA parking in south of parking lot does not meet size and sign requirements. It also does not have an appropriate accessible route into the building. Detectable warning surface brick has gaps and laid uneven which may cause changes in grade over 1/4". Parking stall on north side of building labeled as van accessible but does not meet requirements for van accessibility.	Fire & Life Safety	Ramps	2	\$ 28,500.00	\$ 4,275.00	\$ 32,775.00			
0715	Downing Elementary School	Elementary Schools	Some brick pavers at main entrance are not level or have gaps greater which with settlement could create grade changes than 1/4". Mulch debris build up is ADA parking in south parking lot which may cause it to be inaccessible if not kept clean. Gaps and unlevel detectable warning surface pavers in curb ramps create grade changes greater than 1/4". Curb ramp for ADA parking in south parking lot is too steep on north side.	Fire & Life Safety	Ramps	2	\$ 10,000.00	\$ 1,500.00	\$ 11,500.00			
0734	ECISD Police	Support Facilities	Replace (4) packaged roof top air conditioning units. Units are 4-5 ton with gas heat.	Mechanical	HVAC	2	\$ 25,000.00	\$ 3,750.00	\$ 28,750.00			
0749	Ector Middle School	Middle Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 42,873.00	\$ 6,430.95	\$ 49,303.95			
0770	Ector Middle School	Middle Schools	Replace (16) packaged roof top air conditioning units. Units are 6-10 ton with gas heat.	Mechanical	HVAC	2	\$ 360,000.00	\$ 54,000.00	\$ 414,000.00			
0772	Ector Middle School	Middle Schools	Replace (12) chilled water roof top air conditioning units. Units are 4000-14000 CFM with hot water heat.	Mechanical	HVAC	2	\$ 1,130,000.00	\$ 169,500.00	\$ 1,299,500.00			
0773	Ector Middle School	Middle Schools	Replace (5) hydronic pumps 5-15HP.	Mechanical	HVAC	2	\$ 75,000.00	\$ 11,250.00	\$ 86,250.00			
0778	Ector Middle School	Middle Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 20,866.00	\$ 3,129.90	\$ 23,995.90			
0780	Ector Middle School	Middle Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 2,780,160.00	\$ 417,024.00	\$ 3,197,184.00			
0784	Ector Middle School	Middle Schools	Curb ramp on west side of building is too steep. South ramp in to building entrance on east side is too steep. Curb ramp at northeast corner of building is too steep. Curb ramp for east ADA parking in north parking lot is too steep. Side walk on north side of building is inaccessible. Middle ADA parking in north parking lot has inappropriate placement of curb ramp and its too steep; aisle is too steep. Ramp into entrance on north side of building is too steep. ADA parking on west side of north parking lot: signage is too short; aisle too steep. ADA parking in northwest parking lot: signage is too short. Crosswalks do not have curb ramps. Signs for ADA parking in east parking lot are faded and need replacing. Signage for ADA parking in south parking lot is too short. One ramp into temporary building north of tennis courts has a cross slope greater than 2.0%. One temporary building north of tennis courts does not have an access ramp. Ramps to bleachers are not accessible.	Fire & Life Safety	Ramps	2	\$ 60,250.00	\$ 9,037.50	\$ 69,287.50			
0830	Fly Elementary School	Elementary Schools	Replace electrical main switchgear (2500A). Gear appears to be original equipment.	Electrical	Electrical Gear	2	\$ 120,000.00	\$ 18,000.00	\$ 138,000.00			
0836	Fly Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			

0839	Fly Elementary School	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 708,000.00	\$ 106,200.00	\$ 814,200.00			
0842	Fly Elementary School	Elementary Schools	One temporary building does not have an access ramp. Access ramps on two northern temporary buildings are too steep. Curb ramp at road on south side of building is too steep. Ramp in to entrance to kitchen is too steep. Temporary building on west side does not have an access ramp. Some crosswalks do not have curb ramps. ADA parking in west paved parking lot is not sized to be van accessible. Cracks in concrete and asphalt in accessible route from west ADA parking. ADA parking spot in south parking lot missing sign.	Fire & Life Safety	Ramps	2	\$ 86,000.00	\$ 12,900.00	\$ 98,900.00			
0863	Food Service	Support Facilities	All electrical system need to be evaluated and replace with the new design in place to meet the demand for the facility.	Electrical	Electrical Gear	2	\$ 300,000.00	\$ 45,000.00	\$ 345,000.00			
0864	Food Service	Support Facilities	Remove all old electrical switch gear.	Electrical	Electrical Gear	2	\$ 75,000.00	\$ 11,250.00	\$ 86,250.00			
0867	Food Service	Support Facilities	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 143,205.00	\$ 21,480.75	\$ 164,685.75			
0870	Food Service	Support Facilities	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 125,000.00	\$ 18,750.00	\$ 143,750.00			
0897	Frost ATC and Greenhouse	High Schools SP	Ramp into temporary building is too steep. Ramp into east building at southwest corner is too steep. Curb ramp for ADA parking at east building is too steep. Ramp into east building on north side is too steep.	Fire & Life Safety	Ramps	2	\$ 23,125.00	\$ 3,468.75	\$ 26,593.75			
0926	Goliad Elementary School	Elementary Schools	Replace secondary electrical distribution equipment.	Electrical	Electrical Distribution	2	\$ 100,000.00	\$ 15,000.00	\$ 115,000.00			
0929	Goliad Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0931	Goliad Elementary School	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 612,340.00	\$ 91,851.00	\$ 704,191.00			
0934	Goliad Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
0935	Goliad Elementary School	Elementary Schools	Ramp into temporary building is too steep. Most crosswalks do not have curb ramps. Curb ramp on east side of building does not meet standards; it's too steep and has a cross slope greater than 2.0%. North ADA parking spot in the east parking lot does not meet standards, including curb ramp. Sidewalk leading to building entrance near library on the east side is too steep for a walking path and a ramp. South ADA parking in east parking lot does not meet requirements for van accessibility; the cross slope for the south curb ramp is greater than 2.0%. Crosswalk to main entrance of building has curb ramps that do not meet standards. Sidewalk at south entrance to building near room 5 is too steep for a walking path or a ramp.	Fire & Life Safety	Ramps	2	\$ 38,250.00	\$ 5,737.50	\$ 43,987.50			
0964	Gonzales Elementary School	Elementary Schools	Replace (20) packaged roof top air conditioning units. Units are 3 ton with gas heat. 27 units were replaced in 2015.	Mechanical	HVAC	2	\$ 357,446.80	\$ 53,617.02	\$ 411,063.82			
0966	Gonzales Elementary School	Elementary Schools	Replace electrical main switchgear and associated panel PM (800A).	Electrical	Electrical Distribution	2	\$ 25,000.00	\$ 3,750.00	\$ 28,750.00			
0970	Gonzales Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
0975	Gonzales Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 25,000.00	\$ 3,750.00	\$ 28,750.00			

0976	Gonzales Elementary School	Elementary Schools	None of the crosswalks have curb ramps. Some do not lead to an area with sidewalk. West parking lot ADA parking meets TAS standards for size. Signs need to be updated and installed on post correctly. One ADA parking space parallel to curb in north parking lot is inappropriately placed, does not meet TAS standards for size, and does not have an aisle or sign. Angled ADA parking in north parking lot issues; only one sign and it is an incorrect sign; sign says van accessible, but the spot is not sized appropriately to be van accessible; if spots were not van accessible, they would be sized appropriately. Curb ramps at driveways do not meet standard and lead to discontinued sidewalk. Curb ramps do not have detectable warning surfaces. More ADA parking stalls are required.	Fire & Life Safety	Ramps	2	\$ 51,000.00	\$ 7,650.00	\$ 58,650.00			
1001	Hays Magnet Academy	Elementary Schools	Replace (43) packaged roof top air conditioning units. Units are 3-5 ton with gas heat.	Mechanical	HVAC	2	\$ 650,000.00	\$ 97,500.00	\$ 747,500.00			
1005	Hays Magnet Academy	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1007	Hays Magnet Academy	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 238,929.78	\$ 35,839.47	\$ 274,769.25			
1011	Hays Magnet Academy	Elementary Schools	Accessible route from ADA parking to building and ADA parking itself has pot holes in it in south parking lot. Curb ramp for accessible route on south side of building near main entrance is too steep. Sidewalk at southeast corner of building is too steep for walking path. Crosswalks do not have curb ramps that meet standards. Sidewalk south of boiler room is too steep for a walking path and has a cross slope greater than 2.0%. Ramps into temporary buildings east of D wing are too steep. Cross slope of bottom landing for ramp into temporary building south of C wing is greater than 2.0%. Sidewalk leading north out of B wing is too steep for a walking path. Ramp into temporary building at northeast corner of B wing is too steep.	Fire & Life Safety	Ramps	2	\$ 45,750.00	\$ 6,862.50	\$ 52,612.50			
1025	Information Technology	Support Facilities	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 75,850.00	\$ 11,377.50	\$ 87,227.50			
1027	Information Technology	Support Facilities	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 60,000.00	\$ 9,000.00	\$ 69,000.00			
1032	Instructional Materials & Records Management	Support Facilities	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
1042	Instructional Materials & Records Management	Support Facilities	Replace (3) packaged roof top air conditioning units. Units are 2-7.5 ton with gas heat.	Mechanical	HVAC	2	\$ 45,000.00	\$ 6,750.00	\$ 51,750.00			
1044	Instructional Materials & Records Management	Support Facilities	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 55,325.00	\$ 8,298.75	\$ 63,623.75			
1046	Instructional Materials & Records Management	Support Facilities	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 110,650.00	\$ 16,597.50	\$ 127,247.50			

1076	Ireland Elementary School	Elementary Schools	Replace lined duct campus-wide.	Mechanical	HVAC	2	\$ 400,000.00	\$ 60,000.00	\$ 460,000.00			
1077	Ireland Elementary School	Elementary Schools	Replace approximately (6) 115v exhaust fans.	Mechanical	HVAC	2	\$ 400,000.00	\$ 60,000.00	\$ 460,000.00			
1080	Ireland Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1082	Ireland Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 246,481.74	\$ 36,972.26	\$ 283,454.00			
1085	Ireland Elementary School	Elementary Schools	ADA parking in south parking lot does not have signage. Curb ramp at the aisle for this spots does not meet standards. Cracking and unlevelled concrete at main entrance makes it inaccessible. Crosswalks do not have curb ramps. Cross slope of ADA parking in n	Fire & Life Safety	Ramps	2	\$ 13,750.00	\$ 2,062.50	\$ 15,812.50			
1086	Ireland Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
1113	Johnson Elementary School	Elementary Schools	Replace all lined duct campus-wide.	Mechanical	HVAC	2	\$ 450,000.00	\$ 67,500.00	\$ 517,500.00			
1118	Johnson Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1123	Johnson Elementary School	Elementary Schools	Curb ramps for crosswalks are not existent or do not meet standards. No crosswalk leading ADA parking across traffic to building. No ADA parking near main entrance. Crosswalk leads to an extremely steep sidewalk (Slope of 18% leading down towards roadway). Sidewalk is buckled on the west wall of the building making it inaccessible. Cross slope for sidewalk leading to east parking lot is greater than 2%. Slope of walking surface on east side of building is too steep and its cross slope is too steep as well. Slope of walk way leading to north temporary building is too steep. Metal ramps into two south temporary buildings are too steep and do not have appropriate landings at the bottom of the ramp. Curb ramps on the northwest side of the building are too steep and not appropriate.	Fire & Life Safety	Ramps	2	\$ 43,500.00	\$ 6,525.00	\$ 50,025.00			
1153	Jordan Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1155	Jordan Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 270,000.00	\$ 40,500.00	\$ 310,500.00			
1158	Jordan Elementary School	Elementary Schools	No ADA parking in north parking lot. Curb ramp for entrance on building on north side is too steep and its flares are too steep. Ramps into most temporary buildings are too steep; some bottom landings are too steep as well. Curb ramp to pick up/drop off area on south side of building is too steep. Curb ramps for crosswalks in west parking lot is too steep. ADA parking in west parking lot does not have signage and does not provide direction to accessible route from aisle or a curb ramp. Street crosswalk does not have curb ramp.	Fire & Life Safety	Ramps	2	\$ 110,750.00	\$ 16,612.50	\$ 127,362.50			
1168	Lamar Early Education Center	Early Education Centers	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
1185	Lamar Early Education Center	Early Education Centers	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1187	Lamar Early Education Center	Early Education Centers	Replace sanitary and grease waste and vent system in kitchen. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 150,000.00	\$ 22,500.00	\$ 172,500.00			

1191	Lamar Early Education Center	Early Education Centers	No ADA parking in west parking lot. Ramp into entrance near loading dock at southeast corner of building has a cross slope greater than 2.0%. Cross slope for sidewalk along south side of building has a cross slope greater than 2.0%. Cross slope for all curb ramps south of building has a cross slope greater than 2.0%. Not all crosswalks have curb ramps. Street sign and fire hydrant make sidewalk at southeast corner of property inaccessible. Cross slope for most curb ramp along east sidewalk have a cross slope greater than 2.0%. Curb ramp for ADA parking in east parking lot is too steep; slope for aisle is too steep; signs are faded and need replacing.	Fire & Life Safety	Ramps	2	\$ 16,750.00	\$ 2,512.50	\$ 19,262.50			
1215	Maintenance Operations	Support Facilities	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
1233	Milam Magnet Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
1254	Milam Magnet Elementary School	Elementary Schools	Most crosswalks do not have curb ramps; existing curb ramps for crosswalks do not meet standards. Signs for ADA parking in south parking lot are too short; spot to the north is not van accessible. Significant debris build up from drainage in curb ramp for ADA parking in east parking lot making it inaccessible. Curb ramp is also too steep. ADA parking in east parking lot not van accessible. ADA parking in north parking lot is completely submerged in water and has no striping or accessible route. Ramp into temporary building south of main building is too steep.	Fire & Life Safety	Ramps	2	\$ 23,750.00	\$ 3,562.50	\$ 27,312.50			
1264	New Tech Odessa High School	High Schools SP	Repair existing broken and cracked exterior wall cladding; concrete masonry (CMU)/synthetic plaster at fitness side.	Building Envelope	Wall Repair - Exterior	2	\$ 10,000.00	\$ 1,500.00	\$ 11,500.00			
1283	New Tech Odessa High School	High Schools SP	Replace (2) 120-140 ton air cooled chillers.	Mechanical	HVAC	2	\$ 350,000.00	\$ 52,500.00	\$ 402,500.00			
1284	New Tech Odessa High School	High Schools SP	Replace (68) horizontal 4-pipe FCUs (ceiling mounted). Units are 3 ton with hot water heating coils.	Mechanical	HVAC	2	\$ 1,000,000.00	\$ 150,000.00	\$ 1,150,000.00			
1285	New Tech Odessa High School	High Schools SP	Replace chilled water and heating water pumps (5).	Mechanical	HVAC	2	\$ 75,000.00	\$ 11,250.00	\$ 86,250.00			
1286	New Tech Odessa High School	High Schools SP	Replace heating water boiler (5MMBH).	Mechanical	HVAC	2	\$ 300,000.00	\$ 45,000.00	\$ 345,000.00			
1293	New Tech Odessa High School	High Schools SP	Sidewalk curb ramps do not meet standards. Ramp to entrance on north eastern corner of building is too steep and the handrails do not meet TAS requirements. Ramp into entrance on west side of building near ADA parking is too steep. The landing at the bottom of the ramp has a cross slope greater than 2%. The railing also does not meet TAS standards. The aisle for the ADA parking at this entrance does not have markings on the ground leading to the accessible route as required. Ramp to entrance on the south side of the building near the outdoor tables has the asphalt buckled up greater than 1/4". ADA parking on south side of building has the aisle on the wrong side. ADA parking on northeast side of building has inappropriate curb ramps that extend out into the aisle. Curb ramps to main entrance of building do not meet standard.	Fire & Life Safety	Ramps	2	\$ 72,625.00	\$ 10,893.75	\$ 83,518.75			
1329	Nimitz Middle School	Middle Schools	Replace (5) hydronic pump(s) 5-15HP.	Mechanical	HVAC	2	\$ 75,000.00	\$ 11,250.00	\$ 86,250.00			
1332	Nimitz Middle School	Middle Schools	Replace (3) packaged roof top air conditioning units. Units are 5-7.5 ton with gas heat.	Mechanical	HVAC	2	\$ 60,000.00	\$ 9,000.00	\$ 69,000.00			
1337	Nimitz Middle School	Middle Schools	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 722,075.00	\$ 108,311.25	\$ 830,386.25			
1339	Nimitz Middle School	Middle Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 567,550.95	\$ 85,132.64	\$ 652,683.59			

1343	Nimitz Middle School	Middle Schools	ADA parking in east parking lot meets TAS requirements. ADA parking in east parking lot near football field meets TAS requirement, but signs are too short. The sign to the north is also labeled as van accessible but the parking space does not meet the van accessible requirements. Ramp into temporary building too steep. Inappropriate ramp into building on southwest and west sides of building. One of the doors on the west side is not ADA accessible. Crosswalk on north side does not have a curb ramp. Ramp to main entrance on north side of building covered in leaves and debris from trees making it inaccessible. Bricks at top of ramp create a lip greater than 1/4" at the top of ramp also making it inaccessible.	Fire & Life Safety	Ramps	2	\$ 54,150.00	\$ 8,122.50	\$ 62,272.50			
1366	Noel Elementary School	Elementary Schools	Replace existing metal roof system per District standards.	Building Envelope	Roof Replacement	2	\$ 103,066.84	\$ 15,460.03	\$ 118,526.87			
1385	Noel Elementary School	Elementary Schools	Replace lined duct campus-wide.	Mechanical	HVAC	2	\$ 450,000.00	\$ 67,500.00	\$ 517,500.00			
1388	Noel Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1390	Noel Elementary School	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 686,420.00	\$ 102,963.00	\$ 789,383.00			
1393	Noel Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
1394	Noel Elementary School	Elementary Schools	No ADA parking in north parking lot. Most crosswalks do not have curb ramps. Curb ramp for crosswalk at southeast corner of south parking lot is too steep. ADA parking in south parking lot labeled as van accessible but does not meet size requirements. Most temporary buildings do not have ramps for accessibility; the ones that do are too steep.	Fire & Life Safety	Ramps	2	\$ 98,250.00	\$ 14,737.50	\$ 112,987.50			
1405	Odessa High School	High Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 60,113.00	\$ 9,016.95	\$ 69,129.95			
1432	Odessa High School	High Schools	Main building - Replace (59) packaged roof top air conditioning units. Units are 3 - 4 - 8 ton with gas heat.	Mechanical	HVAC	2	\$ 885,000.00	\$ 132,750.00	\$ 1,017,750.00			
1529	Pease Elementary School	Elementary Schools	Replace all lined duct campus-wide (56 RTU's).	Mechanical	HVAC	2	\$ 470,000.00	\$ 70,500.00	\$ 540,500.00			
1531	Pease Elementary School	Elementary Schools	Replace (3) secondary electrical distribution panels, (2) 100-amp and (1) 200-amp panel.	Electrical	Electrical Distribution	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
1534	Pease Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1536	Pease Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 285,000.00	\$ 42,750.00	\$ 327,750.00			
1539	Pease Elementary School	Elementary Schools	Sidewalk at southwest corner of room 9 is too steep for a walking path. Crosswalks do not have curb ramps. Curb ramp to main entrance on south side of building does not meet standards.	Fire & Life Safety	Ramps	2	\$ 18,500.00	\$ 2,775.00	\$ 21,275.00			
1550	Permian High School	High Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 60,113.00	\$ 9,016.95	\$ 69,129.95			
1576	Permian High School	High Schools	Replace lined duct campus-wide.	Mechanical	HVAC	2	\$ 3,500,000.00	\$ 525,000.00	\$ 4,025,000.00			
1577	Permian High School	High Schools	Replace (15) kva GE transformer in choir wing.	Electrical	Electrical Distribution	2	\$ 10,000.00	\$ 1,500.00	\$ 11,500.00			
1579	Permian High School	High Schools	Replace (2) 200-amp Powell electric panels in B53.	Electrical	Electrical Distribution	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
1581	Permian High School	High Schools	Replace (37.5) kva Federal Pacific Transformer.	Electrical	Electrical Distribution	2	\$ 35,000.00	\$ 5,250.00	\$ 40,250.00			
1582	Permian High School	High Schools	Replace (45) kva Federal Pacific Transformer.	Electrical	Electrical Distribution	2	\$ 35,000.00	\$ 5,250.00	\$ 40,250.00			
1583	Permian High School	High Schools	Replace (5) Powell Electrical distribution panels (1) 200-amp and (4) 100-amp.	Electrical	Electrical Distribution	2	\$ 75,000.00	\$ 11,250.00	\$ 86,250.00			

1588	Permian High School	High Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 2,088,453.09	\$ 313,267.96	\$ 2,401,721.05			
1593	Permian High School	High Schools	Baseball: Replace press box stairs with ADA complaint stairs.	Fire & Life Safety	Renovation	2	\$ 20,000.00	\$ 3,000.00	\$ 23,000.00			
1594	Permian High School	High Schools	Provide campus wayfinding for exterior; visitor parking, athletics, student parking, etc.	Fire & Life Safety	Signage/Way-finding	2	\$ 5,000.00	\$ 750.00	\$ 5,750.00			
1714	Reagan Magnet Elementary School	Elementary Schools	Replace existing exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	Building Envelope	Waterproofing Sealant	2	\$ 30,623.00	\$ 4,593.45	\$ 35,216.45			
1729	Reagan Magnet Elementary School	Elementary Schools	Replace (48) packaged roof top air conditioning units. Units are 3-5 ton with gas heat.	Mechanical	HVAC	2	\$ 720,000.00	\$ 108,000.00	\$ 828,000.00			
1731	Reagan Magnet Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1733	Reagan Magnet Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 250,000.00	\$ 37,500.00	\$ 287,500.00			
1736	Reagan Magnet Elementary School	Elementary Schools	No accessible route to stage. Add accessible ramp route to stage.	Fire & Life Safety	Ramps	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
1737	Reagan Magnet Elementary School	Elementary Schools	ADA parking in south parking lot meets TAS size standards. West sign does not meet height requirements and needs to be raised. ADA parking in west parking lot meets TAS standards. Some temporary buildings do not have access ramps, just stairs. Crosswalks do not have curb ramps for ADA access to sidewalk.	Fire & Life Safety	Ramps	2	\$ 76,250.00	\$ 11,437.50	\$ 87,687.50			
1766	Ross Elementary School	Elementary Schools	Replace lined duct campus-wide.	Mechanical	HVAC	2	\$ 400,000.00	\$ 60,000.00	\$ 460,000.00			
1770	Ross Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1772	Ross Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 240,000.00	\$ 36,000.00	\$ 276,000.00			
1775	Ross Elementary School	Elementary Schools	No accessible route to stage. Add accessible route to stage.	Fire & Life Safety	Ramps	2	\$ 15,000.00	\$ 2,250.00	\$ 17,250.00			
1776	Ross Elementary School	Elementary Schools	Curb ramp on sidewalk in south of parking lot is too steep and has a cross slope greater than 2.0%. Crosswalks have no curb ramp or inappropriate curb ramps. Potholes in crosswalk create a grade change greater than 1/4". Northern most ADA parking spot does not have an adequate aisle. Neither of the ADA parking spaces has a sign. Ramp into temporary building is too steep.	Fire & Life Safety	Ramps	2	\$ 25,500.00	\$ 3,825.00	\$ 29,325.00			
1804	Sam Houston Elementary School	Elementary Schools	Replace (59) packaged roof top air conditioning units. Units are 3 ton with gas heat.	Mechanical	HVAC	2	\$ 885,000.00	\$ 132,750.00	\$ 1,017,750.00			
1805	Sam Houston Elementary School	Elementary Schools	Re-route rusting 4" conduits on roof to underground.	Electrical	Electrical Distribution	2	\$ 150,000.00	\$ 22,500.00	\$ 172,500.00			
1807	Sam Houston Elementary School	Elementary Schools	Replace drinking fountains to be ADA accessible.	Plumbing	Electric Drinking Fountains	2	\$ 53,688.00	\$ 8,053.20	\$ 61,741.20			
1808	Sam Houston Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1810	Sam Houston Elementary School	Elementary Schools	Replace above ground sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item does not include any under-slab plumbing including tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring. Above slab only.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 275,000.00	\$ 41,250.00	\$ 316,250.00			

1814	Sam Houston Elementary School	Elementary Schools	Crosswalks do not have curb ramps. Concrete area west of A wing too steep for ramp and leads to grass area. No accessible exit from outside of multi purpose room. Sidewalk landing at southwest corner of multi purpose room does not meet slope requirements.	Fire & Life Safety	Ramps	2	\$ 55,680.50	\$ 8,352.08	\$ 64,032.58			
1823	San Jacinto Elementary School	Elementary Schools	Replace existing metal roof system per District standards (gym).	Building Envelope	Roof Replacement	2	\$ 169,243.75	\$ 25,386.56	\$ 194,630.31			
1841	San Jacinto Elementary School	Elementary Schools	Replace all lined duct campus-wide.	Mechanical	HVAC	2	\$ 400,000.00	\$ 60,000.00	\$ 460,000.00			
1846	San Jacinto Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1848	San Jacinto Elementary School	Elementary Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 624,420.00	\$ 93,663.00	\$ 718,083.00			
1853	San Jacinto Elementary School	Elementary Schools	No ADA parking in north parking lot. ADA parking in south parking lot: curb ramp has a cross slope greater than 2.0%; vegetation growth in sidewalk joints makes path inaccessible. Curb ramp on south side of building is too steep. Not all crosswalks have curb ramps. Curb ramp to entrance on east side of D hall is too steep. Ramp to entrance at northwest corner of building is too steep. Bottom landing for ramp at entrance at southwest corner of building is too steep. Bottom landing for temporary building on west side of basketball courts is too steep; west ramp is too steep. Ramp for temporary building west of B wing is too steep.	Fire & Life Safety	Ramps	2	\$ 63,250.00	\$ 9,487.50	\$ 72,737.50			
1871	Special Education	Support Facilities	Provide interior graphics for way-finding.	Fire & Life Safety	Signage/Way-finding	2	\$ 3,892.00	\$ 583.80	\$ 4,475.80			
1906	Transportation	Support Facilities	Replace (6) RTUs and (10) evap coolers (100T cooling total).	Mechanical	HVAC	2	\$ 150,000.00	\$ 22,500.00	\$ 172,500.00			
1907	Transportation	Support Facilities	Replace main electrical distribution panels (outside).	Electrical	Electrical Gear	2	\$ 45,000.00	\$ 6,750.00	\$ 51,750.00			
1908	Transportation	Support Facilities	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 95,710.00	\$ 14,356.50	\$ 110,066.50			
1937	Travis Magnet Elementary School	Elementary Schools	Replace (4) packaged roof top air conditioning units. Units are 3-5 ton with gas heat.	Mechanical	HVAC	2	\$ 60,000.00	\$ 9,000.00	\$ 69,000.00			
1938	Travis Magnet Elementary School	Elementary Schools	Replace (39) packaged roof top air conditioning units. Units are 3-5 ton with gas heat.	Mechanical	HVAC	2	\$ 600,000.00	\$ 90,000.00	\$ 690,000.00			
1941	Travis Magnet Elementary School	Elementary Schools	Drinking fountains outside of classroom 119 and 130 are not TAS accessible. Recommend replacement with TAS compliant EDFs	Plumbing	Electric Drinking Fountains	2	\$ 13,422.00	\$ 2,013.30	\$ 15,435.30			
1942	Travis Magnet Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
1947	Travis Magnet Elementary School	Elementary Schools	Ramp exiting west side of building near room L-5 is too steep. Some temporary buildings do not have access ramps. Crosswalks do not have curb ramps. Signs for ADA parking in east parking lot is too low; north parking stall in east parking lot is not size appropriately to be van accessible. ADA parking in south parking lot: curb ramp cross slopes are greater than 2.0% and signs are too short. ADA parking in north parking lot to the west: sign is too short and needs to be replaced.	Fire & Life Safety	Ramps	2	\$ 62,000.00	\$ 9,300.00	\$ 71,300.00			
1967	West Elementary School	Elementary Schools	Curb ramps near southeast corner of east parking lot are too steep as well as some stretches of sidewalk. Gaps and unlevel detectable warning surface pavers in curb ramps create grade changes greater than 1/4" . Landing at top of curb ramp for ADA parking in east parking lot is too steep. Curb ramp near main entrance to building is too steep. Some brick pavers at main entrance are not level or have gaps greater which with settlement could create grade changes than 1/4". Crosswalks do not have curb ramps. Curb ramp on south side of playground is too steep. Railing for ramp west of loading dock does not meet standards. Ramp to the east of loading dock is too steep and cross slope is greater than 2.0%. Sidewalk leading south to pond is too steep for a walking path.	Fire & Life Safety	Ramps	2	\$ 27,250.00	\$ 4,087.50	\$ 31,337.50			

2044	Wilson & Young Middle School	Middle Schools	Replace lined duct campus-wide.	Mechanical	HVAC	2	\$ 900,000.00	\$ 135,000.00	\$ 1,035,000.00			
2048	Wilson & Young Middle School	Middle Schools	Replace domestic water distribution system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, valves, insulation. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Domestic Water	2	\$ 686,960.00	\$ 103,044.00	\$ 790,004.00			
2051	Wilson & Young Middle School	Middle Schools	Replace sanitary waste and vent system throughout campus. Item includes demolition and disposal of existing piping, hangers, insulation, and installing a new piping system, including new hangers, etc. Item also includes any under slab tunneling as required. Item does not include removal and replacement of ceilings, walls or flooring.	Plumbing	Plumbing - Sanitary Sewer	2	\$ 1,373,920.00	\$ 206,088.00	\$ 1,580,008.00			
2055	Wilson & Young Middle School	Middle Schools	Ramp at building exit on northeast side does not meet standard. ADA parking in west parking lot on north side is big enough to be labeled as van accessible. Existing sign for this parking space is too short. ADA parking in west parking lot of the south side has significant sediment build up that could effect the accessibility of the space; parking stall to the east incorrectly labeled as van accessible; no appropriate accessible route from the aisle; incorrect ramp placement in parking stall and ramp is too steep. Both curb ramps at entrance to southwest parking lot have a cross slope greater than 2.0%. Ramp in to building in southwest parking lot is too steep. Most crosswalks do not have curb ramps. ADA parking in south parking lot does not have a crosswalk leading to accessible path. Existing crosswalks in south parking lot do not have a curb ramp. Ramp leading into building at southeast corner is too steep.	Fire & Life Safety	Ramps	2	\$ 43,750.00	\$ 6,562.50	\$ 50,312.50			
2095	Zavala Magnet Elementary School	Elementary Schools	Replace (3) packaged roof top air conditioning units. Units are 2-4 ton with gas heat.	Mechanical	HVAC	2	\$ 36,000.00	\$ 5,400.00	\$ 41,400.00			
2096	Zavala Magnet Elementary School	Elementary Schools	Replace (4) packaged roof top air conditioning units. Units are 4-5 ton with gas heat.	Mechanical	HVAC	2	\$ 90,000.00	\$ 13,500.00	\$ 103,500.00			
2097	Zavala Magnet Elementary School	Elementary Schools	Replace (56) packaged roof top air conditioning units. Units are 3-5 ton with gas heat.	Mechanical	HVAC	2	\$ 850,000.00	\$ 127,500.00	\$ 977,500.00			
2101	Zavala Magnet Elementary School	Elementary Schools	Replace domestic water valves. Item does not include removal and replacement of ceilings, walls or flooring. Add valves only.	Plumbing	Plumbing - Domestic Water	2	\$ 13,910.00	\$ 2,086.50	\$ 15,996.50			
2106	Zavala Magnet Elementary School	Elementary Schools	Curb ramp for ADA parking in northeast parking lot is too steep. Sidewalk into main entrance from ADA parking is too steep for a walking path. Most crosswalks do not have curb ramps. Ramp into northeast corner of building is too steep. Curb ramp at northwest corner of east parking lot is not accessible because of sediment. Curb ramp for ADA parking in east parking lot is too steep; spot is not van accessible because the aisle is not on the passenger side. Sidewalk exiting southwest corner of building is too steep for a walking path. Ramp exiting south of building near rooms 309 and 305 is too steep. Cross slope of ramp into building RC-57 is greater than 2.0%.	Fire & Life Safety	Ramps	2	\$ 16,000.00	\$ 2,400.00	\$ 18,400.00			