181 US Hwy 46
Mine Hill, NJ 07803
(908) 654-8068
(800) 783-0567
Fax 908-654-8069

LEAD IN DRINKING WATER REPORT

Performed At:
Hunterdon Central Regional High School
84 Route 31, Flemington, NJ, 08822

Performed For:
Hunterdon Central Regional High School
84 Route 31, Flemington, NJ, 08822

Prepared By:
LEW Environmental Services, LLC.
181 US Hwy 46
Mine Hill, NJ 07803

Phone (908) 654-8068
Fax (908) 654-8069
Website http://www.LEWCorp.com

Inspection Date: 04/18/2025
Project Number: 2319

Contact Information

Education Agency

Client Contact:	Matthew O'Brien
Client Name:	Hunterdon Central Regional High School
Street Address	84 Route 313, Flemington, NJ, 08822
Phone Number:	(908) 284-7170

Sampler(s)

Site Assessor(s):	Cynthia DiMeo
Signature:	
Date:	April 18, 2025

Firm

Organization:	LEW Environmental Services, LLC.
Certification #:	NJDCA 00015 E
Street:	181 US Hwy 46
City, State & Zip:	Mine Hill, NJ 07803
Phone Number:	908-654-8068
Web Address:	http://www.lewcorp.com

Laboratory

Organization:	Environmental Hazard Services, LLC
Street:	7469 Whitepine Road
City, State & Zip:	Richmond, VA 23237
NJDEP Certification #	VA008
Phone Number:	800-347-4010

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
HCRHS Lower	4/18/2025	4/30/2025	1-HSLC-WF	WF BY CAFE LEFT	<1.00
HCRHS Lower	4/18/2025	4/30/2025	2-HSLC-WF	WF BY CAFE RIGHT	<1.00
HCRHS Lower	4/18/2025	4/30/2025	3-HSLC-BF	BF BY CAFE	<1.00
HCRHS Lower	4/18/2025	4/30/2025	4-HSLC-S	WORK ROOM SINK	<1.00
HCRHS Lower	4/18/2025	4/30/2025	8-HSLC-WF	WF BY RM 518	<1.00
HCRHS Lower	4/18/2025	4/30/2025	9-HSLC-BF	BF BY RM 518	<1.00
HCRHS Lower	4/18/2025	4/30/2025	9A-HSLC-S	SINK IN CHORAL RM	<1.00
HCRHS Lower	4/18/2025	4/30/2025	10-HSLC-WF	WF BY RM 612	<1.00
HCRHS Lower	4/18/2025	4/30/2025	10A-HSLC-BF	BF BY RM 612	<1.00
HCRHS Lower	4/18/2025	4/30/2025	11-HSLC-WF	WF BY RM 646	<1.00
HCRHS Lower	4/18/2025	4/30/2025	12-HSLC-S	SINK IN RM 650	1.61
HCRHS Lower	4/18/2025	4/30/2025	13-HSLC-WF	WF BY RM 652	<1.00
HCRHS Lower	4/18/2025	4/30/2025	13A-HSLC-BF	BF BY RM 652	<1.00
HCRHS Lower	4/18/2025	4/30/2025	14-HSLC-S	S BY BATHROOM IN RM 657	<1.00
HCRHS Lower	4/18/2025	4/30/2025	15-HSLC-S	S BY WINDOW IN RM 657	<1.00
HCRHS Lower	4/18/2025	4/30/2025	16-HSLC-WF	WF BY SS OFFICE	<1.00
HCRHS Lower	4/18/2025	4/30/2025	16A-HSLC-BF	BF BY SS OFFICE	<1.00
HCRHS Lower	4/18/2025	4/30/2025	17-HSLC-S	SINK IN RM 714	<1.00
HCRHS Lower	4/18/2025	4/30/2025	18-HSLC-S	SINK 1 IN RM 716	<1.00
HCRHS Lower	4/18/2025	4/30/2025	19-HSLC-S	SINK 2 IN RM 716	<1.00
HCRHS Lower	4/18/2025	4/30/2025	20-HSLC-S	SINK 3 IN RM 716	<1.00
HCRHS Lower	4/18/2025	4/30/2025	21-HSLC-S	SINK 4 IN RM 716	1.02
HCRHS Lower	4/18/2025	4/30/2025	23-HSLC-S	SINK 6 IN RM 716	<1.00
HCRHS Lower	4/18/2025	4/30/2025	24-HSLC-WF	WF BY RM 810 LEFT	<1.00
HCRHS Lower	4/18/2025	4/30/2025	25-HSLC-WF	WF BY RM 810 RIGHT	<1.00
HCRHS Lower	4/18/2025	4/30/2025	26-HSLC-BF	BF BY RM 810	<1.00
HCRHS Lower	4/18/2025	4/30/2025	27-HSLC-WF	WF BY RM 821 L	<1.00
HCRHS Lower	4/18/2025	4/30/2025	28-HSLC-BF	WF BY RM 821 R	<1.00
HCRHS Lower	4/18/2025	4/30/2025	29-HSLC-S	SINK IN RM 825	1.78
HCRHS Lower	4/18/2025	4/30/2025	30-HSLC-WF	WF BY COMMONS L	<1.00
HCRHS Lower	4/18/2025	4/30/2025	31-HSLC-WF	WATER FOUNTAIN BY COMMONS R	<1.00
HCRHS Lower	4/18/2025	4/30/2025	32-HSLC-BF	BF BY COMMONS	<1.00
HCRHS Lower	4/18/2025	4/30/2025	33-HSLC-S	SINK 1 IN KITCHEN	1.51
HCRHS Lower	4/18/2025	4/30/2025	34-HSLC-S	SINK 2 IN KITCHEN	1.32
HCRHS Lower	4/18/2025	4/30/2025	35-HSLC-S	SINK 3 IN KITCHEN	1.09
HCRHS Lower	4/18/2025	4/30/2025	36-HSLC-S	SINK 4 IN KITCHEN	<1.00
HCRHS Lower	4/18/2025	4/30/2025	37-HSLC-S	SINK 5 IN KITCHEN	<1.00
HCRHS Lower	4/18/2025	4/30/2025	38-HSLC-S	SINK 6 IN KITCHEN	14
HCRHS Lower	4/18/2025	4/30/2025	39-HSLC-S	SINK 7 IN KITCHEN	<1.00
HCRHS Lower	4/18/2025	4/30/2025	40-HSCL-S	SINK 8 IN KITCHEN	1.35
HCRHS Lower	4/18/2025	4/30/2025	41-HSLC-IM	ICE MACHING IN KITCHEN	<1.00
HCRHS Lower	4/18/2025	4/30/2025	42-HSLC-WF	WF BY STORE L	2.33
HCRHS Lower	4/18/2025	4/30/2025	43-HSLC-WF	WF BY STORE R	2.48
HCRHS Lower	4/18/2025	4/30/2025	44-HSLC-WF	WF BY GIRLS LOCKER RM	42
HCRHS Lower	4/18/2025	4/30/2025	45-HSLC-WF	WF IN FOYER OF GIRLS LOCKER RM	<1.00
HCRHS Lower	4/18/2025	4/30/2025	45A-HSLC-BF	BF IN FOYER OF GIRLS LOCKER RM	<1.00
HCRHS Lower	4/18/2025	4/30/2025	46-HSLC-WF	WRESTLING RM WF	<1.00
HCRHS Lower	4/18/2025	4/30/2025	47-HSLC-WF	WF IN BOYS LOCKER RM FOYER	<1.00
HCRHS Lower	4/18/2025	4/30/2025	47A-HSLC-BF	BF IN BOYS LOCKER RM FOYER	<1.00
HCRHS Lower	4/18/2025	4/30/2025	48-HSLC-WF	WF IN BOYS LOCKER RM	5.93
HCRHS Lower	4/18/2025	4/30/2025	49-HSLC-S	SINK IN RM 900	6.3
HCRHS Lower	4/18/2025	4/30/2025	50-HSLC-S	SINK IN RM 904	1.99
HCRHS Lower	4/18/2025	4/30/2025	51-HSLC-WF	WF BY RM 910	<1.00
HCRHS Lower	4/18/2025	4/30/2025	52-HSLC-BF	BF BY RM 910	<1.00
HCRHS Lower	4/18/2025	4/30/2025	53-HSLC-S	SINK IN RM 914	2.66
HCRHS Lower	4/18/2025	4/30/2025	54-HSLC-WF	WF BY RM 919	<1.00
HCRHS Lower	4/18/2025	4/30/2025	55-HSLC-BF	BF BY RM 919	<1.00
HCRHS Lower	4/18/2025	4/30/2025	56-HSLC-S	SINK IN RM 923	<1.00
HCRHS Lower	4/18/2025	4/30/2025	57-HSLC-S	SINK IN RM 648	<1.00
HCRHS Lower	4/18/2025	4/30/2025	58-HSLC-BF	BF IN HALL NEAR TRAINER	<1.00
HCRHS Lower	4/18/2025	4/30/2025	59-HSLC-WF	WF IN HALL NEAR TRAINER	<1.00
HCRHS Lower	4/18/2025	4/30/2025	60-HSLC-S	SINK IN RM 910	2.89
HCRHS Lower	4/18/2025	4/30/2025	61-HSLC-IM	ICE MACHINE IN TRAINER RM	<1.00
HCRHS Lower	4/18/2025	4/30/2025	62-HSLC-WF	WF IN TEACHER ROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
HCRHS Trans & Business Office	4/18/2025	4/28/2025	1-HCRHSBO-S	KITCHEN	<1.00
HCRHS Trans & Business Office	4/18/2025	4/28/2025	2-HCRHSTO-S	OLD BREAK ROOM	<1.00
HCRHS Trans & Business Office	4/18/2025	4/28/2025	3-HCRHSTO-S	NEW BREAK ROOM	<1.00
HCRHS Trans & Business Office	4/18/2025	4/28/2025	4-HCRHSTO-WF	NEW BREAK ROOM	<1.00
HCRHS Trans & Business Office	4/18/2025	4/28/2025	5-HCRHSTO-BF	NEW BREAK ROOM	<1.00
HCRHS Trans & Business Office	4/18/2025	4/28/2025	6-HCRHSTO-WF	TEACHER ROOM	<1.00

Building	DateCollected	AnalysisDate	Sample ID	Sample Description	Concentration (ppb)
HCRHS Upper	4/18/2025	4/29/2025	1-HSUC-WF	WF BY ROOM 200	2.3
HCRHS Upper	4/18/2025	4/29/2025	2-HSUC-S	SINK IN ROOM 207 L	1.57
HCRHS Upper	4/18/2025	4/29/2025	3-HSUC-S	SINK IN ROOM 207 R	1.39
HCRHS Upper	4/18/2025	4/29/2025	4-HSUC-S	BREAK ROOM SINK	<1.00
HCRHS Upper	4/18/2025	4/29/2025	5-HSUC-WF	WF BY ROOM 206	<1.00
HCRHS Upper	4/18/2025	4/29/2025	5A-HSUC-BF	BF BY ROOM 206	<1.00
HCRHS Upper	4/18/2025	4/29/2025	6-HSUC-WF	WF BY HOUSE OFFICE	<1.00
HCRHS Upper	4/18/2025	4/29/2025	7-HSUC-S	OFFICE BREAK ROOM SINK	<1.00
HCRHS Upper	4/18/2025	4/29/2025	8-HSUC-WF	HALL LOBBY WF	<1.00
HCRHS Upper	4/18/2025	4/29/2025	9-HSUC-BF	HALL LOBBY BF	<1.00
HCRHS Upper	4/18/2025	4/29/2025	10-HSUC-WF	WF BY ROOM 304	<1.00
HCRHS Upper	4/18/2025	4/29/2025	11-HSUC-BF	BF BY ROOM 304	<1.00
HCRHS Upper	4/18/2025	4/29/2025	12-HSUC-WF	WF BY ROOM 116	<1.00
HCRHS Upper	4/18/2025	4/29/2025	12A-HSUC-BF	BF BY ROOM 116	<1.00
HCRHS Upper	4/18/2025	4/29/2025	13-HSUC-S	SINK IN ROOM 115	2.02
HCRHS Upper	4/18/2025	4/29/2025	14-HSUC-WF	WF BY ROOM 106	1.51
HCRHS Upper	4/18/2025	4/29/2025	15-HSUC-S	SINK 1 IN ROOM 103	2.94
HCRHS Upper	4/18/2025	4/29/2025	16-HSUC-S	SINK 2 IN ROOM 103	2.18
HCRHS Upper	4/18/2025	4/29/2025	17-HSUC-S	SINK 3 IN ROOM 103	2.99
HCRHS Upper	4/18/2025	4/29/2025	18-HSUC-S	SINK 4 IN ROOM 103	3.52
HCRHS Upper	4/18/2025	4/29/2025	19-HSUC-S	SINK 5 IN ROOM 103	4.44
HCRHS Upper	4/18/2025	4/29/2025	20-HSUC-S	SINK IN ROOM 104	1.56
HCRHS Upper	4/18/2025	4/29/2025	21-HSUC-WF	WF IN HALL NEAR GYM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	21A-HSUC-BF	BF IN HALL NEAR GYM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	22-HSUC-WF	WF IN HALL NEAR LOWER BOILER RM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	23-HSUC-BF	BY BY ROOM 157	<1.00
HCRHS Upper	4/18/2025	4/29/2025	24-HSUC-WS	COOLER FILL STATION IN TRAINER ROOM	1.25
HCRHS Upper	4/18/2025	4/29/2025	25-HSUC-IM	ICE MACHINE IN TRAINER ROOM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	25A-HSUC-WF	WF IN TEAM ROOM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	26-HSUC-WF	WF BY ROOM 157	<1.00
HCRHS Upper	4/18/2025	4/29/2025	27-HSUC-BF	BF BY ROOM 157	<1.00
HCRHS Upper	4/18/2025	4/29/2025	28-HSUC-WF	WF IN GIRLS LOCKER RM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	29-HSUC-WF	WF IN BOYS LOCKER RM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	30-HSUC-WF	WF IN BOYS LOCKER RM	<1.00
HCRHS Upper	4/18/2025	4/29/2025	31-HSUC-WF	WF BY CAFE 172	<1.00
HCRHS Upper	4/18/2025	4/29/2025	32-HSUC-S	KITCHEN SINK 1	<1.00
HCRHS Upper	4/18/2025	4/29/2025	33-HSUC-IM	KITCHEN ICE MACHINE	<1.00
HCRHS Upper	4/18/2025	4/29/2025	34-HSUC-S	KITCHEN SINK 2	<1.00
HCRHS Upper	4/18/2025	4/29/2025	35-HSUC-S	KITCHEN SINK 3	<1.00
HCRHS Upper	4/18/2025	4/29/2025	36-HSUC-S	KITCHEN SINK 4	<1.00
HCRHS Upper	4/18/2025	4/29/2025	37-HSUC-S	KITCHEN SINK 5	1.73
HCRHS Upper	4/18/2025	4/29/2025	38-HSUC-S	KITCHEN SINK 6	<1.00
HCRHS Upper	4/18/2025	4/29/2025	39-HSUC-S	KITCHEN SINK 7	<1.00
HCRHS Upper	4/18/2025	4/29/2025	40-HSUC-S	KITCHEN SINK 8	7.2
HCRHS Upper	4/18/2025	4/29/2025	41-HSUC-WF	WATER FOUNTAIN BY CAFE 174	<1.00
HCRHS Upper	4/18/2025	4/29/2025	42-HSUC-WF	WF BY CAFE 173	<1.00
HCRHS Upper	4/18/2025	4/29/2025	43-HSUC-S	SINK IN CAFE 173	<1.00
HCRHS Upper	4/18/2025	4/29/2025	44-HSUC-BF	BF BY RM 128	<1.00
HCRHS Upper	4/18/2025	4/29/2025	44A-HSUC-WF	WF BY RM 128	<1.00
HCRHS Upper	4/18/2025	4/29/2025	45-HSUC-WF	WF BY RM 137	<1.00
HCRHS Upper	4/18/2025	4/29/2025	46-HSUC-WF	WF BY ROOM 150	<1.00
HCRHS Upper	4/18/2025	4/29/2025	47-HSUC-WF	TEACHER ROOM WF	<1.00