Lead in School Drinking Water Report

Fryelands Elementary School - Post-remediation

Date(s) collected: 2023-09-30
Date(s) analyzed: 2023-10-23

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
374090	Main Building	Sink	Room 05	Only sink	Tap	124
374088	Main Building	Fountain - Multi-Level	Hallway	Across from room 05. Lower fountain	Water Fountain	<1
374089	Main Building	Fountain - Multi-Level	Hallway	Across from room 05	Water Fountain	<1
374091	Main Building	Sink	Room 21	Only sink	Tap	<1

EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: **leadfreekids@doh.wa.gov**