

Results

First draw samples were collected from 40 fixtures and delivered under chain of custody to Apex Laboratories in Tigard, Oregon, for lead analysis using EPA Method 200.8 ICPMS. Samples above the action level of 15 ppb are shown in bold. The following table lists the results of the analysis.

Table 1: Grant High School - Sample Results

Fixture Number	Sample Number	Location / Room No.	Results (ppb)
001	DF-5600	Hallway (Classroom 077)	ND
002	DF-5601	Hallway (Dance Studio 041)	ND
003	DF-5602	Hallway (Dance Studio 041)	ND
004	DF-5603	Hallway (Health Classroom 027)	ND
005	DF-5604	Hallway (Gym North)	ND
006	DF-5605	Hallway (Gym South)	ND
007	DF-5608	Hallway (Classroom 177)	ND
008	DF-5617	Hallway (Classroom 125)	ND
009	DF-5622	Hallway (Gymnasiums), South	ND
010	DF-5623	Hallway (A100)	ND
011	DF-5624	Hallway (Classroom 277)	ND
012	DF-5625	Hallway (Classroom 227)	ND
013	DF-5627	Hallway (Daycare A009)	ND
014	DF-6227	Daycare, Kitchen (Marked as DF-6277 on COC)	1.52
015	DF-6228	Crawler A001H	0.673
016	DF-6229	Infant A001J	0.574
017	DF-6230	Toddler A001K	ND
018	DF-6231	Break room A003L	ND
019	DF-6232	Commons lower level 051, INSTA-HOT	ND
020	DF-6233	Training 026	0.537
021	DF-6234	Student Store	0.753
022	DF-6235	Student Store, INSTA-HOT	ND
023	DF-6238	Hallway (Small Instruction 196)	0.599
024	DF-6239	ISC Classroom 191	0.587
025	DF-6240	Break Room 193	0.348
026	DF-6241	Medicaly Fragile 195	1.02
027	DF-6242	Work Room 120P	1.85
028	DF-6243	Hallway (Text Storage 132)	0.742
029	DF-6244	Break Room 132	ND
030	DF-6245	Work Room 101M	0.408
031	DF-6246	Work Room 120P	ND
032	DF-6247	Concessions (Gymnasiums)	0.537

Fixture Number	Sample Number	Location / Room No.	Results (ppb)
033	DF-6248	Culinary arts A101	ND
034	DF-6249	Hallway (A200)	ND
035	DF-6251	Teacher's Office 290	0.202
036	DF-6252	Teacher's Office 240 (Marked as DF-5652 on COC)	ND
037	DF-6253	Teacher's Office 210	ND
038	DF-6254	Commons Main Level 151	ND
039	DF-6255	Outside (Pool House)	ND
040	DF-6256	Outside (Baseball Diamond)	ND

ND = no lead detected

Lead action level: 15 ppb

Elevated concentrations of lead were not found in any fixture. PBS is available to assist with further investigation and corrective actions upon request.