

Portland Public Schools
Lead and Copper Water Sampling Results
A (Initial) and B (Follow-Up) Sample Data
Ainsworth Elementary School

Sample Identification # and Location	Date/Time Collected	Date/Time Analyzed	Container ID	Analyte	Results	PPS Action Level*	Units
132-3542-A-001A Hallway near Boiler	08/02/18 8:15 AM	08/06/18 8:17 PM	18017334	Copper	<0.1	1.3	ppm
132-3542-A-001A Hallway near Boiler	08/02/18 8:15 AM	08/06/18 8:17 PM	18017334	Lead	6	15	ppb
132-3542-A-001B Hallway near Boiler	08/02/18 8:15 AM	08/06/18 8:18 PM	18017335	Copper	<0.1	1.3	ppm
132-3542-A-001B Hallway near Boiler	08/02/18 8:15 AM	08/06/18 8:18 PM	18017335	Lead	1	15	ppb
132-3539-A-001A Hallway near Lost & Found	08/02/18 8:17 AM	08/06/18 8:51 PM	18017332	Copper	<0.1	1.3	ppm
132-3539-A-001A Hallway near Lost & Found	08/02/18 8:17 AM	08/06/18 8:51 PM	18017332	Lead	6	15	ppb
132-3539-A-001B Hallway near Lost & Found	08/02/18 8:17 AM	08/06/18 8:20 PM	18017333	Copper	<0.1	1.3	ppm
132-3539-A-001B Hallway near Lost & Found	08/02/18 8:17 AM	08/06/18 8:20 PM	18017333	Lead	<1	15	ppb
132-3560-A-001A Kitchen	08/02/18 8:21 AM	08/06/18 8:22 PM	18017337	Copper	0.3	1.3	ppm
132-3560-A-001A Kitchen	08/02/18 8:21 AM	08/06/18 8:22 PM	18017337	Lead	1	15	ppb
132-3560-A-001B Kitchen	08/02/18 8:21 AM	08/06/18 8:24 PM	18017336	Copper	0.3	1.3	ppm
132-3560-A-001B Kitchen	08/02/18 8:21 AM	08/06/18 8:24 PM	18017336	Lead	<1	15	ppb
132-3560-B-001A Kitchen	08/02/18 8:21 AM	08/06/18 8:26 PM	18017331	Copper	0.2	1.3	ppm
132-3560-B-001A Kitchen	08/02/18 8:21 AM	08/06/18 8:26 PM	18017331	Lead	1	15	ppb
132-3560-B-001B Kitchen	08/02/18 8:21 AM	08/06/18 8:27 PM	18017330	Copper	0.3	1.3	ppm
132-3560-B-001B Kitchen	08/02/18 8:21 AM	08/06/18 8:27 PM	18017330	Lead	<1	15	ppb
132-3545-A-001A Cafeteria	08/02/18 8:28 AM	08/07/18 5:10 PM	18017338	Copper	1.2	1.3	ppm
132-3545-A-001A Cafeteria	08/02/18 8:28 AM	08/06/18 8:29 PM	18017338	Lead	5	15	ppb
132-3545-A-001B Cafeteria	08/02/18 8:28 AM	08/07/18 5:14 PM	18017339	Copper	1.7	1.3	ppm
132-3545-A-001B Cafeteria	08/02/18 8:28 AM	08/06/18 8:31 PM	18017339	Lead	3	15	ppb
132-3546-A-001A 1st Floor Rm 1 Hallway	08/02/18 8:35 AM	08/06/18 7:49 PM	18017340	Copper	<0.1	1.3	ppm
132-3546-A-001A 1st Floor Rm 1 Hallway	08/02/18 8:35 AM	08/06/18 7:49 PM	18017340	Lead	2	15	ppb
132-3546-A-001B 1st Floor Rm 1 Hallway	08/02/18 8:35 AM	08/06/18 7:51 PM	18017341	Copper	<0.1	1.3	ppm
132-3546-A-001B 1st Floor Rm 1 Hallway	08/02/18 8:35 AM	08/06/18 7:51 PM	18017341	Lead	1	15	ppb
132-3563-A-001A 1st Hallway	08/02/18 8:42 AM	08/06/18 7:53 PM	18017342	Copper	0.5	1.3	ppm
132-3563-A-001A 1st Hallway	08/02/18 8:42 AM	08/06/18 7:53 PM	18017342	Lead	1	15	ppb
132-3563-A-001B 1st Hallway	08/02/18 8:42 AM	08/06/18 7:55 PM	18017343	Copper	0.1	1.3	ppm
132-3563-A-001B 1st Hallway	08/02/18 8:42 AM	08/06/18 7:55 PM	18017343	Lead	<1	15	ppb
132-3540-A-001A 1st Hallway	08/02/18 8:45 AM	08/06/18 7:57 PM	18017344	Copper	0.5	1.3	ppm
132-3540-A-001A 1st Hallway	08/02/18 8:45 AM	08/06/18 7:57 PM	18017344	Lead	2	15	ppb
132-3540-A-001B 1st Hallway	08/02/18 8:45 AM	08/06/18 7:59 PM	18017345	Copper	0.1	1.3	ppm
132-3540-A-001B 1st Hallway	08/02/18 8:45 AM	08/06/18 7:59 PM	18017345	Lead	0	15	ppb
132-3543-A-001A 1st Hallway	08/02/18 8:50 AM	08/06/18 8:00 PM	18017346	Copper	0.5	1.3	ppm
132-3543-A-001A 1st Hallway	08/02/18 8:50 AM	08/06/18 8:00 PM	18017346	Lead	3	15	ppb
132-3543-A-001B 1st Hallway	08/02/18 8:50 AM	08/06/18 8:02 PM	18017347	Copper	0.1	1.3	ppm
132-3543-A-001B 1st Hallway	08/02/18 8:50 AM	08/06/18 8:02 PM	18017347	Lead	1	15	ppb
132-3558-A-001A 2nd Floor Rm 8 Hallway	08/02/18 8:55 AM	08/06/18 7:28 PM	18017348	Copper	<0.1	1.3	ppm
132-3558-A-001A 2nd Floor Rm 8 Hallway	08/02/18 8:55 AM	08/06/18 7:28 PM	18017348	Lead	6	15	ppb
132-3558-A-001B 2nd Floor Rm 8 Hallway	08/02/18 8:55 AM	08/06/18 7:30 PM	18017349	Copper	<0.1	1.3	ppm
132-3558-A-001B 2nd Floor Rm 8 Hallway	08/02/18 8:55 AM	08/06/18 7:30 PM	18017349	Lead	1	15	ppb
132-3552-A-001A 2nd Floor Rm 5 Hallway	08/02/18 8:57 AM	08/06/18 7:31 PM	18017350	Copper	<0.1	1.3	ppm
132-3552-A-001A 2nd Floor Rm 5 Hallway	08/02/18 8:57 AM	08/06/18 7:31 PM	18017350	Lead	7	15	ppb
132-3552-A-001B 2nd Floor Rm 5 Hallway	08/02/18 8:57 AM	08/06/18 8:04 PM	18017351	Copper	<0.1	1.3	ppm
132-3552-A-001B 2nd Floor Rm 5 Hallway	08/02/18 8:57 AM	08/06/18 8:04 PM	18017351	Lead	<1	15	ppb
132-3584-A-001A Annex Bldg	08/02/18 9:15 AM	08/06/18 7:33 PM	18017352	Copper	0.1	1.3	ppm
132-3584-A-001A Annex Bldg	08/02/18 9:15 AM	08/06/18 7:33 PM	18017352	Lead	7	15	ppb
132-3584-A-001B Annex Bldg	08/02/18 9:15 AM	08/06/18 7:35 PM	18017353	Copper	<0.1	1.3	ppm
132-3584-A-001B Annex Bldg	08/02/18 9:15 AM	08/06/18 7:35 PM	18017353	Lead	2	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.