

Portland Public Schools
Lead and Copper Water Sampling Results
A (Initial) and B (Follow-Up) Sample Data
Ainsworth Elementary School

Sample Identification # and Location	Date/Time Collected	Date/Time Analyzed	Container ID	Analyte	Results	PPS Action Level*	Units
132-3555-A-002A Room 5	09/27/18 6:29 AM	10/02/18 5:12 PM	18024360	Copper	0.6	1.3	ppm
132-3555-A-002A Room 5	09/27/18 6:29 AM	10/02/18 5:12 PM	18024360	Lead	9	15	ppb
132-3555-A-002B Room 5	09/27/18 6:30 AM	10/02/18 5:17 PM	18024367	Copper	0.7	1.3	ppm
132-3555-A-002B Room 5	09/27/18 6:30 AM	10/02/18 5:17 PM	18024367	Lead	2	15	ppb
132-3561-A-002A Room 6	09/27/18 6:37 AM	10/02/18 5:21 PM	18024363	Copper	0.9	1.3	ppm
132-3561-A-002A Room 6	09/27/18 6:37 AM	10/02/18 5:21 PM	18024363	Lead	8	15	ppb
132-3561-A-002B Room 6	09/27/18 6:38 AM	10/03/18 3:57 PM	18024369	Copper	1.0	1.3	ppm
132-3561-A-002B Room 6	09/27/18 6:38 AM	10/02/18 5:26 PM	18024369	Lead	3	15	ppb
132-3564-A-002A Room 9	09/27/18 6:45 AM	10/02/18 5:59 PM	18024362	Copper	0.3	1.3	ppm
132-3564-A-002A Room 9	09/27/18 6:45 AM	10/02/18 5:59 PM	18024362	Lead	77	15	ppb
132-3564-A-002B Room 9	09/27/18 6:46 AM	10/02/18 6:04 PM	18024371	Copper	0.5	1.3	ppm
132-3564-A-002B Room 9	09/27/18 6:46 AM	10/02/18 6:04 PM	18024371	Lead	7	15	ppb
132-3548-A-002A Lounge	09/27/18 7:01 AM	10/02/18 6:09 PM	18024365	Copper	0.3	1.3	ppm
132-3548-A-002A Lounge	09/27/18 7:01 AM	10/02/18 6:09 PM	18024365	Lead	< 1	15	ppb
132-3548-A-002B Lounge	09/27/18 7:02 AM	10/02/18 6:13 PM	18024370	Copper	0.5	1.3	ppm
132-3548-A-002B Lounge	09/27/18 7:02 AM	10/02/18 6:13 PM	18024370	Lead	< 1	15	ppb
132-3551-A-002A Office	09/27/18 7:07 AM	10/02/18 6:18 PM	18024366	Copper	0.4	1.3	ppm
132-3551-A-002A Office	09/27/18 7:07 AM	10/02/18 6:18 PM	18024366	Lead	31	15	ppb
132-3551-A-002B Office	09/27/18 7:08 AM	10/02/18 6:23 PM	18024361	Copper	0.5	1.3	ppm
132-3551-A-002B Office	09/27/18 7:08 AM	10/02/18 6:23 PM	18024361	Lead	3	15	ppb
132-3556-A-002A Room 23	09/27/18 7:42 AM	10/02/18 6:28 PM	18024373	Copper	< 0.1	1.3	ppm
132-3556-A-002A Room 23	09/27/18 7:42 AM	10/02/18 6:28 PM	18024373	Lead	23	15	ppb
132-3556-A-002B Room 23	09/27/18 7:43 AM	10/02/18 6:32 PM	18024368	Copper	< 0.1	1.3	ppm
132-3556-A-002B Room 23	09/27/18 7:43 AM	10/02/18 6:32 PM	18024368	Lead	4	15	ppb
132-3559-A-002A Room 22	09/27/18 7:47 AM	10/02/18 6:37 PM	18024364	Copper	0.1	1.3	ppm
132-3559-A-002A Room 22	09/27/18 7:47 AM	10/02/18 6:37 PM	18024364	Lead	81	15	ppb
132-3559-A-002B Room 22	09/27/18 7:48 AM	10/03/18 4:30 PM	18024372	Copper	0.4	1.3	ppm
132-3559-A-002B Room 22	09/27/18 7:48 AM	10/03/18 4:30 PM	18024372	Lead	230	15	ppb
132-3566-A-002A Room 25	09/27/18 7:58 AM	10/02/18 6:42 PM	18024375	Copper	< 0.1	1.3	ppm
132-3566-A-002A Room 25	09/27/18 7:58 AM	10/02/18 6:42 PM	18024375	Lead	15	15	ppb
132-3566-A-002B Room 25	09/27/18 7:59 AM	10/02/18 7:15 PM	18024376	Copper	< 0.1	1.3	ppm
132-3566-A-002B Room 25	09/27/18 7:59 AM	10/02/18 7:15 PM	18024376	Lead	25	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.