Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Alameda Elementary - 2nd Site Visit

Sample Identification #	Location	Date Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
230-3906-N/A-001-A	Faucet (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-01	Copper	0.270	0.00200	1.3	ppm
230-3906-N/A-001-A	Faucet (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-01	Lead	1.36	0.200	15	ppb
230-3906-N/A-001-B	Faucet (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-02	Copper	0.153	0.00200	1.3	ppm
230-3906-N/A-001-B	Faucet (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-02	Lead	0.225	0.200	15	ppb
230-3903-N/A-001-A	Sprayer (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-03	Copper	0.224	0.00200	1.3	ppm
230-3903-N/A-001-A	Sprayer (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-03	Lead	0.644	0.200	15	ppb
230-3903-N/A-001-B	Sprayer (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-04	Copper	0.224	0.00200	1.3	ppm
230-3903-N/A-001-B	Sprayer (Food Prep) - Kitchen	8/14/2018	8/24/2018	A8H0415-04	Lead	0.635	0.200	15	ppb
230-3912-N/A-001-A	Bottle Filler - Near room 131	8/14/2018	8/23/2018	A8H0415-05RE1	Copper	0.128	0.00200	1.3	ppm
230-3912-N/A-001-A	Bottle Filler - Near room 131	8/14/2018	8/22/2018	A8H0415-05	Lead	1.59	0.200	15	ppb
230-3912-N/A-001-B	Bottle Filler - Near room 131	8/14/2018	8/24/2018	A8H0415-06	Copper	0.0420	0.00200	1.3	ppm
230-3912-N/A-001-B	Bottle Filler - Near room 131	8/14/2018	8/24/2018	A8H0415-06	Lead	ND	0.200	15	ppb
230-3915-N/A-001-A	Drinking Fountain (Stainless) - Near room 131	8/14/2018	8/24/2018	A8H0415-07	Copper	0.0558	0.00200	1.3	ppm
230-3915-N/A-001-A	Drinking Fountain (Stainless) - Near room 131	8/14/2018	8/24/2018	A8H0415-07	Lead	ND	0.200	15	ppb
230-3915-N/A-001-B	Drinking Fountain (Stainless) - Near room 131	8/14/2018	8/24/2018	A8H0415-08	Copper	0.0393	0.00200	1.3	ppm
230-3915-N/A-001-B	Drinking Fountain (Stainless) - Near room 131	8/14/2018	8/24/2018	A8H0415-08	Lead	ND	0.200	15	ppb
230-3897-N/A-001-A	Drinking Fountain (Stainless) - Room 125 Cafeteria	8/14/2018	8/23/2018	A8H0415-09RE1	Copper	0.542	0.00200	1.3	ppm
230-3897-N/A-001-A	Drinking Fountain (Stainless) - Room 125 Cafeteria	8/14/2018	8/22/2018	A8H0415-09	Lead	1.85	0.200	15	ppb
230-3897-N/A-001-B	Drinking Fountain (Stainless) - Room 125 Cafeteria	8/14/2018	8/24/2018	A8H0415-10	Copper	0.130	0.00200	1.3	ppm
230-3897-N/A-001-B	Drinking Fountain (Stainless) - Room 125 Cafeteria	8/14/2018	8/24/2018	A8H0415-10	Lead	0.481	0.200	15	ppb
230-3894-A-001-A	Bubbler (Left one of two) - Hallway near Library	8/14/2018	8/24/2018	A8H0415-11	Copper	0.413	0.00200	1.3	ppm
230-3894-A-001-A	Bubbler (Left one of two) - Hallway near Library	8/14/2018	8/24/2018	A8H0415-11	Lead	2.58	0.200	15	ppb

Analyzed by: Apex Laboratories
Reviewed by: G2 Consultants, Inc.

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

230-3894-A-001-B	Bubbler (Left one of two) - Hallway near Library	8/14/2018	8/24/2018	A8H0415-12	Copper	0.174	0.00200	1.3	ppm
230-3894-A-001-B	Bubbler (Left one of two) - Hallway near Library	8/14/2018	8/24/2018	A8H0415-12	Lead	0.784	0.200	15	ppb
230-3894-B-001-A	Bubbler (Right one of two) - Hallway near Library	8/14/2018	8/25/2018	A8H0415-13RE1	Copper	0.553	0.00200	1.3	ppm
230-3894-B-001-A	Bubbler (Right one of two) - Hallway near Library	8/14/2018	8/25/2018	A8H0415-13RE1	Lead	2.19	0.200	15	ppb
230-3894-B-001-B	Bubbler (Right one of two) - Hallway near Library	8/14/2018	8/24/2018	A8H0415-14	Copper	0.169	0.00200	1.3	ppm
230-3894-B-001-B	Bubbler (Right one of two) - Hallway near Library	8/14/2018	8/24/2018	A8H0415-14	Lead	0.808	0.200	15	ppb
230-3891-A-001-A	Bubbler (Left one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-15	Copper	0.450	0.00200	1.3	ppm
230-3891-A-001-A	Bubbler (Left one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-15	Lead	2.14	0.200	15	ppb
230-3891-A-001-B	Bubbler (Left one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-16	Copper	0.118	0.00200	1.3	ppm
230-3891-A-001-B	Bubbler (Left one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-16	Lead	0.423	0.200	15	ppb
230-3891-B-001-A	Bubbler (Right one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-17	Copper	0.853	0.00200	1.3	ppm
230-3891-B-001-A	Bubbler (Right one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-17	Lead	3.74	0.200	15	ppb
230-3891-B-001-B	Bubbler (Right one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-18	Copper	0.140	0.00200	1.3	ppm
230-3891-B-001-B	Bubbler (Right one of two) - Hallway near Room 115	8/14/2018	8/24/2018	A8H0415-18	Lead	1.84	0.200	15	ppb
230-3889-N/A-001-A	Bottle Filler/Fountain Combination (Bottle Filler only) - Right of Room 103	8/14/2018	8/25/2018	A8H0415-19RE1	Copper	0.0107	0.00200	1.3	ppm
230-3889-N/A-001-A	Bottle Filler/Fountain Combination (Bottle Filler only) - Right of Room 103	8/14/2018	8/25/2018	A8H0415-19RE1	Lead	1.24	0.200	15	ppb
230-3889-N/A-001-B	Bottle Filler/Fountain Combination (Bottle Filler only) - Right of Room 103	8/14/2018	8/25/2018	A8H0415-20RE2	Copper	0.0119	0.00200	1.3	ppm
230-3889-N/A-001-B	Bottle Filler/Fountain Combination (Bottle Filler only) - Right of Room 103	8/14/2018	8/25/2018	A8H0415-20RE2	Lead	0.480	0.200	15	ppb
230-3896-N/A-001-A	Bubbler - 2nd Floor Right of Room 203	8/14/2018	8/25/2018	A8H0415-21RE1	Copper	0.0160	0.00200	1.3	ppm
230-3896-N/A-001-A	Bubbler - 2nd Floor Right of Room 203	8/14/2018	8/25/2018	A8H0415-21RE1	Lead	5.59	0.200	15	ppb
230-3896-N/A-001-B	Bubbler - 2nd Floor Right of Room 203	8/14/2018	8/25/2018	A8H0415-22RE1	Copper	0.0120	0.00200	1.3	ppm
230-3896-N/A-001-B	Bubbler - 2nd Floor Right of Room 203	8/14/2018	8/25/2018	A8H0415-22RE1	Lead	12.2	0.200	15	ppb
230-3871-N/A-001-A	Bubbler - Basement, right of Mechanical Room, Left of B44	8/14/2018	8/23/2018	A8H0415-23RE1	Copper	0.523	0.00200	1.3	ppm
230-3871-N/A-001-A	Bubbler - Basement, right of Mechanical Room, Left of B44	8/14/2018	8/23/2018	A8H0415-23RE1	Lead	1.64	0.200	15	ppb
230-3871-N/A-001-B	Bubbler - Basement, right of Mechanical Room, Left of B44	8/14/2018	8/23/2018	A8H0415-24RE1	Copper	0.205	0.00200	1.3	ppm
230-3871-N/A-001-B	Bubbler - Basement, right of Mechanical Room, Left of B44	8/14/2018	8/23/2018	A8H0415-24RE1	Lead	ND	0.200	15	ppb

Analyzed by: Apex Laboratories
Reviewed by: G2 Consultants, Inc.

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

230-3904-N/A-001-A	Bubbler - Left of Room 143	8/14/2018	8/21/2018	A8H0415-25RE1	Copper	1.02	0.0200	1.3	ppm
230-3904-N/A-001-A	Bubbler - Left of Room 143	8/14/2018	8/23/2018	A8H0415-25RE2	Lead	1.51	0.200	15	ppb
230-3904-N/A-001-B	Bubbler - Left of Room 143	8/14/2018	8/23/2018	A8H0415-26RE1	Copper	0.343	0.00200	1.3	ppm
230-3904-N/A-001-B	Bubbler - Left of Room 143	8/14/2018	8/23/2018	A8H0415-26RE1	Lead	0.362	0.200	15	ppb

*EPA action level for lead is 20 ppb and 1.3 ppm for copper

Analyzed by: Apex Laboratories
Reviewed by: G2 Consultants, Inc.