

**Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
2nd Site Visit - Beaumont Middle School**

Sample Identification #	Location	Date Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
235-1669-N/A-001-A	Drinking Fountain - Gym 26A	8/30/2018	9/11/2018	A8H0865-01RE1	Copper	1.40	0.0100	1.3	ppm
235-1669-N/A-001-A	Drinking Fountain - Gym 26A	8/30/2018	9/11/2018	A8H0865-01	Lead	1.99	0.200	15	ppb
235-1669-N/A-001-B	Drinking Fountain - Gym 26A	8/30/2018	9/11/2018	A8H0865-02RE1	Copper	1.40	0.0100	1.3	ppm
235-1669-N/A-001-B	Drinking Fountain - Gym 26A	8/30/2018	9/11/2018	A8H0865-02	Lead	0.755	0.200	15	ppb
235-1653-N/A-001-A	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-03	Copper	0.737	0.00200	1.3	ppm
235-1653-N/A-001-A	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-03	Lead	9.33	0.200	15	ppb
235-1653-N/A-001-B	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-04	Copper	0.164	0.00200	1.3	ppm
235-1653-N/A-001-B	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-04	Lead	2.06	0.200	15	ppb
235-1656-N/A-001-A	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-05	Copper	0.290	0.00200	1.3	ppm
235-1656-N/A-001-A	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-05	Lead	152	0.200	15	ppb
235-1656-N/A-001-B	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-06	Copper	0.0123	0.00200	1.3	ppm
235-1656-N/A-001-B	Bubbler - Gym 111/109	8/30/2018	9/11/2018	A8H0865-06	Lead	4.56	0.200	15	ppb
235-1659-N/A-001-A	Sink (Food Prep) - Teacher's Lounge	8/30/2018	9/11/2018	A8H0865-07	Copper	0.410	0.00200	1.3	ppm
235-1659-N/A-001-A	Sink (Food Prep) - Teacher's Lounge	8/30/2018	9/11/2018	A8H0865-07	Lead	29.9	0.200	15	ppb
235-1659-N/A-001-B	Sink (Food Prep) - Teacher's Lounge	8/30/2018	9/11/2018	A8H0865-08	Copper	0.114	0.00200	1.3	ppm
235-1659-N/A-001-B	Sink (Food Prep) - Teacher's Lounge	8/30/2018	9/11/2018	A8H0865-08	Lead	8.29	0.200	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.