

**Portland Public Schools
Lead Water Sampling Results
Initial Flush Sample Data
Benson Polytechnic High School - Test 3**

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
115-CH4501-N/A-003-A	Classroom 125	3/21/2019	3/29/2019	A9C0788-01	Lead	9.87	0.20	15	ppb
115-CH4555-N/A-003-A	Classroom E127	3/21/2019	3/29/2019	A9C0788-03	Lead	ND	0.20	15	ppb
115-CH4548-N/A-003-A	Hallway (G8/G10)	3/21/2019	3/29/2019	A9C0788-05	Lead	27.00	0.20	15	ppb
115-CH4548-N/A-003-B	Hallway (G8/G10)	3/21/2019	4/10/2019	A9C0788-06	Lead	13.5	0.20	15	ppb
115-CH4545-N/A-003-A	Classroom D121	3/21/2019	3/29/2019	A9C0788-07	Lead	191.00	0.20	15	ppb
115-CH4545-N/A-003-B	Classroom D121	3/21/2019	4/10/2019	A9C0788-08	Lead	75.80	0.20	15	ppb
115-CH4564-N/A-003-A	Hallway (25)	3/21/2019	3/29/2019	A9C0788-09	Lead	ND	0.20	15	ppb
115-CH4527-N/A-003-A	Classroom C149	3/21/2019	3/29/2019	A9C0788-11	Lead	2.65	0.20	15	ppb
115-CH4533-N/A-003-A	Classroom C112	3/21/2019	3/29/2019	A9C0788-13	Lead	ND	0.20	15	ppb
115-CH4522-N/A-003-A	Classroom C134	3/21/2019	3/29/2019	A9C0788-15	Lead	4.05	0.20	15	ppb
115-CH4525-N/A-003-A	Hallway F102	3/21/2019	3/29/2019	A9C0788-17	Lead	16.50	0.20	15	ppb
115-CH4525-N/A-003-B	Hallway F102	3/21/2019	4/10/2019	A9C0788-18	Lead	3.5	0.20	15	ppb
115-CH4528-N/A-003-A	Hallway F212	3/21/2019	3/29/2019	A9C0788-19	Lead	1.68	0.20	15	ppb
115-CH4484-N/A-003-A	Kitchen	3/21/2019	3/29/2019	A9C0788-21	Lead	1.33	0.20	15	ppb
115-CH4484-N/A-003-B	Kitchen	3/21/2019	3/29/2019	A9C0788-22	Lead	ND	0.20	15	ppb
115-CH4484-N/A-003-C	Kitchen	3/21/2019	3/29/2019	A9C0788-23	Lead	ND	0.20	15	ppb
115-CH4484-N/A-003-D	Kitchen	3/21/2019	3/29/2019	A9C0788-24	Lead	ND	0.20	15	ppb

Analyzed by: Apex Laboratories
Reviewed by: PSI-Intertek

*OHA Action Level = 15ppb

115-CH4484-N/A-003-E	Kitchen	3/21/2019	3/29/2019	A9C0788-25	Lead	ND	0.20	15	ppb
115-CH4484-N/A-003-F	Kitchen	3/21/2019	3/29/2019	A9C0788-26	Lead	ND	0.20	15	ppb
115-CH4484-N/A-003-G	Kitchen	3/21/2019	3/29/2019	A9C0788-27	Lead	ND	0.20	15	ppb

Results highlighted indicate a value at or above PPS Action Level and the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.