

**Portland Public Schools
Lead Water Sampling Results
Initial Flush Sample Data
Blanchard Education Service Center (BESC) - Test 2**

Sample Identification #	Location	Date/Time Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
102-CH1009-N/A-002-A	Central Kitchen	3/19/2019	3/19/2019	A9C0795-01	Lead	7.79	0.20	15	ppb
102-CH1013-N/A-002-A	Central Kitchen	3/19/2019	3/19/2019	A9C0795-03	Lead	2.45	0.20	15	ppb
102-CH1014-N/A-002-A	Central Kitchen	3/19/2019	3/19/2019	A9C0795-05	Lead	82.50	0.20	15	ppb
102-CH1014-N/A-002-B	Central Kitchen	3/19/2019	3/19/2019	A9C0795-06	Lead	9.7	0.20	15	ppb
102-CH1016-N/A-002-A	Central Kitchen	3/19/2019	3/19/2019	A9C0795-07	Lead	1.53	0.20	15	ppb
102-CH1007-N/A-002-A	Central Kitchen	3/19/2019	3/19/2019	A9C0795-09	Lead	24.30	0.20	15	ppb
102-CH1007-N/A-002-B	Central Kitchen	3/19/2019	3/19/2019	A9C0795-10	Lead	19.30	0.20	15	ppb
102-CH1020-N/A-002-A	Hallway (L2-30)	3/19/2019	3/19/2019	A9C0795-11	Lead	7.09	0.20	15	ppb
102-CH1022-A-002-A	Hallway (L1-60)	3/19/2019	3/19/2019	A9C0795-13	Lead	ND	0.20	15	ppb
102-CH1022-B-002-A	Hallway (L1-60)	3/19/2019	3/19/2019	A9C0795-15	Lead	ND	0.20	15	ppb
102-CH1021-N/A-002-A	Central Warehouse	3/19/2019	3/19/2019	A9C0795-17	Lead	15.10	0.20	15	ppb
102-CH1021-N/A-002-B	Central Warehouse	3/19/2019	3/19/2019	A9C0795-18	Lead	17.80	0.20	15	ppb
102-CH1023-N/A-002-A	Hallway (160)	3/19/2019	3/19/2019	A9C0795-19	Lead	ND	0.20	15	ppb
102-CH1024-N/A-002-A	Hallway (160)	3/19/2019	3/19/2019	A9C0795-21	Lead	ND	0.20	15	ppb
102-CH1027-N/A-002-A	Hallway (Music Rm)	3/19/2019	3/19/2019	A9C0795-23	Lead	2.41	0.20	15	ppb
102-CH1028-N/A-002-A	Carpentry Room	3/19/2019	3/19/2019	A9C0795-25	Lead	12.2	0.20	15	ppb
102-CH1026-N/A-002-A	Plumbing Shop	3/19/2019	3/19/2019	A9C0795-27	Lead	ND	0.20	15	ppb

Analyzed by: Apex Laboratories
Reviewed by: PSI-Intertek

*OHA Action Level = 15ppb

102-CH1031-N/A-002-A	Hallway (150)	3/19/2019	3/19/2019	A9C0795-29	Lead	1.66	0.20	15	ppb
102-CH1033-A-002-A	Deli	3/19/2019	3/19/2019	A9C0795-31	Lead	ND	0.20	15	ppb
102-CH1029-A-002-A	Hallway (255)	3/19/2019	3/19/2019	A9C0795-33	Lead	ND	0.20	15	ppb
102-CH1029-B-002-A	Hallway (255)	3/19/2019	3/19/2019	A9C0795-35	Lead	ND	0.20	15	ppb
102-CH1032-A-002-A	Hallway (203)	3/19/2019	3/19/2019	A9C0795-37	Lead	ND	0.20	15	ppb
102-CH1030-N/A-002-A	Hallway (270)	3/19/2019	3/19/2019	A9C0795-39	Lead	4.3	0.20	15	ppb

Results highlighted indicate a value at or above PPS Action Level and the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.